PREPARED 8/21/15, 15:00:06 Harnett County

INSPECTION TICKET INSPECTOR: IVR

PAGE

DATE 8/24/15

-10

ADDRESS . : 138 HOMESTEAD LN SUBDIV: THE HOMESTEAD

PHONE : (910) 672-8900

PHONE :

OWNER . . : CRAWFORD WILLIAM G

PARCEL . . : 04-0682- - -0507- - -

APPL NUMBER: 14-50034599 CP NEW RESIDENTIAL (SFD) DIRECTIONS : T/S: 09/15/2014 10:29 AM VBROWN ----138 HOMESTEAD LANE, OFF OF OAK GROVE

CONTRACTOR : RED DOOR HOMES OF FAYETTEVILLE

CHRUCH RD, HOMESTEAD SUB DIV #8

STRUCTURE: 000 000 66X56 4BDR 2.5BATH SFD W GAR DECK

FLOOD ZONE . . . : FLOOD ZONE X

BEDROOMS : PROPOSED USE SFD

WATER SUPPLY : COUNTY SEPTIC - EXISTING? . . . : NEW TANK ______

PERMIT: CPSF 00 CP * SFD			
	REQUESTED	INSP	DESCRIPTION
TYP/SQ	COMPLETED	RESULT	RESULTS/COMMENTS
B101 01	8/07/15	DT	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002700243
	8/07/15	DA	T/S: 08/06/2015 01:58 PM LBENNETT
			T/S: 08/07/2015 11:15 AM DETAYLOR
			Approved plans call for continuous footer across garage
			door opening.
B101 02	8/10/15	DT	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002700714
	8/10/15	AP	T/S: 08/10/2015 11:34 AM DETAYLOR
B103 01	8/17/15	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 002703756
	8/17/15	DA	T/S: August 17, 2015 11:48 AM BSUTTON
			Left side of front porch foundation does not have proper
			projection. Piers inside front porch have no projection.
			Foundation must be insulated with R-10 foamboard from slab
			down 2 feet or to footing. DO NOT BACKFILL
A814 01	8/24/15	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002707081
B103 02	8/24/15 8:24:15	TI BY	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002707073

------ COMMENTS AND NOTES ---------

J.S. THOMPSON ENGINEERING, INC

structural and geotechnical custom residential design

August 20, 2015

Alan Powell Red Door Homes 4002 Fayetteville Road Raeford, NC 28376

Dear Mr. Powell:

The plan and provided pictures were reviewed for 138 Homestead Road in Angier, North Carolina to address the projection repairs at the outside face of the left porch wall and the pilasters within the front porch as noted by the inspector.

At each location a minimum 12" trench was excavated to the bottom of the footing and (1) row of #4 x 12" rebar dowels at 16" o.c. were embedded per our specifications with a minimum of (2) #4 x 12" rebar dowels at each pilaster. The newly added sections of concrete will provide the required support for all applied loads.

Please call me if you have any questions.

Sincerely,

J.S. Thompson Engineering, Inc. N.C. License No. C-1733

Tripp Amos

Matthew G. Strother, P.E.

606 Wade Avenue Raieigh, NC 27605 (919) 789-9919 OFFICE (919) 789-9921 FAX

