PREPARED \$5/12/16, 14:34:26 INSPECTION TICKET Harnett County

PAGE INSPECTOR: IVR

ADDIFISS : : 101 ATKINS VILLAGE CT SUBDIV: ATKINS VILLAGE PH1 20LTS
PHONE: (919) 233-3886

CONTRACTOR: ROYAL OAKS BUILDING GROUP LLC
OWNER . .: ROYAL OAKS BUILDING LLC PHONE :

PARCEL . . : 04-0672- - -0118- -05-

APPL NUMBER: 16-50038027 CP NEW RESIDENTIAL (SFD) DIRECTIONS : T/S: 02/17/2016 01:18 PM JBROCK ----

ATKINS VILLAGE LOT 5 premise # 53106724

STRUCTURE: 000 000 54X55 4BDR CRAWL W/ GARAGE

FLOOD ZONE . . . : FLOOD ZONE X

BEDROOMS : 4000000.00 PROPOSED USE : SFD

TYP/SQ	CPSF 00 CP * REQUESTED COMPLETED	INSP	DESCRIPTION RESULTS/COMMENTS
B101 01	3/28/16	BS	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 00279469
	3/28/16	DA	T/S: March 28, 2016 09:38 AM BSUTTON
B101 02	4/01/16	BS	
	4/01/16	AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002797629 Brad/Dean,
			This is a projection footing inspection. And a T pole inspection. The premise number is 72898612. And I will have a third-party engineer stamp letter in the box.
			I have already emailed a copy to Jennifer also. Thanks, Rick, 919 6 25 8325. T/S: April 01, 2016 01:00 PM BSUTTON
B103 01	4/01/16	BS	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002798114
	4/01/16	AP	T/S: April 01, 2016 01:01 PM BSUTTONT/S: April 01, 2016 01:03 PM BSUTTON
A814 01	4/07/16	SB	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002799617
	4/07/16	AP	101 ATKINS VILLAGE CT FUQUAY VARINA 27526 T/S: 04/07/2016 10:07 AM SBENNETT
3105 01	4/07/16	BS	R*OPEN FLOOR TIME: 17:00 VRU #: 002799625
	4/07/16	DA	T/S: April 07, 2016 11:18 AM BSUTTON
3105 02	4/08/16	BS	wrong. 3. Need hangers over access door.
	4/08/16	AP	R*OPEN FLOOR TIME: 17:00 VRU #: 002800837
3104 01	5/05/16	JB	T/S: April 08, 2016 03:14 PM BSUTTON
	5/05/16	AP	R*FOUND & SETBACK VERIF SURVEY TIME: 17:00 VRU #: 002812998 T/S: 05/05/2016 02:12 PM JBROCK
425 01	5/06/16	BS	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002813004
	5/06/16	DA	T/S: 05/05/2016 02:12 PM JBROCK

CONTINUED ONTO NEXT PAGE

PREPARED 5/12/16, 14:34:26 Harnett County

INSPECTION TICKET INSPECTOR: IVR

PAGE

18 DATE 5/13/16

ADDRESS : : 101 ATKINS VILLAGE CT

SUBDIV: ATKINS VILLAGE PH1 20LTS

CONTRACTOR : ROYAL OAKS BUILDING GROUP LLC

PHONE : (919) 233-3886

OWNER . . : ROYAL OAKS BUILDING LLC

PHONE :

PARCEL . . : 04-0672- - -0118- -05-

APPL NUMBER: 16-50038027 CP NEW RESIDENTIAL (SFD)

REQUESTED INSP

-----DESCRIPTION

TYP/SQ COMPLETED RESULT RESULTS/COMMENTS

floor. 2. Missing all exterior doors. 3. Repair air barriers at trusses over 1 car and at third floor. 4. No fireplace. 5. Hole in floor at return duct. 6. Insulation and air barrier behind laundry room. 7. CLose chase behind master vanity at stairs. 8. Improper headroom at third floor shower. 9.I joist cut for 1/2 bath plumbing drop. Need

engineering. DO not side/insulate

R425 02 5/13/16 5.13.16

FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002814887

T/S: 05/11/2016 08:26 AM JBROCK ----

eng. letter emailed to brad

COMMENTS AND NOTES -----



Date: May 11, 2016

To: Rick Sargent

Royal Oaks Building Group, LLC 1210 Trinity Road, Suite 102

Raleigh, NC 27607

E-Mail: rsargent@royaloakshomes.com

Re: Damaged Crawl Space I-joist Repair

Lot 5 Atkin's Village - Camellia Plan (Ref 9666)

Summit Job No.: 1852-10R (10193)

To Whom It May Concern:

SUMMIT Engineering, Laboratory & Testing, Inc. (SUMMIT) was contacted on May 11, 2016 by Rick Sargent on behalf of Royal Oaks Building Group, LLC to evaluate the notched crawl space i-joist located under the first floor powder room. Below is a summary of our findings:

Structure Description

This evaluation was performed for the structure during the construction process. The structure is the Camellia plan, under construction on Lot 5 of the Atkin's Village Community. The plan that was analyzed was sealed by Dennis C. Pilarczyk, Jr., P.E. on behalf of **SUMMIT**, dated January 26, 2016.

Observations and Conclusions

Based on our evaluation, the crawl space i-joist, which has been notched at the top flange in the area located under the first floor half bath shall be repaired as follows (repair may be made to either side of the damaged i-joist):

- The full web area of the damaged i-joist shall be packed solid with minimum 3/4" thick OSB/plywood. A continuous piece of 2x4 lumber shall be added to the top and bottom flanges, flush with the top/bottom of the joist. The interior web backer shall be in contact with the i-joist web and the exterior piece of 2x4 lumber.
- The repair shall extend a minimum of 2 feet on each side of the damaged flange area.
- 3) The repair assembly shall be fastened with four rows of 8d nails, spaced at 4 inches on center.

Based on photographs provided by Rick Sargent, on behalf of Royal Oaks Building Group, it appears that the damaged i-joist has been adequately repaired to meet or exceed the requirements stated above.

No other framing members have been evaluated at this time, and shall be framed in accordance with the sealed set of structural plans permitted for this site.


Closing

Opinions, conclusions, and recommendations made in this report are based solely on the performance observations made during the structural analysis pertaining to the scope of work as stated in the opening paragraph of this report. Performance standards are based on minimum building code requirements and the knowledge of our staff as gain through experience and professional training.



We appreciate the opportunity to assist you in this phase of your project and look forward to assisting you on future projects if possible. If you have any questions, please do not hesitate to contact us.

Sincerely, **SUMMIT**



Dennis C. Pilarczyk, Jr., P.E. Structural Department Manager

Alteration of this seal without the express written consent of the sealing engineer is a violation of the provisions set forth in the North Carolina Engineering and Land Survey Act (G.S. 89C) and may result in legal action by the North Carolina Board for Engineers and Land Surveyors.