

ADDRESS . . : 697 COKESBURY PARK LN
 CONTRACTOR : JLS HOMES, LLC
 OWNER . . : JLS HOMES LLC
 PARCEL . . : 05-0635- - -0124- -21-
 APPL NUMBER: 17-50040961 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 03/17/2017 01:17 PM JBROCK ----
 COKESBURY PARK #59

SUBDIV: COKESBURY PARK
 PHONE : (919) 422-7306
 PHONE :

STRUCTURE: 000 000 50X55 3BDR CRAWL W/ GARAGE & DECK

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3000000.00
 SEPTIC - EXISTING? : NEW TANK

PROPOSED USE : SFD
 WATER SUPPLY : COUTNY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	4/05/17 4/05/17	BS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002954431 T/S: April 05, 2017 09:53 AM BSUTTON ----- need tpole premise
B103 01	4/19/17 4/19/17	BS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 002959518 T/S: April 19, 2017 09:52 AM BSUTTON -----
B105 01	4/24/17 4/24/17	BS CA	R*OPEN FLOOR VRU #: 002963122 T/S: April 24, 2017 08:28 AM BSUTTON ----- per contractor
B105 02	4/26/17 4/26/17	BS AP	R*OPEN FLOOR VRU #: 002964054 T/S: April 26, 2017 10:35 AM BSUTTON -----
A814 01	5/23/17 5/22/17	SB AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002975464 697 CAKESBURY PARK LN FUQUAY VARINA 27526 T/S: 05/22/2017 11:33 AM SBENNETT -----
R425 01	5/23/17 5/23/17	BS DA	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002975472 T/S: 05/22/2017 08:11 AM JBROCK ----- T/S: May 23, 2017 11:42 AM BSUTTON ----- 1. Siding installed on house without inspection. 2. Firecaulk holes at entry door/washroom. 3. Truss A1 at garage end has a bad knot in the tension plane of the bottom chord. Have the truss company review this truss for possible failure. 4. Wrong nails in truss hangers. See Cutsheet D2L 5. Finish firestop at top of HVAC chase. 6. Stud columns under girder truss not direct bearing as shown on engineered detail. 7 Strap stud columns under girder truss. Do not insulate
R425 02	5/31/17 <u>5/31/17</u>	TT <u>APBS</u>	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002976876 T/S: 05/30/2017 08:15 AM BPETRICH -----

COMMENTS AND NOTES

Eng. AH




Plate Offsets (X,Y) - [A:0-2-0,0-0-3], [D:0-1-8,0-2-0], [H:0-3-14,0-0-3]

LOADING (psf)	SPACING- 2-0-0	CSL	DEFL. in (loc) l/defl L/d	PLATES	GRIP
TCLL 20.0	Plate Grip DOL 1.15	TC 0.43	Vert(LL) 0.05 N-Q >999 240	MT20	244/190
TCDL 10.0	Lumber DOL 1.15	BC 0.32	Vert(TL) -0.07 N-Q >999 180		
BCLL 0.0 *	Rep Stress Incr YES	WB 0.15	Horz(TL) -0.02 A n/a n/a		
BCDL 10.0	Code IRC2009/TPI2007	Matrix-MSH			
				Weight: 189 lb	FT = 4%


LUMBER-	BRACING-
TOP CHORD 2x4 SP No.2	TOP CHORD Structural wood sheathing directly applied or 6-0-0 oc purlins, except 2-0-0 oc purlins (6-0-0 max.); D-E.
BOT CHORD 2x4 SP No.2	BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.
WEBS 2x4 SP No.3	WEBS 1 Row at midpt C-L, D-L, D-J, E-J, F-J
SLIDER Left 2x6 SP No.2 1-11-0, Right 2x6 SP No.2 1-11-0	

REACTIONS. All bearings 4-8-0 except (j=length) A=Mechanical, H=Mechanical, M=0-3-8.
 (lb) - Max Horz A=300(LC 4)
 Max Uplift All uplift 100 lb or less at joint(s) except A=-129(LC 5), H=-158(LC 6), L=-180(LC 5)
 Max Grav All reactions 250 lb or less at joint(s) M except A=542(LC 1), H=519(LC 1), L=533(LC 1), J=702(LC 1)

FORCES. (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
 TOP CHORD A-B=-301/0, B-C=-389/216, C-D=-232/283, D-E=-51/282, E-F=-198/278, F-G=-358/230, G-H=-290/0
 BOT CHORD A-N=-205/374, M-N=-205/374, L-M=-205/374, I-J=-61/351, H-I=-61/351
 WEBS C-L=-403/251, F-J=-407/244, F-I=0/256

- NOTES- (9)
- 1) Unbalanced roof live loads have been considered for this design.
 - 2) Wind: ASCE 7-05; 100mph; TCCL=6.0psf; BCCL=6.0psf; h=35ft; Cat. II; Exp B; enclosed; MWFRS (low-rise) gable end zone; cantilever left and right exposed; end vertical left and right exposed; Lumber DOL=1.60 plate grip DOL=1.60
 - 3) Provide adequate drainage to prevent water ponding.
 - 4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
 - 5) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members, with BCCL = 10.0psf.
 - 6) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 129 lb uplift at joint A, 158 lb uplift at joint H and 180 lb uplift at joint L.
 - 7) This truss is designed in accordance with the 2009 International Residential Code sections R502.11.1 and R802.10.2 and referenced standard ANSI/TPI 1.
 - 8) Graphical purlin representation does not depict the size or the orientation of the purlin along the top and/or bottom chord.
 - 9) This repair has been prepared based on information and use conditions supplied by client. Designer has made a good faith effort to outline damage and repair conditions as reported by client. When actual field conditions do not approximate those indicated on this drawing, client shall immediately inform the engineer and refrain from applying the repair.

LOAD CASE(S) Standard



This truss is to be fabricated per ANSI/TPI quality requirements. Plates shall be of size and type shown and centered at joints unless otherwise noted. This design is based upon parameters shown, and is for an individual building component to be installed and loaded vertically. Applicability of design parameters and proper incorporation of component is responsibility of the Building Designer. Building Designer shall verify all design information on this sheet for conformance with conditions and requirements of the specific building and governing codes and ordinances. Building Designer accepts responsibility for the correctness or accuracy of the design information as it may relate to a specific building. Certification is valid only when truss is fabricated by a LFP company. Bracing shown is for lateral support of truss members only and does not replace erection and permanent bracing. Refer to Building Component Sales Information (BCSI) for general guidance regarding storage, delivery, erection and bracing available from SBCA and Truss Plate Institute.



SOUTHERN ENGINEERS

James Herman, PE – Owner

Consulting Structural Engineers

TO: JLS HOMES, LLC
P.O. BOX 696
HOLLY SPRINGS, NC 27540

***** FIELD CHANGE ORDER *****

VIA EMAIL: jhiege@jls homes.com

PROJECT #: 17-1087-A

PAGE: 1 of 1

DATE: May 30, 2017

LOCATION: Lot 59, Cokesbury Park

PLANS REF: "Lot 59, Cokesbury Park" by Design Meister

Hanger Attachment: Per roof truss layouts by UFP Mid-Atlantic for the above referenced location, the A3 roof trusses are to be attached to the D2L girder truss with HUS26 hangers. Per USP structural connectors catalog require the hanger is required to be attached using 16d common nails. The hangers were attached using 3-1/4" 12d nails.

Response: Be advised that the above hanger attachment using 3-1/4" 12d nails is structurally acceptable.

In closing, I trust that this letter fulfills your requirements at this time. Should you have any further questions, please do not hesitate to call.

Sincerely,

Jonathan A. Troxler, P.E.
Southern Engineers, P.A.
(License: C-1287)
Cc: wjh/jat

