

ADDRESS : 24 AFTON CT
 CONTRACTOR : ROYAL OAKS BUILDING GROUP LLC
 OWNER : ROYAL OAKS BUILDING GROUP
 PARCEL : 04-0664- - -0020- -24-
 APPL NUMBER: 17-50040972 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : T/S: 03/21/2017 08:39 AM JBROCK ----
 ATKINS VILLAGE #33
 T/S: 06/21/2017 01:56 PM JBROCK ----
 premise # 46617241

SUBDIV:
 PHONE : (919) 233-3886
 PHONE :

STRUCTURE: 000 000 45X67 4BDR CRAWL W/ GARAGE & DECK

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 4000000.00
 SEPTIC - EXISTING? : NEW TANK
 PROPOSED USE : SFD
 WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	6/09/17 6/09/17	JLP DA	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002982387 Temp Pole No premises number and no footings dug
A814 01	6/22/17 6/22/17	SB AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002988053 24 AFTON CT FUQUAY VARINA 27526 T/S: 06/22/2017 01:14 PM SBENNETT -----
E207 01	6/22/17 6/22/17	BS AP	R*ELEC TEMP SERVICE POLE TIME: 17:00 VRU #: 002988061 T/S: 06/21/2017 02:02 PM JBROCK ----- T/S: June 22, 2017 12:19 PM BSUTTON -----
B101 02	6/27/17 6/27/17	JLP DA	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002989812 T/S: 06/26/2017 01:18 PM JBROCK ----- eng letter will be on site 1-Make repairs to undermined footings per engineers letter.
B103 01	6/27/17 6/27/17	JLP DA	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002989820 T/S: 06/26/2017 01:19 PM JBROCK ----- eng letter will be on site 1-Make repairs to undermined footings per engineers letter.
B101 03	6/28/17 <u>6/28/17</u>	TI <u>AP</u> <i>AP</i>	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002990463
B103 02	6/28/17 <u>6/28/17</u>	TI <u>AP</u> <i>AP</i>	R*BLDG FOUND & TEMP SVC POLE VRU #: 002990471

COMMENTS AND NOTES



Faint, illegible text at the top of the page, possibly a header or title.

Faint, illegible text in the upper middle section of the page.

Faint, illegible text in the upper middle section of the page.

Faint, illegible text in the upper middle section of the page.

Faint, illegible text in the upper middle section of the page.

Faint, illegible text in the upper middle section of the page.

Faint, illegible text in the upper middle section of the page.

Faint, illegible text in the upper middle section of the page.

Faint, illegible text in the upper middle section of the page.

Faint, illegible text in the upper middle section of the page.

Faint, illegible text in the upper middle section of the page.

Faint, illegible text in the upper middle section of the page.

Faint, illegible text in the upper middle section of the page.

Faint, illegible text in the upper middle section of the page.

Faint, illegible text in the upper middle section of the page.

Faint, illegible text in the upper middle section of the page.

Faint, illegible text in the upper middle section of the page.

Faint, illegible text in the upper middle section of the page.

Faint, illegible text in the upper middle section of the page.

Faint, illegible text in the upper middle section of the page.

Faint, illegible text in the upper middle section of the page.

Faint, illegible text in the lower right quadrant of the page.

June 13, 2017

Mr. Rich Sherman
Royal Oaks Homes
rsherman@royaloakshomes.com**Report of Observations
Atkins Village North, Lot 33
Fuquay Varina, North Carolina
Our Project Number 121-15-78801**

Gentlemen:

As requested, a representative of TerraTech Engineers, Inc. was present at the above referenced site on June 13, 2017 to perform testing on the crawl space footing excavations for the proposed residential home located in the area of Lot #33. The purpose of our testing was to verify that the design soil bearing pressure is available for the concrete foundations. We understand that an allowable soil bearing pressure of 2,000 pounds per square foot (psf) is required. Our services did not include surveying. Locations are based on the excavations performed by others.

Our field examinations consisted of visual observations, dynamic cone penetrometer testing in accordance with ASTM STP-399, and hand rod probing at selected locations. Dynamic cone penetrometer testing was performed at select locations and to a maximum depth of 4 feet below the over-excavated foundation bearing elevation. Our scope did not include mechanically drilled soil test borings to evaluate deeper subsurface soil conditions that could affect foundation support. Such services can be provided, if desired.


During our site visit, soft soils were encountered to a depth of approximately 1 foot below the planned foundation bearing elevation. We recommended that the soft soils be removed from the footing excavation. We were informed by the contractor that the footing excavations would be backfilled with consolidated #57 washed stone to re-establish the foundation bearing elevation. After these remedial measures were performed and prior to placement of #57 washed stone, the results of our footing examinations indicated that an allowable bearing capacity of 2,000 pounds per square foot (psf) was available at the locations and depths tested at the time of our investigation. Additionally, the foundation dimensions met the plan minimum requirements.

Exposure to the environment, especially rainfall, may weaken the soils beneath the foundation bearing surface, if they are exposed for extended periods of time prior to concrete placement. If the over-excavated soils beneath the foundation bearing surface become softened due to exposure, the soft soils should be compacted or removed and replaced prior to placement of washed stone and concrete.


If you have any questions concerning this information, please do not hesitate to call.

Sincerely,

TerraTech Engineers, Inc. (C-1356)


Thomas O. Helms
Project Engineer

TOH/sk

cc: rsargent@royaloakshomes.com
Christopher S. Pitz, P.E.
Principal Geotechnical Engineer

The first part of the report deals with the general situation in the country. It is a very interesting and informative study of the economic and social conditions of the country at that time.

The second part of the report deals with the specific details of the country's development. It is a very detailed and thorough study of the country's progress in various fields.

The third part of the report deals with the future prospects of the country. It is a very optimistic and hopeful study of the country's potential for growth and development.

The fourth part of the report deals with the role of the government in the country's development. It is a very thoughtful and well-reasoned study of the government's responsibilities and actions.

The fifth part of the report deals with the role of the people in the country's development. It is a very inspiring and motivating study of the people's power and potential.

The sixth part of the report deals with the role of the international community in the country's development. It is a very insightful and well-informed study of the world's impact on the country.

The seventh part of the report deals with the role of the future in the country's development. It is a very visionary and forward-looking study of the country's destiny.

The eighth part of the report deals with the role of the past in the country's development. It is a very reflective and thoughtful study of the country's history and heritage.