INSPECTION TICKET INSPECTOR: IVR

PAGE DATE 38 3/16/18

ADDRESS : 430 COKESBURY PARK LN SUBDIV: COKESBURY PARK CONTRACTOR : TRIANGLE HOME PROS PHONE : (919) 346-1528

OWNER . . : TRIANGLE HOME PROS LLC PHONE :

PARCEL . . : 05-0635- - -0124- -32-

APPL NUMBER: 18-50043076 CP NEW RESIDENTIAL (SFD)
DIRECTIONS: T/S: 01/10/2018 02:51 PM BPETRICH -430 COKESBURY PARK LANE FUQUAY VARINA

430 CORESBURI PARK LAME FUQUAI VARIM

COKESBURY PARK #70

401N TO CHRISTIAN LIGHT - LEFT ONTO COKESBURY RD - LEFT ONTO COKESBURY PARK

LN.

# STRUCTURE: 000 000 50X52 3BD 2BA CRAWL W/GARAGE & DECK

FLOOD ZONE . . . : FLOOD ZONE X

PROPOSED USE . . . . : SFD SEPTIC - EXISTING? . . . : NEW TANK

WATER SUPPLY . . . . . . : COUNTY

#### PERMIT: CPSF 00 CP \* SFD

myp/co	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
TYP/SQ	COMPLEIED	KEPOLI	RESULTS/ COMMENTS
B101 01	2/23/18	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 003093404
	2/23/18	DA	T/S: February 23, 2018 03:28 PM BSUTTON
			Footing needs engineering. Either provide requirements and
			reschedule after corrections are done, or have engineer
			verify corrections and provide sealed letter that states
			footing meets 2012 NC One and Two Family Dwelling Code
A814 01	3/16/18	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 003102308
			T/S: 03/15/2018 12:59 PM DJOHNSON
B101 02	3/16/18	TI	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 003102316
	<u> </u>	<u> </u>	T/S: 03/15/2018 12:59 PM DJOHNSON
	,		CUSTOMER HAS ENGINEER LETTER ON SITE. ALSO THEY NEED A TSP
		1	INSPECTION AND WOULD LIKE INSPECTION AT MID MORNING.
B103 01	3/16/18	TI	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 003102324
	<u> γ</u>	H8 /	T/S: 03/15/2018 01:00 PM DJOHNSON
		'' [	CUSTOMER SAID HE WA TOLD HE COULD SCHEDULE THIS EVEN THOUGH
•		( , '	FOOTING WAS NOT APPROVED.

----- COMMENTS AND NOTES -----

per per cetter



8600 'D' Jersey Ct Raleigh, NC 27617 (P) (919) 218-4421 866.792.5107

March 9, 2018

Firm Lic. No: P-0961

Brian Culver THP Homes 6312 Lauraca Ln. Fuquay-Varina, NC 27526 brian.thphomes@gmail.com

Subject: Crawl space and Rear Deck Footing Preparation Inspection

Location: Lot 70 Cokesbury Park - 430 Cokesbury Ln. (Fuquay-Varina, NC)

Project No: BCH180934 Review Date: 3/7/2018

We are pleased to provide the evaluation of the subject and location referenced above.

## **Observations:**

Crawl space and rear deck footing preparation inspection.

- -Strip Footings are sized (width, depth, and length) and installed per plan.
- -Pier Footings are sized (width depth, and length) and located per plan.
- -Lug Footings are sized (width, depth, and length) and located per plan.
- -Reinforcement (if required) is installed per plan.
- -Footings are clean and free of organic material.
- -Soil bearing capacity was tested by JDS on 03-07-18. The field report is posted in the permit box.

#### **Recommendations:**

Based on our on-site observations and review, the crawl space and rear deck footings have been adequately prepared in accordance with the Town of Fuquay-Varina approved permit plans and details. Additionally, the footings are installed in accordance with 2012 NCRC section R403.1 and is ready for concrete placement.

If you have any questions or if I can be of further assistance to you on this project, please contact me at (919) 218-4421

Respectfully Submitted, Brian Hickey JDS Consulting & Design, PLLC

Reviewing Engineer: Elijah B. Smith, P.E.



8600 'D' Jersey Ct Raleigh, NC 27617 (P) (919) 218-4421 (F) (866) 792-5107

Firm Lic. No: P-0961

Brian Culver
THP Homes

6312 Lauraca Ln.

Fuquay-Varina, NC 27526 brian.thphomes@gmail.com

Issue Date: March 12, 2018

Review Date: 3/2/2018 Project No: BCH180855

Subject: Soil Suitability for Foundation Installation

Location: Lot 70 Cokesbury Park - 430 Cokesbury Lane (Fuquay-Varina, NC)

### **Observations:**

Foundation excavation observation (sub-surface testing with respect to bearing capacity).

## Recommendations:

The exposed soils have been observed and tested for the crawl space and rear deck footings (Probe & DCP). The materials are free of organics and based on our review and testing the soil and conditions for the foundation are suitable for the minimum required bearing pressure of 2000 psf. Additionally, any over-excavated areas (multiple locations, 1ft to 4ft) shall be backfilled with full depth concrete and have (2) #4 rebar placed horizontally extending 5ft in each direction.

If you have any questions or if I can be of further assistance to you on this project, please contact me at (919) 218-4421

Respectfully Submitted, Brian Hickey JDS Consulting & Design, PLLC

Reviewing Engineer: Elijah B. Smith, P.E.

# **General Notes:**

- •Mechanical testing methods vary per site but always include probe rod testing across the entire excavation and augers (minimum 3 locations) at multiple depths with Dynamic Cone Penetrometer (DCP) testing.
- •Bearing capacity test results are voided if significant precipitation or water intrusion has occurred within 48 hours of the initial testing.
- •JDS is not responsible for site conditions that divert water towards the foundation or that prevent drainage away from the foundation that can lead to soft soils and future settlement.
- •This report is assessment of vertical bearing capacity only. Unless specifically noted otherwise retaining wall testing, nor slope stability analysis has been evaluated. JDS shall not be held responsible for current or future retaining wall or slope related issues.
- •It is the contractors responsibility to ensure that all foundation areas are free of loose material, standing water, and any other deleterious materials prior to placement of stone or concrete.



PO Box 80755 Raleigh, NC 27623

www.jdsdesignonline.com

(P) (919) 480-1075

(F) (866) 792-5107

info@jdsdesignonline.com

Soil Suitability f	or Foundation Installation - Field Report - Conditional Approval
	Sealed Report Forthcoming

Client:	·Triangle	Homes				•			
Date:	03/87/	18							
Project Number:	BC#1801	955							
Location:	70 Coke	sbury PA	<u>r</u> K						
Observations:									
JDS performed DCP	and probe rod te	esting to verif	y soil bearing c	onditions for	the areas	indicated below:			
	Basement			h	Other:				
V	Crawl Space	<del></del>	Rear Porch	ı / Patio	•				
	Stem Wall	,	n Deck		•				
	Monolithic Slab	$\rightarrow$	Garage		•				
Results:	4	<del></del>	. ,						
Test results indicate the	ha soils ara suita	able for the m	inimum require	ed hearing pro	essure of				
rest results indicate ti	ne sons are suna	iole for the fil	mmam require	d ocaring pro	cosuic oi.				
	2000 PSF		2500 PSF	_		3000 PSF			
				Γ	OCP Min:	8			
Over-excavation:					MPRP:	~1.25"			
		М							
	Ft t	o <u> </u>	Ft						
Back Filled with:	#57	#67		#78		Concrete			
<del> </del>									
General Notes:									
•Bearing capacity test resu initial testing.	lts are voided if sign	nificant precipita	ation or water intro	ision has occurr	ed within 48	hours of the			
•JDS is not responsible for foundation that can lead to			vards the foundation	on or that preven	nt drainage a	way from the			
•This report is assessment of vertical bearing capacity only. Unless specifically noted otherwise retaining wall testing, nor slope stability analysis has been evaluated. JDS shall not be held responsible for current or future retaining wall or slope related issues.									
•It is the contractors responsibility to ensure that all foundation areas are free of loose material, standing water, and any other deleterious materials prior to placement of stone or concrete.									
•Concrete shall not be placed on to frozen ground or in to excavations containing ice or snow									
	J			-		IV			

1