PREPARED 6/06/18, 14:11:18 PAGE 15 INSPECTION TICKET Harnett County INSPECTOR: IVR DATE 6/07/18 ADDRESS . : 6963 RAWLS CHURCH RD SUBDIV: PHONE : (910) 590-3513 CONTRACTOR: SOUTHEASTERN OUTDOOR PRODUCTS PHONE : OWNER . . : ROBERTS SHANNON U & TIMOTHY L PARCEL . .: 08-0644- - -0084- -02-APPL NUMBER: 17-50042749 CP NEW STORAGE BLDG RESIDENTIAL DIRECTIONS: T/S: 11/14/2017 10:33 AM BPETRICH --6963 RAWLS CHURCH RD FUQUAY VARINA 27526 STRUCTURE: 000 000 30X32 METAL STORAGE BUILDING FLOOD ZONE . . . : FLOOD ZONE X PROPOSED USE STORAGE SEPTIC - EXISTING? . . . : EXISTING WATER SUPPLY : COUNTY PERMIT: CPBP 00 CP BUILDING PERMIT REQUESTED INSP DESCRIPTION

TYP/SO COMPLETED RESULT RESULTS/COMMENTS B114 01 5/24/18 MC 5/24/18 DA R*BLDG MONO SLAB/TEMP SVC POLE TIME: 17:00 VRU #: 003131455 T/S: 05/23/2018 01:00 PM DJOHNSON ------CUSTOMER SAID THIS IS BEFORE THE POUR. T/S: 05/24/2018 02:55 PM MCOOK -----1.need soils compaction test 2. remove all loose soils from footings 3. back right corner form board low R*BLDG MONO SLAB/TEMP SVC POLE TIME: 17:00 VRU #: 003136728

B114 02

----- COMMENTS AND NOTES ------

T/S: 06/06/2018 12:02 PM LLUCAS -----



PO Box 80755 Raleigh, NC 27623 (P) (919) 480-1075 (F) (866) 792-5107

Soil Suitability for Foundation Installation - Field Report - Conditional Approval Sealed Report Forthcoming

Chem Diste Resolu	<u>ces</u>			
Date: 6/6/18				
Project Number: BCH 825	78			
Location: 6963 Rawls	Church R	7		
Observations:				
TDC nonformed DCD and make and teating	. +		· · · · · · · · · · · · · · · · ·	3: 4 . 1 1 1 .
JDS performed DCP and probe rod testing	to verify son t	earing conditions i	or the areas i	ndicated below:
Basement	Basement Front Porch		Other:	
Crawl Space	Re	ear Porch / Patio	_	***
Stem Wall	De			
Monolithic Slab		rage	-	·
Wionontine State	°	aago	_	
Results:				
Test results indicate the soils are suitable for	or the minimum	n required bearing r	recoure of	•
rest results indicate the sons are suitable in	or the himmin	u required bearing p	nessure or.	
X . 2000 PSF	25	00 PSF	3	3000 PSF
			DCP Min:	7
Over-excavation:			MPRP:	1) ((
Over Cacavation.				
Ft to	Ft			
Back Filled with: #57	#67	#78		Concrete
Back Filled with: #57	#07	# / 0		Concrete
General Notes:				
•Bearing capacity test results are voided if significan	t precipitation or	water intrusion has occu	rred within 48 l	nours of the
initial testing.				
•JDS is not responsible for site conditions that divert	r stratar tostrards the	foundation or that pres	ent drainage av	vay from the
foundation that can lead to soft soils and future settle		s touridation of that bies	em dramage av	vay nom aic
 This report is assessment of vertical bearing capacit slope stability analysis has been evaluated. JDS shall 	y only. Unless spe I not be held respo	ecifically noted otherwis	se retaining wall	l testing, nor
related issues.	t dot be neta tespo	distore for current or far	are tetaming we	m or stope
			. 1.	1
•It is the contractors responsibility to ensure that all other deleterious materials prior to placement of ston		re tree of loose material	, standing water	r, and any

•Concrete shall not be placed on to frozen ground or in to excavations containing ice or snow