## Harnett County Department of Public Health

## Improvement Permit

A	building permit cannot be issued with only an Improvement	MITCHIEL 15. (32.1535-)
ISSUED TO: CORTS TORNS T		101 #
NEW REPAIR EXPANSIO		quired prior to Construction Authorization Issuance:
Type of Structure: Ext. 3-02070000		
Proposed Wastewater System Type: 2510 1255		
Projected Daily Flow: 366 GPD		1
Number of bedrooms: 3 Number of Occup	ants: 6 max	
Basement Yes No		
	ired based on final location and elevations of facilities	
Type of Water Supply: Community Public		Permit valid for: Prive years
Permit conditions:		■ No expiration
Authorized State Agent::	Date: 09/21/2	
The issuance of this permit by the Health Department in no way guaran	itees the issuance of other permits. The permit holder is responsible for characteristics	ecking with appropriate governing bodies in meeting their requirements. This
		ership of the site. This permit is subject to compliance with the provisions of
the Laws and Rules for Sewage Treatment and Disposal and to condition	s of this permit.	
	Construction Authorization	
	(Required for Building Permit)	
The construction and installation requirements of Rules .1950, .1952, .1		into this permit and shall be met. Systems shall be installed in accordance
with the attached system layout.		
100 100 100 100 100 100 100 100 100 100	DRODERTY LOCATION.	(3)
ISSUED TO: C-NTIS EDENS J.		LOT #
	SUBDIVISION	LUI #
Facility Type: TXT 3-B-L 5-55	New Expansion 🔁 Repair	
	tures? Yes No	
Type of Wastewater System**	T APPUCABLE	(Initial) Wastewater Flow: 360 GPD
(See note below, if applicable )		
2576 TED	KATION STSTIZL (Repair)	
Installation Requirements/Conditions	Number of trenches3	
Septic Tank Size 1000 gallons	Exact length of each trenchfeet	Trench Spacing: Feet on Center
Pump Tank Sizegallons	Trenches shall be installed on contour at a	Soil Cover: 8 inches
Tomp tank size	Maximum Trench Depth of: 20 inches	(Maximum soil cover shall not exceed
	(Trench bottoms shall be level to +/-1/4"	36" above the trench bottom)
	Wall Mary 1979 Mark	30 above the trench bottom)
C 7011	in all directions)	inches below pipe
Pump Requirements:ft. TDH vs	GPM	
	2 8	Aggregate Depth: inches above pipe
Conditions: STE NOTES ON	SITE PLAN	inches total
WATER LINES (INCLUDING IRRIGATION) MUST I	BE 10FT. FROM ANY PART OF SEPTIC SYSTEM OR	REPAIR AREA.
NO UTILITIES ALLOWED IN INITIAL OR REPAIR D		
**If applicable: I understand the system type specified	d is different from the type specified on the application	n. I accept the specifications of this permit.
Owner/Legal Representative Signature:		Date:
This Construction Authorization is subject to revocation if the site plan,	plat, or the intended use changes. The Construction Authorization shall not	
Construction Authorization is subject to compliance with the provisions of	of the Laws and Rules for Sewage Treatment and Disposal and to the condi-	tions of this permit. SEE ATTACHED SITE SKETCH
Authorized State Agent:	Date:	09/21/2023

## Harnett County Department of Public Health Site Sketch

Property Location: 2342 MITCHELL 15. (51/535)	1 at #
Issued To: Waris Edward 572. Subdivision_	Lot #
Authorized State Agent:	Date: 044(12022
A ANDREW COM	LIN A
DEFORM LINES SHALL  STATED BY STATED  PILE - INSTITUTE OIL STRING  FRONT TO BACK  SHALL BY LOCATION  SHALL BY LOCATION  AND MANGED ONSITE  LICENTIAN LINEARY  CUTANING LINEARY  LOCATIONS  D  2	* CANDITY TO D-BOX  REWAL DISTRIBUTION  * 2000 NAX  * TUSTOUL AS HIGH  UPHILL AS CONTOC  ALLOWS  * LOCATE EXT LINES  AND JUSTALL DIRECT
EXT V EXT WELL	
E EXT	
	3
1 MITCHELL NOS. CSI	

Ricky Holland Precision Septic 554 Homestead Lane Angier, NC 27501 919-639-8929

Property Address: 2342 Mitchell Road, Angier

Inspection For: Heather Figueroa

On August 15, 2022, I was at the property address above to provide a point of sale septic inspection. A copy of the existing septic permit was not available for this 3-bedroom Harnett County property. Potable water is supplied to the home via a private well that is located in front and to the right of the entry driveway. There is an abandoned well to the left side of the driveway.

The sentic tank is located at the back right with the inlet access measuring 19'6" out to the inlet access. When I arrived, the handles to the inlet access were visible in a depressed area slightly below ground level. The riser lid was removed to see grease buildup and the static water level above the pluming inlet pipe of this vacant house. There appeared to be (2) 12-inch concrete risers stacked on top of the tank and not mortared to the tank or each other since root intrusion was evident at the joints. The lid to the septic tank was on the ground by the air conditioning unit. Several very small sweet gum saplings were cut to access the open hole where the distribution box is located. The distribution box lid was on top of the ground and mostly covered with pine straw. This lid appeared to have been off of the box for a considerable length of time due to the root growth all around and in the distribution box. This debris was shoveled out to see two corrugated pipes exiting the box and full of roots. I did not dig the outlet end of the septic tank due to its depth and small saplings that were cut in this area. A water flow test that lasted for 9 minutes and 30 seconds at 5 gallons per minute showed water running over the top of the access riser.

This onsite wastewater system met the rules for failure on this day. The buyer was onsite for the entire inspection. Later on this same day, I was informed that the seller's were willing to contribute towards an entire new system.

Sincerely, Ricky Holland Precision Septic License 1098i