



113633

113633 95 Dive Bomb St 7.9

Customer Information			
Project ID	113633	Zip Code	27546
Homeowner Name	113633	Lender	Dividend
Street Address	95 Dive Bomb St	Utility Provider	Duke Energy - North Carolina
City	Lillington	Region	Raleigh
State	NC	Processed	No
Fleet			
Vehicle Number:	E136	Please select all that apply.	
Vehicle Type:	Box Truck	Installer Phone Number:	
Is there anything that needs to be addressed by the fleet team?	No	Provide a concise description of the problems to assist the Fleet department in swiftly addressing the issue(s).	
Is the Laddervator being utilized for this project?	No		
System Information			
System Size (in kW)	7.9	Inverter Manufacturer	SunPower
Module Manufacturer	SunPower	Inverter Model	IQ8M-72-M-US

Anchor

Module Model

Page 1 of 25 Report Created: 03/22/2024

MSE395SX9R

Roof Attachments			
Were any pilot holes holes missed?	No		
Rail			
Are these U-Series?	No		
Junction Box			
EMT			
Is there EMT on the roof?	No		
Attic			
Was there attic work?	Yes		
Modules			
Take a photo of the module nameplate & confirm that they match the design.	Yes, they match the design.	Reason for modules not matching the design.	
Commissioning			
Has the electrical installation been completed?	No		
Design			
Was there a call to Hotline made during today's installation? If so, please provide a note regarding the reason for the call.	No	Have there been any design changes made in the field? (Must have Hotline Approval: 512-200-2085)	No - Built as Designed
Customer Walkthrough			
Is the homeowner or customer representative present, and available for a walkthrough?	tative present, and for a walkthrough? resent, or declined Call and/or Text the Customer:	"As we closeout this walkthrough, is there anything you would like our customer experience team to handle that	None
HO not present, or declined walkthrough.		is beyond my expertise?" Homeowner Confirmation:	"We recognize the significance of keeping you well-informed throughout this process. Our dedicated Customer Care team will ensure that you receive regular updates concerning the

Page 2 of 25 Report Created: 03/22/2024

If declined, request the HO signature.

"Hey there! We're super excited to let you know that your new equipment is fully installed. Our crew did an quality job following the design and getting the solar portion of the project inspection ready."

"Would you like to accompany me on a walk around your home while I clean up and review the installation? If you notice anything that needs attention, please inform me so I can promptly address it or make a note for further review."

city and utility inspection schedules. These inspections typically require approximately 30-45 days to finalize, as they are coordinated with the utility provider's availability. Once the utility inspection phase successfully concludes and your utility grants permission to operate, we will proceed with registering your warranty and granting you access to your monitoring services. This represents a significant step forward, providing you with comprehensive visibility and control over your project's advancement. As we approach the final stages, we will conclude the project by inviting you to a virtual launch meeting. During this meeting, we will cover the entire process, including how to energize your system, make effective use of the monitoring services, and supply you with essential tax information. This session is designed to ensure your complete comfort and confidence with every aspect of your new setup. Kindly confirm that all matters have been addressed." Yes

Homeowner Signature

Haund Endoloratios

Customer Review:

Link to review: https://www. google.com/search? sca_esv=561932315&q=Freedom

"Before we leave, could you do me a favor and leave a Google Review? Additionally, I wanted to let you know that you'll be receiving a survey within the next few days. This survey will allow you to provide feedback on various topics, including sales, installation, and communication. Your honest feedback would be greatly appreciated!"

Additional Work

Was there any damage incurred during this installation?

No

Is there any other additional work that needs to be addressed?

No

Select all applicable options and provide any relevant notes and photos of the damage(s) identified. Check all relevant options and provide any necessary notes and photos of the required additional work.

FSP Employee Confirmation

Page 3 of 25 Report Created: 03/22/2024

Employee Confirmation

To the best of my knowledge, I confirm that the provided information is accurate and truthful. All requested photos and documentation have been successfully uploaded under the correct Project ID. I have verified and provided evidence that all micro inverters are able to be discovered.

Employee Signature

Kil B-S-

Page 4 of 25 Report Created: 03/22/2024

Customer Information / Photo: Street Address



Ricardo Espana Loc: **35.3754, -78.8713**

Fleet / Photo of Dashboard/Gauges




Ricardo Espana Loc: **35.3755, -78.8712**

Fleet / Parked Truck w/ Safety Cones



Ricardo Espana Loc: **35.3755, -78.8711**

Fleet / Inside/Cab of Truck



Ricardo Espana Loc: **35.3755, -78.8712**

Page 5 of 25 Report Created: 03/22/2024

Fleet / Back of Truck (Doors Open)



Ricardo Espana Loc: **35.3755, -78.8712**

Safety / Safety Equipment in Truck




Ricardo Espana Loc: **35.3755, -78.8713**

Safety / Safety Equipment in Truck



Ricardo Espana Loc: **35.3755**, **-78.8713**

Safety / Safety Equipment in Truck




Ricardo Espana Loc: **35.3755, -78.8714**

Page 6 of 25 Report Created: 03/22/2024

Safety / Controlled Access Zone w/ Safety Cones



Safety / Jobsite Safety Analysis Sheet w/ Signatures



Ricardo Espana Loc: **35.2732**, **-80.8279**


Ricardo Espana Loc: **35.3754, -78.8713**

Safety / Ladder Location



Ricardo Espana Loc: **35.3753, -78.8714**

Safety / Fall Protection PPE (e.g, rope, caribiner)



Ricardo Espana Loc: **35.3754, -78.8715**

Page 7 of 25 Report Created: 03/22/2024

Anchor / Fall Protection Anchor (Fastened into the rafters w/ all 3 lag screws used)



Anchor / Close Up of Sealed Anchor Penetrations (Sealant underneath & a bead of sealant in the holes in the shingle, above the flashing)



Ricardo Espana Loc: **35.3754**, **-78.8715**

Anchor / Fall Protection Anchor (Fastened into the rafters w/ all 3 lag screws used)



Ricardo Espana Loc: **35.3755, -78.8714**

Anchor / Materials used to seal holes (Flashing, caulk, etc.)




Ricardo Espana Loc: **35.3754, -78.8715**

Page 8 of 25 Report Created: 03/22/2024

Roof Attachments / Close Up of Roof Attachment



Ricardo Espana Loc: **35.3755**, **-78.8714**






Ricardo Espana Loc: **35.3755, -78.8714**

Roof Attachments / Wide Shot of Roof Attachment



Ricardo Espana Loc: **35.3754**, **-78.8715**

Roof Attachments / Wide Shot of Roof Attachment




Ricardo Espana Loc: **35.3754**, **-78.8715**

Page 9 of 25 Report Created: 03/22/2024

Roof Attachments / Proper Spacing - Between last Attachment w/ Tape Measure



Rail / Rail Thickness w/ Tape Measure



Ricardo Espana Loc: **35.3754, -78.8714**

Rail / Rail Thickness w/ Tape Measure



Ricardo Espana Loc: **35.3754, -78.8714**

Rail / Leveled Panel-Ready Rail



Ricardo Espana Loc: **35.3755, -78.8714**

Page 10 of 25 Report Created: 03/22/2024

Rail / Leveled Panel-Ready Rail



Rail / Leveled Panel-Ready Rail



Ricardo Espana Loc: **35.3755, -78.8714**

Rail / Splices - All splices with screws clearly visible



Ricardo Espana Loc: **35.3754, -78.8714**

Rail / Splices - All splices with screws clearly visible



Ricardo Espana Loc: **35.3754, -78.8715**

Page 11 of 25 Report Created: 03/22/2024

Rail / Splices - All splices with screws clearly visible



Rail / Splices - All splices with screws clearly visible



Ricardo Espana Loc: **35.3754, -78.8714**

Rail / Splices - All splices with screws clearly visible



Ricardo Espana Loc: **35.3754, -78.8714**

Rail / Splices - All splices with screws clearly visible




Ricardo Espana Loc: **35.3754, -78.8714**

Page 12 of 25 Report Created: 03/22/2024

Rail / Splices - All splices with screws clearly visible



Rail / Splices - All splices with screws clearly visible



Ricardo Espana Loc: **35.3754, -78.8714**

Rail / Splices - All splices with screws clearly visible



Ricardo Espana Loc: **35.3754, -78.8714**

Rail / Splices - All splices with screws clearly visible



Ricardo Espana Loc: **35.3754, -78.8714**

Page 13 of 25 Report Created: 03/22/2024

Rail / Splices - All splices with screws clearly visible



Rail / Splices - All splices with screws clearly visible




Ricardo Espana Loc: **35.3754, -78.8715**

Rail / Splices - All splices with screws clearly visible



Ricardo Espana Loc: **35.3754, -78.8715**

Rail / Splices - All splices with screws clearly visible



Ricardo Espana Loc: **35.3754, -78.8715**

Page 14 of 25 Report Created: 03/22/2024

Rail / Grounding - Lug



Junction Box / Wide Shot of J Box



Ricardo Espana Loc: **35.3754, -78.8714**

Ricardo Espana Loc: **35.3754, -78.8714**

Junction Box / Close Up of J Box w/o Cover (Flashing, Connectors, Grounding, Splicing, Weep Holes, & Labeling)



Ricardo Espana Loc: **35.3754**, **-78.8714**

Junction Box / Marked Interior of J Box Cover (Signed & Dated)



Ricardo Espana Loc: **35.3754, -78.8714**

Page 15 of 25 Report Created: 03/22/2024

EMT / EMT - Pipedown



EMT / EMT - Pipedown



Ricardo Espana Loc: **35.3756, -78.8714**

Attic / Straps & Staples



Attic / Straps & Staples



Ricardo Espana Loc: **35.3755**, **-78.8714** Ricardo Espana Loc: **35.3755**, **-78.8714**

Attic / Straps & Staples



Ricardo Espana Loc: **35.3755**, **-78.8714**

Attic / Straps & Staples




Ricardo Espana Loc: **35.3755**, **-78.8714**

Attic / Straps & Staples



Ricardo Espana Loc: **35.3755, -78.8714**

Attic / Straps & Staples



Ricardo Espana Loc: **35.3755, -78.8714**

Page 17 of 25 Report Created: 03/22/2024

Attic / Roof Deck Under Arrays



Modules / Wire Management - Under Array (Must be taken from ROOF)



Ricardo Espana Loc: **35.3754, -78.8714**

Modules / Wire Management - Under Array (Must be taken from ROOF)



Modules / Wire Management - Under Array (Must be taken from ROOF)



Ricardo Espana Loc: **35.3754, -78.8714** Ricardo Espana Loc: **35.3754, -78.8714**

Modules / Wire Management - Under Array (Can be taken from GROUND)



Modules / Wire Management - Under Array (Can be taken from GROUND)




Ricardo Espana Loc: **35.3753, -78.8714**

Modules / Wire Management - Under Array (Can be taken from GROUND)




 $\label{lem:modules} \begin{tabular}{ll} Modules / Grounding (All rows of modules, including bare copper, row-to-row ground clips, or bonding jumpers) \end{tabular}$



Ricardo Espana Loc: **35.3754**, **-78.8714**

Ricardo Espana Loc: **35.3753, -78.8714**

Modules / Grounding (All rows of modules, including bare copper, row-to-row ground clips, or bonding jumpers)



Modules / Ends - No Panel Edges Cut




Ricardo Espana Loc: **35.3754, -78.8715**

Modules / Grounding (All rows of modules, including bare copper, row-to-row ground clips, or bonding jumpers)



Ricardo Espana Loc: **35.3754, -78.8715**

Modules / Ends - No Panel Edges Cut



Ricardo Espana Loc: **35.3754, -78.8715**


Page 20 of 25 Report Created: 03/22/2024

Modules / Ends - No Panel Edges Cut




Ricardo Espana Loc: **35.3754, -78.8714**

 $\operatorname{Modules}/\operatorname{Micro}\operatorname{Map}$ - Centered ,in frame, & w/ all the MI serial numbers (stickers) visible



Ricardo Espana Loc: **35.3754, -78.8715**

Modules / Micro Map - Centered ,in frame, & w/ all the MI serial numbers (stickers) visible



Ricardo Espana Loc: **35.3754, -78.8715**


Modules / Micro Map - Centered ,in frame, & w/ all the MI serial numbers (stickers) visible



Ricardo Espana Loc: **35.3754, -78.8714**

Page 21 of 25 Report Created: 03/22/2024

Modules / Circuit Map - All circuits & jumper locations labeled



Modules / Circuit Map - All circuits & jumper locations labeled



Ricardo Espana Loc: **35.3755, -78.8713**

Modules / Full Array(s) - Must have images for ALL arrays



Modules / Full Array(s) - Must have images for ALL arrays



Ricardo Espana Loc: **35.3754, -78.8714** Ricardo Espana Loc: **35.3754, -78.8714**

Modules / Full Array(s) - Must have images for ALL arrays



Modules / Full Array(s) - Must have images for ALL arrays



Ricardo Espana Loc: **35.3753**, **-78.8714**

 $\textbf{Modules} \ / \ \textbf{Cantilever - Last attachment to panel-edge w/ tape measurement}$



Modules / Cantilever - Last attachment to panel-edge w/ tape measurement



Ricardo Espana Loc: **35.3754, -78.8715** Ricardo Espana Loc: **35.3754, -78.8715**

Page 23 of 25 Report Created: 03/22/2024

Modules / PV Jumpers - Assembly of M/F heads (Inner Threading)



Modules / PV Jumpers - Assembly of M/F heads (Inner Threading)



Ricardo Espana Loc: **35.3754, -78.8713**

Modules / PV Jumpers - Assembly of M/F heads (Inner Threading)



Ricardo Espana Loc: **35.3754, -78.8713**

Modules / Take a photo of the module nameplate & confirm that they match the design.



Ricardo Espana Loc: **35.3755, -78.8713**

Page 24 of 25 Report Created: 03/22/2024

Commissioning / DC Commissioning - All MIs Discovered (Screenshot)



Ricardo Espana Loc: **35.6882**, **-80.4207**

Page 25 of 25 Report Created: 03/22/2024