
MEMBER REPORT

DAMAGE EVALUATION

2nd Floor, FC1: C22' (i2655) - 2 such damaged joists 1 piece(s) 14" TJI® 110 @ 24" OC



All locations are measured from the outside face of left support (or left cantilever end). All dimensions are horizontal.

Design Results	Actual @ Location	Allowed	Result	LDF	Load: Combination (Pattern)
Member Reaction (lbs)	614 @ 12' 5 1/4"	1935 (3.50")	Passed (32%)	1.00	1.0 D + 1.0 L (Adj Spans)
Shear (lbs)	385 @ 12' 8"	1860	Passed (21%)	1.00	1.0 D + 1.0 L (Adj Spans)
Moment (Ft-lbs)	500 @ 16' 11 13/16"	3740	Passed (13%)	1.00	1.0 D + 1.0 L (Alt Spans)
Live Load Defl. (in)	0.016 @ 16' 7 3/4"	0.198	Passed (L/999+)		1.0 D + 1.0 L (Alt Spans)
Total Load Defl. (in)	0.020 @ 16' 7 13/16"	0.397	Passed (L/999+)		1.0 D + 1.0 L (Alt Spans)
TJ-Pro [™] Rating	67	40	Passed		

System : Floor Member Type : Joist Building Use : Residential Building Code : IBC 2018 Design Methodology : ASD

Deflection criteria: LL (L/480) and TL (L/240).

• Allowed moment does not reflect the adjustment for the beam stability factor.

• A structural analysis of the deck has not been performed.

• Deflection analysis is based on composite action with a single layer of 23/32" Panel (24" Span Rating) that is glued and nailed down.

• Additional considerations for the TJ-Pro™ Rating include: 1/2" Gypsum ceiling.

	Bearing Length			Loads	to Supports		
Supports	Total	Available	Required	Dead	Floor Live	Factored	Accessories
1 - Stud wall - SPF	3.50"	2.38"	1.75"	54	123/-5	178	1 1/8" Rim Board
2 - Stud wall - SPF	3.50"	3.50"	3.50"	87	281	368	None
3 - Stud wall - SPF	3.50"	3.50"	3.50"	112	501	614	None
4 - Stud wall - SPF	3.50"	2.38"	1.75"	62	245/-3	306	1 1/8" Rim Board

• Rim Board is assumed to carry all loads applied directly above it, bypassing the member being designed.

Lateral Bracing	Bracing Intervals	Comments
Top Edge (Lu)	7' 4" o/c	
Bottom Edge (Lu)	7' 4" o/c	

•TJI joists are only analyzed using Maximum Allowable bracing solutions.

•Maximum allowable bracing intervals based on applied load.

ForteWEB Software Operator Raj Honnavara P.E. (TX, CO, OK, LA, NM) Weyerhaeuser (972) 478-6831 raj.honnavara@weyerhaeuser.com Job Notes Lot 23 Duncan Crossing, Smith Douglas Homes - McGinnis Model TC #142168



			Dead	Floor Live	
Vertical Loads	Location	Spacing	(0.90)	(1.00)	Comments
1 - Uniform (PLF)	0 to 2'	N/A	7.8	23.3	Imported Load
2 - Uniform (PLF)	2' to 6'	N/A	15.5	-	Imported Load
3 - Uniform (PLF)	0 to 12' 4 3/8"	N/A	1.6	4.7	Imported Load
4 - Uniform (PLF)	6' to 12'	N/A	7.8	-	Imported Load
5 - Uniform (PLF)	12' to 20' 7"	N/A	7.4	22.2	Imported Load
6 - Uniform (PLF)	12' 4 3/8" to 20' 6 7/16"	N/A	10.0	30.0	Imported Load
7 - Uniform (PLF)	2' to 12'	N/A	-	31.0	Imported Load
8 - Uniform (PLF)	3 1/2" to 2'	N/A	7.8	7.8	Imported Load
9 - Uniform (PLF)	3 1/2" to 12' 4 3/8"	N/A	-	1.6	Imported Load
10 - Uniform (PLF)	12' to 20' 3 1/2"	N/A	-	7.4	Imported Load
11 - Uniform (PLF)	12' 4 3/8" to 20' 3 1/2"	N/A	-	10.0	Imported Load
12 - Uniform (PLF)	3 1/2" to 6' 7 1/2"	N/A	1.2	-	Imported Load
13 - Uniform (PLF)	6' to 6' 7 1/2"	N/A	7.8	-	Imported Load
14 - Uniform (PLF)	12' 4 3/8" to 12' 8"	N/A	5.9	-	Imported Load

					Shear (lbs)			
Holes (Size)	Width	Height	Vertical Offset	Location	Actual	Allowed	Result	Comments
1 - Slotted (M)	7.00"	6.00"	9 1/2"	6' 2"	210	-	Fails	Hole too close to bearing, repair per notes

• Hole locations are measured from the outside face of left support (or left cantilever end) to the centerline of the hole.

• Vertical Offset is measured from the top of the member to the centerline of the hole.

		Shear (lbs)		Moment (Ft-lbs)		Deflection (in)			
Location Analysis	Actual	Allowed	LDF	Actual	Allowed	LDF	Live Load	Total	Comments
1 - <mark>6' 2"</mark>	-179	1860	1.00	-81	3740	1.00	0.002		1 3/4" wide x 4" long x 1/4" deep (max) bottom flange notch at hole- Passes as is


Member Notes

This joist is Structurally Inadequate with the hole being too close to support 2 as shown above. To remedy this situation, notch the top plate at support 2, by 1 1/2", so that the joist is not supported at that point, be cautious not to damage the bottom flange of the joist. This will eliminate one of the supports, and the joist will clear span about 12' in that area. See calculation shown on pages 3 & 4 that reflects this condition.

Weyerhaeuser Notes

Weyerhaeuser warrants that the sizing of its products will be in accordance with Weyerhaeuser product design criteria and published design values. Weyerhaeuser expressly disclaims any other warranties related to the software. Use of this software is not intended to circumvent the need for a design professional as determined by the authority having jurisdiction. The designer of record, builder or framer is responsible to assure that this calculation is compatible with the overall project. Accessories (Rim Board, Blocking Panels and Squash Blocks) are not designed by this software. Products manufactured at Weyerhaeuser facilities are third-party certified to sustainable forestry standards. Weyerhaeuser Engineered Lumber Products have been evaluated by ICC-ES under evaluation reports ESR-1153 and ESR-1387 and/or tested in accordance with applicable ASTM standards. For current code evaluation reports, Weyerhaeuser product literature and installation details refer to www.weyerhaeuser.com/woodproducts/document-library.

The product application, input design loads, dimensions and support information have been provided by Javelin Import from SR-314932



Member with damage as shown (and repaired if required) has adequate structural capacity for the design condition indicated. I have not reviewed the project plans or field conditions. The proper authority is to review the damage evaluation inputs and confirm they are consistent with the intent of the overall building design and field conditions. This damage evaluation is based on the information provided to Weyerhaeuser; if not consistent with the building design and field conditions, it should be rejected or returned to us to be corrected.

ForteWEB Software O	perator
Raj Honnavara P.E. (TX, Weyerhaeuser (972) 478-6831 raj.honnavara@weyerha	


Job Notes Lot 23 Duncan Crossing, Smith Douglas Homes - McGinnis Model TC #142168





MEMBER REPORT

2nd Floor, FC1: Repaired C22' (i2655) - 3 such damaged joists 1 piece(s) 14" TJI® 110 @ 24" OC



All locations are measured from the outside face of left support (or left cantilever end). All dimensions are horizontal.

Design Results	Actual @ Location	Allowed	Result	LDF	Load: Combination (Pattern)
Member Reaction (lbs)	822 @ 12' 5 1/4"	1935 (3.50")	Passed (42%)	1.00	1.0 D + 1.0 L (All Spans)
Shear (lbs)	432 @ 12' 8"	1860	Passed (23%)	1.00	1.0 D + 1.0 L (All Spans)
Moment (Ft-lbs)	-846 @ 12' 5 1/4"	3740	Passed (23%)	1.00	1.0 D + 1.0 L (All Spans)
Live Load Defl. (in)	0.034 @ 6'	0.306	Passed (L/999+)		1.0 D + 1.0 L (Alt Spans)
Total Load Defl. (in)	0.046 @ 5' 10 1/2"	0.611	Passed (L/999+)		1.0 D + 1.0 L (Alt Spans)
TJ-Pro™ Rating	58	40	Passed		

System : Floor Member Type : Joist Building Use : Residential Building Code : IBC 2018 Design Methodology : ASD

Deflection criteria: LL (L/480) and TL (L/240).

• Allowed moment does not reflect the adjustment for the beam stability factor.

• A structural analysis of the deck has not been performed.

• Deflection analysis is based on composite action with a single layer of 23/32" Panel (24" Span Rating) that is glued and nailed down.

• Additional considerations for the TJ-Pro[™] Rating include: 1/2" Gypsum ceiling.

	Bearing Length			Loads	to Supports		
Supports	Total	Available	Required	Dead	Floor Live	Factored	Accessories
1 - Stud wall - SPF	3.50"	2.38"	1.75"	84	198/-15	282	1 1/8" Rim Board
2 - Stud wall - SPF	3.50"	3.50"	3.50"	186	636	822	None
3 - Stud wall - SPF	3.50"	2.38"	1.75"	46	257/-50	303/-4	1 1/8" Rim Board

• Rim Board is assumed to carry all loads applied directly above it, bypassing the member being designed.

Lateral Bracing	Bracing Intervals	Comments
Top Edge (Lu)	7' 4" o/c	
Bottom Edge (Lu)	6' 10" o/c	

•TJI joists are only analyzed using Maximum Allowable bracing solutions.

•Maximum allowable bracing intervals based on applied load.

That man allowable bracing intervals based on applied load

			Dead	Floor Live	
Vertical Loads	Location	Spacing	(0.90)	(1.00)	Comments
1 - Uniform (PLF)	0 to 2'	N/A	7.8	23.3	Imported Load
2 - Uniform (PLF)	2' to 6'	N/A	15.5	-	Imported Load
3 - Uniform (PLF)	0 to 12' 4 3/8"	N/A	1.6	4.7	Imported Load
4 - Uniform (PLF)	6' to 12'	N/A	7.8	-	Imported Load
5 - Uniform (PLF)	12' to 20' 7"	N/A	7.4	22.2	Imported Load
6 - Uniform (PLF)	12' 4 3/8" to 20' 6 7/16"	N/A	10.0	30.0	Imported Load
7 - Uniform (PLF)	2' to 12'	N/A	-	31.0	Imported Load
8 - Uniform (PLF)	3 1/2" to 2'	N/A	7.8	7.8	Imported Load
9 - Uniform (PLF)	3 1/2" to 12' 4 3/8"	N/A	-	1.6	Imported Load
10 - Uniform (PLF)	12' to 20' 3 1/2"	N/A	-	7.4	Imported Load
11 - Uniform (PLF)	12' 4 3/8" to 20' 3 1/2"	N/A	-	10.0	Imported Load
12 - Uniform (PLF)	3 1/2" to 6' 7 1/2"	N/A	1.2	-	Imported Load
13 - Uniform (PLF)	6' to 6' 7 1/2"	N/A	7.8	-	Imported Load
14 - Uniform (PLF)	12' 4 3/8" to 12' 8"	N/A	5.9	-	Imported Load

ForteWEB Software Operator
Raj Honnavara P.E. (TX, CO, OK, LA, NM) Weyerhaeuser (972) 478-6831 raj.honnavara@weyerhaeuser.com

Job Notes Lot 23 Duncan Crossing, Smith Douglas Homes - McGinnis Model TC #142168



					Shear (lbs)			
Holes (Size)	Width	Height	Vertical Offset	Location	Actual	Allowed	Result	Comments
1 - Slotted (M)	7.00"	6.00"	9 1/2"	6' 2"	210	673	Passed (31%)	

Hole locations are measured from the outside face of left support (or left cantilever end) to the centerline of the hole.

• Vertical Offset is measured from the top of the member to the centerline of the hole.

	Shear (lbs)			Moment (Ft-lbs)			Deflection (in)		
Location Analysis	Actual	Allowed	LDF	Actual	Allowed	LDF	Live Load	Total	Comments
<mark>1 - 6' 2"</mark>	-73	1860	1.00	657	3740	1.00	0.034	0.045	1 3/4" wide x 4" long x 1/4" deep (max) bottom flange notch at hole- Passes as is

Weyerhaeuser Notes

Weyerhaeuser warrants that the sizing of its products will be in accordance with Weyerhaeuser product design criteria and published design values. Weyerhaeuser expressly disclaims any other warranties related to the software. Use of this software is not intended to circumvent the need for a design professional as determined by the authority having jurisdiction. The designer of record, builder or framer is responsible to assure that this calculation is compatible with the overall project. Accessories (Rim Board, Blocking Panels and Squash Blocks) are not designed by this software. Products manufactured at Weyerhaeuser facilities are third-party certified to sustainable forestry standards. Weyerhaeuser Engineered Lumber Products have been evaluated by ICC-ES under evaluation reports ESR-1153 and ESR-1387 and/or tested in accordance with applicable ASTM standards. For current code evaluation reports, Weyerhaeuser product literature and installation details refer to www.weyerhaeuser.com/woodproducts/document-library.

The product application, input design loads, dimensions and support information have been provided by Javelin Import from SR-314932

ForteWEB Software Operator Raj Honnavara P.E. (TX, CO, OK, LA, NM) Weyerhaeuser (972) 478-6831 raj.honnavara@weyerhaeuser.com Job Notes Lot 23 Duncan Crossing, Smith Douglas Homes - McGinnis Model TC #142168



6/8/2023 5:06:12 PM UTC ForteWEB v3.5, Engine: V8.2.5.1, Data: V8.1.3.6 File Name: 142168 Page 4 / 4