

¥ 919 773-1200 * \$ 919 773-9658 250 Shipwash Drive, Suite 104 • Garner = North Carolina * 27529 www.tyndallengineering.com

June 5, 2023

Mike Campbell 25 Burton Street Walton, NY 13856 Email: soup0528@gmail.com

Reference: Engineering Services 7934 NC-210 Bunnlevel, NC 28323 TE&D Project No.: 2301-020499



To Whom It May Concern;

As requested by the client, a representative of Tyndall Engineering & Design, PA (TE&D) was onsite to inspect and observe the existing footing and foundation. We understand the previous home was severely damaged by a fire (as well as the subsequent fire suppression) and was completely removed from the lot. We inspected and observed the following:

- 1) Analysis of the existing soil underlying the existing remaining footing.
- 2) Observe the materials/condition of the existing remaining foundation.

The following conclusions and recommendations were noted:

- The underlying soils were visually observed, qualitatively probed, and subjected to Dynamic Cone Penetrometer (DCP) testing in multiple locations at depths to 2'-0" below existing grade. Hand augers were also advanced to depths of 2'-0" below existing grade. The existing soils were found to equal or be in excess of the minimum 2000 psf bearing capacity required by the 2018 North Carolina Residential Building Code. Based on our observations, analysis, and the results of our field-testing program, the underlying soils are structurally adequate to support the anticipated loading conditions of the existing footing.
- 2) We visually observed the foundation as consisting of 8" x 16" CMU walls at the interior and exterior and 16" x 16" CMU piers at the porches. The foundation was observed to be supported by concrete footings. The existing foundation was visually observed and inspected for damage as well as subjected to non-destructive (Schmidt rebound hammer) testing at the garage slab. The concrete at the garage slab was found to equal or be in excess of the minimum 2500 psi compressive strength required by the 2018 North Carolina Residential Building Code. Based on our observations, analysis, and the results of our field-testing, the existing foundation is to be repaired/enhanced per the following:
 - At multiple locations, we observed severe deterioration of the existing mortar joints. Based on our observations and analysis, we recommend the deteriorated mortar joints be removed and repointed with mortar as needed.



v 919 773-1200 • \$ 919 773-9458 250 Shipwash Drive, Suite 104 • Garner • North Carolina • 27529 www.tyndallengineering.com

- b. At the front porch piers, we observed several piers as being damaged at the top course. Based on our observations and analysis, we recommend the damaged piers be repaired as needed by removing the topmost course and replacing it with new 16" x 16" CMU blocks.
- c. We also recommend the remaining sill plates be removed and replaced with new pressure treated 2 x 8 sill plates. New sill plates are to be installed so that the existing anchor bolts are within 1'-0" of plate splices. If this cannot be achieved, or the existing anchor bolts are damaged during removal, the sill plate may be fastened to the existing foundation with 1/2" x 8" Simpson Titen HD screws or 1/2" x 12" threaded rods with nuts and washers. The rods are to be embedded a minimum 10" into the turned down footing with Hilti HIT-HY 200 Epoxy per the manufacturer's specifications. Screws and/or rods are to be installed with spacing no greater than 6'-0" o.c. and within 12" of plate splices.

We appreciate being able to assist you during this phase of the project. If you need further assistance or require additional information, please do not hesitate to contact us.

Sincerely, Tyndall Engineering & Design

nigo Anos

Tripp Amoš PT III | 2301-020499

Prentice Tyndall Jr., P.E.





v 919 773-1200 + ≠ 919 773-9658 250 Shipwash Drive, Suite 104 = Garner = North Carolina = 27529 www.tyndallengineering.com



Site of Inspection



7 919 773-1200 + € 919 773-9658 250 Shipwash Drive, Suite 104 = Garner + North Carolina + 27529 www.tyndallengineering.com



Example of Schmidt rebound hammer testing at garage slab



ד 919 773-1200 • F 919 773-9658 250 Shipwash Drive, Suite 104 • Garner • North Carolina • 27529 www.tyndallengineering.com



Items 2a and 2c) Examples of deteriorated mortar joints and sill plates to be replaced



r 919 773-1200 = r 919 773-9658 250 Shipwash Drive, Suite 104 = Garner = North Carolina = 27529 www.tyndallengineering.com



Item 2b) Examples of damaged piers to be repaired





EAST ELEVATION SCALE: 1/4" = 1'-0"





r NOTICE:SE DRAWINGS ARE DONE WITHSE DRAWINGS ARE DONE WITHHE CLIENT. B R DRAFTING ANDHT TO MAKE COPIES, SELL ORHT TO MAKE COPIES, SELL ORE DERIVATIVE WORKS, ANDUORK AS THEY SEE FITUORK AS THEY SEE FIT
COPYRIGHT ALL DRAFTING DEPICTED IN THE THE EXPRESS PERMISSION OF TH DESIGN LLC RESERVES THE RIGH DISTRIBUTE COPIES, PREPAR PUBLICLY DISPLAY THE L
PRIVATE RESIDENCE 1934 NC-210 BUNNLEVEL, NC
B R DRAFTING & DESIGN LLC 104 SOUTH WHITE STREET SUITE #210 WAKE FOREST, NC 27587 OH 440-703-8010 / NC 919-635-9500 info@brddplans.com / brddplans.com
BLAFTING.
2 6 LAYOUT







DOOR SCHEDULE				
PRODUCT CODE	SIZE	HINGE	REVERSED	COUNT
28X80 COLONIAL A 1	2'-4"	R	NO	1
30X80 COLONIAL A 1	2'-6"	R	NO	2
30X80 COLONIAL POCKET 1	2'-6"	Ν	NO	1
32X80 COLONIAL A 1	2'-8"	L	NO	2
32X80 COLONIAL A 1	2'-8"	R	NO	4
32X80 GLASS SLIDING (SHOWER DOOR)	2'-8"	L	NO	1
36X80 COLONIAL A 1	3'-0"	L	NO	1
60X96 LH ENTRY - 2 SL	5'-0"	L	NA	1
72X96 GLASS FRENCH DOOR	6'-0"	LR	NO	1
60X96 GLASS FRENCH DOOR	5'-0"	LR	NO	1











AFTING DEPICTED IN THESE DRAWINGS ARE DONE WITH RESS PERMISSION OF THE CLIENT, B R DRAFTING AND DRAWN BY: BENJAMIN ROGERS	LLC RESERVES THE RIGHT TO MAKE COPIES, SELL OR RIBUTE COPIES, PREPARE DERIVATIVE WORKS, AND PUBLICLY DISPLAY THE WORK AS THEY SEE FIT DATE: Monday, July 29, 2024
PRIVATE REGIDENCE THE EXE THE EXE	BUNNLEYEL, NC DESIGN DISTR
RAFTING & DESIGN LLC 104 SOUTH WHITE STREET SUITE #210 WAKE FOREST NO 27687	ESIGN OH 440-703-8010 / NC 919-635-9500 info@brddplans.com / brddplans.com
S SD REN	



ELECTRICAL SCALE: 1/4" = 1'-0"

ELECT

can light 6inch ceiling classic ceiling fan 5 bla

ceiling light 22 combination fan outlet outlet gfi switch - rocker s vanity bar light (

LECTRICAL LEGEND				
TRICAL	COUNT	SYMBOL		
	44	0		
	1	• ** *•		
aded 04	2			
	2	জু জুক্		
n and light-square	1			
	26	Φ		
	1	∯œi		
style	25	\$		
02	2	<u> </u>		

SCALE: 1/4" = 1'-0"	DRAWN BY: BENJAMIN ROGERS	DATE: Monday, July 29, 2024
COPYRIGHT NOTICE; ALL DRAFTING DEPICTED IN THESE DRAWINGS ARE DONE WITH	THE EXPRESS PERMISSION OF THE CLIENT, B R DRAFTING AND DESIGN LLC RESERVES THE RIGHT TO MAKE COPIES, SELL OR	DISTRIBUTE COPIES, PREPARE DERIVATIVE WORKS, AND PUBLICLY DISPLAY THE WORK AS THEY SEE FIT
PRIVATE RESIDENCE	1934 NC-210 BLINNI EVEL NC	
B R DRAFTING & DESIGN LLC	104 SOUTH WHITE STREET SUITE #210 WAKE FOREST, NC 27587 OU 440 703 8040 / NC 040 625 6500	info@brddplans.com / brddplans.com
	ESIGN ESIGN	
6 MEC		6

Amminia CONTINUE 2X6 WALL, 2X6 POST NEEDED FOR GIRDER BEARING -REST OF THE WALL DOES NOT NEED TO BE BEARING

60 Ö 20-07 00-5-04-1-11-09

CANTILEVER TRUSSES FOR: **CONTINIOUS 8/12 PLANE**



JOB NUMBER: 2400750

REVISION:

. .

ш