


# TIMMONS GROUP

YOUR VISION ACHIEVED THROUGH OURS.



## FIELD REPORT

<b>Project Name:</b> 94 Lunker Lane	<b>Location:</b> Holly Springs, NC
<b>Project No.:</b> 73747	<b>Permit No.:</b>
<b>Client:</b> Triangle Home Pros	<b>Weather:</b> Sunny
<b>Contractor:</b> Triangle Home Pros	<b>Date:</b> 8/27/25
<b>Technician:</b> Sam Kirley	<b>Portal to Portal Time:</b> 2.0

**Summary:** Rebar Check

**Notes:** Timmons arrived on site as requested by contractor. Technician conducted rebar inspection and found it meet the specifications in plans on site regarding sizing, spacing, splicing, etc. Technician ensured vapor barrier was in place, properly taped and taped around any existing utilities.


**Report By:**  (Signature) Sam Kirley (Print)

**Reviewed By:** George Nicksich **Date:** 8/27/25

Page 1 of 2

# TIMMONS GROUP


YOUR VISION ACHIEVED THROUGH OURS.



## FIELD REPORT PHOTOS

<b>Project Name:</b> 94 Lunker Lane	<b>Location:</b> Holly Springs, NC
<b>Project No.:</b> 73747	<b>Permit No.:</b>
<b>Client:</b> Triangle Home Pros	<b>Weather:</b> Sunny
<b>Contractor:</b> Triangle Home Pros	<b>Date:</b> 8/27/25
<b>Technician:</b> Sam Kirley	<b>Portal to Portal Time:</b> 2.0



Report By:  (Signature) Sam Kirley (Print)

Reviewed By: George Nicksich Date: 8/27/25

Page 2 of 2