## OFFICIAL NORTH CAROLINA WOOD-DESTROYING INSECT INFORMATION REPORT

This is to report that a qualified inspector by the below-named firm has carefully inspected readily accessible areas of the property located at the address below for wood-destroying insects. This report specifically excludes hidden areas and areas not readily accessible (see section 2 below) and the undersigned pest control operator has not made any inspection of such hidden areas or of such areas not readily accessible.

This is not a warranty as to the total absence of wood-destroying insects or damage from same. The inspection described herein was made on the basis of visible evidence. This report is submitted without warranty, guarantee, or representation as to concealed evidence of infestation or damage or as to any future infestation.

1. Seller's Name(s)		
Buyer's Name(s) BRIAN PERKINS		
Address of Property 685 WEST RD. CAMERON	, NC 28326	
Structure(s) Inspected: A. Main Residence Only _		
FINDINGS		
2. Areas of the property which are deemed to be obs	structed or inaccessible:	
Attic area; due to inspectors safety. Below both front p		
Note: Certain areas of all structures are obstructed or inaccessible (see number 2 & 3 or	on the next page for conditions governing this report).	
If there is evidence of a previous or an active infestation of subterranean termites are there is some damage to the wooden members caused by this infestation, no matter how by a qualified building expert. (For the purpose of completing the report "infestation" or under a structure, or in or on debris under the structure.)	nd/or other wood-destroying insects in the wooden members, it must be assumed that we slight. If this is the case, the structural integrity of this property should be evaluated means evidence of past or present activity by a wood-destroying insect visible in, on	
3. Inspection revealed visible evidence of:	Location of visible evidence of infestation:	
<ul> <li>□ A. Subterranean termites</li> <li>□ 1. Control measures were performed.</li> <li>□ 2. No control measures were performed</li> <li>□ 3. Visible evidence of a previously treated infestation, which now appears to be inactive.</li> </ul>		
<ul> <li>□ B. Powder post Beetles</li> <li>□ 1. Control measures were performed.</li> <li>□ 2. No control measures were performed</li> <li>□ 3. An infestation that now appears to be inactive.</li> </ul>		
C. Old House Borers  1. Control measures were performed. 2. No control measures were performed 3. An infestation that now appears to be inactive.		
D. Others  1. Control measures were performed.  2. No control measures were performed  3. An infestation that now appears to be inactive.		
4. No visible evidence of infestation from wood-destroying	ng insects was obtained.	
The following conditions conducive to subterranean term     Wood debris within crawlspace in direct contact with soil.	mites were noted in this property:	
Firm: Canady's Services, Inc.	PCO Lic No 1466PW Date 9/6/2023	
Address: PO Box 1440 Vass, NC 28394	Telephone: 910-245-2100	
	to desire concerned to the control of the control o	

## **CONDITIONS GOVERNING THIS REPORT**

- This report is based on the observations and opinions of the inspector. It must be noted that all buildings have some structural wood members which are not visible or accessible for inspection. It is not always possible to determine the presence of infestations without extensive probing and in some cases actual dismantling of parts of the structure being inspected. Extensive probing and dismantling have not been performed.
- 2. This inspection and report are made on the basis of what was visible at the time of the inspection. An opinion is not given on areas that were enclosed or not readily accessible: finished areas of ground level rooms (basement and split level); areas concealed by wall coverings, floor coverings, furniture, equipment, stored articles; or any portion of the structure in which inspection would necessitate tearing out or marring finished work. Furniture, appliances, equipment, insulation, fixed ceilings, etc. were not moved for inspection purposes.
- 3. Inspection did not include any area to which visible access would require the use of ladders or drills. Such areas were not considered to be readily accessible.
- 4. Detached garages, sheds, lean-tos, other buildings or fences on the property are not included in this report unless specifically noted.
- 5. Neither I nor the company for which I am acting have had, presently have, or contemplate having any interest in this property. I do further state that neither I nor the company for which I am acting is associated in any way with any party to this transaction.

## **REMARKS**

This space should be used t clarify any statement made above.

IT IS THE RESPONSIBILITY OF THE CLOSING AGENT TO OBTAIN PROPER SIGNATURES.		
Purchaser's Signature(s)	Date Acknowledged	

WDIR 100 As approved by the North Carolina Association and Structural Pest Control Committee, North Carolina Department of Agriculture. Revised July 1, 1992

CANADY'S SERVICES, INC.

O - PO BOX 1440 VASS, NC 28394

910-245-2100 NC PestControl Lic1466PW

O - 1096 CLASSIC RD. APEX, NC 27539 919-446-4736 NC PestControl Lic1643PW

INVOICE: 793370 OT

DATE: 09/14/23 08:30a

ACCOUNT: 28802

ROUTE: 43

LAST: / / 43

KELVIN

CG 9/6/23 T/E \$550/\$27

BILL TO CREATIVE STONE OF FAYETTEVILLE 685 WEST ROAD CAMERON, NC 28326

SERVICE TO CREATIVE STONE OF FAYETTEVILLE (SE 685 WEST ROAD CAMERON, NC 28326

PRICE QTY AMOUNT DESCRIPTION 550.00 550.00 Sub-Terr. Termite Treatment SUBTOTAL 550.00 TOTAL DUE 550.00

Installed 8 bait stations