




Harrison Engineering Services PLLC
176 Mine Lake Court, Suite 100
Raleigh, NC 27615
Tel: 877-736-7327
COA Firm #: P-0912

November 21, 2025

Elisa Vargas
77 Fox Wood
Sanford, NC 27332
9197216802
jbmasonry1980@gmail.com



Digitally signed by 2022-10-24_Timothy_T_Berry
on 2025-11-21 16:24:49



RE: Engineer's Report of Structural Additions Compliance for Manufactured Home
Owner: Elisa Vargas, 919-721-6802
Site: 77 Fox Wood, Sanford, NC 27332

To Whom It May Concern:

The above referenced home's site-built additions were physically examined. This report reflects my assessment.

Purpose & Scope of Report

The main purpose of our observations and our scope of work for Elisa Vargas was to assess and report on:

"front porch" addition(s): 1) for structural soundness and safety, and 2) to verify that this addition does not impair the structural performance requirements of this factory-built home as established in Part 3280, Subpart D of HUD's Manufactured Home Construction & Safety Standards (MHCSS). The rear addition is not in scope and not included in this report.

Observations:

1) "Front Porch": A non-conventional framing system has been observed.

a) Stairs:

Stairs were observed. No wood rot or decay was observed. No loose nails and/or screws were observed. A guardrail was observed.

b) Deck:

A 48 inch high deck was observed. No wood rot or decay was observed. No loose nails and/or screws were observed. A guardrail system for the deck was observed.

c) Roof:

A roof was observed. No wood rot or decay was observed. No loose nails and/or screws were observed. The roof was not free-standing, but instead, apparently fastened directly to the home's fascia board. Ceiling soffit appears to be not completely attached. There was not diagonal bracing observed.

This report is the property of Harrison Engineering Services PLLC and cannot be reproduced without our prior consent. It has been issued to the referenced owner (client) at the site indicated for the purpose of a specific loan requirement or insurance policy and it is not intended to be used for acquiring, or take the place of, a permit or entitlement process with the local planning or building jurisdiction. It is site specific and may not be transferred to any other property, property owner, person(s), or entity. This report offers an expression of professional opinion by this engineer, which is based on his best knowledge, information provided by others, and belief. Other professionals may have different opinions. This consultation inspection was of readily accessible areas of the property and is limited to visual observations of apparent conditions existing at the time of the inspection only. Latent and concealed areas, defects, and/or deficiencies were excluded from the inspection; further, equipment, items and systems are not necessarily dismantled; therefore, we do not assume responsibility for conditions of such areas or items. A geotechnical soils report was not performed and it is assumed that the existing soils at the site are adequate to support all structures. Termite, wood destroying organisms, and dry-rot assessments are excluded. This report consists of neither a guarantee, warranty, or insurance policy, expressed or implied, regarding the adequacy, performance, or condition of any inspected structure, item or system. The engineer reserves the right to amend and/or supplement this report in the event additional information be uncovered or made available.