




See Notes

← 199 Windy Farm Ln  
Fuquay Varina, NC

← Slab Detail



← 199 Windy Farm Ln  
Fuquay Varina, NC

← Framing Detail

Provide collar ties in  
upper 1/3 of rafter  
span

All 3 beams shall be  
anchored to existing  
framing

