Joe E Godwin Sr., P.E., P.L.S.

Jason E Godwin, P.L.S.



Email: general@enochengineers.com

www.enochengineers.com

### MATERIALS & TEST DIVISION

#### FIELD REPORT

	PROJECT	4.2	
CLIENT:	JEFFERY HARGROVE	DAIL.	6.11.24
PROJECT:	RESI PORCH SOIL FILL	CONTRACTOR:	J. HARGROVE
ADDRESS:	419 DUNBAR DR	TECHNICIAN:	BH
LOT #:	LILLINGTON NC		

# TEST SUMMARY

PERFORMED NDT ON PORCH FILL MATERIAL AT SITE NOTED ABOVE USING A TARGET DENSITY OF 108PCF.
SOILS CONFIRMED A COMPACTION GREATER THAN OR EQUAL TO 95%.

#### FRONT AND REAR PORCH FILL TESTED

COMP %	WD PCF	DD PCF	MOISTURE %	_
98.24	106.1	109.6	3.3	-
98.77	106.7	110.1	3.4	-
	98.24	98.24 106.1	98.24 106.1 109.6	98.24 106.1 109.6 3.3

## RETURN VISIT REQUIRED

YES

TECHNICIAN:

F South

#### Disclaimer:

Soils & Material inspections, testing results and on-site determinations contained in this report become void after 30 days of non-use of this report and/or following any inclement weather which causes structural soil or material deterioration. Additional testing will be required following a voided report determined by a North Carolina Building Code enforcement official or Enoch Engineers P.A. The client/contractor is responsible for notifying Enoch Engineers P.A. of any soil & material condition changes which could void this report.