

Harnett County 420 Mckinney Pkwy

LILLINGTON,NC 27546 Phone: Fax:

8/23/2024

SUBJECT: BRES2407-0014 BUILDING RESIDENTIAL

To: Brendan Barefoot

Here are the results of all Inspections located at **369 E SOUTH ST**:

Inspection Type: FINAL** Scheduled Date/Time: Completed Date/Time: Inspector: Deen Taylor Result: Remarks: Notes:

Inspection Type:	FOOTING
Scheduled Date/Time:	
Completed Date/Time:	
Inspector:	Deen Taylor
Result:	
Remarks:	
Notes:	

Inspection Type:	FOUNDATION
Scheduled Date/Time:	
Completed Date/Time:	
Inspector:	Deen Taylor
Result:	
Remarks:	
Notes:	

Inspection Type: INSULATION Scheduled Date/Time: Completed Date/Time: Inspector: Deen Taylor Result: Remarks: Notes:





Harnett County 420 Mckinney Pkwy

LILLINGTON,NC 27546 Phone: Fax:

Inspection Type: MONO SLAB Scheduled Date/Time: Completed Date/Time: Inspector: Deen Taylor Result: Remarks: Notes:

Inspection Type: OPEN FLOOR Scheduled Date/Time: Completed Date/Time: Inspector: Deen Taylor Result: Remarks: Notes:

Inspection Type:	SLAB
Scheduled Date/Time:	
Completed Date/Time:	
Inspector:	Deen Taylor
Result:	
Remarks:	
Notes:	

Inspection Type:	UNDER SLAB TRADES
Scheduled Date/Time:	
Completed Date/Time:	
Inspector:	Deen Taylor
Result:	
Remarks:	
Notes:	

Inspection Type:	ROUGH IN REINSPECT
Scheduled Date/Time:	
Completed Date/Time:	
Inspector:	Deen Taylor
Result:	
Remarks:	
Notes:	



50	arnett County 20 Mckinney Pkwy	
Harnett county North carolina	LLINGTON,NC 27546 none: ax:	
Inspection Type Scheduled Date Completed Date Inspector: Result: Remarks: Notes:	 ROUGH IN 8/19/2024 Baniel L Floyd DISAPPROVED 1. Need engineers letter for IvIs in the carport 2. Strap top plate where it was cut out for the Iv 3. Seal all holes in the top and bottom plates 4. Draft stop horizontally every 10ft5. Seal around the tub drain 	
Inspection Type Scheduled Date Completed Date Inspector: Result: Remarks: Notes:	ROUGH IN REINSPECT8/23/2024Fime:8/23/2024Deen TaylorDISAPPROVEDPlumbing for kitchen must be installed and tested along with rest of system. Install insulation baffles. Plumbing boots still not installed around vent.	

