

## Harnett County 420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone: Fax:

'

4/29/2025

SUBJECT: **BRES2408-0051** 

**BUILDING RESIDENTIAL** 

To: FERRARA BETTY L JT W/ROS

Here are the results of all Inspections located at **205 ATKINS PLACE CIR**:

Inspection Type: ENVIR OPERATIONS PERMIT

Scheduled Date/Time: Completed Date/Time:

Inspector: EH Bucket

Result: Remarks: Notes:

Inspection Type: FINAL\*\*

Scheduled Date/Time: Completed Date/Time:

Inspector: Justin Ryan McLeod

Result: Remarks: Notes:

Inspection Type: FOOTING

Scheduled Date/Time: Completed Date/Time:

Inspector: Justin Ryan McLeod

Result: Remarks: Notes:

Inspection Type: FOUNDATION

Scheduled Date/Time: Completed Date/Time:

Inspector: Justin Ryan McLeod

Result: Remarks: Notes:



## **Harnett County**

420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: INSULATION

Scheduled Date/Time: Completed Date/Time:

Inspector: Justin Ryan McLeod

Result: Remarks: Notes:

Inspection Type: MONO SLAB

Scheduled Date/Time: Completed Date/Time:

Inspector: Justin Ryan McLeod

Result: Remarks: Notes:

Inspection Type: OPEN FLOOR

Scheduled Date/Time: Completed Date/Time:

Inspector: Justin Ryan McLeod

Result: Remarks: Notes:

Inspection Type: SLAB

Scheduled Date/Time: Completed Date/Time:

Inspector: Justin Ryan McLeod

Result: Remarks: Notes:

Inspection Type: UNDER SLAB TRADES

Scheduled Date/Time: Completed Date/Time:

Inspector: Justin Ryan McLeod

Result: Remarks: Notes:



## Harnett County 420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: ROUGH IN REINSPECT

Scheduled Date/Time: Completed Date/Time:

Inspector: Justin Ryan McLeod

Result: Remarks: Notes:

Inspection Type: ROUGH IN
Scheduled Date/Time: 11/7/2024
Completed Date/Time: 11/7/2024
Inspector: Scott Guy
Result: DISAPPROVED

Remarks:

Notes: code to lock box garage side door 1993

1/ main bathroom vanity wall multiple exterior wall studs over bored require stud shoe bracket repair install.2/ living room floor repairs per engineer not completed.3/ deleted 4/ repair/ seal hole in floor in main bathroom .5/ replace windows where required .6/ living room ceiling collar

tie fire damaged, requires replacement .7/install insulation vents and baffles were required.8/install insulation depth gauges in attic area if area will use blown insulation.

Inspection Type: ROUGH IN REINSPECT

Scheduled Date/Time: 2/7/2025 Completed Date/Time: 2/7/2025

Inspector: Justin Ryan McLeod Result: DISAPPROVED

Remarks:

Notes: Lock Box(right elevation on slide door) 1993

Inspector TSG changed the inspection assignment from TSG to JRM

1. Items 1 and 7 from previous.2. Windows do not meet energy code requirements for u factor and solar heat gain3. Fill hole in left side bath floor4. Prebatt insulation and air barrier at fireplace cavity5. Several floor joist in front of fireplace missing hangers6. Existing joists on opposite side of new girders should be hangered per engineer letter.7.one 1 ply of the triple 2x10 girders was replaced. Letter stated to replace the beam.8. Roof sheathing appears to not

have been replaced where rafters were burnt beyond salvageable per letter

Inspection Type: ROUGH IN REINSPECT

Scheduled Date/Time: 2/27/2025 Completed Date/Time: 2/27/2025

Inspector: Justin Ryan McLeod

Result: CANCELLED

Remarks: Notes:





## **Harnett County**

420 Mckinney Pkwy

LILLINGTON,NC 27546

Phone: Fax:

Inspection Type: ROUGH IN REINSPECT

Scheduled Date/Time: 4/28/2025 Completed Date/Time: 4/28/2025

Inspector: Justin Ryan McLeod Result: DISAPPROVED

Remarks:

Notes:

1. Need updated letter for swapping out the girders to lvls in lieu of what the engineer stated to do. 2. Lvl girders must be flashed between them and the masonry piers. 3. Need window

tape on all the windows changed out

