

Permit Number: CFFB05-50011582 Description: 3 STORY 12 UNITS / BUILDING 10

Applied: 3/8/2005 Approved: Site Address: 124 GALLERY DR UN101

Issued: 3/8/2005 Finaled: 1/28/2009 City, State Zip Code: SPRING LAKE, NC 28390

Status: CERTIFICATE OF OCCUP Applicant: ANDERSON CREEK PARTNERS BLD10

Parent Permit: Owner: ANDERSON CREEK PARTNERS BLD10

Parent Project: Contractor: **ELMWOOD BUILDERS LLC**

Details:

3 STORY 12 UNITS / BUILDING 10 COMMENTS: FAIRWAY POINT AT ANDERSON CREEK BUILDING #10 FROM ENTRANCE TO ANDERSON CREEK CLUB, TAKE ANDERSON CREEK DRIVE, TURN RIGHT ON BARON'S RUN, TURN RIGHT ON WHISPERING PINES, PROJECT WILL BE ON THE LEFT DJOHNSON

LIST OF INSPECTIONS									
SEQ ID	SCHEDULED DATE	COMPLETED DATE	ТҮРЕ	INSPECTOR	RESULT	REMARKS			
	6/19/2006	6/19/2006	BLDG PLAN REVIEW	Unassigned	APPROVED				
Notes:	Notes:								
	8/30/2007	8/30/2007	C PLUMB UNDER SLAB	Unassigned	APPROVED				
Notes:	Notes:								
	9/11/2007	9/11/2007	C MONOLITH SLAB	Unassigned	APPROVED				
Notes:									
	9/11/2007	9/11/2007	R ELEC TEMP SERVICE POLE	Unassigned	APPROVED				
Notes: T-Pole is between 62 Gallery Dr and 124 Gallery Dr at the power transformer									
	10/17/2007	10/17/2007	C BLDG FOOTING	Unassigned	CANCELLED				
Notes: WILL BE FOR THE BRIDGE FOOTINGS. per Mike									
	12/7/2007	12/7/2007	C BLDG FOOTING	Unassigned	APPROVED				
Notes: This inspection is for the pedestrian bridge footings									
	12/18/2007	12/18/2007	C BLDG ROUGH IN	Unassigned	DISAPPROVED				
Notes: 1) Flex duct for exhaust fans is 14' max. 2) Need letter for studs on first floor per plans. 3) Bond faucet to motor on hydromassage tubs per code. 4) Secure									

1)Flex duct for exhaust fans is 14' max. 2)Need letter for studs on first floor per plans. 3)Bond faucet to motor on hydromassage tubs per code. 4)Secure receptacle boxes for hydromassage tubs. 5)Replace all studs that are over notched or damaged throughout building. 6)All studs with bored holes over 2 studs need to be doubled.



	12/18/2007	12/18/2007	C ELEC ROUGH IN	Unassigned	DISAPPROVED				
Notes:									
receptac	1)Flex duct for exhaust fans is 14' max. 2)Need letter for studs on first floor per plans. 3)Bond faucet to motor on hydromassage tubs per code. 4)Secure receptacle boxes for hydromassage tubs. 5)Replace all studs that are over notched or damaged throughout building. 6)All studs with bored holes over 2 studs need to be doubled.								
	12/18/2007	12/18/2007	C ELEC ROUGH IN	Unassigned	DISAPPROVED				
Notes:									
receptad	1)Flex duct for exhaust fans is 14' max. 2)Need letter for studs on first floor per plans. 3)Bond faucet to motor on hydromassage tubs per code. 4)Secure receptacle boxes for hydromassage tubs. 5)Replace all studs that are over notched or damaged throughout building. 6)All studs with bored holes over 2 studs need to be doubled.								
	12/18/2007	12/18/2007	C MECH ROUGH IN	Unassigned	DISAPPROVED				
Notes:									
receptad	1)Flex duct for exhaust fans is 14' max. 2)Need letter for studs on first floor per plans. 3)Bond faucet to motor on hydromassage tubs per code. 4)Secure receptacle boxes for hydromassage tubs. 5)Replace all studs that are over notched or damaged throughout building. 6)All studs with bored holes over 2 studs need to be doubled.								
	12/18/2007	12/18/2007	C PLUMB ROUGH IN	Unassigned	DISAPPROVED				
Notes:									
receptad	1)Flex duct for exhaust fans is 14' max. 2)Need letter for studs on first floor per plans. 3)Bond faucet to motor on hydromassage tubs per code. 4)Secure receptacle boxes for hydromassage tubs. 5)Replace all studs that are over notched or damaged throughout building. 6)All studs with bored holes over 2 studs need to be doubled.								
	12/18/2007	12/19/2007	ADDRESS CONFIRMATION	Unassigned	CANCELLED				
Notes:									
	1/3/2008	1/3/2008	C BLDG ROUGH IN	Unassigned	APPROVED				
Notes: Re-inspe	ection								
	1/3/2008	1/3/2008	C ELEC ROUGH IN	Unassigned	APPROVED				
Notes: Re-inspe	ection								
	1/3/2008	1/3/2008	C MECH ROUGH IN	Unassigned	DISAPPROVED				
Notes:									
Re-inspe	ection								
exhaust	duct for bathrooms 14' r	max on 3rd floor. check o	n insulation inspectio	on					
	1/3/2008	1/3/2008	C PLUMB ROUGH IN	Unassigned	APPROVED				
Notes:	ation.								
Re-inspe		4 /0 /2000	C MEST BOLISTIN	I la a saissa a d	4,000,000				
Note	1/8/2008	1/8/2008	C MECH ROUGH IN	Unassigned	APPROVED				
Notes: re-inspection of mech rough-in									
	7/31/2008	7/30/2008	ADDRESS CONFIRMATION	Unassigned	APPROVED				
Notes:									
124 GALLERY DR BLDG 10 UNITS 101, 102, 103, 104, 201, 202, 203, 204, 301, 302, 303, 304,									



	8/14/2008	8/14/2008	C INSULATION INSPECTION	Unassigned	APPROVED				
Notes:	Notes:								
	12/19/2008	12/19/2008	R ELEC TEMP SERVICE POLE	Unassigned	APPROVED				
Notes:									
	12/22/2008	12/22/2008	C ELEC TEMP POWER CERT	Unassigned	DISAPPROVED				
sub pan	Notes: 301 1)Missing smoke detector in hall @ spare bedroom. 302 1)Replace double pole 20 amp braeker for fire place, damaged. 201 1)Wires loose for ac sub panel in main panel. 204 1)Wires loose for ac sub panel in main panel. 2)Secure ac sub panel. 303 1)Wires loose for ac sub panel in main panel in main panel. 304 1)Wires loose for ac sub panel.								
	12/23/2008	12/23/2008	R ELEC TEMP POWER CERT	Unassigned	APPROVED				
Notes:									
	1/13/2009	1/13/2009	PZ ZONING/FINAL INSPECTION	Unassigned	APPROVED				
Notes:									
	1/23/2009	1/23/2009	FM FINAL INSPECTION	Unassigned	APPROVED				
Notes:									
	1/26/2009	1/26/2009	C BLDG FINAL	Unassigned	DISAPPROVED				
fan in to	1) 103 & 203 seal holes in sheetrock in mechanical rooms. 2)101 missing grill for heat duct in hall bathroom. 3) 201 missing light in den. 4) 204 exhaust fan in toilet room of master bath does not work. 5) 204 repair holes in sheetrock behind stove & in laundry room. 6) need to sleeve & seal penetrations in fire wall in attic @ wires.								
	1/26/2009	1/26/2009	C ELEC FINAL	Unassigned	DISAPPROVED				
1) 103 8 fan in to	Notes: 1) 103 & 203 seal holes in sheetrock in mechanical rooms. 2)101 missing grill for heat duct in hall bathroom. 3) 201 missing light in den. 4) 204 exhaust fan in toilet room of master bath does not work. 5) 204 repair holes in sheetrock behind stove & in laundry room. 6) need to sleeve & seal penetrations in fire wall in attic @ wires.								
	1/26/2009	1/26/2009	C MECH FINAL	Unassigned	DISAPPROVED				
fan in to	Notes: 1) 103 & 203 seal holes in sheetrock in mechanical rooms. 2)101 missing grill for heat duct in hall bathroom. 3) 201 missing light in den. 4) 204 exhaust fan in toilet room of master bath does not work. 5) 204 repair holes in sheetrock behind stove & in laundry room. 6) need to sleeve & seal penetrations in fire wall in attic @ wires.								
	1/26/2009	1/26/2009	C PLUMB FINAL	Unassigned	DISAPPROVED				
						1 missing light in den. 4) 204 exhaust . 6) need to sleeve & seal penetrations			



in fire wall in attic @ wires.



	1/28/2009	1/28/2009	C BLDG FINAL	Unassigned	APPROVED	
Notes:						
	1/28/2009	1/28/2009	C ELEC FINAL	Unassigned	APPROVED	
Notes:						
	1/28/2009	1/28/2009	C MECH FINAL	Unassigned	APPROVED	
Notes:						
	1/28/2009	1/28/2009	C PLUMB FINAL	Unassigned	APPROVED	
Notes:						