

# SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME \_\_\_\_\_


DATE \_\_\_\_\_

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		0-10	0-10												
Texture Group	.1941(A)(1)	LS	SL												
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
HORIZON 2 DEPTH		10-24	10-24												
Texture Group	.1941(A)(1)	SL/SSCL	SL/SSCL												
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
HORIZON 3 DEPTH															
Texture Group	.1941(A)(1)														
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
HORIZON 4 DEPTH															
Texture Group	.1941(A)(1)														
Consistence	.1941														
Structure	.1941(A)(2)														
Mineralogy	.1941(A)(3)														
SOIL WETNESS	.1942	10"	18"												
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/.1956														
CLASSIFICATION	.1948	X	X												
LONG TERM ACCEPTANCE RATE	.1955	X (2)	X (2)	well											



- ① mottles present in sand
- ② well located at rear of property beyond bus
- ③ Carolina Bay

6" core samples  
 on paper!  
 @ not dir



When decided?  
 for the repair!

④ 2-16 loan  
 16-36 SICL  
 1/50K/50K  
 15.4" months  
 30"

③ 2-20 loan  
 20-36 SICL  
 1/50K/50K  
 30" months  
 14"

⑤ 0-20 loan  
 20-36 SICL  
 1/50K/50K  
 34" months  
 14"

⑥ 0-10 LS  
 10-36 SICL (SICL)  
 1/50K/50K  
 34" months  
 14"

Elizabeth Stone  
 SL 2017 #456  
 6-7-99  
 Confusion

