PREPARED 7/11/06, 14:10:40 Harnett County

INSPECTION TICKET INSPECTOR: IVR

PAGE DATE

56 7/12/06

ADDRESS . : 74 ROBERT BRANCH CIR

CONTRACTOR : R & K ANDERSON BUILDERS INC

SUBDIV: MILL BRANCH PHONE: (919) 656-5212 PHONE : (919) 656-5212

OWNER . . : AUSTIN CONSTRUCTION & DEV #23

PARCEL . . : 08-0652- - -0097- -23-

APPL NUMBER: 06-50015050 CP NEW RESIDENTIAL (SFD) DIRECTIONS: MILL BRANCH LOT 23. TAKE 401N TOWARD

FUQUAY RIGHT ONTO MILL BRANCH CIRCLE LEFT ONTO ROBERT BRANCH CIRCLE LOT ON

RIGHT. -A.DRIGGERS ______

STRUCTURE: 000 000 47X35 3BR SFD FLOOD ZONE : FLOOD ZONE \boldsymbol{X}

PERMIT: CPSF 01 CP * SFD

REQUESTED INSP

DESCRIPTION

TYP/\$Q COMPLETED RESULT RESULTS/COMMENTS

B101 01 7/12/06 TI 7-1206 APBS

R*BLDG FOOTING / TEMP SVC POLE VRU #: 001232954

----- COMMENTS AND NOTES -----

PREPARED 7/26/06, 14:01:29

ADDRESS . : 74 ROBERT BRANCH CIR

INSPECTION TICKET

PAGE

DATE 7/27/06

Harnett County _____

INSPECTOR: IVR

SUBDIV: MILL BRANCH

CONTRACTOR : R & K ANDERSON BUILDERS INC

PHONE: (919) 656-5212

A814 01

B103 01

OWNER . . : AUSTIN CONSTRUCTION & DEV #23

PHONE : (919) 656-5212

PARCEL . . : 08-0652- - -0097- -23-

APPL NUMBER: 06-50015050 CP NEW RESIDENTIAL (SFD)

DIRECTIONS: MILL BRANCH LOT 23. TAKE 401N TOWARD FUOUAY RIGHT ONTO MILL BRANCH CIRCLE

LEFT ONTO ROBERT BRANCH CIRCLE LOT ON

RIGHT. -A.DRIGGERS

STRUCTURE: 000 000 47X35 3BR SFD

FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 01 CP * SFD

DESCRIPTION REQUESTED INSP TYP/SQ COMPLETED RESULT RESULTS/COMMENTS

7/12/06 AP

B101 01 7/12/06 BS R*BLDG FOOTING / TEMP SVC POLE VRU #: 001232954

7/12/06
7/24/06
TI ADDRESS CONFIRMATION
7/19/06
AP 74 ROBERT BRANCH CIR LOT 23
7/27/06
TI NO
R*BLDG FOUND & TEMP SVC POLE VRU #: 001242854

COMMENTS AND NOTES -----

PREPARED 8/01/06, 14:07:08
Harnett County

INSPECTION TICKET INSPECTOR: IVR

PAGE

DATE 8/02/06

ADDRESS . : 74 ROBERT BRANCH CIR

SUBDIV: MILL BRANCH

CONTRACTOR: R & K ANDERSON BUILDERS INC OWNER . .: AUSTIN CONSTRUCTION & DEV #23 PHONE: (919) 656-5212 PHONE: (919) 656-5212

PARCEL . . : 08-0652- - -0097- -23-

APPE NUMBER: 06-50015050 CP NEW RESIDENTIAL (SFD) DIRECTIONS: MILL BRANCH LOT 23. TAKE 401N TOWARD

FUQUAY RIGHT ONTO MILL BRANCH CIRCLE LEFT ONTO ROBERT BRANCH CIRCLE LOT ON

RIGHT. -A.DRIGGERS

STRUCTURE: 000 000 47X35 3BR SFD FLOOD ZONE : FLOOD ZONE X

PERMIT	REQUESTED COMPLETED	SFD INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 0	1 7/12/06	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001232954
	7/12/06	AP	
A814 0	1 7/24/06	TI	ADDRESS CONFIRMATION VRU #: 001238431
	7/19/06	AP	74 ROBERT BRANCH CIR LOT 23
B103 0	1 7/27/06	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001242854
'	7/27/06	AP	
A814·0	2 8/01/06	ΤI	ADDRESS CONFIRMATION VRU #: 001242694
1	7/26/06	CA	
B113 0		TI	R*BLDG WATER/DAMP PROOFING VRU #: 001246681
1	8.2.06	_APB3_	

PREPARED 8/16/06, 13:59:04
Harnett County

INSPECTION TICKET INSPECTOR: IVR

PAGE

DATE 8/17/06

ADDRESS . : 74 ROBERT BRANCH CIR

SUBDIV: MILL BRANCH

CONTRACTOR: R & K ANDERSON BUILDERS INC
OWNER . .: AUSTIN CONSTRUCTION & DEV #23

PHONE: (919) 656-5212 PHONE: (919) 656-5212

PARCEL . . : 08-0652- - -0097- -23-

APPL NUMBER: 06-50015050 CP NEW RESIDENTIAL (SFD) DIRECTIONS: MILL BRANCH LOT 23. TAKE 401N TOWARD

FUQUAY RIGHT ONTO MILL BRANCH CIRCLE LEFT ONTO ROBERT BRANCH CIRCLE LOT ON

RIGHT. -A.DRIGGERS

STRUCTURE: 000 000 47X35 3BR SFD
FLOOD ZONE . . . : FLOOD ZONE X

PERMI	T: C	PSF 01 CP *	SFD INSP	DESCRIPTION
TYP/S	SQ.	COMPLETED	RESULT	RESULTS/COMMENTS
B101	01	7/12/06	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001232954
		7/12/06	AP	
A814	01	7/24/06	TI	ADDRESS CONFIRMATION VRU #: 001238431
		7/19/06	AP	74 ROBERT BRANCH CIR LOT 23
В103	01	7/27/06	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001242854
		7/27/06	AP	
A814	02	8/01/06	TI	ADDRESS CONFIRMATION VRU #: 001242694
		7/26/06	CA	
B113	01	8/02/06	BS	R*BLDG WATER/DAMP PROOFING VRU #: 001246681
		8/02/06	AP	
B105	01	8/17/06	T.J	R*OPEN FLOOR VRU #: 001257240
		8.17.06	DABS	

----- COMMENTS AND NOTES ------

PREPARED 8/22/06, 13:59:16 Harnett County

INSPECTION TICKET INSPECTOR: IVR

PAGE . 28

DATE 8/23/06

ADDRESS . : 74 ROBERT BRANCH CIR

SUBDIV: MILL BRANCH

CONTRACTOR : R & K ANDERSON BUILDERS INC OWNER . . : AUSTIN CONSTRUCTION & DEV #23

PHONE: (919) 656-5212 PHONE: (919) 656-5212

PARCEL . .: 08-0652- - -0097- -23-

APPL NUMBER: 06-50015050 CP NEW RESIDENTIAL (SFD) DIRECTIONS: MILL BRANCH LOT 23. TAKE 401N TOWARD

> FUQUAY RIGHT ONTO MILL BRANCH CIRCLE LEFT ONTO ROBERT BRANCH CIRCLE LOT ON

RIGHT. -A.DRIGGERS

STRUCTURE: 000 000 47X35 3BR SFD FLOOD ZONE . . . : FLOOD ZONE X

PERM	IT:	CPSF 01 CP *	SFD	
ľ		REQUESTED	INSP	DESCRIPTION
TYP/	SQ	COMPLETED	RESULT	RESULTS/COMMENTS
B101	01		BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001232954
		7/12/06	AP	
A814	01	7/24/06	TI	ADDRESS CONFIRMATION VRU #: 001238431
		7/19/06	AP	74 ROBERT BRANCH CIR LOT 23
B103	01	7/27/06	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001242854
		7/27/06	ΑP	
A814	02	8/01/06	TI	ADDRESS CONFIRMATION VRU #: 001242694
		7/26/06	CA	
B113	01	8/02/06	BS	R*BLDG WATER/DAMP PROOFING VRU #: 001246681
		8/02/06	AP	
B105	01	8/17/06	BS	R*OPEN FLOOR VRU #: 001257240
		8/17/06	/DA	Need engineers letter or engineered plan on 3'6" cantilever
				at bathroom. Crawlspace access must be moved from underneath
		÷	•	cantilever. Call for reinspection BEFORE ANY ROOF LOAD IS
				APPLIED. ok to cover floor and frame walls
B105	02	8/23/06	TI_	R*OPEN FLOOR VRU #: 001260851
		8.23.04	APBS	

PREPARED 10/06/06, 14:44:27 Harnett County

INSPECTION TICKET INSPECTOR: IVR

PAGE

DATE 10/09/06

SUBDIV: MILL BRANCH ADDRESS . : 74 ROBERT BRANCH CIR

PHONE: (919) 656-5212 PHONE: (919) 656-5212

OWNER . . : AUSTIN CONSTRUCTION & DEV #23 PARCEL . . : 08-0652- - -0097- -23-

CONTRACTOR : R & K ANDERSON BUILDERS INC

APPL NUMBER: 06-50015050 CP NEW RESIDENTIAL (SED)

DIRECTIONS: MILL BRANCH LOT 23. TAKE 401N TOWARD

FUQUAY RIGHT ONTO MILL BRANCH CIRCLE LEFT ONTO ROBERT BRANCH CIRCLE LOT ON

RIGHT. -A.DRIGGERS

STRUCTURE: 000 000 47X35 3BR SFD

FLOOD ZONE . . . : FLOOD ZONE X

PERMIT:	CPSF 01 CP *	SFD	
	REQUESTED	INSP	DESCRIPTION
TYP/SQ	COMPLETED	RESULT	RESULTS/COMMENTS
B101 01	7/12/06	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001232954
	7/12/06	AP	
A814 01	7/24/06	ΤΙ	ADDRESS CONFIRMATION VRU #: 001238431
	7/19/06	AP	74 ROBERT BRANCH CIR LOT 23
B103 01	7/27/06	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001242854
	7/27/06	AP	
A814, 02	8/01/06	TI	ADDRESS CONFIRMATION VRU #: 001242694
	7/26/06	CA	
B113 01	8/02/06	BS	R*BLDG WATER/DAMP PROOFING VRU #: 001246681
į	8/02/06	AP	
B105 01	8/17/06	BS	R*OPEN FLOOR VRU #: 001257240
	8/17/06	DA	Need engineers letter or engineered plan on 3'6" cantilever at bathroom. Crawlspace access must be moved from underneath cantilever. Call for reinspection BEFORE ANY ROOF LOAD IS APPLIED. ok to cover floor and frame walls
B105; 02	8/23/06	BS	R*OPEN FLOOR VRU #: 001260851
1	8/23/06	AP	
R427 01	10/06/06	ΊΙ	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 001288257
	10/06/06	CA	
R327 01	10/09/06	TI	THREE TRADE ROUGH IN >2500 VRU #: 001288216
	10/06/06	CA	
R427 02	10/09/06	DORS	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 001288265
i			1 /

Called in wrong.

PREPARED 10/18/06, 13:58:04 Harnett County

INSPECTION TICKET INSPECTOR: IVR

PAGE

DATE 10/19/06

_____ ADDRESS . : 74 ROBERT BRANCH CIR

SUBDIV: MILL BRANCH

CONTRACTOR : R & K ANDERSON BUILDERS INC OWNER . . : AUSTIN CONSTRUCTION & DEV #23

PHONE: (919) 656-5212 PHONE: (919) 656-5212

PARCEL . . : 08-0652- - -0097- -23-

APPL NUMBER: 06-50015050 CP NEW RESIDENTIAL (SFD) DIRECTIONS: MILL BRANCH LOT 23. TAKE 401N TOWARD

FUQUAY RIGHT ONTO MILL BRANCH CIRCLE LEFT ONTO ROBERT BRANCH CIRCLE LOT ON

RIGHT. -A.DRIGGERS

STRUCTURE: 000 000 47X35 3BR SFD FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: 0	CPSF 01 CP * :		
	REQUESTED	INSP	DESCRIPTION
TYP/SQ	COMPLETED	RESULT	RESULTS/COMMENTS
B101 01	7/12/06	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001232954
	7/12/06	AP	
A814 01	7/24/06	TI	ADDRESS CONFIRMATION VRU #: 001238431
Ì	7/19/06	AP	74 ROBERT BRANCH CIR LOT 23
B103 01	7/27/06	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001242854
•	7/27/06	AP	
A814 02	8/01/06	TI	ADDRESS CONFIRMATION VRU #: 001242694
	7/26/06	CA	
B113 01	8/02/06	BS	R*BLDG WATER/DAMP PROOFING VRU #: 001246681
	8/02/06	AP	
B105 01	8/17/06	BS	R*OPEN FLOOR VRU #: 001257240
Ì	8/17/06	DA	Need engineers letter or engineered plan on 3'6" cantilever
			at bathroom. Crawlspace access must be moved from underneath
			cantilever. Call for reinspection BEFORE ANY ROOF LOAD IS
			APPLIED. ok to cover floor and frame walls
в105 02	8/23/06	BS	R*OPEN FLOOR VRU #: 001260851
	8/23/06	AP	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 001288257
R427 01	10/06/06	TI	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 001288257
ļ	10/06/06	CA	power TN - 2500 - WDU #+ 001288216
R327 01	10/09/06	TΙ	THREE TRADE ROUGH IN >2500 VRU #: 001288216
:	10/06/06	CA	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 001288265
R427 02	10/09/06	2	
l	10/09/06	(DP)	1. Insulate water lines and trap in garage ceiling and rodent proof shower/tub trap. 2. 3" drain drilled through
:			center of floor joist. Not allowed by code. Provide
Ì			engineering. 3. Garage floor is hanging off foundation, and
			is carrying a large point load (steel beam for floor
ļ			above). Provide an engineers repair.
ļ			Plumbing not finished or testedINSPECTION STOPPED. DO
•			NOT SIDE OR INSULATE.
			\$50.00 reinspection fee
		m.r.	FOUR TRADE ROUGH IN >2500 VRU #: 001294619
R427 03	10/19/06	NLD!	TOUR TRADE ROUGH IN 22500 THE WILL STATE THE
	10-19-06	Tro	

_____ COMMENTS AND NOTES -----

PAGE

DATE 10/23/06

ADDRESS : 74 ROBERT BRANCH CIR SUBDIV: MILL BRANCH
CONTRACTOR - R & K ANDERSON BULLDERS INC PHONE : (919) 656-5212

CONTILACTOR: R & K ANDERSON BUILDERS INC PHONE: (919) 656-5212
OWNER . .: AUSTIN CONSTRUCTION & DEV #23 PHONE: (919) 656-5212

PARCEL . . : 08-0652- - -0097- -23-

APPL NUMBER: 06-50015050 CP NEW RESIDENTIAL (SFD)
DIRECTIONS: MILL BRANCH LOT 23. TAKE 401N TOWARD
FUQUAY RIGHT ONTO MILL BRANCH CIRCLE
LEFT ONTO ROBERT BRANCH CIRCLE LOT ON

RIGHT. -A.DRIGGERS

STRUCTURE: 000 000 47X35 3BR SFD

STRUCTURE: 000 000 47X35 3BR SFD FLOOD ZONE X

PERMI	r: CPSF 01 C	P * SFD	
į	REQUESTI	ED INSP	DESCRIPTION
TYP/S	Q COMPLETI	ED RESULT	RESULTS/COMMENTS
B101	01 7/12/00	6 BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001232954
1	7/12/0	6 AP	
A814	7/24/0	6 TI	ADDRESS CONFIRMATION VRU #: 001238431
	7/19/0	6 AP	74 ROBERT BRANCH CIR LOT 23
B103	7/27/0	6 BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001242854
	7/27/0	6 AP	
A814	02 8/01/0	6 TI	ADDRESS CONFIRMATION VRU #: 001242694
1	7/26/0	6 CA	
B113	01 8/02/0	6 BS	R*BLDG WATER/DAMP PROOFING VRU #: 001246681
	8/02/0	6 AP	
B105	01 8/17/00	6 BS	R*OPEN FLOOR VRU #: 001257240
	8/17/00	6 DA	Need engineers letter or engineered plan on 3'6" cantilever at bathroom. Crawlspace access must be moved from underneath cantilever. Call for reinspection BEFORE ANY ROOF LOAD IS APPLIED. ok to cover floor and frame walls
B105	02 8/23/0	6 BS	R*OPEN FLOOR VRU #: 001260851
	8/23/0	6 AP	
R427	01 10/06/0	6 TI	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 001288257
1	10/06/0	6 CA	
R327	01 10/09/0	6 TI	THREE TRADE ROUGH IN >2500 VRU #: 001288216
	10/06/0	6 CA	
R427	02 10/09/0	6 BS	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 001288265
	10/09/0	6 DP	1. Insulate water lines and trap in garage ceiling and rodent proof shower/tub trap. 2. 3" drain drilled through center of floor joist. Not allowed by code. Provide engineering. 3. Garage floor is hanging off foundation, and is carrying a large point load (steel beam for floor above). Provide an engineers repair. Plumbing not finished or tested INSPECTION STOPPED. DO NOT SIDE OR INSULATE.
1			\$50.00 reinspection fee
R427			FOUR TRADE ROUGH IN >2500 VRU #: 001294619
!	10/19/0	6 DA	1.Missing valley support over rec room, missing hip rafter support above wall to attic space. (circled on plan) 2. Nail joints in osb to blocking on all corners. 3. Install midstory guides on plumbing vents. ok to side/ insulate. Have engineering available at insulation inspection
R427	04 10/23/0 10-13:0	AEBS	FOUR TRADE ROUGH IN >2500 VRU #: 001296485

----- COMMENTS AND NOTES -

Engineering Atlatched



Mr. Jeff Bateman

Bateman Civil Survey Company, PC 330 Raleigh Street, Suite 200 Holly Springs, NC 27540 (o) (919) 577-1080 bcsco@earthlink.net

Subject:

Lot 23, Mill Branch Subdivision

2300-sf± residence

Lot 23, Mill Branch Subdivision, Kipling, Harnett County, NC 27526

VSi # 06431

Dear Mr. Bateman,

To your request, we present our structural inspection report.

This report provides our observations and recommendations with respect to the structural framing observed at the residence during our limited visual inspection on October 13, 2006.

We trust you find our report satisfactory. Please do not hesitate to call should you have any questions.

Sincerely,

SEAL 026463

OCT 2 0 2006

Vertical Solutions, Inc.

Michael L. Lassiter, S.E., P.E., C.W.I.

Structural Engineer, Civil Engineer, and Certified Weld Inspector



STRUCTURAL INSPECTION REPORT

LOT 23 MILL BRANCH SUBDIVISON 2300-sf± RESIDENCE

KIPLING, HARNETT COUNTY, NORTH CAROLINA

VSi # 06431



Prepared For:

BATEMAN CIVIL SURVEY COMPANY



TABLE OF CONTENTS

Introduction	
Project Description	1
Limited Structure Description	
Inspection Description	
Observations and Recommendations	2
Appendix A	Repair Drawings



INTRODUCTION

At the request of Mr. Jeff Bateman, of Bateman Civil Survey Company (Bateman), Vertical Solutions, Inc. (VSi) performed a limited condition inspection at the residence. We present our observations and recommendations in this report.

PROJECT DESCRIPTION

Bateman requested a limited structural inspection of the residence. VSi was referred to the contractor for further description. Mr. Michael Lassiter, S.E., P.E., C.W.I. of VSi contacted Mr. David Austin to discuss extents of the inspection. Mr. Austin requested we inspect (2) areas of framing, including:

- 1) Wall framing in proximity of garage
- 2) Floor framing in proximity of master bathroom.

Mr. Austin requested any corrective action required to the framing.

LIMITED STRUCTURE DESCRIPTION

The residence is located at Lot 23, Mill Branch Subdivision south of Kipling, Harnett County, North Carolina. It is a $2300\text{-sf} \pm \text{two-story}$, wood-framed structure with siding. The plan dimensions are about $54'-4'' \times 45'-6''$ outside to outside.

The wall framing in the proximity of the garage includes load-bearing elements. A built-up column supporting roof and floor loads is located in the back-right and right side walls. Both of these columns terminate at the first floor framing level. The floor framing overhangs the foundation wall at each column.

The floor framing at the master bathroom includes 2x10 joists at 16 inches on center spanning 14'-0" and cantilevering 3'-6" over the foundation wall at the right side of the house.

INSPECTION DESCRIPTION

A site visit by Mr. Lassiter and Mr. Cliff Stickney of VSi was performed on October 13, 2006. Our work included visual inspection of the wall framing in the proximity of the garage and the floor framing at the cantilever floor framing at the master bathroom. For more information, refer to the photos recorded.



OBSERVATIONS AND RECOMMENDATIONS


Observations and Notes Photograph Item 1 Observation: The floor framing beneath the 7-stud built-up column at the right-side wall in the garage overhangs the foundation wall by 5 inches. Recommendation: Install a built-up column beneath floor framing at column. Refer to drawings in appendix for more details. Item 2 Observation: The floor framing beneath the built-up column at the right-rear corner of the garage overhangs the foundation wall by 6 inches. Recommendation: Install built-up column beneath the floor framing at column. Refer to drawings in appendix for more details.



OBSERVATIONS AND RECOMMENDATIONS

Photograph **Observations and Notes** Item 3 Observation: A joist repair was observed beneath the cantilevered portion of the floor framing at the master bathroom, 2'-6" from the front wall. This repair conceals damage to original joist. Recommendation: Install a 2x10 joist beside repair. Refer to drawings in appendix for more details. Item 4 Observation: A damaged joist was observed beneath the cantilevered portion of the floor framing at the master bathroom, 1'-0" from the rear wall. Recommendation: Install a 2x10 joist beside damaged joist. Refer to drawings in appendix for more details.

SHEET	DESCRIPTION	REV
5-1	PLAN AT GARAGE	0
5-2	DETAIL 1 - WALL REPAIR	0
5-3	PLAN AT MASTER BATHROOM	0
5-4	DETAIL 2 - JOIST REPAIR	0
IND	EX OF SHEETS	




PLAN AT GARAGE

SCALE: 3/16" = 1'-0"

NOTES:

ALL WOOD SHALL BE NUMBER 2 SOUTHERN YELLOW PINE.
 ALL WORK SHALL BE IN ACCORDANCE WITH 2002 EDITION OF NORTH CAROLINA BUILDING CODE



		0 10-20-06	REV DATE
PREPARED FOR:	BATEMAN CIVIL SURVEY COMPANY	Hody Springs, NC 27540 Office: (019) 577-1080	

CHECKED BY:


Ĭ


SHEET NUMBER:

.# IS∧

OT 23, MILL BRANCH SUB. KIPLING, NC 27526 (HARNETT COUNTY)

354-8 Rainch Street
vertical Holy Springs NC 2756-0579
solutions omes: (919) 221-1789
Fac (919) 221-1789





PLAN AT MASTER BATHROOM


SCALE: 3/18 = 1-0

NOTES:

ALL WOOD SHALL BE NUMBER 2 SOUTHERN YELLOW PINE.
ALL WORK SHALL BE IN ACCORDANCE WITH 2002 EDITION OF NORTH CAROLINA
BUILDING CODE







This product is preferable to similar connectors because of a) easier installation, b) higher loads, c) lower installed cost, or a combination of these features.

NEW! The HDU series of holdowns are the latest in a long series of innovations from Simpson. These holdowns combine the advantages of low deflection and high capacity from the pre-deflected geometry with the ease of installation of Simpson's patented SDS screws.


HDU SPECIAL FEATURES:

- · Pre-deflected body virtually eliminates deflection due to material stretch.
- . Uses SDS screws which install easily, reduces fastener slip, and provides a greater net section area of the post compared to bolts.
- SDS1/4x21/2 screws are supplied with the holdowns. (Lag screws will not achieve the same load.) This ensures the proper fasteners are used and is convenient for the installer.
- . No stud bolts to countersink at openings.

MATERIAL: See table. FINISH: Galvanized INSTALLATION:

- . Use all specified fasteners. See General Notes.
- . Place the HDU over the anchor bolt.
- . No additional washer required.
- . To tie double 2x members together, the Designer must determine the fasteners required to bind the members to act as one unit without splitting the wood.
- . See SSTB Anchor Bolts on page 33-34 for anchorage options.
- . See Simpson Anchor Systems catalog for tested, load-rated retrofit anchors or request T-ANCHORSPEC for more information.

CODES: See page 12 for Code Listing Key Chart.



For holdowns, per ASTM test standards, anchor bolt nut should be finger-tight plus 1/2 to 1/2 turn with a hand wrench, with consideration given to possible future wood shrinkage. Care should be taken to not over-torque the nut. Impact wrenches should not be used 🦠

				Dime	anoian		Fas	leners ·	Allowable T	ension Loads	Holdown Deflection	
Model No.	Ga .	W	Н	2 8 3	્દ	Anchor Bolt	Number of SDS 1/4 x 2 1/2	(133/160)	SPF/HF (133/160)	at Highest Allowable Design Load	Code Rel.	
HDU2-SDS2.5	14	3	B11/16	31/4	11/4	5/8	6	2625	2260	.017		
HDU4-SDS2.5	14	3	1015/16	31/4	11/4	5/8	10	4190	3600	.049		
HDU5-SDS2.5	14	3	133/16	31/4	11/4	5/8	14	5430	4670	.061	160	
HDU8-SDS2.5	. 10	3	. 16%	31/2	.11/4	. 7/8	20	\$*\\\\}\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	7180	.037		
HDU11-SDS2.5	10	3	221/4	31/2	174	1	30	11275	9695	.040		

- 1. Allowable loads have been increased for earthquake or wind load durations with no further increase allowed; reduce where other load durations govern.
- 2. Loads are based on static tests on wood posts, limited by the lowest of 0.125" deflection, lowest test ultimate divided by 3 or the calculated values of the SDS 1/x21/2 screws.
- 3. The Designer must specify anchor bolt type, length and embedment.
- 4. When using structural composite lumber columns screws must be applied to the wide face of the column.
- 5. Post design shall be by Designer.

Catalog C-2006 & Capyright 2005 SIMPSON STRONG-TIE CO., INC.

- 6. SDS screws install best with a low speed 1/2" right angle drill with a 3/4" hex head driver.
- 7. Deflection values are valid for holdowns flush with and raised off of sill plate.
- 8. When using structural composite lumber columns, screws must be applied to the wide face of the column.


RP6 Retro Plate


The RP6 heavy steel plate fits on the outside of masonry buildings, helps tie the walls to the roof or floor structure with a 3/4" diameter rod.

FINISH: Simpson gray paint. Optional hot-dip galvanized finish; see Corrosion-Resistance, page 6-7, and specify HDG.

'ERIAL: 36' steel. Available with additional corrosion protection. Check with factory.

INSTALLATION: Use a 3/4" diameter rod.







HSS/SS Stud Shoes

Stud Shoes reinforce studs notched in construction. They are NOT a total replacement of removed material. Installs over pipe up to 23%" outside diameter.

HSS2-3 is designed for triple 2x studs.

HSS Stud Shoes provide tension load capacity as well as increased compression loads. Flared flange provides greater strength.

MATERIAL: 16 gauge. FINISH: Galvanized.

INSTALLATION: Use all specified fasteners. See General Notes.

- HSS: Bend flanges at 90° angle during installation, then bend back and screw into position (screws supplied).
- Bend flanges one cycle only.

CODES: See page 12 for Code Listing Key Chart.

HSS2-SDS1.5 (16 gauge) Heavy stud shoes to reinforce and protect single 2x studs where pipe is located. Uses 12 SDS1/4 x11/2 screws (included). International Residential Code - 2000/2003 R602.6 and P2603.2.1 International Building Code*- 2000/2003 2308.9.10 & 2308.9.11 J.C.B.O.-Uniform Building Code - 1997 2320.11.9 & 2320.11.10 International Plumbing Code - 2000/2003 305.8

HSS2-3-SDS3 (16 gauge) Heavy stud shoe for triple 2x stud. Uses 12 SDS1/ax2 screws (included). International Residential Code*- 2000/2003 R602.6 and P2603.2.1

International Building Code*- 2000/2003 2308.9.10 & 2308.9.11 International Plumbing Code - 2000/2003 305.8


I.C.B.O.-Uniform Building Code - 1997 2320.11.9 & 2320.11.10

SS1.5 (16 gauge) stud shoes reinforce and protect plumbing in 2x. International Residential Code*- 2000/2003 R602.6 and P2603.2.1 International Building Code* - 2000/2003 R002.0 and P2003.2. International Building Code* - 2000/2003 2308.9.10 & 2308.9.11 International Plumbing Code - 2000/2003 305.8 I.C.B.O.-Uniform Building Code - 1997 2320.11.9 & 2320.11.10


<u></u>	[· 🛊 🛊 Allo	wable Load:	1 (2)	
Madel	Stud		1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	Code		
No.	Size	Fasteners	" 🎏 Compr	ession X	Tension	Ref.
		. 41	Floor (100)	Roof (125)	5 2 7 28 2 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	
SS1.5	2x	12-10dx11/2	500	500		
SS2.5	3x	12-10dx11/2	500	500		
SS3	2-2×	12-10d	665	785		6, 121
SS4.5	3-2x	14-10d	665	785		J, 121
HSS2-SDS1.5	2x	12-SDS1/4x11/2	`√§1200 ँ°	3°1200 √	ு1000 €	
HSS2-2-SDS3	2-2x	12-SDS1/4x3	1200 €	1200	1000	
HSS2-3-SDS3	3-2x	12-SDS1/4x3	11000€	³ ^ 1000	° 970	6
HSS4-SDS3	4x	12-SDS1/4x3		≲ 1200` _e	1000.	6, 121

1. Roof loads are 125% of floor loads unless limited by other criteria. Floor loads may be adjusted for other load durations according to the code, provided they do not exceed roof loads. 2. NAILS: 10d = 0.148" dia. x 3" long, 10dx1½ = 0.148" dia. x 1½" long.


See page 16-17 for other nail sizes and information.



US Patent 6,176,057




HSS2-3



STEP 1 Install HSS (HSS2-3 shown) over stud with flanges bent at a 90° angle.



STEP 2 Bend HSS (HSS2-3 shown) flanges one time only. Screw into position.



Typical SS3 Installation



Typical SS1

SS

Installation


RPS Strap Ties

The RPS meets IBC, IRC, UBC and City of Los Angeles code requirements for HVAC and pipes in walls.


FINISH: Galvanized, some products available in ZMAX. See Corrosion-Resistance, page 6-7.

INSTALLATION: Use all specified fasteners. See General Notes. CODES: See page 12 for Code Listing Key Chart.

RPS28 (16 gauge) to reinforce top plate, and RPS28Z (16 gauge ZMAX™) to reinforce sill plate. International Residential Code - 2000/2003 R602.6.1 International Building Code"- 2000/2003 2308.9.8 I.C.B.O.- Uniform Building Code - 1997 2320.11.7



RPS



Typical RPS Installation (Only one strap may be necessary to meet IRC requirements)

Available with additional corrosion protection. Check with factory.

Model	Ga	Dimensions		Notch	Fasteners (Total)			Allowable Loads (Code Ret.	
No.		W	ī	Width	Nails 🐬	133)	x (160) 🦠	(133)	्(160) 🦫	6,865
RPS18		1½	18 7 /16	≤ 51/2"	12-16d	1150	1380	990	1190	
	1	11/2	225/16		12-16d	¥1150 °	1380 **	990 %	1190 😙	33, 96,
RPS22	16	11/2	221/16	≤ 51/2"	16-16d	∡1535 %	1805	1325	1585	122, 128
	'-	11/2	281/16		12-16d	1150	1380	990	1190	,
RPS28		11/2	285/16	≤ 12°	16-16d	1535	1805	1325	1585	

1. Loads include a 33% or 60% load duration increase on the fasteners for earthquake or wind loading, but DO NOT include a 33% stress increase on the steel capacity. Refer to page 13 for further explanation. 2. To meet the prescriptive IRC requirement 16d box nails (0.135" dia x 3½") may be used at 0.75 of the table load. 3. NAILS: 16d = 0.162" dia. x 3½" long. See page 16-17 for other nail sizes and information.

PREPARED 10/24/06, 14:00:45 Harnett County

INSPECTION TICKET INSPECTOR: IVR

PAGE DATE 10/25/06

25

ADDRESS . : 74 ROBERT BRANCH CIR

SUBDIV: MILL BRANCH

CONTRACTOR : R & K ANDERSON BUILDERS INC

PHONE: (919) 656-5212 PHONE: (919) 656-5212

OWNER . . : AUSTIN CONSTRUCTION & DEV #23

PARCEL . : 08-0652- - -0097- -23-APPL NUMBER: 06-50015050 CP NEW RESIDENTIAL (SFD)

DIRECTIONS: MILL BRANCH LOT 23. TAKE 401N TOWARD

FUQUAY RIGHT ONTO MILL BRANCH CIRCLE

LEFT ONTO ROBERT BRANCH CIRCLE LOT ON

RIGHT. -A.DRIGGERS _____

STRUCTURE: 000 000 47x35 3BR SFD FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 01 CP * SFD				
	REQUESTED	INSP	DESCRIPTION	
mxp /co	COMPLETED			
TYP/SQ	COMPLETED	KESSEI	ALLOUDIO, COMMENTO	
B101 01	7/12/06	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001232954	
Biorjoi	7/12/06	AP		
A814 01		TI	ADDRESS CONFIRMATION VRU #: 001238431	
1014 01	7/19/06	AP	74 ROBERT BRANCH CIR LOT 23	
B103 01	7/27/06	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001242854	
B, 03 0.	7/27/06	AP		
A814 02	8/01/06	TI	ADDRESS CONFIRMATION VRU #: 001242694	
	7/26/06	CA		
B113 01	8/02/06	BS	R*BLDG WATER/DAMP PROOFING VRU #: 001246681	
	8/02/06	AP		
B105 01		BS	R*OPEN FLOOR VRU #: 001257240	
	8/17/06	DA	Need engineers letter or engineered plan on 3'6" cantilever	
			at bathroom. Crawlspace access must be moved from underneath	
			cantilever. Call for reinspection BEFORE ANY ROOF LOAD IS	
			APPLIED. ok to cover floor and frame walls	
в105 02	8/23/06	BS	R*OPEN FLOOR VRU #: 001260851	
	8/23/06	AP		
R427 01	10/06/06	TI	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 001288257	
ļ	10/06/06	CA		
R327 01	10/09/06	TI	THREE TRADE ROUGH IN >2500 VRU #: 001288216	
į	10/06/06	CA	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 001288265	
R427 02	10/09/06	BS	1001 1111	
	10/09/06	DP	1. Insulate water lines and trap in garage ceiling and rodent proof shower/tub trap. 2. 3" drain drilled through	
			center of floor joist. Not allowed by code. Provide	
• •			engineering. 3. Garage floor is hanging off foundation, and	
			is carrying a large point load (steel beam for floor	
			above).Provide an engineers repair.	
			Plumbing not finished or testedINSPECTION STOPPED. DO	
			NOT SIDE OR INSULATE.	
			\$50.00 reinspection fee	
R427 03	10/19/06	BS	FOUR TRADE ROUGH IN >2500 VRU #: 001294619	
	10/19/06	DA	1.Missing valley support over rec room, missing hip rafter	
			support above wall to attic space. (circled on plan) 2.	
!			Nail joints in osb to blocking on all corners. 3. Install	
į			midstory guides on plumbing vents.	
i			ok to side/ insulate. Have engineering availible at	
		p.a	insulation inspection FOUR TRADE ROUGH IN >2500 VRU #: 001296485	
R427 04	10/23/06		FOUR TRADE ROUGH IN >2500 VRU #: 001296485 connect bath fans to their vents.	
i	10/23/06	(^{AE})	ok to side, ok to insulate	
T130 01	10/25/06	TT T	R*INSULATION INSPECTION VRU #: 001298214	
I129 01	10/25/06	ADRS	K thoughtion thou porton the fire of fact the	
	10-25 06			

PREPARÉD 7/30/07, 14:00:07 Harnett County

INSPECTION TICKET INSPECTOR: IVR

PAGE 4 DATE 7/31/07

ADDRESS . : 74 ROBERT BRANCH CIR

SUBDIV: MILL BRANCH

ADDRESS : 74 ROBERT BRANCH CIR SUBDIV: MILL BRANCH
CONTRACTOR R & K ANDERSON BUILDERS INC PHONE : (919) 656-5212
OWNER AUSTIN CONSTRUCTION & DEV #23 PHONE : (919) 656-5212

PARCEL . .: 08-0652- - -0097- -23-

APPL NUMBER: 06-50015050 CP NEW RESIDENTIAL (SFD) DIRECTIONS: MILL BRANCH LOT 23. TAKE 401N TOWARD

FUQUAY RIGHT ONTO MILL BRANCH CIRCLE LEFT ONTO ROBERT BRANCH CIRCLE LOT ON

RIGHT. -A.DRIGGERS

STRUCTURE: 000 000 47X35 3BR SFD FLOOD ZONE . . . : FLOOD ZONE X

1	REQUESTED		
P/SQ	COMPLETED	RESULT	RESULTS/COMMENTS
01 01	7/12/06	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001232954
İ	7/12/06	AP	
14 01	7/24/06	TI	ADDRESS CONFIRMATION VRU #: 001238431
	7/19/06	AP	√74 ROBERT BRANCH CIR LOT 23
03 01	7/27/06	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001242854
Į.	7/27/06	AP	
14 02	8/01/06	TI	ADDRESS CONFIRMATION VRU #: 001242694
1	7/26/06	AP	
13 ¹ 01	8/02/06	BS	R*BLDG WATER/DAMP PROOFING VRU #: 001246681
1	8/02/06	AP	
05 01	8/17/06	BS	R*OPEN FLOOR VRU #: 001257240
:	8/17/06	DA	Need engineers letter or engineered plan on 3'6" cantilever
	3, . , , 00		at bathroom. Crawlspace access must be moved from underneath
			cantilever. Call for reinspection BEFORE ANY ROOF LOAD IS
			APPLIED. ok to cover floor and frame walls
05 02	8/23/06	BS	R*OPEN FLOOR VRU #: 001260851
05 02	8/23/06	AP	R OF EN I BOOK THO W. SU (BOOS)
27 01	10/06/06	TI	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 001288257
27 101	10/06/06	CA	FOOR TRADE ROOM! IN >2500 TIME: 17:00 TRO #: 001200251
7 01		TI	THREE TRADE ROUGH IN >2500 VRU #: 001288216
27 01	10/09/06		THREE TRADE ROOGH IN >2500 VRO #: 001200210
27 02	10/06/06 10/09/06	CA BS	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 001288265
27 02	10/09/06	DP	1. Insulate water lines and trap in garage ceiling and rodent proof shower/tub trap. 2. 3" drain drilled through center of floor joist. Not allowed by code. Provide engineering. 3. Garage floor is hanging off foundation, and is carrying a large point load (steel beam for floor above). Provide an engineers repair.
27 03	10/19/06	BS	Plumbing not finished or testedINSPECTION STOPPED. DO NOT SIDE OR INSULATE. \$50.00 reinspection fee FOUR TRADE ROUGH IN >2500 VRU #: 001294619
	10/19/06	DA	1. Missing valley support over rec room, missing hip rafter support above wall to attic space. (circled on plan) 2. Nail joints in osb to blocking on all corners. 3. Install midstory guides on plumbing vents. ok to side/ insulate. Have engineering available at insulation inspection
27 04	10/23/06	BS	FOUR TRADE ROUGH IN >2500 VRU #: 001296485
J, 04	10/23/06	AE	connect bath fans to their vents.
	10,23,00		ok to side, ok to insulate
29 01	10/25/06	BS	R*INSULATION INSPECTION VRU #: 001298214
١٠ ري	10/25/06	AP	
	10/23/00	4 1 L	✓ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001318849

PREPARED 7/30/07, 14:00:07 INSPECTION TICKET PAGE DATE 7/31/07 INSPECTOR: IVR Harnett County ADDRESS . : 74 ROBERT BRANCH CIR SUBDIV: MILL BRANCH CONTRACTOR : R & K ANDERSON BUILDERS INC PHONE: (919) 656-5212 PHONE: (919) 656-5212 OWNER . . . AUSTIN CONSTRUCTION & DEV #23 PARCEL . .: 08-0652- - -0097- -23-APPL NUMBER: 06-50015050 CP NEW RESIDENTIAL (SFD) REQUESTED INSP DESCRIPTION
TYP/SQ COMPLETED RESULT RESULTS/COMMENTS

12/04/06

AΡ R431 01 7/31/07 TI P

FOUR TRADE FINAL >2500 VRU #: 001456557

---- COMMENTS AND NOTES ------

Violation Notice Do Not Remove

Harnett County Inspection Department 102 East Front St P.O. Box 65 Lillington, NC 27546 Phone (910) 893-4876 Fax (910) 893-2793

App #06-50015015

- 1. Front stairs shall have hand rail. More than 3 risers.
- 2. Garage door missing design pressure rating for 100 mph wind zone.
- 3. Handrail in garage does not meet 200 # load in any direction
- 4. Bottom step exceeds 8 1/4 inches.
- 5. Trim attic access stairs and install insulation.

\$50 re-inspection fee.

\sim .		$\overline{}$	~~	
C'ode	Enforcement	f 1	itti	CIAL

Signature	_Ken Slattum_	
	_	

PREPARED 8/03/07, 14:20:07 Harnett County

INSPECTION TICKET INSPECTOR: IVR

PAGE DATE

8/06/07

ADDRESS . : 74 ROBERT BRANCH CIR SUBDIV: MILL BRANCH CONTRACTOR : R & K ANDERSON BUILDERS INC PHONE : (919) 656-5212 OWNER : AUSTIN CONSTRUCTION & DEV #23

PHONE: (919) 656-5212

PARCEL . .: 08-0652- - -0097- -23-

APPL NUMBER: 06-50015050 CP NEW RESIDENTIAL (SFD)

TYP/\$	Q	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
		12/04/06	AP	
R431	01	7/31/07	KS	FOUR TRADE FINAL >2500 VRU #: 001456557
į		7/31/07	DP	1. Front stairs shall have handrails.
				Garage door missing DP rating for 100mph wind zone
				Handrail in garage will not support a 200#load in all
1			,	directions
			₹	4) Bottom step exceeds 8 1/4 inches
1			•	75. Trim attic ladder and install insulation.
R431	02	8/03/07	ΤI	FOUR TRADE FINAL >2500 VRU #: 001459478
i		8/02/07	CA	
R431	03_	\$-6007 \$-607	ABS	FOUR TRADE FINAL >2500 VRU #: 001460096

----- COMMENTS AND NOTES ------

A Stairs

PREPARED 8/03/07, 14:20:07 Harnett County

INSPECTION TICKET INSPECTOR: IVR

PAGE

DATE 8/06/07

ADDRESS . : 74 ROBERT BRANCH CIR

SUBDIV: MILL BRANCH

CONTRACTOR : R & K ANDERSON BUILDERS INC

CONTRACTOR: R & K ANDERSON BUILDERS INC PHONE: (919) 656-5212 OWNER : AUSTIN CONSTRUCTION & DEV #23 PHONE: (919) 656-5212 PHONE: (919) 656-5212

PARCEL . . : 08-0652- - -0097- -23-

APPL NUMBER: 06-50015050 CP NEW RESIDENTIAL (SFD)

DIRECTIONS: MILL BRANCH LOT 23. TAKE 401N TOWARD

FUQUAY RIGHT ONTO MILL BRANCH CIRCLE

LEFT ONTO ROBERT BRANCH CIRCLE LOT ON

RIGHT. -A.DRIGGERS

STRUCTURE: 000 000 47X35 3BR SFD FLOOD ZONE . . . : FLOOD ZONE X

	REQUESTED		
YP/SQ 	COMPLETED	RESULT	RESULTS/COMMENTS
101;01	7/12/06	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001232954
	7/12/06	AP	
814 01	7/24/06	TI	ADDRESS CONFIRMATION VRU #: 001238431
	7/19/06	· AP	√74 ROBERT BRANCH CIR LOT 23
03 01	7/27/06	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001242854
	7/27/06	AP	
314 02	8/01/06	TI	ADDRESS CONFIRMATION VRU #: 001242694
1	7/26/06	AP	
113 01	8/02/06	BS	R*BLDG WATER/DAMP PROOFING VRU #: 001246681
13 101	8/02/06	AP	R BBO Wildie, Bran Indon Ind
NOT 01	8/02/06	BS	R*OPEN FLOOR VRU #: 001257240
05 01			Need engineers letter or engineered plan on 3'6" cantilever
	8/17/06	DA	at bathroom. Crawlspace access must be moved from underneat
			cantilever. Call for reinspection BEFORE ANY ROOF LOAD IS
			APPLIED. ok to cover floor and frame walls
105 02	8/23/06	BS	R*OPEN FLOOR VRU #: 001260851
1	8/23/06	AΡ	
127 01	10/06/06	ΤI	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 001288257
	10/06/06	CA	
327 01	10/09/06	ΤI	THREE TRADE ROUGH IN >2500 VRU #: 001288216
	10/06/06	CA	
427 02	10/09/06	BS	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 001288265
	10/09/06	DP	1. Insulate water lines and trap in garage ceiling and rodent proof shower/tub trap. 2. 3" drain drilled through center of floor joist. Not allowed by code. Provide engineering. 3. Garage floor is hanging off foundation, and
			is carrying a large point load (steel beam for floor
			above).Provide an engineers repair.
			Plumbing not finished or testedINSPECTION STOPPED. DO
			NOT SIDE OR INSULATE.
			\$50.00 reinspection fee
427 03	10/19/06	BS	FOUR TRADE ROUGH IN >2500 VRU #: 001294619
Ì	10/19/06	DA	1.Missing valley support over rec room, missing hip rafter
			support above wall to attic space. (circled on plan) 2.
			Nail joints in osb to blocking on all corners. 3. Install
			midstory guides on plumbing vents.
			ok to side/ insulate. Have engineering availible at
			insulation inspection
427 04	10/23/06	BS	FOUR TRADE ROUGH IN >2500 VRU #: 001296485
12/ 07	10/23/06	AE	connect bath fans to their vents.
	10/23/00		ok to side, ok to insulate
120 01	10/25/06	P.C.	R*TNSHIATION TNSPECTION VRU #: UU 2982 4
129 01	10/25/06 10/25/06	BS AP	R*INSULATION INSPECTION VRU #: 001298214

COUNTY OF HARNETT DEPARTMENT OF BUILDING INSPECTION AND PLANNING/DEVELOPMENT CERTIFICATE OF OCCUPANCY

This certificate issued pursuant to the requirements of Section 105 of the North Carolina State Building Code and the Harnett County Zoning Ordinance certifies at the time of issuance this structure was in compliance with the various ordinances of the County of Harnett regulating development and building construction or use. For the following:

Use Classification: Type of Construction: Owner of Building: Building Address: Zoning District: Zoning Permit No.: Date: 8-10-07	Conditional Use Permit No.: Building Permit No.: Electrical Permit No.: Insulation Permit No.: Plumbing Permit No.: Mech. Permit No.: Envir. C.O. No.:
Building Official	Zoning Official