PREPARED 3/07/07, 14:01:24 INSPECTION TICKET
Harnett County INSPECTOR: IVR

10

DATE 3/08/07

PAGE

ADDRESS : 745 COLONIAL HILLS DR SUBDIV: COLONIAL HILLS
CONTRACTOR : DEESE ROBERT W PHONE : (910) 893-4180

CONTRACTOR : DEESE ROBERT W PHONE : OWNER . . : SOUTHEAST DEV/CUMBERLAND #44 PHONE :

PARCEL . : 03-0507- - -0226- -62-APPL NUMBER: 06-50015962 CP NEW RESIDENTIAL (SFD)

DIRECTIONS: COLONIAL HILLS LOT 44. 210 RIGHT ON RAY RD RIGHT ON NURSERY RD LEFT ON DOCS

RD ONE MILE ON LEFT. -A.DRIGGERS

STRUCTURE: 000 000 56X48 3BR SFD FLOOD ZONE X

\_\_\_\_\_\_

PERMIT: CPSF 00 CP \* SFD

REQUESTED INSP DESCRIPTION

TYP/SQ COMPLETED RESULT RESULTS/COMMENTS

B101 01 3/08/07 TI R\*BLDG FOOTING / TEMP SVC POLE VRU #: 001367309

----- COMMENTS AND NOTES -----

T-8 ole 10078

17 PAGE INSPECTION TICKET PREPARED 3/13/07, 14:02:34 DATE 3/14/07 INSPECTOR: IVR Harnett County SUBDIV: COLONIAL HILLS ADDRESS . : 745 COLONIAL HILLS DR PHONE: (910) 893-4180 CONTRACTOR : DEESE ROBERT W OWNER . .: SOUTHEAST DEV/CUMBERLAND #44 PHONE : PARCEL . .: 03-0507- - -0226- -62-APPL NUMBER: 06-50015962 CP NEW RESIDENTIAL (SFD) DIRECTIONS : COLONIAL HILLS LOT 44. 210 RIGHT ON RAY RD RIGHT ON NURSERY RD LEFT ON DOCS RD ONE MILE ON LEFT. -A.DRIGGERS STRUCTURE: 000 000 56X48 3BR SFD FLOOD ZONE . . . : FLOOD ZONE X PERMIT: CPSF 00 CP \* SFD REQUESTED INSP DESCRIPTION TYP/SQ COMPLETED RESULT RESULTS/COMMENTS 

B101 01 3/08/07 CE R\*BLDG FOOTING / TEMP SVC POLE VRU #: 001367309 3/08/07 AP

B103 01

3/14/07 TI R\*BLDG FOUND & TEMP SVC POLE VRU #: 001370448

----- COMMENTS AND NOTES ------

PREPARED 3/21/07, 13:58:33 Harnett County

INSPECTION TICKET INSPECTOR: IVR

PAGE

15 DATE 3/22/07

ADDRESS . : 745 COLONIAL HILLS DR

SUBDIV: COLONIAL HILLS PHONE: (910) 893-4180

CONTRACTOR : DEESE ROBERT W OWNER . . : SOUTHEAST DEV/CUMBERLAND #44

PHONE :

PARCEL . . : 03-0507- - -0226- -62-

APPL NUMBER: 06-50015962 CP NEW RESIDENTIAL (SFD)

DIRECTIONS: COLONIAL HILLS LOT 44. 210 RIGHT ON RAY RD RIGHT ON NURSERY RD LEFT ON DOCS

RD ONE MILE ON LEFT. -A.DRIGGERS 

STRUCTURE: 000 000 56X48 3BR SFD

FLOOD ZONE . . . : FLOOD ZONE X 

PERMIT:	CPSF 00 CP * REQUESTED COMPLETED	SFD INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/08/07	CE	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001367309
	3/08/07	AP	
B103 01	3/14/07	CE	R*BLDG FOUND & TEMP SVC POLE VRU #: 001370448
	3/14/07	AP	
A814 01	3/21/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001374321
	3/20/07	AP	745 Colonial Hills Dr
B105 01	3/22/07_	TI.	R*OPEN FLOOR VRU #: 001374354
	3-22-7	HU-CE	

----- COMMENTS AND NOTES -------

PREPARED 4/13/07, 13:59:22 Harnett County

INSPECTION TICKET INSPECTOR: IVR 

PAGE

15 DATE 4/16/07

ADDRESS . : 745 COLONIAL HILLS DR

SUBDIV: COLONIAL HILLS PHONE: (910) 893-4180

CONTRACTOR : DEESE ROBERT W

PHONE :

OWNER . . : SOUTHEAST DEV/CUMBERLAND #44

PARCEL . . : 03-0507- - -0226- -62-APPL NUMBER: 06-50015962 CP NEW RESIDENTIAL (SFD)


DIRECTIONS: COLONIAL HILLS LOT 44. 210 RIGHT ON RAY RD RIGHT ON NURSERY RD LEFT ON DOCS

RD ONE MILE ON LEFT. -A.DRIGGERS 

STRUCTURE: 000 000 56x48 3BR SFD

FLOOD ZONE . . . : FLOOD ZONE  $\boldsymbol{X}$ 

PERMIT:	CPSF 00 CP * REQUESTED COMPLETED	SFD INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/08/07	CE	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001367309
	3/08/07	AP	
B103 01	3/14/07	CE	R*BLDG FOUND & TEMP SVC POLE VRU #: 001370448
	3/14/07	AP	
A814 01	3/21/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001374321
	3/20/07	AP	745 Colonial Hills Dr
B105 01	3/22/07	CE	R*OPEN FLOOR VRU #: 001374354
	3/22/07	AP	
R425 01	4/16/07	TI\	FOUR TRADE ROUGH IN VRU #: 001389733
		OH JH	



## ITW Building Components Group, Inc.

1950 Marley Drive Haines City, FL 33844 Florida Engineering Certificate of Authorization Number: 567 Document ID:1T6D2302Z0209110301 Page 1 of 1

Job Identification: REPAIR/CS-1411-STD NO BRICK (REPAIR/CS-1411-S-)

Truss Count: 1

Model Code: Standard Building Code

Truss Criteria: ANSI/TPI-1995(STD)

Engineering Software: Alpine Software, Version 7.33.

Structural Engineer of Record:

Minimum Design Loads: Roof - 40.0 PSF @ 1.15 Duration

Floor - N/A Wind - 110 MPH ASCE 7-98 -Closed

1. Determination as to the suitability of these truss components for the structure is the responsibility of the building designer/engineer of record, as defined in ANSI/TPI 1

2. The drawing date shown on this index sheet must match the date shown on the individual truss component drawing.

3. As shown on attached drawings; the drawing number is preceded by: HCUSR2302

Revised Trusses

Revisea	1143303
	Danings Date
# Ref Description	07099005 04/09/07
1 58805A2	070000

Seal Date: 04/09/200

-Truss Design Engineers Arthur R. Fisher

1950 Marley Dince Haines City, FL 33811

This truss is repaired to stub 3/4" from right end as shown. Refer to drawing HCUSR2302 07033037 for plates and other data not given here Shore Truss and any supported spans in proper position as repair is being made. Repair(s) must comply with Alpine designs & specifications (REPAIR/CS-1411-STD NO BRICK - A2) Bearing blocks: Nail type: 12d\_Box\_or\_Gun\_(0.128"x3.25",\_min.)\_nails BRG X-LOC #BLOCKS LENGTH/BLK #NAILS/BLK WALL PLATE 1 0.000' 1 12" 4 Match Truss cutting through steel connector plates and all remaining connector plate/wood contact areas must stay intact and fully embedded. Bearing block to be same size and species as bottom chord. Refer to drawing CNBRGBLK1103 for additional information. Deflection meets L/240 live and L/180 total load. The use of a carbide-tip saw blade is recommended when PLT TYP. Wave TW Building Components Group, Inc. Haines City, FL 33844 ALPINE ΤPI 5X4 (B2) ≡ DAMAGED TRUSSES MUST BE CAREFULLY EVALUATED TO DETERMINE THE EXTENT OF DAMAGE AND THE FEASIBILITY OF REPAIR. IN SOME CASES THE PRIDENT SOLUTION IS TO SCRAP THE DAMAGED TRUSSES AND REBUILD. INTERNAL MOOD FIBER DAMAGE AND EXCESSIVE R=1709 U=261 W=3.5" REPAIR WORK SHOWN ON THIS DRAWING APPLIES ONLY TO THOSE SECTIONS OF THE TRUSS REPAIR WORK SHOWN ON THIS DRAWING APPLIES DAMAGED. A QUALIFIED THISD PARTY REPORTED BY THE TRUSS MANUFACTURER TO HAVE BEEN DAMAGED. A QUALIFIED THISD PARTY INSPECTOR SHALL CHECK TRUSSES TO DETERMINE THE EXTENT OF ANY FURTHER DAMAGE. IF ANY, IT IS VITAL THAT THE TRUSS FABRICATOR AND BUILDING CONTRACTOR CONSIDER THE (1.5" Effective Contact) CAUSE OF THE DAMAGE IN THEIR DECISION WHETHER TO REPAIR OR REBUILD. COMMECTOR STRESS FROM BEHIDING OR SHOCK CANNOT BE READILY DETECTED. THEREFORE. AND VERIFY THAT REPAIRS HAVE BEEN PERFORMED AS INDICATED ON THIS DRAWING 2X3// 8-3-0 9-0-0 5X6≡ Design Crit: TPI-1995(STD) 12 3X10 Ⅲ TRUSS REPAIR 3X5≡ 22-6-12 Over 2 Supports 3X4≡ -8 В2 5-10-0 12-0-0 22-7-8 7X8≡ 2X3 ≡ 3X5≡ 9 BC attic room floor loading: LL = 40.00 psf; DL = 10.00 psf; from 5-2-0 to 17-2-0. 1-9-0 3X10 III Gusset Plates are 1/2" APA RATED SHEATHING, 24/0, (Plywood or OSB)EXP 1 or 2. Apply gusset to each face of truss and attach with evenly distributed 6d Common (0.113x2.0") Nails specified in circles. Hatched 8X8≡ the truss profile Marinum Nail/Screw Spacing Requirements
Based on ANSI/AF&PA NDS-2001:
End Distance 1-3/4" Edge Distance 5/8" End Distance 1-3/4" Edge Distance 5/8" Spacing Between Rows 5/8" Spacing in a Row 1-3/4" Maximum Number of Rows for Member Size: lines indicate portions on gussets protruding outside of 2×10 12 6X6≡ 9-0-12 10 Rows 6 - 6 - 122X3∥ THIS DWG PREPARED FROM CL AR.F. 24X12X1/2"(G1) =¥ ¥ 0-0-12 Stub that may be trimmed flush with cut BC LL BC DL TC DL SPACING DUR. FAC. TC LL TOT . LD . NC/-/1/-/-/R/F 10.0 PSF 20.0 PSF 40.0 PSF 1.15 10.0 PSF 24.0" 0.0 PSF DATE REF R2302- 58805 SEQN-HC-ENG DAL/AF DRW HCUSR2302 07099005 Scale = .25"/Ft. 1T6D2302Z02 04/09/07 18558 10-6-0 REV

Regal Industries
P.O. Box 509
Hope Bills, NC 28348

Apr 09, 2007

Page 1 of 1

1 Trusses

## REPAIR/CS-1411-STD NO BRICK / REPAIR/CS-1411-S

	D intion	 DrawNo
#_	Description	 07099005
<001>	58805A2	 0,000000

PAGE INSPECTION TICKET /19/07 DATE PREPARED 4/18/07, 14:00:13 INSPECTOR: IVR SUBDIV: COLONIAL HILLS PHONE: (910) 893-4180 ADDRESS . : 745 COLONIAL HILLS DR CONTRACTOR : DEESE ROBERT W PHONE : OWNER . . : SOUTHEAST DEV/CUMBERLAND #44 PARCEL . .: 03-0507- - -0226- -62-APPL NUMBER: 06-50015962 CP NEW RESIDENTIAL (SFD) DIRECTIONS : COLONIAL HILLS LOT 44. 210 RIGHT ON RAY RD RIGHT ON NURSERY RD LEFT ON DOCS ------STRUCTURE: 000 000 56x48 3BR SFD FLOOD ZONE . . . : FLOOD ZONE X PERMIT: CPSF 00 CP \* SFD DESCRIPTION REQUESTED INSP COMPLETED RESULT RESULTS/COMMENTS ------R\*BLDG FOOTING / TEMP SVC POLE VRU #: 001367309 TYP/SQ 3/08/07 CE R\*BLDG FOUND & TEMP SVC POLE VRU #: 001370448 B101 01 3/08/07 AP 3/14/07 CE ADDRESS CONFIRMATION TIME: 17:00 VRU #: 00137432 B103 01 3/14/07 AP ΤI 745 Colonial Hills Dr 3/21/07 A814 01 R\*OPEN FLOOR VRU #: 001374354 ΑP 3/20/07 CE 3/22/07 B105 01 Bath room exhaust fans need to be vented to the out de.

Missing fire caulk in garage at top plate. FOUR TRADE ROUGH IN VRU #: 001389733 3/22/07 AΡ 4/16/07 R425 01 4/16/07 Need to repair truss beside stairway next to garaca. Finish bracing on T6 truss in middle. Water lines & drain lines under house need to be supported per code. Pier under masterbath needs to be motared back : ace. R\*INSULATION INSPECTION VRU #: 001391226

FOUR TRADE ROUGH IN VRU #: 001391218

----- COMMENTS AND NOTES -----

4/19/07

4/19/07

I129 01

R425 02

PAGE /11/07 INSPECTION TICKET DATE INSPECTOR: IVR PREPARED 6/08/07, 13:59:54 SUBDIV: COLONIAL HILLS PHONE: (910) 893-4180 ADDRESS . : 745 COLONIAL HILLS DR CONTRACTOR : DEESE ROBERT W PHONE : OWNER . . : SOUTHEAST DEV/CUMBERLAND #44 PARCEL . . : 03-0507- - -0226- -62-APPL NUMBER: 06-50015962 CP NEW RESIDENTIAL (SFD) DIRECTIONS: COLONIAL HILLS LOT 44. 210 RIGHT ON RAY RD RIGHT ON NURSERY RD LEFT ON DOCS -----STRUCTURE: 000 000 56X48 3BR SFD FLOOD ZONE . . . : FLOOD ZONE X PERMIT: CPSF 00 CP \* SFD DESCRIPTION REQUESTED INSP TYP/SQ COMPLETED RESULT RESULTS/COMMENTS 3/08/07 CE R\*BLDG FOUND & TEMP SVC POLE VRU #: 001370448 B101 01 3/08/07 AP ADDRESS CONFIRMATION TIME: 17:00 VRU #: 0013743 CE 3/14/07 B103 01 AP 3/14/07 √745 Colonial Hills Dr TI 3/21/07 R\*OPEN FLOOR VRU #: 001374354 A814 01 ΑP 3/20/07 CE 3/22/07 FOUR TRADE ROUGH IN VRU #: 001389733 B105 01 1) Bath room exhaust fans need to be vented to the de. 3/22/07 AP JH 4/16/07 2) Missing fire caulk in garage at top plate. R425 01 3) Need to repair truss beside stairway next to gara  $\cdot$ DA 4/16/07 4) Finish bracing on T6 truss in middle. 5) Water lines & drain lines under house need to be 6) Pier under masterbath needs to be motared back lace. R\*INSULATION INSPECTION VRU #: 001391226 JΗ 4/19/07 I129 01 FOUR TRADE ROUGH IN VRU #: 001391218 AΡ 4/19/07 ✓ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 06 4:2006 JΗ 4/19/07 R425 02

FOUR TRADE FINAL VRU #: 001426808

MR COMMENTS AND NOTES

AΡ

JW

ΑP

TI

4/19/07

5/16/07

5/16/07

6/11/07

H824 01

R429 01

## COUNTY OF HARNETT DEPARTMENT OF BUILDING INSPECTION AND PLANNING/DEVELOPMENT CERTIFICATE OF OCCUPANCY This certificate issued pursuant to the requirements of Section 105 of the North Carolina State Building Code and the Harnett County Zoning Ordinance certifies at the time of issuance this structure was in compliance with the various ordinances of the County of Harnett regulating development and building construction or use. For the following: Conditional Use Permit No.: Building Permit No.: <u>66-500159</u> Use Classification: Res. Type of Construction: Electrical Permit No.: Owner of Building: Southeast Dev. Building Address: 745 Colonal Hills Dr. Insulation Permit No.: 17 Plumbing Permit No.: Mech. Permit No.: Zoning District: Envir. C.O. No.: Zoning Permit No.: Date: 6-11-7 Miles Roam Building Official Zoning Official