

COMMENTS:

6/20/2007

An inspection was made of the drainfield installation for lot 38 in the easement allotted for lot 38. In an attempt to run the pump it was discovered that the pipe stubbed out for the supply line did not go to the easement for Lot 38. Instead it went to lot 51.

Present by OT + Jay Adcock