PREPARED 5/16/07, 14:01:48 INSPECTION TICKET PAGE 51 Harnett County INSPECTOR: IVR DATE 5/17/07

ADDRESS . : 164 SHERMAN PINES DR SUBDIV: SHERMAN PINES

CONTRACTOR :

PHONE : PHONE: (919) 796-1122

OWNER . . : HOMETOWN DEVELOPERS LLC #14 PARCEL . : 08-0655- - -0118- -50-

APPL NUMBER: 07-50017243 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : SHERMAN PINES #14

401N TO SHERMAN PINES DR LEFT TO LOT ON

RT. JDAVIS

STRUCTURE: 000 000 70X54 3BR

FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

REQUESTED INSP DESCRIPTION
TYP/SQ COMPLETED RESULT RESULTS/COMMENTS

B101 01 5/17/07 TI

R*BLDG FOOTING / TEMP SVC POLE VRU #: 001411421

PREPARED 5/23/07, 13:58:45 INSPECTION TICKET PAGE INSPECTOR: IVR DATE 5/24/07 Harnett County

ADDRESS . : 164 SHERMAN PINES DR SUBDIV: SHERMAN PINES

CONTRACTOR :

PHONE : PHONE: (919) 796-1122

OWNER . . : HOMETOWN DEVELOPERS LLC #14

PARCEL . .: 08-0655- - -0118- -50-

APPL NUMBER: 07-50017243 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : SHERMAN PINES #14

401N TO SHERMAN PINES DR LEFT TO LOT ON

RT. JDAVIS

STRUCTURE: 000 000 70X54 3BR

FLOOD ZONE . . . : FLOOD ZONE X

R*BLDG FOOTING / TEMP SVC POLE VRU #: 001411421

PERMIT: CPSF 00 CP * SFD

DESCRIPTION REQUESTED INSP TYP/SQ COMPLETED RESULT RESULTS/COMMENTS

B101 01 5/17/07 BS 5/17/07 AP B103 01 5/24/07 TI 5/24/07 DPBS R*BLDG FOUND & TEMP SVC POLE VRU #: 001415203

INSPECTION TICKET PAGE 50 PREPARED 5/25/07, 14:05:40 DATE 5/29/07 INSPECTOR: IVR Harnett County

SUBDIV: SHERMAN PINES

ADDRESS . : 164 SHERMAN PINES DR

PHONE :

PHONE: (919) 796-1122

CONTRACTOR:

OWNER . . : HOMETOWN DEVELOPERS LLC #14

PARCEL . : 08-0655- - -0118- -50-

APPL NUMBER: 07-50017243 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : SHERMAN PINES #14

401N TO SHERMAN PINES DR LEFT TO LOT ON

RT. JDAVIS

STRUCTURE: 000 000 70X54 3BR

FLOOD ZONE . . . : FLOOD ZONE X

4.00 PROPOSED USE : SFD # BEDROOMS :

SEPTIC - EXISTING? . . . : NEW

PERMIT: CPSF 00 CP * SFD

REQUESTED INSP DESCRIPTION
COMPLETED RESULT RESULTS/COMMENTS B101 01 5/17/07 BS R*BLDG FOOTING / TEMP SVC POLE VRU #: 001411421 5/17/07 AP B103 01 5/24/07 BS 5/24/07 DP R*BLDG FOUND & TEMP SVC POLE VRU #: 001415203 1. Clean exterior to footing and damproof. 2. Several piers not in center 1/3 of their footing, some are hanging off of their footing. 3. Left side of bay missed the footing.

(piers are marked with a piece of concrete on top.)

B103 02

R*BLDG FOUND & TEMP SVC POLE VRU #: 001416881

INSPECTION TICKET PREPARED 5/30/07, 15:20:04 Harnett County PAGE INSPECTOR: IVR DATE

ADDRESS . : 164 SHERMAN PINES DR CONTRACTOR : SUBDIV: SHERMAN PINES

PHONE :

OWNER . . : HOMETOWN DEVELOPERS LLC #14 PHONE: (919) 796-1122

PARCEL . . : 08-0655- - -0118- -50-

APPL NUMBER: 07-50017243 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : SHERMAN PINES #14

401N TO SHERMAN PINES DR LEFT TO LOT ON

RT. JDAVIS

PERMIT: (CPSF 00 CP * SFD REQUESTED INS COMPLETED RESU				
B101 01	5/17/07 BS 5/17/07 AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001411421			
B103 01	5/24/07 BS 5/24/07 DP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001415203 1. Clean exterior to footing and damproof. 2. Several piers not in center 1/3 of their footing, some are hanging off of their footing. 3. Left side of bay missed the footing. (piers are marked with a piece of concrete on top.)			
B103 02	5/29/07 BS 5/29/07 AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001416881			
A814 01	5/30/07 TI	ADDRESS CONFIRMATION VRU #: 001415212			
B105 01	5/30/07 AB	R*OPEN FLOOR VRU #: 001418530 VOICE MESSAGE LEFT			
COMMENTS AND NOTES					

PREPARED 7/12/07, 14:00:35 INSPECTION TICKET PAGE 23
Harnett County INSPECTOR: IVR DATE 7/13/07

ADDRESS , : 164 SHERMAN PINES DR SUBDIV: SHERMAN PINES

CONTRACTOR: PHONE:

OWNER . . : HOMETOWN DEVELOPERS LLC #14 PHONE : (919) 796-1122

PARCEL . : 08-0655- - -0118- -50-

APPL NUMBER: 07-50017243 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : SHERMAN PINES #14

401N TO SHERMAN PINES DR LEFT TO LOT ON

RT. JDAVIS

STRUCTURE: 000 000 70X54 3BR FLOOD ZONE . . . : FLOOD ZONE X

PERMIT:	CPSF 00 CP * SFD REQUESTED INSP COMPLETED RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/17/07 BS 5/17/07 AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001411421
B103 01	5/24/07 BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001415203
	5/24/07 DP	 Clean exterior to footing and damproof. Several piers not in center 1/3 of their footing, some are hanging off of their footing. Left side of bay missed the footing. (piers are marked with a piece of concrete on top.)
B103 02	5/29/07 BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001416881
	5/29/07 AP	
B105 01	5/30/07 BS	R*OPEN FLOOR VRU #: 001418530
	5/30/07 AP	VOICE MESSAGE LEFT
A814 01	5/30/07 TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001415212
	5/31/07 AP	164 SHERMAN PINES DR
R427 01	7/13/07 DPBS	FOUR TRADE ROUGH IN >2500 VRU #: 001445065

COMMENTS AND NOTES

Tyndall Engineering & Design, PA

69 Shipwash Dr.

Garner, North Carolina 27529 Phone: (919) 773-1200(O) Fax: (919) 773-9658 (F)

June 26, 2007

Hometown Development 7113 Nibhek Ct. Fuquay-Varina, NC 27526 Fax: (919) 542-6538

Reference: Framing Observations

Lot 14, Sherman Pines Fuquay-Varina, NC Project No.: 07AH-261

A representative of Tyndall Engineering & Design analyzed the above referenced project; specifically the following items listed below were reviewed:

- Observation of over-framing at the front three gables in-lieu of the plan specified structural valleys.
- Analyze (2) 11-7/8" LVL at center dormer supporting the main rafters and ceiling joists.
- 3) Analyze 16" TJI floor joists at 16" O.C. in the garage.

The following conclusions and recommendations were presented for the abovementioned items:

- Based on our observations and analysis, the over-framing at the front three dormers in-lieu of the plan specified valleys are adequate as constructed to support the anticipated loading conditions. No further action is required.
- Based on our observations and analysis, the (2) 11-7/8" LVL at the center dormer is adequate to support the anticipated loading conditions. No further action is required.
- 3) Based on our observations and analysis, the existing 16" TII floor joists at 16" O.C. in the garage are adequate to support the anticipated loading conditions. No further action is required.

We appreciate being able to assist you during this phase of the project. If you need further assistance or require additional information please do not hesitate to contact us.

Sincerely,

Tyndall Engineering & Design

I de Ols Hangy

Adam M. Hargraves AMH/07AH-261

Page 1 of 1


CoDocuments and Settings/Temp1'My Documents: Adam/LETTIERS 2002'07AH-261 Hometown Devel OVER FRAMING 07AH-261 Hometown Dev. LVL ISSUES.doc



16" TJI® 360 @ 16" o/c

User: 2 6/4/2007 10:48:11 AM Pape 1 Engine Version: 6.25.71

THIS PRODUCT MEETS OR EXCEEDS THE SET DESIGN CONTROLS FOR THE APPLICATION AND LOADS LISTED



LOADS:

Analysis is for a Joist Member.

Primary Load Group - Residential - Living Areas (psf): 40.0 Live at 100 % duration, 10.0 Dead

SUPPORTS:

		Input Width		Vertical Reactions (lbs) Live/Dead/Uplift/Total	Detail	Other
1	Stud wall	3.50"	2.25"	640 / 160 / 0 / 800	A3: Rim Board	1 Ply 1 1/4" x 16" 0.8E TJ-Strand Rim Board®
2	Stud wall	3.50"	2.25"	640 / 160 / 0 / 800	A3: Rim Board	1 Ply 1 1/4" x 16" 0.8E TJ-Strand Rim Board®

⁻See TJ SPECIFIER'S / BUILDERS GUIDE for detail(s): A3: Rim Board

DESIGN CONTROLS:

	Maximum	Design	Control	Control	Location
Shear (lbs)	786	-781	2190	Passed (36%)	Rt. end Span 1 under Floor loading
Vertical Reaction (lbs)	786	786	1202	Passed (65%)	Bearing 2 under Floor loading
Moment (Ft-Lbs)	4635	4635	8405	Passed (55%)	MID Span 1 under Floor loading
Live Load Defl (in)		0.433	0.590	Passed (L/653)	MID Span 1 under Floor loading
Total Load Defl (in)		0.541	1.179	Passed (L/523)	MID Span 1 under Floor loading
TJPro		33	30	Passed	Span 1

⁻Deflection Criteria: STANDARD(LL:L/480,TL:L/240).

TJ-Pro RATING SYSTEM

-The TJ-Pro Rating System value provides additional floor performance information and is based on a GLUED & NAILED 19/32" Panels (20" Span Rating) decking. The controlling span is supported by walls. Additional considerations for this rating include: Ceiling - None. A structural analysis of the deck has not been performed by the program. Comparison Value: 1.84

ADDITIONAL NOTES:

- -IMPORTANT! The analysis presented is output from software developed by Trus Joist (TJ). TJ warrants the sizing of its products by this software will be accomplished in accordance with TJ product design criteria and code accepted design values. The specific product application, input design loads, and stated dimensions have been provided by the software user. This output has not been reviewed by a TJ Associate.
- -Not all products are readily available. Check with your supplier or TJ technical representative for product availability.
- -THIS ANALYSIS FOR TRUS JOIST PRODUCTS ONLY! PRODUCT SUBSTITUTION VOIDS THIS ANALYSIS.
- -Allowable Stress Design methodology was used for Building Code UBC analyzing the TJ Distribution product listed above.

PROJECT INFORMATION:

lot 14 SHERMAN PINES

OPERATOR INFORMATION:

John Herman Stock Building Supply 7704 Burwell Rd Raleigh, NC 27615

Phone: 919-369-5057 Fax : 919-850-8277

john.herman@stocksupply.com

⁻Deflection analysis is based on composite action with single layer of 19/32" Panels (20" Span Rating) GLUED & NAILED wood decking.

⁻Bracing(Lu): All compression edges (top and bottom) must be braced at 4' 6" o/c unless detailed otherwise. Proper attachment and positioning of lateral bracing is required to achieve member stability.

5
)
•
3
)
֚֡֡֞֞֜֞֜֜֡֡֡֡
33/1
)
)
I
)

Cron		TJI® Joist Spacing) d
opali	16" o.c.	19.2" o.c.	24" o.c.
20'	14" TJI® 230, 11 ⁷ / ₈ " TJI® 360	14" TJI® 360	14" TJI® 360
22'	16" TJI® 230, 14" TJI® 360	16" TJI® 360	16" TJI® 360 ⁽²⁾
24'	16" TJI® 360	16" TJI® 560	16" TJI® 560 ⁽²⁾
26'	16" TJI® 560, 18" TJI® 360 ⁽¹⁾	18" TJI® 360 ⁽¹⁾⁽²⁾	18" TJI® 560 ⁽¹⁾⁽²⁾

1. Do not rafter cut 18" or deeper joists.

^{2.} Minimum end bearing of 3 1/2" required.

ADDRESS .. : 164 SHERMAN PINES DR

SUBDIV: SHERMAN PINES

CONTRACTOR :

PHONE :

OWNER . . : HOMETOWN DEVELOPERS LLC #14

PHONE: (919) 796-1122

PARCEL . . : 08-0655- - -0118- -50-

APPL NUMBER: 07-50017243 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : SHERMAN PINES #14

401N TO SHERMAN PINES DR LEFT TO LOT ON

RT. JDAVIS

STRUCTURE: 000 000 70X54 3BR FLOOD ZONE . . . : FLOOD ZONE X

7/19/07

7-19-07 APBS

PERMIT: CPSF 00 CP * SFD REQUESTED INSP DESCRIPTION TYP/SQ COMPLETED RESULT RESULTS/COMMENTS 5/17/07 BS 5/17/07 AP B101 01 R*BLDG FOOTING / TEMP SVC POLE VRU #: 001411421 B103 01 5/24/07 BS R*BLDG FOUND & TEMP SVC POLE VRU #: 001415203 5/24/07 DP 1. Clean exterior to footing and damproof. 2. Several piers not in center 1/3 of their footing, some are hanging off of their footing. 3. Left side of bay missed the footing. (piers are marked with a piece of concrete on top.) B103 02 5/29/07 BS R*BLDG FOUND & TEMP SVC POLE VRU #: 001416881 5/29/07 AP B105 01 5/30/07 BS R*OPEN FLOOR VRU #: 001418530 5/30/07 AP VOICE MESSAGE LEFT A814 01 5/30/07 TI ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001415212 5/31/07 AP 164 SHERMAN PINES DR R427 01 7/13/07 BS FOUR TRADE ROUGH IN >2500 VRU #: 001445065 DP 1. Install two front windows (tempered) 2. Install windows 7/13/07 over rear door. 3. All ceiling joists w/ OSB on top must be furred up to accept R-30 C insulation (min 8.25") 4. Plan Calls for 2- 11.75 LVL at left side over kitchen/dining entry from great room. 5. Plan calls for triple 9.25 LVL at tub areas upstairs. 6. Rodent proof all tub/ shower drains w/ sheet metal 7. Repair Floor joist cut for master toilet drop. 8. No pressure on gas test. DO NOT SIDE OR INSULATE.

------ COMMENTS AND NOTES -----

FOUR TRADE ROUGH IN >2500 VRU #: 001449131

Affic Acoust

Tyndall Engineering & Design, PA

69 Shipwash Dr.

Garner, North Carolina 27529 Phone: (919) 773-1200(O) Fax: (919) 773-9658 (F)

July 16, 2007

Hometown Development 7113 Niblick Ct. Fuquay-Varina, NC 27526 Fax: (919) 542-6538

Reference: Framing Observations Lot 14, Sherman Pines Fuguay-Varina, NC Project No.: 07AH-294

A representative of Tyndall Engineering & Design analyzed the above referenced project; specifically the following items listed below were reviewed:

- 1) Analyze (2) 9 1/2" LVL with (2) 2x10 dropped header at the kitchen in-lieu of the plan specified (2) 11-1/4" LVL.
- 2) Analyze (2) 9 1/4" LVL at the kitchen in-lieu of the plan specified (3) 9 1/4" LVL.
- 3) Analyze (2) 9 1/4" LVL at the fireplace in-lieu of the plan specified (2) 11-1/4" LVL.

The following conclusions and recommendations were presented for the abovementioned items:

- 1) Based on our observations and analysis, the existing (2) 9 1/4" LVL with a dropped (2) 2x10 is not adequate to support the anticipated loading conditions. The dropped (2) 2x10 header should be replaced by a (2) 9 1/4" LVL member.
- 2) Based on our observations and analysis, the (2) 9 1/4" LVL member in-lieu of the plan specified (3) 9 1/4" LVL member is not adequate to support the anticipated loading conditions. The (2) 9 1/4" LVL member should be enhanced to a (3) 9 1/4" LVL.
- 3) Based on our observations and analysis, the (2) 9 1/2" LVL member at the fireplace inlieu of the plan specified (2) 11-1/4" LVL is adequate to support the anticipated loading conditions, provided that the member is supported at the corners of the fireplace with a minimum of (4) 2x4 studs. The point loads at the fireplace are adequately supported by the 16"x16" masonry piers in the foundation.

We appreciate being able to assist you during this phase of the project. If you need further assistance or require additional information please do not hesitate to contact us.

Sincerely.

Tyndall Engineering & Design

du OHHap

Adam M. Hargraves AMH/07AH-294

Page 1 of 1

Ci/Documents and Settings\Temp\\My Documents\Adam\LETTERS 2007/07AH-294 Hometown Devel BEAM SIZE/07AH-294 Hometown Dev. BEAM SIZE.doc

PREPARED 7/24/07, 14:01:14 INSPECTION TICKET PAGE 28
Harnett County INSPECTOR: IVR DATE 7/25/07

PHONE :

ADDRESS . : 164 SHERMAN PINES DR SUBDIV: SHERMAN PINES

CONTRACTOR :

OWNER . . : HOMETOWN DEVELOPERS LLC #14 PHONE : (919) 796-1122

PARCEL . .: 08-0655- - -0118- -50-

APPL NUMBER: 07-50017243 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : SHERMAN PINES #14

401N TO SHERMAN PINES DR LEFT TO LOT ON

RT. JDAVIS

STRUCTURE: 000 000 70X54 3BR FLOOD ZONE . . . : FLOOD ZONE X

PERMIT:	CPSF 00 CP *	SFD	
	REQUESTED		DESCRIPTION
TYP/SQ	COMPLETED	RESULT	RESULTS/COMMENTS
B101 01	5/17/07		R*BLDG FOOTING / TEMP SVC POLE VRU #: 001411421
	5/17/07	AP	
B103 01	5/24/07		R*BLDG FOUND & TEMP SVC POLE VRU #: 001415203
	5/24/07	DP	1. Clean exterior to footing and damproof. 2. Several piers not in center 1/3 of their footing, some are hanging off of their footing. 3. Left side of bay missed the footing. (piers are marked with a piece of concrete on top.)
B103 02	5/29/07	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001416881
	5/29/07	AP	,
B105 01	5/30/07	BS	R*OPEN FLOOR VRU #: 001418530
	5/30/07	AP	VOICE MESSAGE LEFT
A814 01	5/30/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001415212
	5/31/07	AP	164 SHERMAN PINES DR
R427 01	7/13/07	BS	FOUR TRADE ROUGH IN >2500 VRU #: 001445065
	7/13/07	DP	1. Install two front windows (tempered) 2. Install windows over rear door. 3. All ceiling joists w/ OSB on top must be furred up to accept R-30 C insulation (min 8.25") 4. Plan Calls for 2- 11.75 LVL at left side over kitchen/dining entry from great room. 5. Plan calls for triple 9.25 LVL at tub areas upstairs. 6. Rodent proof all tub/ shower drains w/ sheet metal 7. Repair Floor joist cut for master toilet drop. 8. No pressure on gas test. DO NOT SIDE OR INSULATE.
R427 02	7/19/07 7/19/07	BS DA	FOUR TRADE ROUGH IN >2500 VRU #: 001449131 1. Need access to attic areas above kitchen and master . 2. Where OSB is installed on top of joists fir up or remove
I129 01	7/24/07	TI	OSB for insulation.
1123 01	7/24/07	CA	R*INSULATION INSPECTION VRU #: 001452298
R427 03	7/24/07	TI	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 001452580
7.17. 00	7/24/07	CA	100K INDE KOOON IN 2200 IIME: 17:00 VKU #: 001452580
1129 02	7/25/07	TIAPRS	R*INSULATION INSPECTION VRU #: 001452945
R427 04	7/25/07		FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 001452937

COMMENTS AND NOTES

_TREPARED 10/10/07, 14:00:48 Harnett County

INSPECTION TICKET INSPECTOR: IVR

PAGE

DATE 10/11/07

18

ADDRESS . : 164 SHERMAN PINES DR

SUBDIV: SHERMAN PINES

CONTRACTOR :

PHONE :

PHONE: (919) 796-1122

OWNER . . : HOMETOWN DEVELOPERS LLC #14

PARCEL . . : 08-0655- - -0118- -50-

APPL NUMBER: 07-50017243 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : SHERMAN PINES #14

401N TO SHERMAN PINES DR LEFT TO LOT ON

RT. JDAVIS

STRUCTURE: 000 000 70X54 3BR

FLOOD ZONE . . . : FLOOD ZONE X

PERMIT:	CPSF 00 CP *	SFD INSP	DESCRIPTION
TYP/SQ	COMPLETED	RESULT	RESULTS/COMMENTS
B101 01		BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001411421
	5/17/07	AP	
B103 01	5/24/07	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001415203
	5/24/07	DP	 Clean exterior to footing and damproof. 2. Several piers not in center 1/3 of their footing, some are hanging off of their footing. 3. Left side of bay missed the footing. (piers are marked with a piece of concrete on top.)
B103 02	5/29/07	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001416881
	5/29/07	AP	
B105 01	5/30/07	BS	R*OPEN FLOOR VRU #: 001418530
	5/30/07	AP	VOICE MESSAGE LEFT
A814 01	5/30/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001415212
	5/31/07	AP	√164 SHERMAN PINES DR
R427 01	7/13/07	BS	FOUR TRADE ROUGH IN >2500 VRU #: 001445065
	7/13/07	DP	1. Install two front windows (tempered) 2. Install windows over rear door. 3. All ceiling joists w/ OSB on top must be furred up to accept R-30 C insulation (min 8.25") 4. Plan Calls for 2- 11.75 LVL at left side over kitchen/dining entry from great room. 5. Plan calls for triple 9.25 LVL at tub areas upstairs. 6. Rodent proof all tub/ shower drains w/ sheet metal 7. Repair Floor joist cut for master toilet drop. 8. No pressure on gas test. DO NOT SIDE OR INSULATE.
R427 02	7/19/07	BS	FOUR TRADE ROUGH IN >2500 VRU #: 001449131
	7/19/07	DA	 Need access to attic areas above kitchen and master . 2. Where OSB is installed on top of joists fir up or remove OSB for insulation.
I129 01	7/24/07	TI	R*INSULATION INSPECTION VRU #: 001452298
	7/24/07	CA	
R427 03	7/24/07	TI	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 001452580
	7/24/07	CA	
I129 02	7/25/07	BS	R*INSULATION INSPECTION VRU #: 001452945
	7/25/07	AP	
R427 04		BS	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 001452937
	7/25/07	AP	<i>t</i>
H824 01	8/17/07	JM	√ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001470079
	8/17/07	AP	
R431 01	10-11-07	DABS	FOUR TRADE FINAL >2500 VRU #: 001502788

 PREPARED 12/05/07, 14:02:17
 INSPECTION TICKET
 PAGE
 13

 Harnett County
 INSPECTOR: IVR
 DATE
 12/06/07

ADDRESS . : 164 SHERMAN PINES DR SUBDIV: SHERMAN PINES

CONTRACTOR: PHONE:

OWNER . .: HOMETOWN DEVELOPERS LLC #14 PHONE : (919) 796-1122

PARCEL . : 08-0655- - -0118- -50-

APPL NUMBER: 07-50017243 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : SHERMAN PINES #14

401N TO SHERMAN PINES DR LEFT TO LOT ON

RT. JDAVIS

STRUCTURE: 000 000 70X54 3BR FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD REQUESTED INSP DESCRIPTION COMPLETED RESULT RESULTS/COMMENTS TYP/SQ 5/17/07 BS R*BLDG FOOTING / TEMP SVC POLE VRU #: 001411421 B101 01 AP 5/17/07 B103 01 5/24/07 BS R*BLDG FOUND & TEMP SVC POLE VRU #: 001415203 5/24/07 DΡ 1. Clean exterior to footing and damproof. 2. Several piers not in center 1/3 of their footing, some are hanging off of their footing. 3. Left side of bay missed the footing. (piers are marked with a piece of concrete on top.) B103 02 5/29/07 BS R*BLDG FOUND & TEMP SVC POLE VRU #: 001416881 AP 5/29/07 B105 01 5/30/07 BS R*OPEN FLOOR VRU #: 001418530 5/30/07 AP VOICE MESSAGE LEFT ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001415212 TI A814 01 5/30/07 AP √064 SHERMAN PINES DR 5/31/07 R427 01 7/13/07 BS FOUR TRADE ROUGH IN >2500 VRU #: 001445065 1. Install two front windows (tempered) 2. Install windows 7/13/07 DP over rear door. 3. All ceiling joists w/ OSB on top must be furred up to accept R-30 C insulation (min 8.25") 4. Plan Calls for 2- 11.75 LVL at left side over kitchen/dining entry from great room. 5. Plan calls for triple 9.25 LVL at tub areas upstairs. 6. Rodent proof all tub/ shower drains w/ sheet metal 7. Repair Floor joist cut for master toilet drop. 8. No pressure on gas test. DO NOT SIDE OR INSULATE. FOUR TRADE ROUGH IN >2500 VRU #: 001449131 R427 02 7/19/07 BS 7/19/07 DA 1. Need access to attic areas above kitchen and master . 2. Where OSB is installed on top of joists fir up or remove OSB for insulation. I129 01 7/24/07 TI R*INSULATION INSPECTION VRU #: 001452298 CA 7/24/07 FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 001452580 R427 03 7/24/07 TICA 7/24/07 I129 02 7/25/07 R*INSULATION INSPECTION VRU #: 001452945 7/25/07 AP R427 04 7/25/07 BS FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 001452937 AP 7/25/07 H824 01 8/17/07 JM VENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001470079 8/17/07 AP R431 01 10/11/07 FOUR TRADE FINAL >2500 VRU #: 001502788 BS 10/11/07 1. Need ladder for attic 2. Rails at rear door 3. Tempered glass at master tub. 12/06/07 FOUR TRADE FINAL >2500 VRU #: 001530962 R431 02

This certificate issued pursuant to the requirements of Section 105 of the North Carolina State Building Code and the Harnett County Zoning Ordinance certifies at the time of issuance this structure was in compliance with the various ordinances of the County of Harnett regulating development and building DEPARTMENT OF BUILDING INSPECTION CERTIFICATE OF OCCUPANCY Zoning Official Conditional Use Permit No.: AND PLANNING/DEVELOPMENT Electrical Permit No.: Insulation Permit No.: Plumbing Permit No.: Building Permit No .: Mech. Permit No.: Envir. C.O. No.: _ **COUNTY OF HARNET!** construction or use. For the following: **Building Official** Date: Owner of Building: Han Building Address: 164 Type of Construction: Use Classification: Zoning Permit No.: Zoning District: