PREPARED 3/11/08, 14:02:03 Harnett County

INSPECTION TICKET INSPECTOR: IVR

PAGE

DATE 3/12/08

ADDRESS . : 255 BASKET OAK DR

SUBDIV: FOREST OAKS PH 3 99LOTS

PHONE: (919) 481-0503

CONTRACTOR : CAVINESS LAND DEVELOPMENT OWNER . . : CAVINESS LAND DEVELOPMENT INC

PHONE: (910) 481-0503

PARCEL . .: 01-0536-05- -0028- -30-

APPL NUMBER: 07-50019043 CP NEW RESIDENTIAL (SFD) DIRECTIONS: FOREST OAKS #143-27W TO NURSERY RD TO

LEMUEL BLACK S/D ON LEFT.JD

STRUCTURE: 000 000 48X60 4BR W/GARAGE (UK)

FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

REQUESTED INSP

DESCRIPTION

TYP/SQ COMPLETED RESULT RESULTS/COMMENTS

P309 01 3/12/08 TI AV TI R*PLUMB UNDER SLAB VRU #: 001575679

_____COMMENTS AND NOTES -----

PREPARED 3/14/08, 14:00:51 INSPECTION TICKET PAGE 14 INSPECTOR: IVR DATE 3/17/08 Harnett County

ADDRESS . : 255 BASKET OAK DR SUBDIV: FOREST OAKS PH 3 99LOTS

CONTRACTOR : CAVINESS LAND DEVELOPMENT PHONE: (919) 481-0503 PHONE: (910) 481-0503 OWNER . . : CAVINESS LAND DEVELOPMENT INC

PARCEL . .: 01-0536-05- -0028- -30-

APPL NUMBER: 07-50019043 CP NEW RESIDENTIAL (SFD) DIRECTIONS : FOREST OAKS #143-27W TO NURSERY RD TO

LEMUEL BLACK S/D ON LEFT.JD

STRUCTURE: 000 000 48x60 4BR W/GARAGE (UK)

DA-MR

FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

REQUESTED INSP DESCRIPTION TYP/SQ COMPLETED RESULT RESULTS/COMMENTS ______ P309 01 3/12/08 JS R*PLUMB UNDER SLAB VRU #: 001575679 3/12/08 AP

3/17/08 TI R*BLDG SLAB INSP VRU #: 001577857 B111 01

PREPARED 3/17/08, 14:10:52 Harnett County

INSPECTION TICKET INSPECTOR: IVR

PAGE

21 DATE 3/18/08

ADDRESS . : 255 BASKET OAK DR

SUBDIV: FOREST OAKS PH 3 99LOTS

CONTRACTOR : CAVINESS LAND DEVELOPMENT OWNER . . : CAVINESS LAND DEVELOPMENT INC

PHONE: (919) 481-0503 PHONE: (910) 481-0503

PARCEL . .: 01-0536-05- -0028- -30-

APPL NUMBER: 07-50019043 CP NEW RESIDENTIAL (SFD) DIRECTIONS : FOREST OAKS #143-27W TO NURSERY RD TO

LEMUEL BLACK S/D ON LEFT.JD

STRUCTURE: 000 000 48X60 4BR W/GARAGE (UK)

AP-MZ

FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD REQUESTED INSP TYP/SQ COMPLETED RESULT	DESCRIPTION RESULTS/COMMENTS
P309 01 3/12/08 JS 3/12/08 AP	R*PLUMB UNDER SLAB VRU #: 001575679
B111 01 3/17/08 DA	R*BLDG SLAB INSP VRU #: 001577857 1. footer for outside perimeter walls must be 16" wide or provide engineering garage walls 2. truss plans call for interior bearing walls interior bearing wall sole plates must be anchored with bolts or approved straps and must penetrate 7" into concrete, so a lug footing is required under all load-bearing interior walls 3. footer must be 12" below the frost line R403.1.4 wood walls must be a min, of 6" above the grade R319.5, so, the monolithic pour must be 18" thick at the footer
B111 02 3/18/08 TI	R*BLDG SLAB INSP VRU #: 001578749

----- COMMENTS AND NOTES -----

PREPARED 4/17/08, 8:20:32 Harnett County

INSPECTION TICKET INSPECTOR: IVR

PAGE

DATE 4/17/08

SUBDIV: FOREST OAKS PH 3 99LOTS

ADDRESS . : 255 BASKET OAK DR

CONTRACTOR : CAVINESS LAND DEVELOPMENT OWNER . . : CAVINESS LAND DEVELOPMENT INC

PHONE: (910) 481-0503

PHONE: (919) 481-0503

PARCEL -. : 01-0536-05- -0028- -30-

APPL NUMBER: 07-50019043 CP NEW RESIDENTIAL (SFD)

DIRECTIONS: FOREST OAKS #143-27W TO NURSERY RD TO

LEMUEL BLACK S/D ON LEFT.JD

STRUCTURE: 000 000 48x60 4BR W/GARAGE (UK)

FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD					
	REQUESTED	INSP	DESCRIPTION		
TYP/SQ	COMPLETED	RESULT	RESULTS/COMMENTS		
P309 01	3/12/08	JS	R*PLUMB UNDER SLAB VRU #: 001575679		
	3/12/08	AP			
B111 01	3/17/08	MR	R*BLDG SLAB INSP VRU #: 001577857		
	3/17/08	DA	 footer for outside perimeter walls must be 16" wide or provide engineering garage walls 		
			2. truss plans call for interior bearing walls. interior bearing wall sole plates must be anchored with bolts or approved straps and must penetrate 7" into concrete, so a lug footing is required under all load-bearing interior walls		
			3. footer must be 12" below the frost line R403.1.4 wood walls must be a min, of 6" above the grade R319.5, so, the monolithic pour must be 18" thick at the footer		
B111 02	3/18/08	MR	R*BLDG SLAB INSP VRU #: 001578749		
	3/18/08	AP			
R425 01	4/17/08	# 1H	FOUR TRADE ROUGH IN VRU #: 001595287		
			COMMENTS AND NOTES		

PREPARED 4/23/08, 14:06:38 INSPECTION TICKET Harnett County INSPECTOR: IVR

INSPECTION TICKET

PAGE DATE

4/24/08

______ SUBDIV: FOREST OAKS PH 3 99LOTS

ADDRESS . : 255 BASKET OAK DR

PHONE: (919) 481-0503

CONTRACTOR : CAVINESS LAND DEVELOPMENT

OWNER . . : CAVINESS LAND DEVELOPMENT INC PHONE: (910) 481-0503

PARCEL . . : 01-0536-05- -0028- -30-

APPL NUMBER: 07-50019043 CP NEW RESIDENTIAL (SFD) DIRECTIONS : FOREST OAKS #143-27W TO NURSERY RD TO

LEMUEL BLACK S/D ON LEFT.JD

STRUCTURE: 000 000 48X60 4BR W/GARAGE (UK)

FLOOD ZONE . . . : FLOOD ZONE X

TYP/SQ	REQUESTED COMPLETED	INSP, RESULT	DESCRIPTION RESULTS/COMMENTS
P309 01	3/12/08	JS	R*PLUMB UNDER SLAB VRU #: 001575679
	3/12/08	AP	
B111 01	3/17/08	MR	R*BLDG SLAB INSP VRU #: 001577857
	3/17/08	DA .	 footer for outside perimeter walls must be 16" wide or provide engineering garage walls
			2. truss plans call for interior bearing walls interior
			bearing wall sole plates must be anchored with bolts or
			approved straps and must penetrate 7" into concrete, so a
			lug footing is required under all load-bearing interior
			walls
			3. footer must be 12" below the frost line R403.1.4 wood walls must be a min, of 6" above the grade R319.5, so, the monolithic pour must be 18" thick at the footer
B111 02	3/18/08	MR	R*BLDG SLAB INSP VRU #: 001578749
	3/18/08	AP	TO BE SELECTION OF THE
R425 01	4/17/08	III.	FOUR TRADE ROUGH IN VRU #: 001595287
	4/17/08	DA	Missing nail guard @ top plate in master bath @ shower.
	1, 11, 00	()	A) Missing uplift clips on truss A4 @ point 15, A3 @ point
			12& A7 @ point 6.
			Need footing for screened porch.
R425 02	4/24/08	$_{\text{TI}}$ \mathcal{A}^{1}	FOUR TRADE ROUGH IN VRU #: 001598408
	.,,	AT 710	
I129 01	4/24/08	RI /	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001598416
	-,	HP JH	customer said ok to insulate & have inspected with rough in
		-11 \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ 	reinspection. customer said no footings needed - no
			footing inspection needed because monolithic. if footing
			inspection needed - please schedule.jd

1.0 3 PREPARED 9/22/08, 8:17:18

INSPECTION TICKET

PAGE

9/22/08

Harnett County INSPECTOR: IVR DATE

ADDRESS . : 255 BASKET OAK DR

SUBDIV: FOREST OAKS PH 3 99LOTS

CONTRACTOR : CAVINESS LAND DEVELOPMENT

PHONE: (919) 481-0503 PHONE : (910) 481-0503

OWNER . . : CAVINESS LAND DEVELOPMENT INC

PARCEL . . : 01-0536-05- -0028- -30-

APPL NUMBER: 07-50019043 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : FOREST OAKS #143-27W TO NURSERY RD TO

LEMUEL BLACK S/D ON LEFT.JD

STRUCTURE: 000 000 48X60 4BR W/GARAGE (UK)

FLOOD ZONE . . . : FLOOD ZONE X

PROPOSED USE : SFD # BEDROOMS : 4.00

SEPTIC - EXISTING? . . . : NEW

PERMIT: (CPSF 00 CP * REQUESTED COMPLETED	SFD INSP RESULT	DESCRIPTION RESULTS/COMMENTS
P309 01	3/12/08	JS	R*PLUMB UNDER SLAB VRU #: 001575679
	3/12/08	AP	•
B111 01	3/17/08	MR	R*BLDG SLAB INSP VRU #: 001577857
	3/17/08	ĎA	 footer for outside perimeter walls must be 16" wide or provide engineering garage walls
			2. truss plans call for interior bearing walls interior
			bearing wall sole plates must be anchored with bolts or
			approved straps and must penetrate 7" into concrete, so a
			<pre>lug footing is required under all load-bearing interior walls</pre>
			3. footer must be 12" below the frost line R403.1.4
			wood walls must be a min, of 6" above the grade R319.5, so, the monolithic pour must be 18" thick at the footer
B111 02	3/18/08	MR	R*BLDG SLAB INSP VRU #: 001578749
B111 02	3/18/08	AP	R-BIDG SHAB INSP VRU #: UUIS/0/49
R425 01	4/17/08	JН	FOUR TRADE ROUGH IN VRU #: 001595287
1425 01	4/17/08	DA	1) Missing nail guard @ top plate in master bath @ shower.
	4/1//00	DR	2) Missing uplift clips on truss A4 @ point 15, A3 @ point
			12& A7 @ point 6.
			3) Need footing for screened porch.
R425 02	4/24/08	JH	FOUR TRADE ROUGH IN VRU #: 001598408
	4/24/08	AP	
I129 01	4/24/08	JH	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001598416
	4/24/08	AP	customer said ok to insulate & have inspected with rough in
			reinspection. customer said no footings needed - no
			footing inspection needed because monolithic. if footing
			inspection needed - please schedule.jd
R429 01	9/19/08	TI	FOUR TRADE FINAL VRU #: 001679696
	9/18/08	CA	CANCELLED FINAL INSPECTION FOR 09/19/08. NO ADDRESS
	•		CONFIRMATION. N-TART
R431 01	9/22/08	TI 111	FOUR TRADE FINAL >2500 TIME: 17:00 VRU #: 001680487
		HP UK	

------ COMMENTS AND NOTES -----





Service Bulletin

SR-015 Rev. 1 SUPERCEDES SR-015

DATE:

January 31, 2008

TO:

All Service and Parts Managers

SUBJECT:

GSC130361AA/BA and GSH130361A* Nuisance Tripping of Overcurrent

Protection Device

We have received field reports of GSC130361AA and GSC130361BA model condensing units and the GSH130361A* model heat pump unit experiencing nuisance tripping of the 20 Amp overcurrent protection devices. In many cases we have found that the required HACR type breaker had not been used and once the HACR type breaker was installed the nuisance tripping was corrected.

After reevaluating the electrical characteristics on these units it was determined that the maximum overcurrent device could be increased from a 20 Amp to a 25 Amp HACR type breaker or time delay fuse of the same size. Therefore Goodman is updating the specifications of these units to approve the use of 25 amp overcurrent protection devices.

Literature and rating plates are being revised to show the 25 Amp maximum overcurrent protection device for the GSC130361AA and GSC130361BA condensing units and the GSH130361A* heat pump unit only. Note: Any units installed that are experiencing nuisance tripping of this breaker or fuse should first have the following items checked prior to making the change from 20 Amp to 25 Amp maximum overcurrent protection device.



WARNING

HIGH VOLTAGE!

Disconnect ALL power before servicing.

Multiple power sources may be present.

Failure to do so may cause property damage,
personal injury or death.



- 1. Breaker must be a HVAC type breaker or time delay fuse of the same size.
- 2. Units matched with TXV equipped indoor coils must have the appropriate hard start kit installed. Refer to Service Bulletin SR-004, Rev.1 for approved hard start kits.
- 3. Unit must have the proper charge verified by superheat or subcooling method as described in the installation instructions.

After checking the above items and the unit continues to experience nuisance tripping of the overcurrent protection device, the 20 Amp breaker or fuse should be replaced with a 25 Amp HACR type breaker or time delay fuse of the same size.

Technical Services Department • 1810 Wilson Parkway • Fayetteville, TN 37334 Main: 888.593.9988 • Service Fax: 931.438.2273

FITTE CIRC (s a trademark of Maytag Corporation and is used under license to Goodman Company, L.P.
All rights reserved.

COUNTY OF HARNETT DEPARTMENT OF BUILDING INSPECTION AND PLANNING/DEVELOPMENT CERTIFICATE OF OCCUPANCY

This certificate issued pursuant to the requirements of Section 105 of the North Carolina State Building Code and the Harnett County Zoning Ordinance certifies at the time of issuance this structure was in compliance with the various ordinances of the County of Harnett regulating development and building construction or use. For the following:

Use Classification: SFD	L PERMIT NUMBERS
Owner: Coviness Land Dovelopmen	1 Building Permit No.:
911 Address: 255 Busket oak dr	Electrical Permit No.:
· .	Insulation Permit No.:
	Plumbing Permit No.:
State: Zip Code:	Mech. Permit No.:
1 Date 9-23-96	MFG. Home:
- Jame 7 tall	
Building Official	