PREPARED 10/29/09, 13:59:02 INSPECTION TICKET PAGE INSPECTOR: IVR Harnett County DATE 10/30/09 ADDRESS . : 59 BEN CT SUBDIV: BEN WOODS 10 LOTS CONTRACTOR : THOMAS CONSTRUCTION & REALTY PHONE: (910) 893-8950 OWNER . . : M G M BUILDERS PHONE : PARCEL . . : 12-0547- - -0013- -11-APPL NUMBER: 08-50020557 CP NEW RESIDENTIAL (SFD) DIRECTIONS : HWY 210 S APPROX 4 MILES TO BENWOODS S/D IS ON LEFT JUST PAST TEMPLE RD LOT 9 JB STRUCTURE: 000 000 60X60 3BDR CRAWL W/ GARAGE FLOOD ZONE . . . : FLOOD ZONE X # BEDROOMS : 3.00 PROPOSED USE : SFD SEPTIC - EXISTING? . . . : NEW WATER SUPPLY : COUNTY PERMIT: CPSF 00 CP * SFD REQUESTED INSP DESCRIPTION

10/26/09 AP A814 01 10/30/09 TI ADDRESS CONFIRMATION VRU #: 001843853 10/30/09 TI JH

TYP/SQ COMPLETED RESULT RESULTS/COMMENTS

R*BLDG FOUND & TEMP SVC POLE VRU #: 001843861 WOULD LIKE INSPECTION AFTER LUNCH TIME ANY TIME AFTER 1PM

-T-P-COMMENTS AND NOTES Gremise# 02562660

B101 01 10/26/09 DT R*BLDG FOOTING / TEMP SVC POLE VRU #: 001841733

 PREPARED 11/02/09, 13:59:35
 INSPECTION TICKET
 PAGE 4

 Harnett County
 INSPECTOR: IVR
 DATE 11/03/09

ADDRESS . : 59 BEN CT

SUBDIV: BEN WOODS 10 LOTS

CONTRACTOR : THOMAS CONSTRUCTION & REALTY

PHONE: (910) 893-8950

OWNER . . : M G M BUILDERS

PHONE :

PARCEL . . : 12-0547- - -0013- -11-

APPL NUMBER: 08-50020557 CP NEW RESIDENTIAL (SFD) DIRECTIONS: HWY 210 S APPROX 4 MILES TO BENWOODS

S/D IS ON LEFT JUST PAST TEMPLE RD LOT

9 JB

STRUCTURE: 000 000 60X60 3BDR CRAWL W/ GARAGE

FLOOD ZONE . . . : FLOOD ZONE X

BEDROOMS : 3.00 PROPOSED USE : SFD SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: C	PERMIT: CPSF 00 CP * SFD REQUESTED INSP DESCRIPTION					
TYP/SQ	COMPLETED	RESULT	RESULTS/COMMENTS			
B101 01	10/26/09	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001841733			
A814 01	10/26/09 10/30/09	AP TI	ADDRESS CONFIRMATION VRU #: 001843853			
B103 01	10/30/09	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001843861			
2203 02	10/30/09	AP	WOULD LIKE INSPECTION AFTER LUNCH TIME ANY TIME AFTER 1PM			
B105 01	11/03/09	₩ <u>)</u>	t-pole passed			

PREPARED 11/18/09, 13:59:32
Harnett County

INSPECTION TICKET INSPECTOR: IVR

PAGE

DATE 11/19/09

ADDRESS . : 59 BEN CT CONTRACTOR : THOMAS CONSTRUCTION & REALTY

PARCEL . : 12-0547- - -0013- -11-

SUBDIV: BEN WOODS 10 LOTS PHONE: (910) 893-8950

THOMAS CONSTRUCTION & REAL.

PHONE : (9

OWNER . . : M G M BUILDERS

APPL NUMBER: 08-50020557 CP NEW RESIDENTIAL (SFD) DIRECTIONS: HWY 210 S APPROX 4 MILES TO BENWOODS

S/D IS ON LEFT JUST PAST TEMPLE RD LOT

9 JB

STRUCTURE: 000 000 60X60 3BDR CRAWL W/ GARAGE

FLOOD ZONE . . . : FLOOD ZONE X

SEPTIC - EXISTING? . . . : NEW WATER SUPPLY : COUNTY

TYP/SQ	CPSF 00 CP * REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	10/26/09	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001841733
	10/26/09	AP	
B103 01	10/30/09	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001843861
	10/30/09	AP	WOULD LIKE INSPECTION AFTER LUNCH TIME ANY TIME AFTER 1PM
			t-pole passed
A814 01	10/30/09	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001843853
	11/04/09	AP	59 ben ct lot 9
			bunnlevel 28323
			T/S: 11/04/2009 04:25 PM TWARD
B105 01	11/03/09	DT	R*OPEN FLOOR TIME: 17:00 VRU #: 001845031
	11/03/09	AP	T/S: 11/02/2009 11:30 AM VBROWN
R425 01	11/19/09	TI	FOUR TRADE ROUGH IN VRU #: 001852557
	11.19.09	JARK .	requests pm inspection

----- COMMENTS AND NOTES -----

BP006U01

Barnett County
Edit Narrative

11/19/09
11:04:05

Application number, type . . : 08 50020557 CP NEW RESIDENTIAL (SFD)
Property address : 59 BEN CT

Type information, press Enter.

1. Nut and washer missing in garage. 2. Support top of both valleys to a load wall below (left side of roof) 3.
Electrical Not firestopped. 4. Flash rear porch. 5. Need a Rescheck from insulation contractor at insulation inspection. Ceiling will have to be R-38, and all floored areas of ceiling will not hold R-38. 6.Plumbing pressure test is ok. No water on drain test. Ok to side. DO NOT INSULATE.

More...

F3=Exit F5=Copy F6=Insert F7=Delete F8=Time stamp F12=Cancel F21=User defaults

PREPARED 11/24/09, 14:00:31

INSPECTION TICKET

PAGE

DATE 11/25/09

Harnett County

INSPECTOR: IVR

SUBDIV: BEN WOODS 10 LOTS

ADDRESS . : 59 BEN CT

PHONE : (910) 893-8950

CONTRACTOR : THOMAS CONSTRUCTION & REALTY

M BUILDERS PHONE :

OWNER . . : M G M BUILDERS

PARCEL . . : 12-0547- - -0013- -11-

APPL NUMBER: 08-50020557 CP NEW RESIDENTIAL (SFD)
DIRECTIONS: HWY 210 S APPROX 4 MILES TO BENWOODS

S/D IS ON LEFT JUST PAST TEMPLE RD LOT

9 JB

STRUCTURE: 000 000 60X60 3BDR CRAWL W/ GARAGE

FLOOD ZONE . . . : FLOOD ZONE X

BEDROOMS : 3.00 PROPOSED USE : SFD

SEPTIC - EXISTING? . . . : NEW WATER SUPPLY : COUNTY

TYP/SQ	REQUESTED COMPLETED		DESCRIPTION RESULTS/COMMENTS
B101 01	10/26/09	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001841733
	10/26/09	AP	" PDDG 10011MG / IBME 54C FOLE
B103 01		JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001843861
	10/30/09	AP	WOULD LIKE INSPECTION AFTER LUNCH TIME ANY TIME AFTER 1PM t-pole passed
A814 01	10/30/09	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001843853
	11/04/09	AP	59 ben ct lot 9
			bunnlevel 28323
			T/S: 11/04/2009 04:25 PM TWARD
B105 01	11/03/09	DT	R*OPEN FLOOR TIME: 17:00 VRU #: 001845031
	11/03/09	AP	T/S: 11/02/2009 11:30 AM VBROWN
R425 01	11/19/09	/BS	FOUR TRADE ROUGH IN VRU #: 001852557
	11/19/09	(DA)	requests pm inspection
			1. Nut and washer missing in garage. 2. Support top of both valleys to a load wall below (left side of roof) 3. Electrical Not firestopped. 4. Flash rear porch. 5. Need a Rescheck from insulation contractor at insulation inspection. Ceiling will have to be R-38, and all floored areas of ceiling will not hold R-38. 6. Plumbing pressure test is ok. No water on drain test. Ok to side. DO NOT INSULATE.
R425 02	11/25/09	₩ O	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001855345
	11-23	H	T/S: 11/24/2009 12:51 PM VBROWN

COMMENTS AND NOTES -----

PREPARED 12/02/09, 13:58:28
Harnett County

INSPECTION TICKET

PAGE

DATE 12/03/09

INSPECTOR: IVR 'Harnett County

PHONE :

ADDRESS . : 59 BEN CT CONTRACTOR : THOMAS CONSTRUCTION & REALTY

SUBDIV: BEN WOODS 10 LOTS PHONE: (910) 893-8950

OWNER . . : M G M BUILDERS PARCEL . . : 12-0547- - -0013- -11-

APPL NUMBER: 08-50020557 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : HWY 210 S APPROX 4 MILES TO BENWOODS S/D IS ON LEFT JUST PAST TEMPLE RD LOT

STRUCTURE: 000 000 60X60 3BDR CRAWL W/ GARAGE

FLOOD ZONE . . . : FLOOD ZONE X

BEDROOMS : 3.00 PROPOSED USE : SFD WATER SUPPLY : COUNTY SEPTIC - EXISTING? : NEW

TYP/SQ	CPSF 00 CP * REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	10/26/09	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001841733
	10/26/09	AP	
B103 01	10/30/09	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001843861
	10/30/09	AP	WOULD LIKE INSPECTION AFTER LUNCH TIME ANY TIME AFTER 1PM t-pole passed
A814 01	10/30/09	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001843853
	11/04/09	AP	59 ben ct lot 9
			bunnlevel 28323
			T/S: 11/04/2009 04:25 PM TWARD
B105 01	11/03/09	DT	R*OPEN FLOOR TIME: 17:00 VRU #: 001845031
	11/03/09	ΆP	T/S: 11/02/2009 11:30 AM VBROWN
R425 01	11/19/09	BS	FOUR TRADE ROUGH IN VRU #: 001852557
	11/19/09	DA	requests pm inspection 1. Nut and washer missing in garage. 2. Support top of both valleys to a load wall below (left side of roof) 3. Electrical Not firestopped. 4. Flash rear porch. 5. Need a Rescheck from insulation contractor at insulation inspection. Ceiling will have to be R-38, and all floored areas of ceiling will not hold R-38. 6. Plumbing pressure test is ok. No water on drain test. Ok to side. DO NOT INSULATE.
R425 02	11/25/09	KS	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001855345
	11/25/09	AP	T/S: 11/24/2009 12:51 PM VBROWNNo res check at rough-in T/S: 11/25/2009 10:08 AM KSLATTUM
I129 01	12/03/09 12/3/05	Ar DT	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001857291 T/S: 12/02/2009 01:45 PM RDCONTE



Generated by REScheck-Web Software

Compliance Certificate

Project Title: The Fiona

Energy Code:

2009 IECC

Location:

Harnett County, North Carolina

Construction Type:

Single Family

Glazing Area Percentage: Heating Degree Days:

7% 3499

Climate Zone:

4

Construction Site:

Owner/Agent:

Designer/Contractor:

Lot 9 Benwoods Alabama

Lillington, North Carolina 27546

ma Alabama

Complaints Passeousing UA trade of					
Compliance: Maximum UA: 283 Your UA: 283	Andrew College College	n year oo a mada a	The state of the state of	colonia de la compansa y a	the state of the special states
Assembly	Gross Area or Perimeter	R-Value	Cont R-Value		r UA
Ceiling: Flat or Scissor Truss	500	30.0	0.0		18
Celling: Flat or Scissor Truss	1149	0.0	38.0		29
Walls: Wood Frame, 16in. o.c.	1526	13.0	0.0		116
Windows: Vinyl Frame, 2 Pane w/ Low-E	88			0.350	31
Back Door: Glass	17			0.400	7
Front Door: Glass	9			0.400	4
Floor: All-Wood Joist/Truss Over Uncond. Space	1649	19.0	0.0		78

Compliance Statement: The proposed building design described here is consistent with the building plans, specifications, and other calculations submitted with the permit application. The proposed building has been designed to meet the 2009 IECC requirements in REScheck-Web and to compty with the mandatory requirements listed in the REScheck Inspection Checklist.

Name - Title Signature Date

Project Title: The Fiona Report date: 12/02/09

Data filename: Page 1



Generated by REScheck-Web Software

Inspection Checklist

Ceilings:	
☐ Ceiling: Flat or Scissor Truss, R-30.0 cavity insulation Comments:	_
☐ Ceiling: Flat or Scissor Truss, R-38.0 continuous insulation Comments:	-
Above-Grade Walls:	
☐ Walls: Wood Frame, 16in. o.c., R-13.0 cavity insulation Comments:	_
Windows:	
☐ Windows: Vinyl Frame, 2 Pane w/ Low-E, U-factor: 0.350 For windows without labeled U-factors, describe features: #Panes Frame Type Thermal Break? Yes No Comments:	-
Doors: ☐ Back Door: Glass, U-factor: 0.400	
Comments:	
Floors: ☐ Floor: All-Wood Joist/Truss Over Uncond. Space, R-19.0 cavity insulation	
Comments:	
Floor insulation is installed in permanent contact with the underside of the subfloor decking.	
Air Leakage: Use Joints (including rim joist junctions), attic access openings, penetrations, and all other such openings in envelope that are sources of air leakage are sealed with caulk, gasketed, weatherstripped or otherwise sealed barrier material, suitable film or solid material.	the building ed with an air
Air barrier and sealing exists on common walls between dwelling units, on exterior walls behind tubs/shopenings between window/door jambs and framing.	
\Box Recessed lights in the building thermal envelope are 1) type IC rated and ASTM E283 labeled and 2) segasket or caulk between the housing and the interior wall or ceiling covering.	
Access doors separating conditioned from unconditioned space are weather-stripped and insulated (with compression or damage) to at least the level of insulation on the surrounding surfaces. Where loose fill insulation or retainer is installed to maintain insulation application.	hout insulation ation exists, a
☐ Wood-burning fireplaces have gasketed doors and outdoor combustion air.	
Air Sealing and Insulation:	
Building envelope air tightness and insulation installation complies by either 1) a post rough-in blower deless than 7 ACH at 33.5 psf OR 2) the following items have been satisfied: Air barriers and thermal barrier: Installed on outside of air-permeable insulation and breaks or joints in	
are filled or repaired. Ceiling/attic: Air barrier in any dropped ceiling/soffit is substantially aligned with insulation and any ga Above-grade walls: Insulation is installed in substantial contact and continuous alignment with the bui barrier. Floors: Air barrier is installed at any exposed edge of insulation.	ps are sealed. Ilding envelope ai
Plumbing and wiring: Insulation is placed between outside and pipes. Batt insulation is cut to fit aroun plumbing, or sprayed/blown insulation extends behind piping and wiring. Corners, headers, narrow framing cavities, and rim joists are insulated.	d wiring and

Project Title: The Fiona Report date: 12/02/09 Data filename: Page 2

	provided. — Insulation R-values and glazing U-factors are clearly marked on the building plans or specifications.
	Duct Insulation: ☐ Supply ducts in attics are insulated to a minimum of R-8. All other ducts in unconditioned spaces or outside the building envelope are insulated to at least R-6.
	Duct Construction and Testing: ☐ Building framing cavities are not used as supply ducts.
	All joints and seams of air ducts, air handlers, filter boxes, and building cavities used as return ducts are substantially airtight by means of tapes, mastics, liquid sealants, gasketing or other approved closure systems. Tapes, mastics, and fasteners are rated UL 181A or UL 181B and are labeled according to the duct construction. Metal duct connections with equipment and/or fittings are mechanically fastened. Crimp joints for round metal ducts have a contact lap of at least 1 1/2 inches and are fastened with a minimum of three equally spaced sheet-metal screws. Exceptions:
	Joint and seams covered with spray polyurethane foam. Where a partially inaccessible duct connection exists, mechanical fasteners can be equally spaced on the exposed portion of the joint so as to prevent a hinge effect.
	Continuously welded and locking-type longitudinal joints and seams on ducts operating at less than 2 in. w.g. (500 Pa). Duct tightness test has been performed and meets one of the following test criteria: Postconstruction leakage to outdoors test: Less than or equal to 126.8 cfm (8 cfm per 100 ft2 of conditioned floor area) Postconstruction total leakage test (including air handler enclosure): Less than or equal to 190.2 cfm (12 cfm per 100 ft2 of conditioned floor area) pressure differential of 0.1 inches w.g.
	Rough-in total leakage test with air handler installed: Less than or equal to 95.1 cfm (6 cfm per 100 ft2 of conditioned floor area) when tested at a pressure differential of 0.1 inches w.g. Rough-in total leakage test without air handler installed: Less than or equal to 63.4 cfm (4 cfm per 100 ft2 of conditioned floor area).
	Heating and Cooling Equipment Sizing: Additional requirements for equipment sizing are included by an inspection for compliance with the International Residential Code.
	☐ For systems serving multiple dwelling units documentation has been submitted demonstrating compliance with 2009 ECC Commercial Building Mechanical and/or Service Water Heating (Sections 503 and 504).
	Circulating Service Hot Water Systems: ☐ Circulating service hot water pipes are insulated to R-2
	 Circulating service hot water pipes are insulated to R-2. Circulating service hot water systems include an automatic or accessible manual switch to turn off the circulating pump when the system is not in use.
	leating and Cooling Piping Insulation: □ HVAC piping conveying fluids above 105 degrees F or chilled fluids below 55 degrees F are insulated to R-3.
	Swimming Pools: ☐ Heated swimming pools have an on/off heater switch.
١	Pool heaters operating on natural gas or LPG have an electronic pilot light.
	 Timer switches on pool heaters and pumps are present. Exceptions: Where public health standards require continuous pump operation. Where pumps operate within solar- and/or waste-heat-recovery systems.
	Heated swimming pools have a cover on or at the water surface. For pools heated over 90 degrees F (32 degrees C) the over has a minimum insulation value of R-12. Exceptions:

Project Title: The Fiona Report date: 12/02/09 Data filename: Page 3

	Shower/tub on exterior wall: Insulation exists between showers/tubs and exterior wall.
Sur	nrooms:
	Sunrooms that are thermally isolated from the building envelope have a maximum fenestration U-factor of 0.50 and the ximum skylight U-factor of 0.75. New windows and doors separating the sunroom from conditioned space meet the building rmal envelope requirements.
Mat	terials Identification and Installation:
	Materials and equipment are installed in accordance with the manufacturer's installation instructions.
	Insulation is installed in substantial contact with the surface being insulated and in a manner that achieves the rated
R-va	alue.
	Materials and equipment are identified so that compliance can be determined.
	Manufacturer manuals for all installed heating and cooling equipment and service water heating equipment have been

Covers are not required when 60% of the heating energy is from site-recovered energy or solar energy so	ource.
, Lighting Requirements:	
 □ A minimum of 50 percent of the lamps in permanently installed lighting fixtures can be categorized as one of Compact fluorescent T-8 or smaller diameter linear fluorescent 40 lumens per watt for lamp wattage <= 15 50 lumens per watt for lamp wattage > 15 and <= 40 60 lumens per watt for lamp wattage > 40 	f the following:
Other Requirements:	
Snow- and ice-melting systems with energy supplied from the service to a building shall include automatic c capable of shutting off the system when a) the pavernent temperature is above 50 degrees F, b) no precipitation c) the outdoor temperature is above 40 degrees F (a manual shutoff control is also permitted to satisfy requirements.	is falling, and
Certificate:	
A permanent certificate is provided on or in the electrical distribution panel listing the predominant insulation window U-factors; type and efficiency of space-conditioning and water heating equipment. The certificate does not obstruct the visibility of the circuit directory label, service disconnect label or other required labels.	
NOTES TO FIELD: (Building Department Use Only)	

Project Title: The Fiona Report date: 12/02/09 Data filename: Page 4

	2009 IECC	Energy
V	Efficiency	Energy Certificate
nsulation Ra	fina se	R'Value

Ceiling / Roof	38.00	
Walf	13.00	
Floor / Foundation	19.00	
Ductwork (unconditioned space	:es):	
Glass & Door Rating	U:Factor	_ Shee
Window	0.35	0.33
Door	0.40	0.34
leating & Cooling Equipme	intia Efficiency	
Heating System:		
Cooling System:		
Water Heater:		
lame:		Date:
iomments:		

Project Title: The Fiona Report late: 12/02/09

)ata filename: Page 5

PREPARED 3/12/10, 13:58:59

Harnett County

INSPECTION TICKET

INSPECTOR: IVR

PAGE

DATE 3/15/10

ADDRESS . : 59 BEN CT SUBDIV: BEN WOODS 10 LOTS

CONTRACTOR : THOMAS CONSTRUCTION & REALTY

PHONE: (910) 893-8950

OWNER . . : M G M BUILDERS PHONE :

PARCEL . . : 12-0547- - -0013- -11-

APPL NUMBER: 08-50020557 CP NEW RESIDENTIAL (SFD) DIRECTIONS : HWY 210 S APPROX 4 MILES TO BENWOODS

S/D IS ON LEFT JUST PAST TEMPLE RD LOT

9 JB

STRUCTURE: 000 000 60X60 3BDR CRAWL W/ GARAGE

FLOOD ZONE . . . : FLOOD ZONE X

BEDROOMS : 3.00 PROPOSED USE : SFD SEPTIC - EXISTING? . . . : NEW WATER SUPPLY : COUNTY

PERMIT:	CPSF 00 CP *	SFD	
	REQUESTED	INSP	DESCRIPTION
	COMPLETED		RESULTS/COMMENTS
	10/26/09		R*BLDG FOOTING / TEMP SVC POLE VRU #: 001841733
	10/26/09	AP	
B103 01	10/30/09	JН	R*BLDG FOUND & TEMP SVC POLE VRU #: 001843861
	10/30/09	AP	WOULD LIKE INSPECTION AFTER LUNCH TIME ANY TIME AFTER 1PM t-pole passed
A814 01	10/30/09	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001843853
	11/04/09	ΆP	√59 ben ct lot 9
			bunnlevel 28323
			T/S: 11/04/2009 04:25 PM TWARD
B105 01	11/03/09	DT	R*OPEN FLOOR TIME: 17:00 VRU #: 001845031
	11/03/09	AP	T/S: 11/02/2009 11:30 AM VBROWN
R425 01	11/19/09	BS	FOUR TRADE ROUGH IN VRU #: 001852557
	11/19/09	DA	requests pm inspection
			1. Nut and washer missing in garage. 2. Support top of both
			valleys to a load wall below (left side of roof) 3.
			Electrical Not firestopped. 4. Flash rear porch. 5. Need a
			Rescheck from insulation contractor at insulation
			inspection. Ceiling will have to be R-38, and all floored
			areas of ceiling will not hold R-38. 6.Plumbing pressure
			test is ok. No water on drain test. Ok to side. DO NOT INSULATE.
R425 02	11/25/09	KS	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001855345
	11/25/09	AP	T/S: 11/24/2009 12:51 PM VBROWN
			No res check at rough-in
			T/S: 11/25/2009 10:08 AM KSLATTUM
I129 01	12/03/09	DT	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001857291
	12/03/09	AP	T/S: 12/02/2009 01:45 PM RDCONTE
H824 01	1/13/10	BM	VENVIR. OPERATIONS PERMIT TIME: 08:00 VRU #: 001871052
	1/13/10	AP	T/S: 01/14/2010 10:19 AM SSTEWART
			T/S: 01/14/2010 10:19 AM SSTEWART
R429 01	3/15/10 3/15/10	DA DC	FOUR TRADE FINAL VRU #: 001894748
	· · · - · · - · · · · · · · · · · ·	· · · · · · · ·	

PREPARED: 3/24/10, 13:58:12

INSPECTION TICKET

PAGE

5

Harnett County INSPECTOR: IVR DATE 3/25/10

ADDRESS . : 59 BEN CT SUBDIV: BEN WOODS 10 LOTS CONTRACTOR : THOMAS CONSTRUCTION & REALTY PHONE: (910) 893-8950

OWNER . . : M G M BUILDERS PHONE :

PARCEL . . : 12-0547- - -0013- -11-

APPL NUMBER: 08-50020557 CP NEW RESIDENTIAL (SFD) DIRECTIONS : HWY 210 S APPROX 4 MILES TO BENWOODS S/D IS ON LEFT JUST PAST TEMPLE RD LOT

9 JB 025 42460

FLOOD ZONE . . . : FLOOD ZONE X

BEDROOMS : 3.00 PROPOSED USE : SFD SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD REQUESTED INSP DESCRIPTION COMPLETED RESULT RESULTS/COMMENTS TYP/SQ B101 01 10/26/09 DT R*BLDG FOOTING / TEMP SVC POLE VRU #: 001841733 AP 10/26/09 B103 01 10/30/09 JH R*BLDG FOUND & TEMP SVC POLE VRU #: 001843861 WOULD LIKE INSPECTION AFTER LUNCH TIME ANY TIME AFTER 1PM 10/30/09 AP t-pole passed ADDRESS CONFIRMATION VRU #: 001843853 A814 01 10/30/09 TW TIME: 17:00 11/04/09 AΡ √59 ben ct lot 9 bunnlevel 28323 T/S: 11/04/2009 04:25 PM TWARD ------B105 01 11/03/09 DTR*OPEN FLOOR TIME: 17:00 VRU #: 001845031 11/03/09 AP T/S: 11/02/2009 11:30 AM VBROWN -----R425 01 11/19/09 BS FOUR TRADE ROUGH IN VRU #: 001852557 11/19/09 DA requests pm inspection 1. Nut and washer missing in garage. 2. Support top of both valleys to a load wall below (left side of roof) 3. Electrical Not firestopped. 4. Flash rear porch. 5. Need a Rescheck from insulation contractor at insulation inspection. Ceiling will have to be R-38, and all floored areas of ceiling will not hold R-38. 6. Plumbing pressure test is ok. No water on drain test. Ok to side. DO NOT INSULATE. R425 02 11/25/09 FOUR TRADE ROUGH IN TIME: 17:00 KS VRU #: 001855345 T/S: 11/24/2009 12:51 PM VBROWN -----11/25/09 AΡ No res check at rough-in T/S: 11/25/2009 10:08 AM KSLATTUM -------I129 01 12/03/09 DTR*INSULATION INSPECTION TIME: 17:00 VRU #: 001857291 12/03/09 AΡ T/S: 12/02/2009 01:45 PM RDCONTE ------ENVIR. OPERATIONS PERMIT TIME: 08:00 H824 01 1/13/10 ВМ VRU #: 001871052 T/S: 01/14/2010 10:19 AM SSTEWART ------1/13/10 AP T/S: 01/14/2010 10:19 AM SSTEWART -----------R429 01 FOUR TRADE FINAL VRU #: 001894748 3/15/10 DТ 3/15/10 1. Foundation vents must be four inches above grade. 2. Water meter not set. 3. Caulk toilets to floor. 4. Bathroom exhaust vents do not terminate to outside.

5. Dryer vent must be 12 inches above grade.

------ CONTINUED ONTO NEXT PAGE

6. Need handrail for rear steps. More than three risers. 7. Need insulation depth guage in attic for each 300 sq ft. PREPARED: 3/24/10, 13:58:12

INSPECTION TICKET INSPECTOR: IVR

PAGE

DATE 3/25/10

6

ADDRESS . : 59 BEN CT

SUBDIV: BEN WOODS 10 LOTS

CONTRACTOR : THOMAS CONSTRUCTION & REALTY

PHONE : (910) 893-8950

OWNER . . : M G M BUILDERS

PARCEL . . : 12-0547- - -0013- -11-

APPL NUMBER: 08-50020557 CP NEW RESIDENTIAL (SFD)

DESCRIPTION REQUESTED INSP TYP/SQ COMPLETED RESULT RESULTS/COMMENTS

T/S: 03/15/2010 10:03 AM DETAYLOR -----

PHONE :

R429 02 3/25/10 TI FOUR TRADE FINAL VRU #: 001899780

3/25/10 AS DE

County of Harnett **Building Inspections Department** Planning Services

Certificate of Compliance: Occupancy: ___

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the

various ordinances of the County of H		•	_
Use Classification: Residential		Permit Numbers	
Name: Thomas Construction	ion a Realty	Building:	
	, , , , , , , , , , , , , , , , , , ,	Electrical:	1 ⁰⁵
Address: 59 Ben Ct		Insulation:	200
Bundevel NC 28323		Plumbing:	>
		Plumbing: / Mechanical: 0	
		MFG Home:	
Date: 3 12 = 110	Building Official	1. 7	ه