

ADDRESS : 66 EMMA CT  
CONTRACTOR : RBC HOMES INC  
OWNER : ABJ INVESTMENTS LLC  
PARCEL : 12-0555- - -0216- -35-  
APPL NUMBER: 09-50022914 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : T/S: 09/24/2009 01:28 PM JBROCK ----  
KENLAN FARMS #35  
US HWY 401 S TO RIGHT ON MCNEILL HOBBS  
RD TO LEFT ON WIRE RD PASS JOSEY  
WILLIAMS ON THE LEFT AND TURN RIGHT ON  
KENLAN RD

SUBDIV: KENLAN FARMS PH1 SET1 41LOTS  
PHONE : (910) 423-3555  
PHONE :

STRUCTURE: 000 000 30X50 3BDR CRAWL W/ GARAGE

FLOOD ZONE : FLOOD ZONE X

# BEDROOMS : 3.00

PROPOSED USE : SFD

SEPTIC - EXISTING? : NEW

WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
--------	------------------------	----------------	---------------------------------

B101 01	11/06/09 <u>11/6/09</u>	TI <u>AP-MR</u>	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001847194
---------	----------------------------	--------------------	---

COMMENTS AND NOTES

"No" on T-Pole  
needs Repair

ADDRESS . . : 66 EMMA CT  
CONTRACTOR : RBC HOMES INC  
OWNER . . . : ABJ INVESTMENTS LLC  
PARCEL . . . : 12-0555- - -0216- -35-  
APPL NUMBER: 09-50022914 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : T/S: 09/24/2009 01:28 PM JBROCK ----  
KENLAN FARMS #35  
US HWY 401 S TO RIGHT ON MCNEILL HOBBS  
RD TO LEFT ON WIRE RD PASS JOSEY  
WILLIAMS ON THE LEFT AND TURN RIGHT ON  
KENLAN RD

SUBDIV: KENLAN FARMS PH1 SET1 41LOTS  
PHONE : (910) 423-3555  
PHONE :

STRUCTURE: 000 000 30X50 3BDR CRAWL W/ GARAGE

FLOOD ZONE . . . . : FLOOD ZONE X  
# BEDROOMS . . . . : 3.00  
SEPTIC - EXISTING? . . . . : NEW  
PROPOSED USE . . . . . : SFD  
WATER SUPPLY . . . . . : COUNTY

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/06/09	MR	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001847194
	11/06/09	AP	T/S: 11/06/2009 12:44 PM MREARIC ----- t pole needs repair
B103 01	11/12/09	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001848704
	<u>11-12-9</u>	<u>DA-MP</u>	

COMMENTS AND NOTES

N.R.

ADDRESS : 66 EMMA CT  
 CONTRACTOR : RBC HOMES INC  
 OWNER : ABJ INVESTMENTS LLC  
 PARCEL : 12-0555- - -0216- -35-  
 APPL NUMBER: 09-50022914 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : T/S: 09/24/2009 01:28 PM JBROCK ----  
 KENLAN FARMS #35  
 US HWY 401 S TO RIGHT ON MCNEILL HOBBS  
 RD TO LEFT ON WIRE RD PASS JOSEY  
 WILLIAMS ON THE LEFT AND TURN RIGHT ON  
 KENLAN RD  
 T/S: 11/17/2009 01:33 PM DJOHNSON --  
 \*\*\*\*\*PREMISE # 28253863\*\*\*\*\*

SUBDIV: KENLAN FARMS PH1 SET1 41LOTS  
 PHONE : (910) 423-3555  
 PHONE :

STRUCTURE: 000 000 30X50 3BDR CRAWL W/ GARAGE

FLOOD ZONE : FLOOD ZONE X

# BEDROOMS : 3.00

SEPTIC - EXISTING? : NEW

PROPOSED USE : SFD

WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/06/09 11/06/09	MR AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001847194 T/S: 11/06/2009 12:44 PM MREARIC ----- t pole needs repair
B103 01	11/12/09 11/12/09	MR DA	R*BLDG FOUND & TEMP SVC POLE VRU #: 001848704 T/S: 11/12/2009 11:13 AM MREARIC ----- not ready
A814 01	11/18/09 11/18/09	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001851922 66 emma ct lot 35 ----- linden 28356 -----
B103 02	11/18/09 11/18/09	JH CA	T/S: 11/18/2009 02:11 PM TWARD ----- R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001852029 T/S: 11/17/2009 02:37 PM NTART ----- per Barry -----
B103 03	12/01/09 <i>12-1-09</i>	TI <i>AP JH</i>	R*BLDG FOUND & TEMP SVC POLE VRU #: 001855964

COMMENTS AND NOTES

ADDRESS : 66 EMMA CT  
CONTRACTOR : RBC HOMES INC  
OWNER : ABJ INVESTMENTS LLC  
PARCEL : 12-0555- - -0216- -35-  
APPL NUMBER: 09-50022914 CP NEW RESIDENTIAL (SFD)

SUBDIV: KENLAN FARMS PH1 SET1 41LOTS  
PHONE : (910) 423-3555  
PHONE :

DIRECTIONS : T/S: 09/24/2009 01:28 PM JBROCK ----  
KENLAN FARMS #35  
US HWY 401 S TO RIGHT ON MCNEILL HOBBS  
RD TO LEFT ON WIRE RD PASS JOSEY  
WILLIAMS ON THE LEFT AND TURN RIGHT ON  
KENLAN RD  
T/S: 11/17/2009 01:33 PM DJOHNSON --  
\*\*\*\*\*PREMISE # 28253863\*\*\*\*\*

STRUCTURE: 000 000 30X50 3BDR CRAWL W/ GARAGE

FLOOD ZONE : FLOOD ZONE X  
# BEDROOMS : 3.00 PROPOSED USE : SFD  
SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/06/09 11/06/09	MR AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001847194 T/S: 11/06/2009 12:44 PM MREARIC ----- t pole needs repair
B103 01	11/12/09 11/12/09	MR DA	R*BLDG FOUND & TEMP SVC POLE VRU #: 001848704 T/S: 11/12/2009 11:13 AM MREARIC ----- not ready
A814 01	11/18/09 11/18/09	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001851922 66 emma ct lot 35 ----- linden 28356 ----- -----
B103 02	11/18/09 11/18/09	JH CA	T/S: 11/18/2009 02:11 PM TWARD ----- R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001852029 T/S: 11/17/2009 02:37 PM NTART ----- per Barry -----
B103 03	12/01/09 12/01/09	JH AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001855964 -----
B105 02	12/04/09 <i>12.4.09</i>	TI <i>ABS</i>	R*OPEN FLOOR VRU #: 001857572 -----
B105 01	12/04/09 12/03/09	TI CA	R*OPEN FLOOR VRU #: 001857564 T/S: 12/03/2009 02:31 PM NTART -----

COMMENTS AND NOTES

ADDRESS : 66 EMMA CT  
CONTRACTOR : RBC HOMES INC  
OWNER : ABJ INVESTMENTS LLC  
PARCEL : 12-0555- - -0216- -35-  
APPL NUMBER: 09-50022914 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : T/S: 09/24/2009 01:28 PM JBROCK ----  
KENLAN FARMS #35  
US HWY 401 S TO RIGHT ON MCNEILL HOBBS  
RD TO LEFT ON WIRE RD PASS JOSEY  
WILLIAMS ON THE LEFT AND TURN RIGHT ON  
KENLAN RD  
T/S: 11/17/2009 01:33 PM DJOHNSON --  
\*\*\*\*\*PREMISE # 28253863\*\*\*\*\*

SUBDIV: KENLAN FARMS PH1 SET1 41LOTS  
PHONE : (910) 423-3555  
PHONE :

STRUCTURE: 000 000 30X50 3BDR CRAWL W/ GARAGE

FLOOD ZONE : FLOOD ZONE X  
# BEDROOMS : 3.00  
SEPTIC - EXISTING? : NEW  
PROPOSED USE : SFD  
WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/06/09 11/06/09	MR AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001847194 T/S: 11/06/2009 12:44 PM MREARIC ----- t pole needs repair
B103 01	11/12/09 11/12/09	MR DA	R*BLDG FOUND & TEMP SVC POLE VRU #: 001848704 T/S: 11/12/2009 11:13 AM MREARIC ----- not ready
A814 01	11/18/09 11/18/09	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001851922 66 emma ct lot 35 ----- linden 28356 -----
B103 02	11/18/09 11/18/09	JH CA	T/S: 11/18/2009 02:11 PM TWARD ----- R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001852029 T/S: 11/17/2009 02:37 PM NTART ----- per Barry -----
B103 03	12/01/09 12/01/09	JH AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001855964 -----
B105 02	12/04/09 12/04/09	BS AP	R*OPEN FLOOR VRU #: 001857572 T/S: December 04, 2009 11:27 AM BSUTTON -----
B105 01	12/04/09 12/03/09	TI CA	R*OPEN FLOOR VRU #: 001857564 T/S: 12/03/2009 02:31 PM NTART -----
R425 01	1/06/10 <i>1-6-10</i>	TI <i>Op JV</i>	FOUR TRADE ROUGH IN VRU #: 001867761

COMMENTS AND NOTES

# Violation Notice

## Do Not Remove

Harnett County Inspection Department  
Jimmy Hall (910)984-4768  
Permit #09-50022914  
Date: 1/06/10

- 1) Replace damaged stud to right of garage door.
- 2) Fire caulk refrigerant lines @ top plate in back wall of garage.
- 3) Missing roof boots for plumbing.
- 4) Support all pex water lines every 32" per code.
- 5) Need 100psi on water lines test froze.
- 6) Fire caulk @top plate on vent pipe over washer box.
- 7) Top plate joint @ refrigerator needs stud under it.
- 8) Fire caulk ¾" pipe @ top plate to right of fire box.
- 9) Nail osb to right of window that is right of fire place.
- 10) Half Bath missing duct for exhaust fan.
- 11) Need 2 studs under each end of header for stairs.
- 12) Roof truss for front porch does not match truss drawings & need truss repair letter for notched truss on front porch.

Stop inspection on first floor to many violations Pay \$50 RE FEE

ADDRESS : 66 EMMA CT  
CONTRACTOR : RBC HOMES INC  
OWNER : ABJ INVESTMENTS LLC  
PARCEL : 12-0555- - -0216- -35-  
APPL NUMBER: 09-50022914 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : T/S: 09/24/2009 01:28 PM JBRÖCK ----  
KENLAN FARMS #35  
US HWY 401 S TO RIGHT ON MCNEILL HOBBS  
RD TO LEFT ON WIRE RD PASS JOSEY  
WILLIAMS ON THE LEFT AND TURN RIGHT ON  
KENLAN RD  
T/S: 11/17/2009 01:33 PM DJOHNSON --  
\*\*\*\*\*PREMISE # 28253863\*\*\*\*\*

SUBDIV: KENLAN FARMS PH1 SET1 41LOTS  
PHONE : (910) 423-3555  
PHONE :

STRUCTURE: 000 000 30X50 3BDR CRAWL W/ GARAGE

FLOOD ZONE : FLOOD ZONE X

# BEDROOMS : 3.00

PROPOSED USE : SFD

SEPTIC - EXISTING? : NEW

WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/06/09	MR	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001847194
	11/06/09	AP	T/S: 11/06/2009 12:44 PM MREARIC ----- t pole needs repair
B103 01	11/12/09	MR	R*BLDG FOUND & TEMP SVC POLE VRU #: 001848704
	11/12/09	DA	T/S: 11/12/2009 11:13 AM MREARIC ----- not ready
A814 01	11/18/09	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001851922
	11/18/09	AP	66 emma ct lot 35 ----- linden 28356 ----- -----
B103 02	11/18/09	JH	T/S: 11/18/2009 02:11 PM TWARD ----- R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001852029
	11/18/09	CA	T/S: 11/17/2009 02:37 PM NTART ----- per Barry -----
B103 03	12/01/09	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001855964
	12/01/09	AP	-----
B105 02	12/04/09	BS	R*OPEN FLOOR VRU #: 001857572
	12/04/09	AP	T/S: December 04, 2009 11:27 AM BSUTTON -----
B105 01	12/04/09	TI	R*OPEN FLOOR VRU #: 001857564
	12/03/09	CA	T/S: 12/03/2009 02:31 PM NTART -----
R425 01	1/06/10	JH	FOUR TRADE ROUGH IN VRU #: 001867761
	1/06/10	DP	1)Replace damaged stud to right of garage door.2)Fire caulk refrigerant lines @ top plate in back wall of garage.3)Missing roof boots for plumbing. 4)Support all pex water lines every 32" per code. 5)Need 100psi on water lines test frooze. 6)Fire caulk @top plate on vent pipe over washer box. 7)top plate joint @ refrigerator needs stud under it. 8)Fire caulk 3/4" pipe @ top plate right of fire box. 9)Nail osb to right of window right of fire box.10)Half bath missing duct for exhaust fan. 11)Need 2 studs under each end of header for stairs. 12)Roof truss for front porch does not match plans & are notched for leger need letter. STOP INSPECTION @ FIRST FLOOR TO MANY VIOLATIONS PAY \$50 RE

PREPARED 1/08/10, 13:58:37  
Harnett County

INSPECTION TICKET  
INSPECTOR: IVR

PAGE 8  
DATE 1/11/10

-----  
ADDRESS : 66 EMMA CT  
CONTRACTOR : RBC HOMES INC  
OWNER : ABJ INVESTMENTS LLC  
PARCEL : 12-0555- - -0216- -35-  
APPL NUMBER: 09-50022914 CP NEW RESIDENTIAL (SFD)  
-----

SUBDIV: KENLAN FARMS PH1 SET1 41LOTS  
PHONE : (910) 423-3555  
PHONE :

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
			FEE
R425 02	1/08/10	JH	FOUR TRADE ROUGH IN VRU #: 001868504
	1/08/10	CA	T/S: 01/08/2010 10:55 AM JBROCK -----
R425 03	1/11/10	TI	FOUR TRADE ROUGH IN VRU #: 001869015
	<u>1/11/10</u>	<u>AP DT</u>	

----- COMMENTS AND NOTES -----



**Trenco**

818 Soundside Rd  
Edenton, NC 27932

Re: J94455


RBC / Lot 35 Kenlan Farms / Harnett Co.

The truss drawing(s) referenced below have been prepared by Truss Engineering Co. under my direct supervision based on the parameters provided by Comtech, Inc - Fayetteville.

Pages or sheets covered by this seal: E5569117 thru E5569117

My license renewal date for the state of North Carolina is December 31, 2010.

North Carolina COA: C-0844



January 8, 2010


Lassiter, Frank

The seal on these drawings indicate acceptance of professional engineering responsibility solely for the truss components shown. The suitability and use of this component for any particular building is the responsibility of the building designer, per ANSI/TPI-2002 Chapter 2.  
Engineering services provided by Truss Engineering Company.

Job J94455	Truss J1	Truss Type MONO TRUSS	Qty 7	Ply 1	RBC / Lot 35 Kenton Farms / Harnett Co. Job Reference (optional)	E5509117
---------------	-------------	--------------------------	----------	----------	---	----------

Comtech, Inc., Fayetteville, NC 28309

7.220 s Dec 29 2009 MiTek Industries, Inc. Fri Jan 08 11:03:47 2010 Page 1



Scale = 1:12.3

TRUSS MUST BE CONNECTED TO THE BEARINGS FOR ALL VERTICAL AND HORIZONTAL REACTIONS (BY OTHERS)

CUT AND REMOVE SECTION INDICATED BY DASHED LINES. LUMBER TO BE CUT CLEANLY AND ACCURATELY, NO PLATES ARE TO BE DISTURBED.

Plate Offsets (X,Y): [3:0-2-4,0-1-8]

LOADING (psf)	SPACING	2-0-0	CSI	DEFL	in	(loc)	Vdefl	L/d	PLATES	GRIP
TCLL 20.0	Plates Increase	1.15	TC 0.11	Vert(LL)	0.00	2	****	360	MT20	244/190
TCDL 10.0	Lumber Increase	1.15	BC 0.05	Vert(TL)	-0.01	2-5	>999	240		
BCLL 0.0 *	Rep Stress Incr	YES	WB 0.01	Horz(TL)	-0.00	3	n/a	n/a		
BCDL 10.0	Code	IRC2003/TPI2002	(Matrix)							Weight: 16 lb

**LUMBER**

TOP CHORD 2 X 4 SYP No.1  
BOT CHORD 2 X 4 SYP No.1  
WEBS 2 X 4 SYP No.3

**BRACING**

TOP CHORD Structural wood sheathing directly applied or 4-0-0 oc purlins.  
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.

**REACTIONS** (lb/size) 2=240/0-3-8 (min. 0-1-8), 3=134/Mechanical  
Max Horz 2=81(LC 3)  
Max Uplift 2=117(LC 3), 3=38(LC 3)


**FORCES** (lb) - Maximum Compression/Maximum Tension

TOP CHORD 1-2=0/16, 2-3=44/25  
BOT CHORD 2-5=0/0, 4-5=0/0  
WEBS 3-5=0/41

**NOTES**

- 1) Wind: ASCE 7-02; 100mph; TC DL=6.0psf; BC DL=5.0psf; h=15ft; Cat. II; Exp C; enclosed; MWFRS (low-rise) gable end zone and C-C Interior(1) zone; cantilever left and right exposed; end vertical left and right exposed; C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
- 2) \* This truss has been designed for a live load of 20.0psf on the bottom chord in all areas with a clearance greater than 6-0-0 between the bottom chord and any other members.
- 3) Refer to girder(s) for truss to truss connections.
- 4) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 117 lb uplift at joint 2 and 38 lb uplift at joint 3.
- 5) This truss is designed in accordance with the 2003 International Residential Code sections R502.11.1 and R802.10.2 and referenced standard ANSI/TPI 1.
- 6) Gap between inside of top chord bearing and first diagonal or vertical web shall not exceed 0.500in.

LOAD CASE(S) Standard



January 8, 2010

**WARNING** - Verify design parameters and READ NOTES ON THIS AND INCLUDED MITEK REFERENCE PAGE MI-7473 rev. 10-08 BEFORE USE. Design valid for use only with MiTek connectors. This design is based only upon parameters shown, and is for an individual building component. Applicability of design parameters and proper incorporation of component is responsibility of building designer - not truss designer. Bracing shown is for lateral support of individual web members only. Additional temporary bracing to insure stability during construction is the responsibility of the erector. Additional permanent bracing of the overall structure is the responsibility of the building designer. For general guidance regarding fabrication, quality control, storage, delivery, erection and bracing, consult ANSI/TPI1 Quality Criteria, D58-09 and ICSI Building Component Safety Information available from Truss Plate Institute, 281 N. Lee Street, Suite 312, Alexandria, VA 22314.

ENGINEERING BY  
**TRENCO**  
A MITEK AFFILIATE  
818 Soundside Road  
Edenton, NC 27932

Trenco, Edenton, North Carolina



- TOE-NAILS SHALL BE STARTED AND DRIVEN AT THE ANGLE SHOWN, BASED ON THE CONNECTION LAYOUT USED.
- THE END DISTANCE, EDGE DISTANCE, AND SPACING OF NAILS SHALL BE SUCH AS TO AVOID SPLITTING OF THE WOOD.
- ALLOWABLE VALUE SHALL BE BASED ON THE SPECIE WITH LOWER NAIL CAPACITY BETWEEN THE TWO MEMBERS IN THE CONNECTION.

TOE-NAIL SINGLE SHEAR VALUES PER NDS 2005 (lb/nail)



		DIAM.	SYP	DF	HF	SPF	SPF-S
NAIL LENGTH, L	3.5" LONG	.131	88	80	69	68	59
		.135	93	85	74	72	63
		.162	118	108	93	91	80
	3.25" LONG	.128	84	76	66	65	57
		.131	88	80	69	68	59
		.148	106	97	84	82	72
	3.0" LONG	.120	73	67	58	57	50
		.128	84	76	66	65	57
		.131	88	80	69	68	59
.148		106	97	84	82	72	

VALUES SHOWN ARE CAPACITY PER TOE-NAIL.  
 APPLICABLE DURATION OF LOAD INCREASES MAY BE APPLIED.

EXAMPLE:  
 (3) - 16d NAILS (.162" diam. x 3.5") WITH SPF CHORD SPECIES


For load duration increase of 1.15:  
 3 (nails) X 91 (lb/nail) X 1.15 (DOL) = 314 lb Maximum Capacity

SQUARE CUT



45 DEGREE ANGLE BEVEL CUT

VIEWS SHOWN ARE FOR ILLUSTRATION PURPOSES ONLY




**WARNING** - Verify design parameters and READ NOTES ON THIS AND INCLUDED MITEK REFERENCE PAGE MII-7473 rev. 10-08 BEFORE USE.  
 Design valid for use only with MiTek connectors. This design is based only upon parameters shown, and is for an individual building component.  
 Applicability of design parameters and proper incorporation of component is responsibility of building designer - not truss designer. Bracing shown is for lateral support of individual web members only. Additional temporary bracing to insure stability during construction is the responsibility of the erector. Additional permanent bracing of the overall structure is the responsibility of the building designer. For general guidance regarding fabrication, quality control, storage, delivery, erection and bracing, consult ANSIT/PTI Quality Criteria, 058-69 and ICSI Building Component Safety Information available from Truss Plate Institute, 281 N. Lee Street, Suite 312, Alexandria, VA 22314.




818 Soundside Road  
 Edenton, NC 27832

# Symbols

## PLATE LOCATION AND ORIENTATION



Center plate on joint unless x, y offsets are indicated. Dimensions are in 1/16-in. increments. Apply plates to both sides of truss and fully embed teeth.



\*For 4 x 2 orientation, locate plates 0-1/8" from outside edge of truss.



\*This symbol indicates the required direction of slots in connector plates.

\*Plate location details available in Mitek 20/20 software or upon request.

## PLATE SIZE

4 X 4


The first dimension is the plate width measured perpendicular to slots. Second dimension is the length parallel to slots.

## LATERAL BRACING LOCATION



Indicated by symbol shown and/or by text in the bracing section of the output. Use T, I or Eliminator bracing if indicated.

## BEARING




Indicates location where bearings (supports) occur. Icons vary but reaction section indicates joint number where bearings occur.


## Industry Standards:

ANSI/FP11: National Design Specification for Metal Plate Connected Wood Truss Construction.  
DSB-89: Design Standard for Bracing.  
BCSI: Building Component Safety Information, Guide to Good Practice for Handling, Installing & Bracing of Metal Plate Connected Wood Trusses.

# Numbering System



dimensions shown in feet-inches-sixteenths (Drawings not to scale)



JOINTS ARE GENERALLY NUMBERED/LETTERED CLOCKWISE AROUND THE TRUSS STARTING AT THE JOINT FARTHEST TO THE LEFT.

CHORDS AND WEBS ARE IDENTIFIED BY END JOINT NUMBERS/LETTERS.

## PRODUCT CODE APPROVALS

ICC-ES Reports:

ESR-1311, ESR-1352, ER-5243, 96048  
9730, 95-43, 96-31, 9667A  
NER-487, NER-561  
95110, 84-32, 96-67, ER-3907, 9432A

© 2004 Mitek® All Rights Reserved



Mitek Engineering Reference Sheet: MIL-7473 rev. 10-08

# General Safety Notes

## Failure to Follow Could Cause Property Damage or Personal Injury

1. Additional stability bracing for truss system, e.g. diagonal or X-bracing, is always required. See BCSI.
2. Truss bracing must be designed by an engineer. For wide truss spacing, individual lateral braces themselves may require bracing, or alternative T, I, or Eliminator bracing should be considered.
3. Never exceed the design loading shown and never stack materials on inadequately braced trusses.
4. Provide copies of this truss design to the building designer, erection supervisor, property owner and all other interested parties.
5. Cut members to bear tightly against each other.
6. Place plates on each face of truss at each joint and embed fully. Knots and wane at joint locations are regulated by ANSI/FP 1.
7. Design assumes trusses will be suitably protected from the environment in accord with ANSI/FP 1.
8. Unless otherwise noted, moisture content of lumber shall not exceed 19% at time of fabrication.
9. Unless expressly noted, this design is not applicable for use with fire retardant, preservative treated, or green lumber.
10. Camber is a non-structural consideration and is the responsibility of truss fabricator. General practice is to camber for dead load deflection.
11. Plate type, size, orientation and location dimensions indicated are minimum plating requirements.
12. Lumber used shall be of the species and size, and in all respects, equal to or better than that specified.
13. Top chords must be sheathed or punfs provided at spacing indicated on design.
14. Bottom chords require lateral bracing at 10 ft. spacing, or less, if no ceiling is installed, unless otherwise noted.
15. Connections not shown are the responsibility of others.
16. Do not cut or alter truss member or plate without prior approval of an engineer.
17. Install and load vertically unless indicated otherwise.
18. Use of green or treated lumber may pose unacceptable environmental, health or performance risks. Consult with project engineer before use.
19. Review all portions of this design (front, back, words and pictures) before use. Reviewing pictures alone is not sufficient.
20. Design assumes manufacture in accordance with ANSI/FP 1 Quality Criteria.

ADDRESS : 66 EMMA CT  
CONTRACTOR : RBC HOMES INC  
OWNER : ABJ INVESTMENTS LLC  
PARCEL : 12-0555- - -0216- -35-  
APPL NUMBER: 09-50022914 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : T/S: 09/24/2009 01:28 PM JBROCK ----  
KENLAN FARMS #35  
US HWY 401 S TO RIGHT ON MCNEILL HOBBS  
RD TO LEFT ON WIRE RD PASS JOSEY  
WILLIAMS ON THE LEFT AND TURN RIGHT ON  
KENLAN RD  
T/S: 11/17/2009 01:33 PM DJOHNSON --  
\*\*\*\*\*PREMISE # 28253863\*\*\*\*\*

SUBDIV: KENLAN FARMS PH1 SET1 41LOTS  
PHONE : (910) 423-3555  
PHONE :

STRUCTURE: 000 000 30X50 3BDR CRAWL W/ GARAGE

FLOOD ZONE . . . . : FLOOD ZONE X  
# BEDROOMS . . . . . : 3.00  
SEPTIC - EXISTING? . . . . : NEW  
PROPOSED USE . . . . . : SFD  
WATER SUPPLY . . . . . : COUNTY

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/06/09 11/06/09	MR AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001847194 T/S: 11/06/2009 12:44 PM MREARIC ----- t pole needs repair
B103 01	11/12/09 11/12/09	MR DA	R*BLDG FOUND & TEMP SVC POLE VRU #: 001848704 T/S: 11/12/2009 11:13 AM MREARIC ----- not ready
A814 01	11/18/09 11/18/09	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001851922 66 emma ct lot 35 ----- linden 28356 ----- -----
B103 02	11/18/09 11/18/09	JH CA	T/S: 11/18/2009 02:11 PM TWARD ----- R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001852029 T/S: 11/17/2009 02:37 PM NTART ----- per Barry -----
B103 03	12/01/09 12/01/09	JH AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001855964 -----
B105 02	12/04/09 12/04/09	BS AP	R*OPEN FLOOR VRU #: 001857572 T/S: December 04, 2009 11:27 AM BSUTTON -----
B105 01	12/04/09 12/03/09	TI CA	R*OPEN FLOOR VRU #: 001857564 T/S: 12/03/2009 02:31 PM NTART -----
R425 01	1/06/10 1/06/10	JH DP	FOUR TRADE ROUGH IN VRU #: 001867761 1)Replace damaged stud to right of garage door.2)Fire caulk refrigerant lines @ top plate in back wall of garage.3)Missing roof boots for plumbing. 4)Support all pex water lines every 32" per code. 5)Need 100psi on water lines test frooze. 6)Fire caulk @top plate on vent pipe over washer box. 7)top plate joint @ refrigerator needs stud under it. 8)Fire caulk 3/4" pipe @ top plate right of fire box. 9)Nail osb to right of window right of fire box.10)Half bath missing duct for exhaust fan. 11)Need 2 studs under each end of header for stairs. 12)Roof truss for front porch does not match plans & are notched for leger need letter. STOP INSPECTION @ FIRST FLOOR TO MANY VIOLATIONS PAY \$50 RE

PREPARED 1/12/10, 14:00:07  
Harnett County

INSPECTION TICKET  
INSPECTOR: IVR

PAGE 16  
DATE 1/13/10

ADDRESS : 66 EMMA CT  
CONTRACTOR : RBC HOMES INC  
OWNER : ABJ INVESTMENTS LLC  
PARCEL : 12-0555- - -0216- -35-  
APPL NUMBER: 09-50022914 CP NEW RESIDENTIAL (SFD)

SUBDIV: KENLAN FARMS PH1 SET1 41LOTS  
PHONE : (910) 423-3555  
PHONE :

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
			FEE
R425 02	1/08/10	JH	FOUR TRADE ROUGH IN VRU #: 001868504
	1/08/10	CA	T/S: 01/08/2010 10:55 AM JBROCK
R425 03	1/11/10	DT	FOUR TRADE ROUGH IN VRU #: 001869015
	1/11/10	AP	
I129 01	1/13/10	TI	R*INSULATION INSPECTION VRU #: 001869676
	<u>1/13/10</u>	<u>APDT</u>	

----- COMMENTS AND NOTES -----

ADDRESS : 66 EMMA CT  
 CONTRACTOR : RBC HOMES INC  
 OWNER : ABJ INVESTMENTS LLC  
 PARCEL : 12-0555- - -0216- -35-  
 APPL NUMBER: 09-50022914 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : T/S: 09/24/2009 01:28 PM JBROCK ----  
 KENLAN FARMS #35  
 US HWY 401 S TO RIGHT ON MCNEILL HOBBS  
 RD TO LEFT ON WIRE RD PASS JOSEY  
 WILLIAMS ON THE LEFT AND TURN RIGHT ON  
 KENLAN RD  
 T/S: 11/17/2009 01:33 PM DJOHNSON --  
 \*\*\*\*\*PREMISE # 28253863\*\*\*\*\*

SUBDIV: KENLAN FARMS PH1 SET1 41LOTS  
 PHONE : (910) 423-3555  
 PHONE :

**STRUCTURE: 000 000 30X50 3BDR CRAWL W/ GARAGE**

FLOOD ZONE : FLOOD ZONE X  
 # BEDROOMS : 3.00 PROPOSED USE : SFD  
 SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

**PERMIT: CPSF 00 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/06/09 11/06/09	MR AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001847194 T/S: 11/06/2009 12:44 PM MREARIC ----- t pole needs repair
B103 01	11/12/09 11/12/09	MR DA	R*BLDG FOUND & TEMP SVC POLE VRU #: 001848704 T/S: 11/12/2009 11:13 AM MREARIC ----- not ready
A814 01	11/18/09 11/18/09	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001851922 ✓ 66 emma ct lot 35 ----- linden 28356 -----
B103 02	11/18/09 11/18/09	JH CA	T/S: 11/18/2009 02:11 PM TWARD ----- R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001852029 T/S: 11/17/2009 02:37 PM NTART ----- per Barry
B103 03	12/01/09 12/01/09	JH AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001855964 -----
B105 02	12/04/09 12/04/09	BS AP	R*OPEN FLOOR VRU #: 001857572 T/S: December 04, 2009 11:27 AM BSUTTON -----
B105 01	12/04/09 12/03/09	TI CA	R*OPEN FLOOR VRU #: 001857564 T/S: 12/03/2009 02:31 PM NTART -----
R425 01	1/06/10 1/06/10	JH DP	FOUR TRADE ROUGH IN VRU #: 001867761 1)Replace damaged stud to right of garage door.2)Fire caulk refrigerant lines @ top plate in back wall of garage.3)Missing roof boots for plumbing. 4)Support all pex water lines every 32" per code. 5)Need 100psi on water lines test frooze. 6)Fire caulk @top plate on vent pipe over washer box. 7)top plate joint @ refrigerator needs stud under it. 8)Fire caulk 3/4" pipe @ top plate right of fire box. 9)Nail osb to right of window right of fire box.10)Half bath missing duct for exhaust fan. 11)Need 2 studs under each end of header for stairs. 12)Roof truss for front porch does not match plans & are notched for leger need letter. STOP INSPECTION @ FIRST FLOOR TO MANY VIOLATIONS PAY \$50 RE

-----  
ADDRESS . : 66 EMMA CT SUBDIV: KENLAN FARMS PH1 SET1 41LOTS  
CONTRACTOR : RBC HOMES INC PHONE : (910) 423-3555  
OWNER . . : ABJ INVESTMENTS LLC PHONE :  
PARCEL . . : 12-0555- - -0216- -35-  
APPL NUMBER: 09-50022914 CP NEW RESIDENTIAL (SFD)  
-----

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
			FEE
R425 02	1/08/10	JH	FOUR TRADE ROUGH IN VRU #: 001868504
	1/08/10	CA	T/S: 01/08/2010 10:55 AM JBROCK -----
R425 03	1/11/10	DT	FOUR TRADE ROUGH IN VRU #: 001869015
	1/11/10	AP	
I129 01	1/13/10	DT	R*INSULATION INSPECTION VRU #: 001869676
	1/13/10	AP	
H824 01	1/20/10	OT	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001875178
	1/20/10	AP	T/S: 01/22/2010 11:11 AM SSTEWARD ----- T/S: 01/22/2010 11:11 AM SSTEWARD -----
R429 01	4/01/10	TI	FOUR TRADE FINAL VRU #: 001902972

4-1-10 *op JV*

----- COMMENTS AND NOTES -----



ADDRESS : 66 EMMA CT  
 CONTRACTOR : RBY HOMES INC  
 OWNER : ABJ INVESTMENTS LLC  
 PARCEL : 12-0555- - -0216- -35-  
 APPL NUMBER: 09-50022914 CP NEW RESIDENTIAL (SFD)  
 DIRECTIONS : T/S: 09/24/2009 01:28 PM JBROCK ----  
 KENLAN FARMS #35  
 US HWY 401 S TO RIGHT ON MCNEILL HOBBS  
 RD TO LEFT ON WIRE RD PASS JOSEY  
 WILLIAMS ON THE LEFT AND TURN RIGHT ON  
 KENLAN RD  
 T/S: 11/17/2009 01:33 PM DJOHNSON --  
 \*\*\*\*\*PREMISE # 28253863\*\*\*\*\*

SUBDIV: KENLAN FARMS PH1 SET1 41LOTS  
 PHONE : (910) 423-3555  
 PHONE :

**STRUCTURE: 000 000 30X50 3BDR CRAWL W/ GARAGE**

FLOOD ZONE . . . . . : FLOOD ZONE X  
 # BEDROOMS . . . . . : 3.00  
 SEPTIC - EXISTING? . . . . . : NEW  
 PROPOSED USE . . . . . : SFD  
 WATER SUPPLY . . . . . : COUNTY

**PERMIT: CPSF 00 CP \* SFD**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/06/09 11/06/09	MR AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001847194 T/S: 11/06/2009 12:44 PM MREARIC ----- t pole needs repair
B103 01	11/12/09 11/12/09	MR DA	R*BLDG FOUND & TEMP SVC POLE VRU #: 001848704 T/S: 11/12/2009 11:13 AM MREARIC ----- not ready
A814 01	11/18/09 11/18/09	TW AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001851922 ✓66 emma ct lot 35 ----- linden 28356 -----
B103 02	11/18/09 11/18/09	JH CA	T/S: 11/18/2009 02:11 PM TWARD ----- R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001852029 T/S: 11/17/2009 02:37 PM NTART ----- per Barry -----
B103 03	12/01/09 12/01/09	JH AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001855964 -----
B105 02	12/04/09 12/04/09	BS AP	R*OPEN FLOOR VRU #: 001857572 T/S: December 04, 2009 11:27 AM BSUTTON -----
B105 01	12/04/09 12/03/09	TI CA	R*OPEN FLOOR VRU #: 001857564 T/S: 12/03/2009 02:31 PM NTART -----
R425 01	1/06/10 1/06/10	JH DP	FOUR TRADE ROUGH IN VRU #: 001867761 1)Replace damaged stud to right of garage door.2)Fire caulk refrigerant lines @ top plate in back wall of garage.3)Missing roof boots for plumbing. 4)Support all pex water lines every 32" per code. 5)Need 100psi on water lines test frooze. 6)Fire caulk @top plate on vent pipe over washer box. 7)top plate joint @ refrigerator needs stud under it. 8)Fire caulk 3/4" pipe @ top plate right of fire box. 9)Nail osb to right of window right of fire box.10)Half bath missing duct for exhaust fan. 11)Need 2 studs under each end of header for stairs. 12)Roof truss for front porch does not match plans & are notched for leger need letter. STOP INSPECTION @ FIRST FLOOR TO MANY VIOLATIONS PAY \$50 RE

ADDRESS : 66 EMMA CT  
 CONTRACTOR : RHC HOMES INC  
 OWNER : ABJ INVESTMENTS LLC  
 PARCEL : 12-0555- - -0216- -35-  
 APPL NUMBER: 09-50022914 CP NEW RESIDENTIAL (SFD)

SUBDIV: KENLAN FARMS PH1 SET1 41LOTS  
 PHONE : (910) 423-3555  
 PHONE :

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
			FEE
R425 02	1/08/10	JH	FOUR TRADE ROUGH IN VRU #: 001868504
	1/08/10	CA	T/S: 01/08/2010 10:55 AM JBROCK -----
R425 03	1/11/10	DT	FOUR TRADE ROUGH IN VRU #: 001869015
	1/11/10	AP	
I129 01	1/13/10	DT	R*INSULATION INSPECTION VRU #: 001869676
	1/13/10	AP	
H824 01	1/20/10	OT	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001875178
	1/20/10	AP	T/S: 01/22/2010 11:11 AM SSTEWARD ----- T/S: 01/22/2010 11:11 AM SSTEWARD -----
R429 01	4/01/10	JH	FOUR TRADE FINAL VRU #: 001902972
	4/01/10	DP	<ul style="list-style-type: none"> <li>✗ Seal holes @ water heater.</li> <li>2) Need 20amp tamper proof receptacle @ microwave.</li> <li>✗ Cleanout to grade.</li> <li>✗ Label AHU in attic &amp; crawl space.</li> <li>✗ Breaker for condensing unit to big &amp; they are not wired.</li> <li>✗ Caulk master bathroom toilet.</li> </ul>
R429 02	4/06/10	TI	FOUR TRADE FINAL TIME: 17:00 VRU #: 001904911
	<u>4-6-10</u>	<u>DP JH</u>	T/S: 04/05/2010 10:13 AM DJOHNSON -----

COMMENTS AND NOTES

ADDRESS : 66 EMMA CT SUBDIV: KENLAN FARMS PH1 SET1 41LOTS  
CONTRACTOR : RBC HOMES INC PHONE : (910) 423-3555  
OWNER : ABJ INVESTMENTS LLC PHONE :  
PARCEL : 12-0555- - -0216- -35-  
APPL NUMBER: 09-50022914 CP NEW RESIDENTIAL (SFD)  
DIRECTIONS : T/S: 09/24/2009 01:28 PM JBROCK ----  
KENLAN FARMS #35  
US HWY 401 S TO RIGHT ON MCNEILL HOBBS  
RD TO LEFT ON WIRE RD PASS JOSEY  
WILLIAMS ON THE LEFT AND TURN RIGHT ON  
KENLAN RD  
T/S: 11/17/2009 01:33 PM DJOHNSON --  
\*\*\*\*\*PREMISE # 28253863\*\*\*\*\*

STRUCTURE: 000 000 30X50 3BDR CRAWL W/ GARAGE  
FLOOD ZONE : FLOOD ZONE X  
# BEDROOMS : 3.00 PROPOSED USE : SFD  
SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP \* SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/06/09	MR	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001847194
	11/06/09	AP	T/S: 11/06/2009 12:44 PM MREARIC ----- t pole needs repair
B103 01	11/12/09	MR	R*BLDG FOUND & TEMP SVC POLE VRU #: 001848704
	11/12/09	DA	T/S: 11/12/2009 11:13 AM MREARIC ----- not ready
A814 01	11/18/09	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001851922
	11/18/09	AP	66 emma ct lot 35 ----- linden 28356 -----
			T/S: 11/18/2009 02:11 PM TWARD -----
B103 02	11/18/09	JH	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001852029
	11/18/09	CA	T/S: 11/17/2009 02:37 PM NTART ----- per Barry -----
B103 03	12/01/09	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001855964
	12/01/09	AP	-----
B105 02	12/04/09	BS	R*OPEN FLOOR VRU #: 001857572
	12/04/09	AP	T/S: December 04, 2009 11:27 AM BSUTTON -----
B105 01	12/04/09	TI	R*OPEN FLOOR VRU #: 001857564
	12/03/09	CA	T/S: 12/03/2009 02:31 PM NTART -----
R425 01	1/06/10	JH	FOUR TRADE ROUGH IN VRU #: 001867761
	1/06/10	DP	1)Replace damaged stud to right of garage door.2)Fire caulk refrigerant lines @ top plate in back wall of garage.3)Missing roof boots for plumbing. 4)Support all pex water lines every 32" per code. 5)Need 100psi on water lines test frooze. 6)Fire caulk @top plate on vent pipe over washer box. 7)top plate joint @ refrigerator needs stud under it. 8)Fire caulk 3/4" pipe @ top plate right of fire box. 9)Nail osb to right of window right of fire box.10)Half bath missing duct for exhaust fan. 11)Need 2 studs under each end of header for stairs. 12)Roof truss for front porch does not match plans & are notched for leger need letter. STOP INSPECTION @ FIRST FLOOR TO MANY VIOLATIONS PAY \$50 RE

ADDRESS : 66 EMMA CT SUBDIV: KENLAN FARMS PH1 SET1 41LOTS  
CONTRACTOR : RBC HOMES INC PHONE : (910) 423-3555  
OWNER : ABJ INVESTMENTS LLC PHONE :  
PARCEL : 12-0555- - -0216- -35-  
APPL NUMBER: 09-50022914 CP NEW RESIDENTIAL (SFD)

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
			FEE
R425 02	1/08/10	JH	FOUR TRADE ROUGH IN VRU #: 001868504
	1/08/10	CA	T/S: 01/08/2010 10:55 AM JBROCK -----
R425 03	1/11/10	DT	FOUR TRADE ROUGH IN VRU #: 001869015
	1/11/10	AP	
I129 01	1/13/10	DT	R*INSULATION INSPECTION VRU #: 001869676
	1/13/10	AP	
H824 01	1/20/10	OT	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001875178
	1/20/10	AP	T/S: 01/22/2010 11:11 AM SSTEWARD ----- T/S: 01/22/2010 11:11 AM SSTEWARD -----
R429 01	4/01/10	JH	FOUR TRADE FINAL VRU #: 001902972
	4/01/10	DP	1)Seal holes @ water heater. 2)Need 20amp tamper proof receptacle @ microwave. 3)Cleanout to grade. 4)Label AHU in attic & crawl space. 5)Breaker for condensing unit to big & they are not wired. 6)Caulk master bathroom toilet.
R429 02	4/06/10	JH	FOUR TRADE FINAL TIME: 17:00 VRU #: 001904911
	4/06/10	DP	T/S: 04/05/2010 10:13 AM DJOHNSON ----- Previous violation was not corrected per code item #2. -----
R429 03	4/08/10	TI	FOUR TRADE FINAL TIME: 17:00 VRU #: 001906445
	<u>4-8-10</u>	<u>APJH</u>	T/S: 04/07/2010 12:33 PM RDCONTE -----

----- COMMENTS AND NOTES -----

**COUNTY OF HARNETT  
DEPARTMENT OF BUILDING INSPECTION  
AND PLANNING/DEVELOPMENT  
CERTIFICATE OF OCCUPANCY**

This certificate issued pursuant to the requirements of Section 105 of the North Carolina State Building Code and the Harnett County Zoning Ordinance certifies at the time of issuance this structure was in compliance with the various ordinances of the County of Harnett regulating development and building construction or use. For the following:

Use Classification: SFO  
Type of Construction: V  
Owner of Building: RBC Homes Inc  
Building Address: 66 Emma Ct  
Zoning District: \_\_\_\_\_  
Zoning Permit No.: \_\_\_\_\_  
Date: 4-8-10  
James T Hall  
Building Official

Conditional Use Permit No.: \_\_\_\_\_  
Building Permit No.: \_\_\_\_\_  
Electrical Permit No.: \_\_\_\_\_  
Insulation Permit No.: \_\_\_\_\_  
Plumbing Permit No.: \_\_\_\_\_  
Mech. Permit No.: \_\_\_\_\_  
Envir. C.O. No.: \_\_\_\_\_  
41562005-60  
Zoning Official