INSPECTION TICKET PREPARED 3/01/10, 13:59:47 PAGE 38 INSPECTOR: IVR Harnett County DATE 3/02/10 ADDRESS . : 89922 *UNASSIGNED SUBDIV:

CONTRACTOR : KEITH BULLOCK BUILDERS INC. PHONE: (919) 639-7424 OWNER . . : BRYAN CHARLES & LINDA PHONE: (919) 557-5050

PARCEL . . : 05-0642- - -0003- -14-

APPL NUMBER: 10-50023623 CP NEW RESIDENTIAL (SFD) DIRECTIONS: T/S: 01/19/2010 11:33 AM RDCONTE ---

194 JACKSON ROAD

TAKE 401 N TOWARDS FUOUAY. T/L ON CHRISTIAN LIGHT ROAD. GO APROX 1.5MI, T/L ON JACKSON ROAD. 194 JACKSON IS AT THE 2ND GROUP OF MAILBOXES ON THE

RIGHT.

STRUCTURE: 000 000

FLOOD ZONE . . . : FLOOD ZONE X

BEDROOMS 4.00 PROPOSED USE : SFD

SEPTIC - EXISTING? . . . : EXISTING WATER SUPPLY : EXT WELL

PERMIT: CPSF 00 CP * SFD

REQUESTED INSP DESCRIPTION

TYP/SQ COMPLETED RESULT RESULTS/COMMENTS

B101 01 3/02/10 TI R*BLDG FOOTING / TEMP SVC POLE VRU #: 001889004

----- COMMENTS AND NOTES -----

INSPECTION TICKET PREPARED 3/10/10, 13:58:58 PAGE 22 INSPECTOR: IVR Harnett County DATE 3/11/10 ______

ADDRESS . : 89922 *UNASSIGNED SUBDIV:

PHONE: (919) 639-7424 CONTRACTOR : KEITH BULLOCK BUILDERS INC. PHONE: (919) 557-5050 OWNER . . : BRYAN CHARLES & LINDA

PARCEL . : 05-0642- - -0003- -14-

APPL NUMBER: 10-50023623 CP NEW RESIDENTIAL (SFD) DIRECTIONS: T/S: 01/19/2010 11:33 AM RDCONTE ---

194 JACKSON ROAD

TAKE 401 N TOWARDS FUQUAY. T/L ON CHRISTIAN LIGHT ROAD. GO APROX 1.5MI, T/L ON JACKSON ROAD. 194 JACKSON IS AT

THE 2ND GROUP OF MAILBOXES ON THE

RIGHT.

STRUCTURE: 000 000

FLOOD ZONE . . . : FLOOD ZONE X

SEPTIC - EXISTING? . . . : EXISTING WATER SUPPLY

WATER SUPPLY : EXT WELL ______

PERMIT: CPSF 00 CP * SFD

REQUESTED INSP DESCRIPTION COMPLETED RESULT RESULTS/COMMENTS TYP/SQ 3/02/10 BS R*BLDG FOOTING / TEMP SVC POLE VRU #: 001889004 B101 01

3/02/10 AP T/S: March 02, 2010 12:48 PM BSUTTON ------

3/11/10 TI R*BLDG FOUND & TEMP SVC POLE VRU #: 001893598 B103 01 3-11-10 <u>AEBS</u>

PREPARED 3/17/10, 13:59:00 Harnett County

INSPECTION TICKET

PAGE

3/18/10

INSPECTOR: IVR DATE

ADDRESS . : 89922 *UNASSIGNED CONTRACTOR : KEITH BULLOCK BUILDERS INC. SUBDIV:

PHONE: (919) 639-7424

OWNER . . : BRYAN CHARLES & LINDA

PHONE: (919) 557-5050

PARCEL . .: 05-0642- - -0003--14-

APPL NUMBER: 10-50023623 CP NEW RESIDENTIAL (SFD)

DIRECTIONS: T/S: 01/19/2010 11:33 AM RDCONTE ---

194 JACKSON ROAD

TAKE 401 N TOWARDS FUQUAY. T/L ON CHRISTIAN LIGHT ROAD. GO APROX 1.5MI, T/L ON JACKSON ROAD. 194 JACKSON IS AT

THE 2ND GROUP OF MAILBOXES ON THE

RIGHT.

STRUCTURE: 000 000

FLOOD ZONE . . . : FLOOD ZONE X

BEDROOMS 4.00 PROPOSED USE : SFD

SEPTIC - EXISTING? . . . : EXISTING WATER SUPPLY : EXT WELL

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/02/10	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001889004
	3/02/10	AP	T/S: March 02, 2010 12:48 PM BSUTTON
B103 01	3/11/10	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001893598
	3/11/10	AE	Damproof exterior, leave open for inspection. Will check at open floor
A814 01	3/16/10	FB	ADDRESS CONFIRMATION VRU #: 001893605
	3/15/10	AP	T/S: 03/15/2010 04:39 PM FBURGESS115
B105 01	3/18/10 3′/8′/6	4985	R*OPEN FLOOR VRU #: 001896121

----- COMMENTS AND NOTES

PREPARED 4/19/10, 15:13:27

INSPECTION TICKET

PAGE

31 4/20/10

Harnett County INSPECTOR: IVR DATE 4/20/10

ADDRESS . : 89922 *UNASSIGNED

SUBDIV:

CONTRACTOR : KEITH BULLOCK BUILDERS INC.

PHONE : (919) 639-7424 PHONE : (919) 557-5050

OWNER . . : BRYAN CHARLES & LINDA PARCEL . . : 05-0642- - -0003- -14-

APPL NUMBER: 10-50023623 CP NEW RESIDENTIAL (SFD)

DIRECTIONS: T/S: 01/19/2010 11:33 AM RDCONTE ---

194 JACKSON ROAD

TAKE 401 N TOWARDS FUQUAY. T/L ON CHRISTIAN LIGHT ROAD. GO APROX 1.5MI, T/L ON JACKSON ROAD. 194 JACKSON IS AT THE 2ND GROUP OF MAILBOXES ON THE

RIGHT.

STRUCTURE: 000 000

FLOOD ZONE . . . : FLOOD ZONE X

SEPTIC - EXISTING? . . . : EXISTING WATER SUPPLY : EXT WELL

PERMIT: CPSF 00 CP * SFD			
	REQUESTED	INSP	DESCRIPTION
TYP/SQ	COMPLETED	RESULT	RESULTS/COMMENTS
B101 01	3/02/10	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001889004
	3/02/10	AP	T/S: March 02, 2010 12:48 PM BSUTTON
B103 01	3/11/10	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001893598
	3/11/10	AE	Damproof exterior, leave open for inspection. Will check at open floor
A814 01	3/16/10	FB	ADDRESS CONFIRMATION VRU #: 001893605
	3/15/10	AP	T/S: 03/15/2010 04:39 PM FBURGESS
B105 01	3/18/10	BS	R*OPEN FLOOR VRU #: 001896121
	3/18/10	AP	T/S: March 18, 2010 09:31 AM BSUTTON
R427 01	4/20/10 4-2p.10	DATSS	FOUR TRADE ROUGH IN >2500 VRU #: 001912808

PREPARED 4/23/10, 13:58:45 Harnett County

INSPECTION TICKET

PAGE

4/26/10

INSPECTOR: IVR

DATE

______ ADDRESS . : 89922 *UNASSIGNED SUBDIV:

CONTRACTOR : KEITH BULLOCK BUILDERS INC.

PHONE: (919) 639-7424 PHONE : (919) 557-5050

OWNER . . : BRYAN CHARLES & LINDA PARCEL . .: 05-0642- - -0003- -14-

APPL NUMBER: 10-50023623 CP NEW RESIDENTIAL (SFD)

DIRECTIONS: T/S: 01/19/2010 11:33 AM RDCONTE ---

194 JACKSON ROAD

BS

TAKE 401 N TOWARDS FUQUAY. T/L ON CHRISTIAN LIGHT ROAD. GO APROX 1.5MI, T/L ON JACKSON ROAD. 194 JACKSON IS AT

THE 2ND GROUP OF MAILBOXES ON THE

RIGHT.

STRUCTURE: 000 000

B101 01

FLOOD ZONE . . . : FLOOD ZONE X

BEDROOMS 4.00 PROPOSED USE SFD

SEPTIC - EXISTING? . . . : EXISTING WATER SUPPLY : EXT WELL

	REQUESTED	INSP
TYP/SQ	COMPLETED	RESULT

3/02/10

PERMIT: CPSF 00 CP * SFD

DESCRIPTION	
RESULTS/COMMENTS	

		3/02/10	AP
B103	01	3/11/10	BS
		3/11/10	AE
A814	01	3/16/10	FB
		3/15/10	AP
B105	01	3/18/10	BS
		3/18/10	AP
R427	01	4/20/10	BS
		4/20/10	(DA)

R*BLDG FOUND & TEMP SVC POLE VRU #: 001893598 Damproof exterior, leave open for inspection. Will check at open floor ADDRESS CONFIRMATION VRU #: 001893605

T/S: March 02, 2010 12:48 PM BSUTTON ------

R*BLDG FOOTING / TEMP SVC POLE VRU #: 001889004

T/S: 03/15/2010 04:39 PM FBURGESS ------194 JACKSON RD FUQUAY VARINA, NC 27526

R*OPEN FLOOR VRU #: 001896121

T/S: March 18, 2010 09:31 AM BSUTTON ------FOUR TRADE ROUGH IN >2500 VRU #: 001912808

🔐. Need tempered glass at rear side door. 1/Insulate water line for master shower head. 1 Stud column for garage 9.25 LVL should be 4 (beside electrical panel) 4. Rear porch header should be 3-2x10. Plan shows covered porch beam hangered into screen porch beam- roof hip supported above. 5 Add studs at double 2x10 right of foyer per plan

.NEED ENGINEERING ON THE FOLLOWING- Stud height in garage supporting roof and floor exceeds 10' Need a detail on ceiling joist to beam connection, or that its ok the way it is done. Added beam carrying ceiling load right of front foyer, not shown on plan. Verify that side nailing studs to rafters is acceptable rafter support. DO not cover rear

porch ceilings/beams. ok to insulate

I129 01

R227 01

TI

R*INSULATION INSPECTION VRU #: 001915486

TWO TRADE ROUGH IN >2500 VRU #: 001915477

------ COMMENTS AND NOTES ---------



7 919 773-1200 • # 919 773-9658 69 Shipwash Driva • Garner • North Caroline • 27529 www.tyndallengineering.com

April 22, 2010

Keith Bullock Builders, Inc. 72 Overlook Ct. Angier, NC 27501

Reference:

Inspection Issues

Plan:

DK 2859

Project No.

10GAR-R0009

To Whom It May Concern:

A representative of Tyndall Engineering & Design analyzed plan items for the above referenced project. Specifically, the following items listed were analyzed:

- 1) Garage stud wall height of approximately 12'-0".
- Floor joist connection to W8x21 in Family Room.
- 3) Knee wall connection to roof rafters in second floor.
- 4) Connection between rear Covered Porch header and rear Screened Porch header.

The following conclusions and recommendations were presented for the abovementioned items:

- 1) Based on our plan review and analysis, the 12'-0" tall studs shall be either 2x6 @ 16" o.c., or (2)2x4 @ 16" o.c. For the (2)2x4 option, the studs may be framed side-by-side or as a "T" section. The plan specified beam stud columns are adequate as framed.
- 2) The web of the W8x21 shall be packed out with 2x lumber. The floor joists shall bear on a ledger. See sheet 3 for required framing detail
- 3) The rafters may be nailed to the 2x4 knee wall studs in lieu of bearing on top of the knee wall. The rafters must be secured with minimum (5)10d nails at each connection. See sheet 3 for required framing detail.



7 919 773-1200 = 2 919 773-9658 69 Shipwash Drive = Garner = North Carolina = 27529 - www.tyndalfenginearing.com

4) The header connection is framed as shown on sheet 4. This connection is an adequate substitute for the plan specified LUS210-3 hanger.

We appreciate being able to assist you during this phase of the project. If you need further assistance or require additional information please do not hesitate to contact us.


Sincerely,

Tyndall Engineering & Design

Alan W. Lewis E.I. AWL/10GAR-R0009

Page 2 of 4

	W. 8 x21
PALK OUT WEG AS	LEDGER
DXIOF5 PER S	
FRAMIN	GAT STEEL BEAM
	PER PLAN -CS>10d NAILS
ax 4 kvee	
KNEE WALL	Consider Viole
TYNDALL ENGINEERING & DESIGN, PA. 1919 773-1200 - 1919 773-9458 49 Shipwash Drive - Garner - North Carolina - 27319 www.tyndallenginaering.com	LOCATION FRAMING DETAILS CALCULATED BY AUL DATE 4-22-10 SHEET NO. 3 OF 4 SCALE NTS





r 919 773-1200 • s 910 273-9658 69 Shipwash Drivo • Garnor • North Carolina • 27529 www.tyndallongineering.com

April 20, 2010

Keith Bullock Builders, Inc. 72 Overlook Ct. Angier, NC 27501

Reference:

Attic Framing

Plan:

DK 2859

Project No.

10GAR-R0009

To Whom It May Concern:

A representative of Tyndall Engineering & Design analyzed plan items for the above referenced project. Specifically, the following items listed were analyzed:

1) Framing in attic near stairs.

The following conclusions and recommendations were presented for the above-mentioned items:

1) Based on our plan review and analysis, the plan specified wall in the attic near the stairs may be removed. The plan specified point load shall be supported by (2) 2x8 ceiling joists. The double 2x8 ceiling joists shall be secured to a (2)2x8 rafter with (2)1/2" x 6" lag screws. The reader is referred to the attached pages. These changes will adequately support the anticipated loading conditions.

Prentice Ty

We appreciate being able to assist you during this phase of the project. If you need further assistance or require additional information please do not hesitate to contact us.


Sincerely,


Tyndall Engineering & Design

Alan W. Lewis E.I.

AWL/10GAR-R0009

Page 1 of 3





PREPARED 6/16/10, 14:09:17 INSPECTION TICKET PAGE 20 Harnett₂County INSPECTOR: IVR DATE 6/17/10

ADDRESS . : 89922 *UNASSIGNED SUBDIV:

CONTRACTOR : KEITH BULLOCK BUILDERS INC. PHONE: (919) 639-7424 OWNER . . : BRYAN CHARLES & LINDA PHONE: (919) 557-5050

PARCEL . . : 05-0642- - -0003- -14-

APPL NUMBER: 10-50023623 CP NEW RESIDENTIAL (SFD) DIRECTIONS: T/S: 01/19/2010 11:33 AM RDCONTE ---

194 JACKSON ROAD

TAKE 401 N TOWARDS FUQUAY. T/L ON CHRISTIAN LIGHT ROAD. GO APROX 1.5MI, T/L ON JACKSON ROAD. 194 JACKSON IS AT THE 2ND GROUP OF MAILBOXES ON THE

RIGHT.

STRUCTURE: 000 000

FLOOD ZONE . . . : FLOOD ZONE X

BEDROOMS : PROPOSED USE SFD 4.00

SEPTIC - EXISTING? . . . : EXISTING WATER SUPPLY : EXT WELL

	CPSF 00 CP * REQUESTED	INSP	DESCRIPTION
TYP/SQ	COMPLETED	RESULT	RESULTS/COMMENTS
B101 01	3/02/10	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001889004
	3/02/10	AP	T/S: March 02, 2010 12:48 PM BSUTTON
B103 01	3/11/10	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001893598
	3/11/10	ΑE	Damproof exterior, leave open for inspection. Will check at open floor
A814 01	3/16/10	FB	✓ ADDRESS CONFIRMATION VRU #: 001893605
	3/15/10	AP	T/S: 03/15/2010 04:39 PM FBURGESS
			194 JACKSON RD FUQUAY VARINA, NC 27526
B105 01	3/18/10	BS	R*OPEN FLOOR VRU #: 001896121
	3/18/10	AP	T/S: March 18, 2010 09:31 AM BSUTTON
R427 01	4/20/10	BS	FOUR TRADE ROUGH IN >2500 VRU #: 001912808
	4/20/10	D A	1. Need tempered glass at rear side door. 2. Insulate water
			line for master shower head. 3.Stud column for garage 9.25
			LVL should be 4 (beside electrical panel) 4.Rear porch
			header should be 3-2x10.Plan shows covered porch beam
			hangered into screen porch beam- roof hip supported above.
			5 Add studs at double 2x10 right of foyer per plan
			.NEED ENGINEERING ON THE FOLLOWING- Stud height in garage
			supporting roof and floor exceeds 10' Need a detail on
			ceiling joist to beam connection, or that its ok the way it
			is done. Added beam carrying ceiling load right of front
			foyer, not shown on plan. Verify that side nailing studs to
			rafters is acceptable rafter support. DO not cover rear
			porch ceilings/beams. ok to insulate
I129 01		BS	R*INSULATION INSPECTION VRU #: 001915486
	4/27/10	AP	T/S: April 27, 2010 07:25 AM BSUTTON
R227 01	, ,	BS	TWO TRADE ROUGH IN >2500 VRU #: 001915477
	4/27/10	AP	T/S: April 27, 2010 07:25 AM BSUTTON
R431 01	6/17/10	TI	FOUR TRADE FINAL >2500 VRU #: 001942241
	6.17.10	14-MR	

County of Harnett Building Inspections Department Planning Services

Certificate of Compliance: \times Occupancy: \times

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: R-3	Permit Numbers
Name:	Building: 10-50023623
Bryan, Charles + Linda Address:	Electrical:
Address:	Insulation:
194 Jackson Rd.	Plumbing:'
	Mechanical: / ·
	MFG Home:
Date: 6	al: au 1 1 1 7 1