

# COMMENTS:

ON 9-9-10 - MET NEEL FLOYD ON Lot 99 About Layout to Septic System for this lot. OT was present  
NEEL proposed a layout I TOLD him to submit Layout, that we under circumstances Agreed that new layout  
ON 9-10-10 - THAT morning I CAME TO WORK Layout on my desk was sort of contrary to discussion  
that we all HAD, I TOLD NEEL THAT there was a bad spot in center of BACKLARD.

IF HE DIDNT see IT then I would agree on Layout. - The Layout basically dis-regarded  
what I HAD TOLD NEEL About Repair Area in BACKLARD. I went OUT ON 9-10-10

DOG A HOLE IN THE AREA discussed and it was out AT 22" I TO  
CALL OT TO come BACK OUT TO confirm. HE DID BUT HIS OPINION WAS THAT  
IT WAS 24" TO 26" MAX SOIL DEPTH so he said give the report to NEEL Floyd

JUST make him amend his new proposal to AT GRADE Repair, CALL N.F.  
to re-submit Report AS discussed. Above Con permit issue -

HAD TO GO WITH OT professional opinion on repair.

J. B. ...

9230

System does NOT GET ESTABLISHED EXACTLY AS permitted for consultant's layout  
DETAILS when in process discussed NOT being Tr. Repair Change etc.