		ter Section				Propert Lot #: File #: Code:	y ID:		
Evalu	er: ess: osed Facility tion of Site: r Supply: nation Metho of Wastewal	d: 1	t: Date Desig Prop Prop Public Auger Bo Sewage	Evaluated: 7/28) gn Flow (.1949): # erty Recorded: Individual ring P Industrial	it Cut		Other		
P R O F I	.1940 Landscape Position/ Slope %	Horizon Depth (ln.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
L E #			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Clasa	.1944 Restr Horiz	Profile Class & LTAR
١	25-24/6	0-48	65	VFR ristrip					5,8
2		0-48	65	Nau unime					5.8
3		0-28	65	VER NO AG					5.8
-									
						· · · · · · · · · · · · · · · · · · ·			

Description	Initial	Repair System	Other Factors (.1946):
	System		Site Classification (1948): 5
Available Space (.1945)			Evaluated By:
System Type(s)	CON	CON	Others Present: &~
Site LTAR	8.	.8	

2~75 @ 24-76