## **County of Harnett Building Inspections Department Planning Services** Certificate of Compliance: \_\_\_ Occupancy: \_\_\_\_ / Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following: **Permit Numbers** Use Classification: Residential Name: Red Door Homes Building: Electrical: Insulation: Plumbing: Address: 147 Hawksworth Pl Cameron, NC 28326 Mechanical: MFG Home: Date: 1/13/12 **Building Official:**

all the result in the first of the control of the c

PREPARED 1/12/12, 14:24:10 INSPECTION TICKET PAGE INSPECTION TICK DATE 1/13/12 Harnett County INSPECTOR: IVR

ADDRESS . : \*UNASSIGNED SUBDIV:

RIGHT ONTO 24W/87N TO SAWYER RD THEN

PHONE : (910) 481-0503 CONTRACTOR : RED DOOR HOMES OF FAYETTEVILLE PHONE: (910) 497-2852 OWNER . . : THOMAS MELISSA L

PARCEL . .: 09-9566-01- -0011- -47-

APPL NUMBER: 11-50027480 CP NEW RESIDENTIAL (SFD) DIRECTIONS: T/S: 09/06/2011 08:31 AM DJOHNSON --STARWOOD AT OVERHILLS PHS 2-A LOT 42 210S TO OVERHILLS RD TO NURSERY RD THEN

RIGHT ONTO HAWKSWORTH PLACE

16


STRUCTURE: 000 000 41X34 4 BR ATT GARAGE PORCH SLAB

FLOOD ZONE . . . : FLOOD ZONE X

PROPOSED USE . . . . . . . SFD # BEDROOMS . . . . . . : 4.00 SEPTIC - EXISTING? WATER SUPPLY . COUNTY

TYP/SQ	CPSF 00 CP * REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	10/05/11	DT	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002144756
	10/05/11	DA	T/S: 10/04/2011 12:59 PM VBROWN
			1. Lugs in footing not dug to specified depths, see plans.
			2. 36x36x12 lug is also only 35 inches wide in addition to
			not being deep enough.
			T/S: 10/05/2011 09:51 AM DETAYLOR
3101 02	10/06/11	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002145464
	10/06/11	AP	
814 01	10/28/11	TW	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002154938
	10/28/11	AP	T/S: 10/27/2011 02:51 PM DJOHNSON
			147 HAWKSWORTH PL LOT 42 CAMERON 28326
			T/S: 10/28/2011 08:27 AM TWARD
103 01	10/28/11	FS	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002154920
	10/28/11	DA	T/S: 10/27/2011 02:51 PM DJOHNSON
			T/S: 10/28/2011 01:30 PM FSPIVEY
			back fill befor foundation inspection
103 02	10/31/11	DT	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002155471
	10/31/11	AP	
3111 01	11/02/11	DT	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 002156180
	11/02/11	AP	T/S: 11/01/2011 10:14 AM VBROWN
309 01	11/02/11	DT	R*PLUMB UNDER SLAB TIME: 17:00 VRU #: 002156479
	11/02/11	AP	T/S: 11/01/2011 03:21 PM DJOHNSON
207 01	11/18/11	$\mathtt{DT}$	R*ELEC TEMP SERVICE POLE TIME: 17:00 VRU #: 002162543
	11/18/11	AP	T/S: 11/16/2011 04:38 PM VBROWN
427 01	11/23/11	JH	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 002164465
	11/23/11	DA	T/S: 11/22/2011 11:16 AM VBROWN
			1) Missing nuts & washers on anchor bolts @ garage door.
			2) Frame out for exposed 3" pipe in laundry room. 3) Add stud
			to left of slidding back door over 16" span. 4) Missing
			anchor bolts throughout house per code. 5) Fire caulk
			refrigerant lines @ top plate in back right bedroom on end
			wall. 6)Missing stud on back wall to left of window in loft
			over 16" span.
427 02	12/01/11	DT	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 002166338
	12/01/11	DA	T/S: 11/30/2011 10:10 AM VBROWN
			Fire block where wall was built out for 3 inch line in

----- CONTINUED ONTO NEXT PAGE -----



PREPARED 1/12/12, 14:24:10 Harnet County

ADDRESS . : \*UNASSIGNED

INSPECTION TICKET

PAGE DATE 17 1/13/12

1-

INSPECTOR: IVR

SUBDIV:

CONTRACTOR : RED DOOR HOMES OF FAYETTEVILLE OWNER . . : THOMAS MELISSA L

PHONE : (910) 481-0503 PHONE : (910) 497-2852

PARCEL . .: 09-9566-01- -0011- -47-

APPL NUMBER: 11-50027480 CP NEW RESIDENTIAL (SFD)

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS	
			laundry room.	
			Okay to side and insulate.	
			T/S: 12/01/2011 01:40 PM DETAYLOR	
I129 01	12/05/11	DT	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002167971	
	12/05/11	DA	T/S: 12/05/2011 10:43 AM DETAYLOR	
			1. Where wall was built out for plumbing is still not fire	
			blocked. Wall cavity must be blocked from ceiling cavity.	
			\$50.00 Re-inspection fee	
R427 03	12/05/11	DT	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 002167989	
	12/05/11	DP	T/S: 12/05/2011 10:42 AM DETAYLOR	
I129 02	12/06/11	DT	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002168607	
	12/06/11	AP	T/S: 12/05/2011 01:52 PM VBROWN	
			T/S: 12/06/2011 09:50 AM DETAYLOR	
R427 04	12/06/11	DT	FOUR TRADE ROUGH IN >2500 TIME: 17:00 VRU #: 002168623	
	12/06/11	AP	T/S: 12/05/2011 01:52 PM VBROWN	
			T/S: 12/06/2011 09:50 AM DETAYLOR	
H824 01	12/22/11	OT	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002176170	
	12/22/11	AP	T/S: 12/28/2011 10:04 AM SZIMMER	
			T/S: 12/28/2011 10:04 AM SZIMMER	
R431 01	1/13/12	TI	FOUR TRADE FINAL >2500 TIME: 17:00 VRU #: 002180511	
	1/13/12	OTAP	WOULD LIKE MORNING INSPECTION	
COMMENTS AND NOTES				