Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Sheet: Property ID: Lot #: File #:

Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: Applica	int: Lelv—C			
Address:	Date Evaluate	ed: 3-4-13		
Proposed Facility: \mathcal{FD}	Design Flow	(.1949): <i>360</i>	Property Size:	
Location of Site:	Property Reco			
Water Supply:	Public Individua	al Well	☐ Spring	Other
Evaluation Method: Aug		Pit Cut		
Type of Wastewater:	Sewage	Industrial Process	☐ Mixed	
Type of Wastewater:	☐ Sewage ☐	Industrial Process	☐ Mixed	

P R O F I .1940 L Landscape Horiz		SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
Position/ Slope %	Depth (In.)	.1941 Structure/ Texture	.1941 Consistence Mineralogy	Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
	0-30	SC MAR	vecanous					
	30.42	sc-ling	Frm 1 FBK 5.P	90 " 755 PL				.6'4
	0-20	3 C	Mannow					
	20 36	Sucan	Kon 1 88 LS.P.	327.50		15		. 3
	6120	SC A	FUCANONS	30 75m	DE	U		
	70-36	St-Ciny ,	an 1832 S.P.	3.1		,		.3
	0-18	SL HERM	FUGAN3NS	le 30782		X		&
,	8-34	is com	an SBUS.P.	5.1				<i>e</i> 3
	0-12	SL .	Encon N3WP		U) 		
/	7-30	SC-CTSy.	an MRKS.P.	26-7/52-	-			.25
		,			$\mathcal{N}_{\mathcal{A}}$	(A)		
				Accept			7 3	
					<u> </u>		NOVO	wh
					7	500 0		MI
							,	
1	Landscape Position/ Slope %	2 Andscape Position/ Depth (In.) 30 42 0 - 20 20 36 6 20 70 36	1940 Landscape Position/ Slope % Horizon Depth (In.) 1941 Structure/ Texture 30 42 X-Liny 0-20 36 X-Liny 70-36 X-Liny	1940 Landscape Position/ Slope % Horizon Depth (In.) Structure/ Texture 1941 Consistence Mineralogy 30 42 & Liny Francist SR 0-20 20 36 & Learn Kall Bass.P. 6-20 SL Carry Rucansor Rucans	1940 Landscape Position/ Slope % Horizon Depth (In.) Structure/ Texture 1941 1941 1941 Structure/ Texture Consistence Mineralogy Color 19-30 30 42 X-Ling Francists Francists 0-20 20 36 20 37 20 36 20 36 20 36 20 36 20 37 20 36 20 36 20 36 20 36 20 37 20 36 20 36 20 36 20 36 20 36 20 37 20 36 20 36 20 36 20 36 20 37 20 36 20 36 20 36 20 37 20 36 20 36 20 36 20 36 20 36 20 37 20 36 20 36 20 37 20 36 20 37 20 36 20 37 20 36 20 37 20 36 20 37 20 36 20 37 20 36 20 36 20 37 20 36 20 36 20 36 20 37 20 36 20 36 20 36 20 36 20 37 20 36 20 36 20 36 20 36 20 37 20 36 20 36 20 36 20 37 20 36 20	1940 Landscape Position/ Slope % Horizon Depth (In.) 1941 1941 1941 1941 Soil Wetness/ Soil Depth (In.) 1942 Soil Wetness/ Color 1943 Soil Depth (In.) 1943 Soil Depth (In.) 1944 1945 1945 1945 1946 1947 1948 Soil Wetness/ Color 1948 Soil Depth (In.) 1948 Soil Wetness/ Soil Depth (In.) 1949 1940 1941 1941 1941 1942 Soil Wetness/ Color 1948 Soil Depth (In.) 1949 1943 Soil Depth (In.) 1944 1945 Soil Depth (In.) 1946 1946 1947 1948	1940 Landscape Position/ Depth (In.) Structure/ Consistence Mineralogy 1941 1941 1941 1942 Soil 1943 1945 Sapro Color Depth (In.) Structure/ Mineralogy 1942 Soil Sapro Depth (In.) Class 1943 1956 Sapro Depth (In.) Class 1943 1956 Sapro Depth (In.) 1941 Consistence Mineralogy Profile FACTORS 1942 Soil Soil Sapro Depth (In.) Class 1942 Landscape Ann 133K 5 R 4u "7,837R 1947 1948 19	1940 Landscape Position/ Position/ Slope %

Description	Initial	Repair System	Other Factors (.1946):	
	System /		Site Classification (.1948):	13
Available Space (.1945)		/	Evaluated By:	
System Type(s)	284	28	Others Present:	Local
Site LTAR	13	, 3-25		