Divis	sion of Enviro Site Wastewat	nmental H	Health and Nati lealth		Sheet: Property ID: Lot #: File #:				
	for ON-		TE EVALUAT STEWATER S			Code:			
Locat Wate Evalu		Auge	Date Desig Prope	Evaluated: 5 yn Flow (.1949):X erty Recorded: ndividual IV Pit Industrial F	Vell Cut	eg 🗌 Oth	er		
P R O F I	.1940		SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
L E #	Landscape Position/ Slope %	Horizon Depth (In.)	.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	. 1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTA
)	25	0-6"	FILL						
į		6:30	53K 5(2	FIST					
		30-45	55K 52	FR 35/NC	· · · · · · · · · · · · · · · · · · ·				<b>P</b> 5
		40-72	65	FI 5/8 FI 55/NC VFR NS/VR					
L									
д		0-10	G 52	rfanslar					
		10.24	SBY SQ	VFR. VSAVK Fr. 55) ER					P5 .5
		24- <b>60</b>	65	van ushu					
3		ÅL0	632	VESNEWP					
A-4-1-1		10-24	SBKGQ	Fn sslap					
		24-65	G S	VFT NS) APP					
					······				

Description	Initial	Repair System	Other Factors (.1946):
	System		Site Classification (.1948): (7)
Available Space (.1945)	J	$\checkmark$	Evaluated By
System Type(s)	25%	260	Others Present:
Site LTAR	.5	.5	
		-	

1×110 e 30-48