## **COUNTY OF HARNETT Building Inspections Department Planning Services** Certificate of Compliance: Occupancy: X Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following: Use Classification: SFD **Permit Numbers** Name: Pugh Enterprises LLC Building: 16-50038935 Electrical: Address: 57 Wexford Dr. Insulation: Plumbing: \_\_\_\_\_ Fuguay Varina NC 27526 Mechanical: ..... MFG Home: \_\_\_\_ Building Official: Brad Sutton Date: 04/18/2017

PREPARED 4/17/17, 14:26:41 Harnett County INSPECTION TICKET INSPECTOR: IVR

PAGE

DATE 4/18/17

ADDRESS . : 57 WEXFORD DR

SUBDIV: WEXFORD SUBDIVISION

CONTRACTOR : PUGH ENTERPRISES, LLC

PHONE : (919) 931-2581

OWNER . . : ALEXANDER ZACHARY A

PHONE :

PARCEL . .: 04-0665- - -0025- -22-

APPL NUMBER: 16-50038935 CP NEW RESIDENTIAL (SFD)
DIRECTIONS: 57 WEXFORD DR/ WEFORD LOT 22 FUQUAY

VARINA

STRUCTURE: 000 000 25X31.7 3BDR CRAWL W/ DECK

FLOOD ZONE . . . : FLOOD ZONE X

# BEDROOMS . . . . : 3.00 PROPOSED USE . . . : SFD SEPTIC - EXISTING? . . . : NEW TANK WATER SUPPLY . . . . : COUNTY

PERMIT:	CPSF 00 CP * REQUESTED COMPLETED	INSP RESULT	RESULTS/COMMENTS	operations has been done - signed off been done - signed off fixet was in the after frinted.
B101 01	11/14/16 11/14/16	BS AP	T/S: 11/09/2016 01:3 T/S: November 14, 201	P SVC POLE TIME: 17:00 VRU #: 002896843 66 PM JFORBES
				e back and checked footing after ast also state it is in accordance with
B103 01	12/02/16 12/02/16	BS DA	R*BLDG FOUND & TEMP S T/S: 12/01/2016 12:3 T/S: December 02, 201	SVC POLE TIME: 17:00 VRU #: 002905701 55 PM JFORBES
			be dug out and pinned T/S: December 06, 201	Pier not on center 1/3 of footing must d. Shown to contractor de 10:54 AM BSUTTON de repair. Ok to pour. Will check or inspection
A814 01	12/12/16	SB	ADDRESS CONFIRMATION	_
	12/12/16	AP	57 WEXFORD DR FUQUAY	The second secon
				O AM SBENNETT
B103 02	12/12/16	BS	R*BLDG FOUND & TEMP S	
	12/12/16	AP	T/S: 12/09/2016 01:3	2 PM JBROCK 6 09:20 AM BSUTTON
B105 01	12/12/16	BS		17:00 VRU #: 002909349
	12/12/16	AP	T/S: 12/09/2016 01:3	2 PM JBROCK
R425 01	1/23/17	BS		TIME: 17:00 VRU #: 002923084
	1/23/17	DA	T/S: 01/20/2017 11:4 T/S: January 23, 2017	A AM DJOHNSON 09:03 AM BSUTTON a and firestop not done. No inspection
R425 02	1/24/17	BS	FOUR TRADE ROUGH IN	TIME: 17:00 VRU #: 002923589
	1/24/17	DA	T/S: January 24, 2017 1. Finish firestop. M under stairs, and unu	02:38 PM BSUTTON  Missing at kitchen pantry bottom plate, used holes at HVAC chase. 2. Need  3. Bath vent must go out to exterior.
			5	ast have stops removed before final. OK
I129 01	1/31/17	BS	R*INSULATION INSPECTI	ON TIME: 17:00 VRU #: 002925980
	1/31/17	DA	T/S: 01/27/2017 02:4	

PREPARED 4/17/17, 14:26:41 Harnett County

INSPECTION TICKET INSPECTOR: IVR

PAGE

DATE 4/18/17

ADDRESS . : 57 WEXFORD DR

SUBDIV: WEXFORD SUBDIVISION

CONTRACTOR : PUGH ENTERPRISES, LLC

PHONE : (919) 931-2581

OWNER . . : ALEXANDER ZACHARY A

PHONE :

PARCEL . . : 04-0665- - -0025- -22-

APPL NUMBER: 16-50038935 CP NEW RESIDENTIAL (SFD)

TYP/SQ	REQUESTED COMPLETED	RESULT	DESCRIPTION RESULTS/COMMENTS
			Firefoam Unused hole at top plate of HVAC chase upstairs.
			Firefoam water heater lines under stairs. All windows and
			doors must be foam sealed for insulation inspection. Remove
			plastic at unfaced insulation at front door. Plastic is not
			allowed behind drywall. Unfaced insulation is approved
	*		without a vapor barrier.
R425 03	1/31/17	BS	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002926004
	1/31/17	DA	T/S: 01/27/2017 02:42 PM JBROCK
			T/S: January 31, 2017 10:12 AM BSUTTON
			Firefoam Unused hole at top plate of HVAC chase upstairs.
			Firefoam water heater lines under stairs. All windows and
			doors must be foam sealed for insulation inspection. Remove
			plastic at unfaced insulation at front door. Plastic is not
			allowed behind drywall. Unfaced insulation is approved
	417		without a vapor barrier.
I129 02	2/02/17	BS	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002927747
	2/02/17	DA	T/S: 01/31/2017 03:56 PM DJOHNSON
			T/S: February 02, 2017 11:09 AM BSUTTON
R425 04	2/02/17	BS	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002927739
	2/02/17	DP	T/S: 01/31/2017 03:56 PM DJOHNSON
			T/S: February 02, 2017 11:08 AM BSUTTON
			Hole at HVAC chase still not firefoamed. Cannot use
			insulation to pack out windows and doors. It must be foam.
			Reinspection fee applies
I129 03	2/03/17	BS	R*INSULATION INSPECTION TIME: 17:00 VRU #: 002928562
	2/03/17	AP	T/S: 02/02/2017 12:31 PM DJOHNSON
			T/S: February 03, 2017 09:31 AM BSUTTON
R425 05	2/03/17	BS	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002928570
	2/03/17	AP	T/S: 02/02/2017 12:31 PM DJOHNSON
			T/S: February 03, 2017 09:31 AM BSUTTON
P307 01	2/13/17	BS	R*PLUMB WATER CONNECTION TIME: 17:00 VRU #: 002931871
	2/13/17	AP	T/S: 02/09/2017 02:56 PM DJOHNSON
			T/S: February 13, 2017 11:09 AM BSUTTON
R429 01		BS	FOUR TRADE FINAL TIME: 17:00 VRU #: 002951770
	3/30/17	DA	T/S: 03/29/2017 12:38 PM LBENNETT
			T/S: March 30, 2017 12:22 PM BSUTTON
			not ready. ok for power. need premise
R429 02	4/11/17	BS	FOUR TRADE FINAL TIME: 17:00 VRU #: 002957025
	4/11/17	DA	T/S: 04/10/2017 12:49 PM LBENNETT
			T/S: April 11, 2017 01:26 PM BSUTTON
			1. Sheetrock incomplete under stairs. must cover stair area
			also. 2. Need energy certificate. 3. Nail toenails at
			hangers at deck joists. 4. Strap exterior girder of deck to
			joist bolted to house. 5. Support HVAC drain under house
			with strap.
R429 03	4/18/17	Mer	FOUR TRADE FINAL TIME: 17:00 VRU #: 002959716
	4187	710)	T/S: 04/17/2017 09:46 AM LBENNETT