PREPARED 12/14/16, 14:14:24 Harnett County

INSPECTION TICKET INSPECTOR: IVR

PAGE

18 DATE 12/15/16

______ ADDRESS ..: 707 COKESBURY PARK LN

SUBDIV: COKESBURY PARK

CONTRACTOR : JLS HOMES, LLC

PHONE: (919) 422-7306 PHONE :

OWNER . . : JLS HOMES LLC PARCEL . .: 05-0635- - -0124- -22-

APPL NUMBER: 16-50039531 CP NEW RESIDENTIAL (SFD)

DIRECTIONS: T/S: 08/19/2016 12:50 PM JBROCK ----

COKESBURY PARK PH III #60 - 707

COKESBURY PARK LN

T/S: 11/04/2016 09:25 AM JFORBES ---

PREMISE NUMBER 55408100

STRUCTURE: 000 000 25X45 3BDR CRAWL W/ GARAGE & DECK

FLOOD ZONE . . . : FLOOD ZONE X

11/15/16

12/09/16

12/09/16

R425 01

ΑP

BS

DA

BEDROOMS 3000000.00 PROPOSED USE SFD SEPTIC - EXISTING? . . . : NEW TANK WATER SUPPLY : COUNTY

PERMIT: CPSF 00 CP * SFD REOUESTED INSP DESCRIPTION COMPLETED RESULT RESULTS/COMMENTS ______ B101 01 10/13/16 BS R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002883965 10/13/16 AP No tpole at site B103 01 11/03/16 BS R*BLDG FOUND & TEMP SVC POLE VRU #: 002893337 ΑP Call me at 919-291-0198 should you have questions. 11/03/16 Jared Hiegel T/S: November 03, 2016 08:19 AM BSUTTON ------Need a premise number for tpole ADDRESS CONFIRMATION TIME: 17:00 A814 02 11/03/16 SB VRU #: 002894079 707 COKESBURY PARK LN FUQUAY VARINA 27526 11/03/16 T/S: 11/03/2016 10:34 AM SBENNETT ------ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002893352 A814 01 11/03/16 SB 11/03/16 CA 707 COKEBURY PARK LN FUQUAY VARINA 27526 T/S: 11/03/2016 10:31 AM TWARD -----B105 01 11/09/16 BS 11/09/16 DA T/S: November 09, 2016 08:20 AM BSUTTON -----Load point squash blocks and between joist blocking not installed. See I joist layout and plan B105 02 11/10/16 BS R*OPEN FLOOR VRU #: 002896405 T/S: November 10, 2016 07:44 AM BSUTTON -----DP 11/10/16 No corrections made. \$50 re fee B105 03 R*OPEN FLOOR TIME: 17:00 VRU #: 002897783 11/15/16 BS

as well? Thanks,

Jared Hiegel

FOUR TRADE ROUGH IN VRU #: 002908218

T/S: 11/14/2016 08:51 AM DJOHNSON -----

T/S: November 15, 2016 08:10 AM BSUTTON -----

919-291-0198 we would like to meet you out there. Also is it safe to assume this inspection will cover the exterior

T/S: December 09, 2016 08:32 AM BSUTTON ------

If you could give us a call when your on the way,

PREPARED 12/14/16, 14:14:24 Harnett County

INSPECTION TICKET INSPECTOR: IVR

PAGE DATE 12/15/16

19

ADDRESS ..: 707 COKESBURY PARK LN

SUBDIV: COKESBURY PARK PHONE: (919) 422-7306

PHONE :

CONTRACTOR : JLS HOMES, LLC OWNER . . : JLS HOMES LLC PARCEL . . : 05-0635- - -0124- -22-

APPL NUMBER: 16-50039531 CP NEW RESIDENTIAL (SFD)

REQUESTED DESCRIPTION INSP

TYP/SQ COMPLETED RESULT RESULTS/COMMENTS -----

> Need 2 inch square plate washers at garage door. 2. Front door and right rear window header not framed per framing detail. 3.Window header in master undersized. 4. Need a hold down device at front bedroom window per plan. 5. Pony wall in crawlspace notched for HVAC linset. Needs strap or 16 gauge structural nailplate. 6. Fininsh install of

fireplace. OK to side.

R*INSULATION INSPECTION VRU #: 002910636

FOUR TRADE ROUGH IN VRU #: 002910644

----- COMMENTS AND NOTES -----

I129 01

12/15/16 R425 02 15/16

SOUTHERN ENGINEERS

James Herman, PE - Owner

Consulting Structural Engineers

TO: JLS HOMES, LLC P.O. BOX 696

HOLLY SPRINGS, NC 27540

***** FIELD CHANGE ORDER ******

VIA EMAIL: jhiegel@jlshomes.com

PROJECT #: 16-1427-A

PAGE: 1 of 1

DATE: December 13, 2016

LOCATION: Lot 60, Cokesbury Park

PLANS REF: "Plan 1563" by Design Meister

CS-PF Framing: Plans specify each end of (2)2x12 header above the front entry door and the back end of the (2)2x12 above the 2'-0" window to the rear of the fireplace extend to the wall corners. The header ends were not extended full to the exterior wall corner but terminated at the first full height wall stud (king stud) at the header ends.

Response: Be advised that the installed framing will be structurally acceptable provided the headers are strapped per details "E" and "F" on sheet SD as well as the addition of (2) CS16 straps at each end of the front entry header and back end window header at the fireplace. Additional Strapping shall extend from top plate across header and 20" down jack studs.

In closing, I trust that this letter fulfills your requirements at this time. Should you have any further questions, please do not hesitate to call.

Sincerely,

D. Mark Minshew, P.E. Southern Engineers, P.A. (License: C-1287)

Cc: wjh/ddm



3716 Benson Drive Raleigh, NC 27609 (919) 878-1617 (888) 200-7607 fax: (919) 873-9029 <u>www.southernengineers.com</u> email: <u>southern@southernengineers.com</u>