PREPARED 4/23/18, 13:58:22
Harnett County

INSPECTION TICKET INSPECTOR: IVR

PAGE DATE

4/24/18

ADDRESS . : 192 MILLWOOD LN

SUBDIV: ADAMS FARMS SUBDIVISION

CONTRACTOR:

PHONE :

continueron .

OWNER . . : COOPER ROBIN W JT W/ROS & WOOD

PARCEL . . : 04-0673- - -0121- -12-

APPL NUMBER: 18-50043039 CP NEW RESIDENTIAL (SFD)
DIRECTIONS: T/S: 01/08/2018 08:59 AM LLUCAS ----

TRAVEL HWY 210 TOWARDS HWY 55 IN ANGIER
- MILLWOOD LN WILL BE ON YOUR RIGHT THE LOT IS THE LAST ONE ON THE RIGHT THE ONLY LOT WITHOUT A HOUSE BUILT

STRUCTURE: 000 000 54X60 4BDR 3BTH W/GARAGE CRWL

FLOOD ZONE . . . : FLOOD ZONE X

WATER SUPPLY : COUNTY

WAIDA DOFFEL COUNT

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
A814 01	2/14/18	SB	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 003089042
	2/15/18	ĀР	192 MILLWOOD LN ANGIER 27501 T/S: 02/15/2018 11:04 AM SBENNETT
B101 01	2/20/18	MC	R*BLDG FOOTING / TEMP SVC POLE VRU #: 003091371
	2/20/18	AP	T/S: 02/20/2018 03:09 PM MCOOK
			1. did not inspect 5 deck footing will check at later time
B103 01	3/12/18	MC	R*BLDG FOUND & TEMP SVC POLE VRU #: 003099881
	3/12/18	AP	T/S: 03/12/2018 02:02 PM MCOOK
B101 02	3/15/18	MC	R*BLDG FOOTING / TEMP SVC POLE VRU #: 003101912
	3/15/18	AP .	T/S: 03/15/2018 01:43 PM MCOOK
			1. called in at 9:15am
B105 01	3/19/18	· MC	R*OPEN FLOOR VRU #: 003101841
	3/19/18	DA	T/S: 03/19/2018 02:23 PM MCOOK
			1. 31vl support on 2-2x10 header at crawl door , need
			engineer of record to look at to make sure load ok
R425 01	4/24/18	TI O	FOUR TRADE ROUGH IN VRU #: 003116860
	1 11	1)/	HVAC and Plumbing would like to be there during the
			inspection. If you could please text or call me Tuesday
			morning at 919-414-6534 so I can let them know an estimated
			time you will be at the house that would be great! Thank
			you

VIOLATION NOTICE

DO NOT REMOVE!


Harnett County Inspection Department


108 East Front Street • P.O. Box 65

Lillington, NC 27546

Job Name: COOPER Date: 4/24/08 Address: 192 M. HUND LN. Lot No.: Permit No.: 18-50043039 (Check Box for Violation) (Check Box for Violation) Footing Foundation Bldg. Elec. Plumb. Mech. Insul. Floor Fr. Floor Slab MFG. Home Modular Damp/Water Structural Wall Sheath. Other Proof. Violations Found: Official And And Barten where Ceguized Danstall And Cross Office of Strict Washers Structural Wall Sheath. Other Proof. Dissipation No.: 10 Lates At Han Bath At shower lines floor Dissipation No.: 10 Lates At Han Bath At shower lines floor District Own DN Water Lines. Code Enforcement Official Signature: Wall for the Structural Wall Structural Wall Structural Wall Structural Wall Structural Wall Shower Lines floor Date: 4/24/18	e e		i ilojie. (3	10/ 033-7323 L	vr. 1 - 1 av. (2	10/033-2/33					
Address: 192 Milluly LN. Lot No.: Permit No.: 18-50043039. (Check Box for Violation) [Footing Foundation Bldg. Elec. Plumb. Mech. Insul. Floor Fr. Floor Slab MFG. Home Modular Damp/Water Structural Wall Sheath. Other Proof. Violations Found: O Properly Not All (ATTACH) FREEBOX (2) Properly Flack Algorithms Found: D Install All (ATTACH) FREEBOX (2) Properly Flack Algorithms Found (3) Install All (ATTACH) FREEBOX (2) Properly Flack Algorithms Found (4) Insul. Floor Fr. [D Missing No. Plates At Hau Bath of slower lines floor [D ADR Fest Jow on water lines.	Job Name	: Coope	5 <u>C</u>			Date: 4/24/4	<u>'S</u>				
(Check Box for Violation) Footing Foundation Bldg. Elec. Plumb. Mech. Insul. Floor Fr. Floor Slab MFG. Home Modular Damp/Water Structural Wall Sheath. Other Proof. Violations Found: Officerly Notation (ATTACH) FREEDOX Officerly Flash Allow Front Porch 3) Anstall Art Add Barrer where required Danstall Art Rose Orner of Structural Where required Danstall Art Rose Orner fines floor (D) Missing NA Rest Ion DN Water Lines. Code Enforcement Official	Address:_	192 Mil	lway LN.	-,	·	· · · · · · · · · · · · · · · · · · ·		·			
(Check Box for Violation) Footing Foundation Bidg. Elec. Plumb. Mech. Insul. Floor Fr. Floor Slab MFG. Home Modular Damp/Water Structural Wall Sheath. Other Proof. Violations Found: @ Properly No. 1411 (ATTAH) FILES OX @ Properly Flash Allow Floor Porch @ Prostall Art ADI BARRIER where (equived @ twistall Art (Proc) 9/16+ stop @ twistall BARRIES informations (a) Missing NAI Plates At Han Bath At shower lines floor (b) ADI Fest Jon DN WAter Lines.	Lot No.: _		·								
Footing Foundation Bldg. Elec. Plumb. Mech. Insul. Floor Fr. Floor Slab MFG. Home Modular Damp/Water Structural Wall Sheath. Other Proof. Violations Found: O More the Notaria (ATTACH) FINEBOX (2) Properly Flash Alou-Front Porch (3) Install AT (ADM BARRITH Where (equived) O DINSTALL ALL (DREE) ON Set stop (3) Install BARRIES MASHINGS (b) Missing NAI Plates At Han Buth At shower lines floor O ADE FOST ION ON MATER LINES.				(Check Bo							
Floor Slab MFG. Home Modular Damp/Water Structural Wall Sheath. Other Proof. Violations Found: @ Properly No. LAIN (ATTAH) FREEBOX @ Properly Flash Alow Front Porch @ Pristall AN ADA BARRETA where required @ tristall AN AREA OTHER stop @ tristall BARRES wysterics @ missing NAI Plates At Han BAth At shower lines floor @ ADA test low on water lines.	_	☐ Foundation	Bldg.	Elec.	Plumb.	Mech.	Insul.	☐ Floor Fram			
Front Porch 3 Install All ADA BARRIER Where (equived a) toustall All CDRE DIAGRAS WAS AND BARRIES MYSTAIRS (a) Missing NAI Plates At HAM BATH At shower lines floor a) ADR test low DN WATER Lines.			☐ Modular	Damp/Water	☐ Structural	`□ Wall Sheath.	Other				
Front Porch 3 Install ALL ADA BARRIER Where (equived a) toustall ALL (EDRE) DIATES top 5) FOR the BARRIER MYSTAIRS (a) Missing NAIL Plates At HALL BATH AT shower lines floor a) ADR Test low on water lines.	Violations Fo	ound: <u>O Prop</u>	erly net	All (ATTA	H) FIRE	sox a Prop	ecly FlA	sh Along			
D tousfall Au Gree Oract stop 5 postall BAGALS upstairs (b) Missing NAI Plates At HAU BATH At shower lines floor (c) ADR test low DN water lines. Code Enforcement Official	Front &	Porch 3 I	NSTAIL AT	(ADR B	ARRITA	where le	quived				
Code Enforcement Official	D tols	Stall AU	REDE 1911	1 Ft stop	(E) \$N	STALL BAFFIE	s wester	9005			
Code Enforcement Official	(Mis	sida NAil	Plates A.	+ Hay	BAHL AT	shower li	110 5 f/0	0/			
Code Enforcement Official							· · · · · · · · · · · · · · · · · · ·				
			- DI (VVX.)		· · · · · · · · · · · · · · · · · · ·						
		·	- ":,,,,	' - 7/- , 							
			 			 					
	· · · · · · · · · · · · · · · · · · ·			· · · · · · · · · · · · · · · · · · ·	· .	· · · · · · · · · · · · · · · · · · ·	 ;, .				
				· · · · · · · · · · · · · · · · · · ·	,	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·	 , ,			
		<u> </u>		-··- -		·	·, · · · · · ·	•			
		· · · · · · · · · · · · · · · · · · ·	·	· 		·		·			
			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	· · · · · · · · · · · · · · · · · · ·	·	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·	to			
	Cada Enfarce	ament Official		•							
Signature: Date: 4/24/18			1/1/			· ·	/ / _				
	Signature: _	-1/1/2	4600	· · · · · · · · · · · · · · · · · · ·	····	Date: <u>//</u>	24/18	· · · · · · · · · · · · · · · · · · ·			

It is unlawful for any subcontractor, general contractor, or owner to cover or cause to be covered any part of the work with flooring, sheetrock, earth or other material until the proper inspector had ample time to approve the installation





Mark E. Jones, PE Structural Engineering and Design

March 20, 2018

Karen Wood 192 Millwood Lane Angier, NC 27501

Ref: Site Observations and Analysis

192 Millwood Lane

Angier, NC

Project No. 17-298

To Whom it may concern;

The above referenced site was observed on March 19, 2018 for the following items:

1. Verify header above crawl access.

Based on analysis, the conclusions regarding the condition(s) are:

1. The builder has provided a 2-2x10 header across the crawl access opening. There is floor and roof load as well as a point load at this location. The 2-2x10 header is adequate to support the imposed loads. No action is required.

Thank you for this opportunity to assist you. If you have any questions or need any further assistance, please do not hesitate to all CARO.

Respectfully.

Mark E. Jones, PE