

ON 5/17/05 I OBSERVED THAT A STORAGE BUILDING HAD BEEN
CONSTRUCTED AT THE REAR OF LOT 31. A UTILITY LINE HAD BEEN
TRENCHED FROM THE HOUSE TO THE BUILDING. ROCK FROM THE
DRAIN LINE WAS OBSERVED ON THE SURFACE. THE BLACK PIPE
WAS VISIBLE IN THE UTILITY TRENCH. IT HAD BEEN DAMAGED.
THERE WAS NO EFFLUENT SURFACING ON THIS DAY.

OLIVER TOLKSDORF