Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Sheet: Property ID: Lot #:

File #:

Code:

GH 2008-0008 Meyers Repair 473 Bisorla

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Applicant: 452 Meyer Owner: Date Evaluated: 11-5-20 Address: Proposed Facility: 555 Design Flow (.1949): 42 Property Size: Location of Site: Property Recorded: Public Individual ☐ Well Water Supply: ☐ Spring Other Evaluation Method: Auger Boring ☐ Pit ☐ Cut ☐ Industrial Process Type of Wastewater: Sewage ☐ Mixed

P									
R O F	.1940		SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
L E #	Landscape Position/ Slope %	Horizon Depth (In.)	.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1,2	4100	0-8	5L	Rochs					×
3		8-36	54L	CAL 5BL SP.	28" 31	36"+	_	Churles ATZG"	e5 e3
4									
	34								
					,				

Description	Initial	Repair System	Other Factors (.1946):
	System		Site Classification (.1948): PS
Available Space (.1945)			Evaluated By:
System Type(s)		25%/ (ON/A	Others Present:
Site LTAR		03	

COMMENTS: ____

LANDSCAPE POSITIONS	<u>GROUP</u>	<u>TEXTURES</u>	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

IV SIC-SILTY CLAY 0.4 - 0.1 C-CLAY

SC-SANDY CLAY

SC-SANDI CLAI

STRUCTURE
SG-SINGLE GRAIN
M- MASSIVE
CR-CRUMB
GR-GRANULAR
SBK-SUBANGULAR BLOCKY
ABK-ANGULAR BLOCKY
PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE

EXPANSIVE

