HARNETT COUNTY HEALTH DEPARTMENT ENVIRONMENTAL HEALTH SECTION 307 W. CORNELIUS HARNETT BLVD. LILLINGTON, NC 27546 910-893-7547 PHONE 910-893-9371 FAX

Application for Repair

01 2 11	4	EMAIL ADDRESS:		
NAME KUBY B. NE	cal	PHONE NUMBER 919	-812-4700	
NAME Ruby B. Ne	_atayette Ro	nd, Frquey Va	IVINI	
MAILING ADDRESS (IF DIFFFERENT	THAN PHYSICAL) 35 A	W. Myrtle Driv	le, Angier, NC	
IF RENTING, LEASING, ETC., LIST PROPERTY OWNER NAME				
N/A	NA	1443	2001	
SUBDIVISION NAME	LOT #/TRACT #	STATE RD/HWY	SIZE OF LOT/TRACT	
Type of Dwelling: [] Modular		Stick built [] Other		
Number of bedrooms 3 [] Basement No				
Garage: Yes [] No X Carport	Dishwasher: Yes X No	o [] Ga	rbage Disposal: Yes No. 1	
Water Supply: [] Private Well	[] Community System	, ,		
Directions from Lillington to your site: Hwy to Harth to Right on				
La fayotte Ros	40. Home	on Left		
	,			
In order for Environmental Health	to help you with your repo	ir. you will need to comply by	Completing the full t	
 A <u>"surveyed and recorded m</u> wells on the property by sho 	and deed to your proper	ty" must be attached to this appl	ication. Please inform us of any	
2 The outlet end of the tank an				

utlet end of the tank and the distribution box will need to be uncovered and property lines flagged. After the tank is uncovered, property lines flagged, underground utilities marked, and the orange sign has been placed, you will need to call us at 910-893-7547 to confirm that your site is ready for evaluation.

Your system must be repaired within 30 days of issuance of the Improvement Permit or the time set within receipt of a violation letter. (Whichever is applicable.)

By signing below, I certify that all of the above information is correct to the best of my knowledge. False information will result in the denial of the permit. The permit is subject to revocation if the site plan, intended use, or ownership changes.

HOMEOWNER INTERVIEW FORM

It is important that you answer the following questions for our inspectors. Please do not leave any blanks if possible, and answer all questions to the best of your ability. Thank You.

Have you received a violation letter for a failing system from our office? [] YES VI NO Also, within the last 5 years have you completed an application for repair for this site? [] YES [NO
Year home was built (or year of septic tank installation) 980
Installer of system
Septic Tank Pumper Not Remembered
Designer of System
However, Vacant Since 6/12
1. Number of people who live in house? # adults # children # total
2. What is your average estimated daily water usage?gallons/month or daycounty
water. If HCPU please give the name the bill is listed in Ruby B. Nea 1
3. If you have a garbage disposal, how often is it used? daily [] weekly [] monthly 4. When was the septic tank last pumped? Unknown How often do you have it pumped? unknown
F. Maria Land C.
5. If you have a dishwasher, how often do you use it? [X] daily [] every other day [] weekly 6. If you have a washing machine, how often do you use it? [X] daily [] every other day [] weekly [] monthly
7. Do you have a water softener or treatment system? [] YES [NO Where does it drain?
you have a water sortener of treatment system: [] 123 [/], NO where does it drain?
8. Do you use an "in tank" toilet bowl sanitizer? [] YES NO
9. Are you or any member in your household using long term prescription drugs, antibiotics or
chemotherapy?] [] YES [NO If yes please list
10. Do you put household cleaning chemicals down the drain? [] YES [NO If so, what kind?
11. Have you put any chemicals (paints, thinners, etc.) down the drain? [] YES [X] NO
12. Have you installed any water fixtures since your system has been installed? [] YES NO If yes,
please list any additions including any spas, whirlpool, sinks, lavatories, bath/showers, toilets
13. Do you have an underground lawn watering system? [] YES [X] NO
14. Has any work been done to your structure since the initial move into your home such as, a roof, gutter
drains, basement foundation drains, landscaping, etc? If yes, please list Water parted, gutters
15. Are there any underground utilities on your lot? Please check all that apply:
[>] Power [>] Phone [] Cable [] Gas [>] Water
16. Describe what is happening when you are having problems with your septic system, and when was this
C1 - 1' - 17
Home is vacant. Under Contract to Sell. Bill Hardree performed a septi inspection. Had Not Had any problem, Vacanted on 17. Do you notice the problem as being patterned or linked to a specific event (i.e., wash clothes, heavy 6/12
performed a septi inspection. Had Not Had any problem, Vacabled on
17. Do you notice the problem as being patterned or linked to a specific event (i.e., wash clothes, heavy 6)
rains, and household guests?) [] YES [NO If Yes, please list

Hardee's Septic Tank Service



1061 White Memorial Church Road Willow Spring, NC 27592 919-639-2060



September 17, 2013

Rich Vinesett Freedom Realty Firm 205 Braxton Village Way Holly Springs, NC 27540

Dear Mr. Vinesett:

At your request, an inspection was done of the septic system at 779 Lafayette Rd., Fuquay-Varina, on September 16, 2013.

The septic tank is located on the left side of the house (facing the house from the road), 12.5 feet almost straight out from the crawlspace vent at the left rear corner of the house. The influent end is about 22 inches below ground level. The effluent end is 25 inches below ground level. The entire tank is underneath the asphalt driveway. There is a round riser bringing the access at the influent end to level with the top of the asphalt. We had to chisel around the lid a little to get it off. There were several old cracks in the riser lid and the lid fell into four pieces when it was removed. There is no inner lid. The lid was pieced back together on the riser when we were finished. To get to the access lid at the effluent end, the asphalt had to be chopped out. It was several inches thick. The lid at the effluent end measures 7 inches by 25 inches. The tank sits perpendicular to the side wall of the house.

The tank consists of 2 compartments with a total estimated capacity of about 1200 gallons. Upon opening the accesses, it was noted that the level in the tank was about 21 inches below normal operating level. This could be due to the house having been vacant for an extended period of time or it could be due to a leak in the tank. The tank was filled to normal operating level. Normally, we return a couple of days later to recheck the level. If the level is still at normal, it indicates there is no leak. If the level is down, it indicates a leak in the tank. It was unnecessary to wait a couple of days. The level was down 6 inches in 3 hours. This indicates a significant leak. Patching the tank would not be practical, as there is no access to the effluent end of the tank. The influent end has 20 inches of sludge (mostly digested materials) in the bottom and no crust (mostly undigested and partially digested materials) floating on top. The effluent end has 16 inches of sludge in the bottom and no crust floating on top. These levels represent 39%

of the tank's operating capacity. Pumping is usually recommended when the total solids (sludge plus crust) reach no more than 25% of the tank's capacity.

The sanitary tee is constructed of concrete. It is in place and intact.

The distribution box (d-box) is located 2.5 feet almost straight out from the effluent end of the septic tank. It is 30 inches below ground level. It is also underneath the asphalt. It was accessed by chopping through the asphalt. The d-box is showing some slight deterioration but not enough to be a problem at this time. There is a single line coming into the d-box from the septic tank and there are 3 lines leaving it going to the drain field.

The 3 drain lines (aka field lines, leach lines, effluent lines, nitrification lines, etc.) lengths unknown (there is no Operations Permit available to indicate length or the direction they take), leave the d-box and run under the asphalt for a distance. They are fairly deep in the ground and no gravel drain lines were found with the probe. It is assumed that they curve around through the wooded section and into the front yard, although it has not been ascertained. To test the drain lines, water was run into the system, via water hose, at a measured rate of 5 gallons per minute for 60 minutes (300 gallons). The center line appears to be taking most of the water. The outer line (farthest from the house) is taking some water. The inner line (closest to the house) is taking very little water. Together, the lines took the 300 gallons but there is a chance that the center line may get hydraulically overloaded if there is much usage. Water from the drain lines is dispersed in 2 ways: evaporation and dispersal into the ground, eventually reaching plants and the water table. The pavement prevents any evaporation from taking place. The accessible areas where the drain lines could run were checked for seepage before, during, and after the test. None was noted.

Because we didn't have an Operations Permit to confirm our findings, such items as tank size and length of drain lines are estimated when possible. Sometimes drain lines take turns that are not easily found by probing but the estimates are done to the best of our ability.

It is recommended that a septic tank be pumped on a routine basis. There is some really informative literature on a Web site sponsored by NCSU and the NC Cooperative Extension Service. It can help you determine how often pumping should be done and it will probably answer any questions you might have about septic systems. You can link to it by accessing my Web site. http://www.hardees-septic-tank.com

Sincerely,

Bill Hardee


Bill Harde

Owner

On-site Wastewater Inspection

Pre-Inspection Contract, signed by Client is attached to In	spection	
Property Address 779 Lafam the Rd.		
FULUAY VARINA Street	MC St	27526
City	St	Zip
Client Name: RIGH VINESCH GREEDOM	REALTY FIRM	
Current owner of Record RUBY B. NEAL		
Date of Inspection: 9-16-13		
	attached swarn statement	hy owner or
owner's representative	attached sworn statement	by owner or
A/A Gallons per day for designed system size or number of bedrooms	as stated in available local	health department
information		
Inspection shall include any part of the system located more than 5 fee	t from the primary structu	re that is a part of
the operations permit		
Copy of Operations permit from Co	unty Environmental Healt	h Attached
Operations permit not available		
System requires a certified subsurface water pollution control system of	operator pursuant to G.S.	90A-44
Current Operator's Name	D	
Type of water supply Well Public Water Community Water	attached inot avail	able
Type of water supply 12 well 12 Public water [] Community water	Spring	
Location of Septic Tank and septic tank details:		
12.5 ft from house or structure		
120 ft from well if applicable		
ft from water line if applicable		
Nor makke Oft. from property line if said property lines are known or	marked	
11 2 K4 distance from finished grade to ton of tank or access rise	r .	
Access riser(s) Vyes no Describe WELLENTER	15 BALLY - NO INN	ER LIP,
Tank lids intact wes In no 2156K LID BRUKEN	J' EGGLUZNTLIDA	K
Tank has baffle wall Vyes on Describe condition of ba	offle wall: 6000	7
UNK. Inflow to tank is noted as sufficient		No. A. Marine Ma
Inflow to tank is noted as insufficient or blocked		
Water level in tank is relative to tank outlet 564 ATT	ALHOJLETTER	
Outlet T is present ves no Describe condition of Ou	itlet T: GONCAGTE -	IN PLACE & INTAC
Outlet has filter _ yes _ no Describe condition of filter:		
Effluent leaves the outlet Vyes no		
Roots present in tank yes Ino Describe extent of root	ts:	
Y&3 Evidence of tank leakage Describe: JEE ATTACHE	DLETTER	
Evidence of non-permitted connections, such as downspot	uts or sump pumps	
165 Connection present from house to tank		
Connection present from tank to next component		
29% Percentage of solids in tank		
Unable to locate tank. System inspection cannot be compl	ietea until tank is located	
Date tank was last pumped Wunknow		
Date tank was last pumped		tonk noode to be
pumped. Client has declined to have the tank pumped at inspection and h		
pumped. Chem has decimed to have the tank pumped at inspection and it	ereby acknowledges they i	iave so decimen.
Client Signature	Date	

Does system have pump tank? yes (complete blanks below) no	*
ft from house or structure	
ft from well or spring if applicable	
ft from water line if applicable	
ft. from property line if property lines are known or marked	
Distance from finished grade to top of tank or access riser	
Access risers in place yes no	
ft from septic tank	
Access risers in place Describe type:	
Describe condition of tank lids	
Location of control panel:	
Electrical connections are in place and properly grounded	
Audible and visible alarms (as applicable) work	
Pump turns on and effluent is delivered to next component	
Unable to operate pump due to lack of electricity at site at	
time of inspection	
Dispersal field: Type of system: Conventional Accepted Innovative Experimental Control	lled
Demonstration Pretreatment; Type of Pretreatment	and the second s
Brief Description of System Type GRAVITY FLOW	
NOT MARKEDIT. from property line if property lines are known or marked	
ft from septic/pump tank	
3 # of lines	
length of lines	
Evidence of past or current surfacing at time of inspection	
Briefly describe:	1 - 2 2 1
Evidence of traffic over the dispersal field DXNEWAY OVER SEPTIC TAI Vegetation, grading and drainage noted that may effect the condition of the system	UK / D-BOX /
vegetation, grading and drainage noted that may effect the condition of the system	IOT PRAIN LINES
system components Effluent is reaching the dispersal field SEE MTACHED LATTER	
Effluent is reaching the dispersal field The All All All All All All All All All Al	
Conditions present that prevented or hindered the inspection PAVED DRIVAVAY	
Conditions present that prevented or mindered the inspection PAVE-U VELVENTA	
Adverse conditions present that require repair or subsequent observation or warrants further evaluation by	the
local health department. Description of adverse condition: TANK LEAKING	the
Consequences of the adverse condition:	
Consequences of the auters committon.	
Client should contact County Environmental Health and/or a certified on-site wastewater contr	actor
	actor
Other pertinent facts noted during inspection: SEE ATTACHED LETTER	
other pertinent meta noted during inspection.	
	-
25	
	_
Inspector Name: WILLIAM R. HARDER, TK - Certification # 1087 I	
1300000 11 11 11 11 11	12 (6 -0)
Address 1061 UHITE MEMORIAL CHURCH Ry., WILLOW SPRING, 1	UC 27572
0.0 /20 0	-
Phone 919-639-2000	_
No representation, warranties or opinions are hereby given, written or expressed otherwise, as to the future	
performance of onsite wastewater system described herein. This onsite wastewater system inspection is a presen	itation
of system facts in place on date of inspection.	
Inspector Signature: William R. Hander Date	
Inspector Signature: Date Date	
	And the second s



S-H-HC-61



Zoning Overlay Results

O Zoom in O Zoom out O Pan



Map Scale = One Inch=71 feet

Owner Information:

PID

080653 0103

NAME

NEAL RUBY B

ADDRESS No Data

CITYST

FUQUAY VARINA, NC 27529

ACRES

1.26720802

Zoning Overlay Results

Zoning

Acres

445

RA-30 1.27

Download Results:

ZoningPolygon 080653 0103,zip

(2 tracks)



Zoning Overlay Results

O Zoom in O Zoom out O Pan



Map Scale = One Inch=55 feet

Owner Information:

PID 080653 0118 03
NAME NEAL RUBY B

ADDRESS No Data

CITYST FUQUAY VARINA, NC 27529

ACRES 0.5435811

Zoning Overlay Results

ID	Zoning	Acres
445	RA-30	0.54

Download Results:

ZoningPolygon 080653 0118 03.: