

- VISITED SITE ON 10/30/06. REPAIR SYSTEM BREAKING OUT IN 2 SPOTS. TURNED BULL RUN VALVE TO INITIAL SYSTEM. WILL MONITOR SYSTEMS
- SITE VISIT ON 2/1/07. REPAIR SYSTEM STILL BREAKING OUT IN 4 SPOTS. TURNED VALVE AGAIN TO VERIFY WHICH SYSTEM WAS BEING USED. WILL RETURN NEXT WEEK.
- SITE VISIT ON 2/7/07. SYSTEM STILL BREAKING OUT BY TREE. VALVE AT BM TURNED. ASKED HOME OWNER TO UNCOVER D-BOX WHICH WAS LOCATED FOR HER CALL US WHEN ITS OPEN.
- TALKED WITH MR. BECK ABOUT UNCOVERING D-BOX. HE SAID HE WOULD HAVE IT DONE BY THE FIRST OF THE WEEK OF 2/12 - 17/2007
- SITE VISIT ON 2/21/07. TANK & D-BOX COVERED UP. FAILING AREA OF 2ND SYSTEM HAD DRIED UP. ORIGINAL SYSTEM HAS WATER SITTING ON IT BUT NOT FAILING. MR. BECK WILL RELANDSCAPE SYSTEM TO KEEP WATER FROM PONING ON SYSTEM AREA.
- SITE VISIT MADE ON 6/6/07 IN RESPONSE TO COMPLAINT. BOTH DRAINFIELD AREAS WERE DRY