



Laura Eberle

163 Rawls Meadow Ln Fuquay-Varina, North Carolina 27526 TX Crew 1 Cody Clifton

Job Setup			
Deal ID (Base ID)	336383	CREW - Crew Lead & Uniform pics (entire crew on jobsite)	Cody Clifton
Customer Name	Laura Eberle	INITIAL CONTACT w/homeowner - Greet, job	Yes
ADDRESS	163 Rawls Meadow Ln Fuquay-Varina, North Carolina 27526	review and walk through completed? Note any initial homeowner concerns/issues?	
TIME of Arrival	6:30 am	PRE-EXISTING - issues, damages?	No
CREW NAME	TX Crew 1	REVIEW REQUEST invite sent to homeowner?	Yes
		Midpoint Inspection Required?	No

PLEASE ENTER THE DELIVERY TIME AND ANY SHIPMENT INFORMATION IN THE BLUE RAVEN APP

THIS NEEDS TO BE
COMPLETED PRIOR TO
STARTING THE JOB. PLEASE
ENTER THE DELIVERY TIME
AND ANY SHIPMENT
INFORMATION IN THE BLUE
RAVEN APP

original design?

No Answer Needed

Take a picture of all equipment installed on the home with the UL listing and part number.

Roof			
Design Error - Layout	No	ROOF CONDUIT - Is there roof conduit?	No
DESIGN CHANGES - any array layout changes?	No	Additional roof notes, AHJ requirement or other	
Attic			
Review the wire run. Did any of the staples pierce any part of the wire?	No	Engineering Error - Structure	No
		Were structural upgrades	No
WIRE SIZE - Is it different than	No	called out in the permit pack?	

Page 1 of 28 Report Created: 06/25/2021

Roof Leak Prevention			
Walk through the attic and check for shiners. Did you locate any?	No		
Electrical			
Electrician	Jimmy Hernandez	Is the utility Pacific Power or Rocky Mountain Power?	No
Is the install in Colorado?	No	ANY ELECTRICAL CHANGES from physical on site plans?	No
PLANS on-site?	Yes	Design Error - Electrical	No
Any red-line changes from the AHJ on physical plans?	Not on site	SPECIFIC AHJ REQUIREMENT NOTE	No
ANY ISSUES? code violations, clearance issues, design issues, material issues, etc.,	No	Is This an Illinois Install?	No
DIRECTORY PLACARD required?	No		
Thermostat			
THERMOSTAT installed?	Yes	Thermostat set up, ac/heat tested and explained how to	Yes
Was a PEK required?	No	use to homeowner?	
Completion			
Is it Monday?	No	Did any damage occur to the home during installation?	No
Job Completed?	Yes	Create separate Incident Report in Site Capture.	
What state is the installation taking place in	North Carolina	Final walk through complete? (Job site left super clean, gates closed all tools picked up)	Absolutely
explained why stickers not scanned in:		Did you complete a homeowner completion review	yes
SYSTEM COMMISSIONED? Did you commission and send	Yes	and walk through? Review and or review request	Yes
production report or verified production with ops?		completed?	1 50
Was a Wi-Fi connection achieved between the envoy and home network?	Yes	Were there any materials or parts you needed that were not on the BOM and should have	No
Did you install the system as originally designed?	Yes	been to complete the job? (e.g. low material qty, incorrect materials, missing materials)	
		Job notes, Issues, concerns, and any feed back?	

Page 2 of 28 Report Created: 06/25/2021

Office Feedback		
Feedback for Surveyor	Data Base Update	
Scheduling Issue		

Page 3 of 28 Report Created: 06/25/2021

Job Setup - CREW - Crew Lead & Uniform pics (entire crew on jobsite)




Job Setup - RAZ - Restricted area zones, safety cones and hazard tape. This needs to be completed prior to starting work.



TX Dallas Crew 1

Job Setup - JHA: Job Hazard Analysis photo (take a clear picture and make sure its all legible) This needs to be completed prior to starting work.



TX Dallas Crew 1 Loc: **35.5325**, **-78.8542**

Job Setup - LADDER: set up and secured (4 rungs over the eave, need to use a bullhorn or gutter guard and the ladder must be secured to the home.



TX Dallas Crew 1 Loc: **35.5326, -78.8542**

Page 4 of 28 Report Created: 06/25/2021

PLEASE ENTER THE DELIVERY TIME AND ANY SHIPMENT INFORMATION IN THE BLUE RAVEN APP - Photo of at least one module label



TX Dallas Crew 1 Loc: **35.9201, -78.8454**

Roof - FALL PRO - Every crew member working on the roof with a harness, rope and anchor.




TX Dallas Crew 1 Loc: **35.5326, -78.8541**

Roof - FALL PRO - Every crew member working on the roof with a harness, rope and anchor.



TX Dallas Crew 1 Loc: **35.5327**, **-78.8541**

Roof - FALL PRO - Every crew member working on the roof with a harness, rope and anchor.



TX Dallas Crew 1 Loc: **35.5326**, **-78.854**

Page 5 of 28 Report Created: 06/25/2021

Roof - ATTACHMENT LAYOUT - showing COMPLETE layouts, staggered attachments, span measurement and picture of the mount flashings installed correctly. (2 pics per array min)



Roof - ATTACHMENT LAYOUT - showing COMPLETE layouts, staggered attachments, span measurement and picture of the mount flashings installed correctly. (2 pics per array min)



Roof - ATTACHMENT LAYOUT - showing COMPLETE layouts, staggered attachments, span measurement and picture of the mount flashings installed correctly. (2 pics per array min)



TX Dallas Crew 1 Loc: **35.5327, -78.8541**

TX Dallas Crew 1


Roof - ATTACHMENT LAYOUT - showing COMPLETE layouts, staggered attachments, span measurement and picture of the mount flashings installed correctly. (2 pics per array min)



TX Dallas Crew 1 Loc: **35.5327**, **-78.854**

Page 6 of 28 Report Created: 06/25/2021

Roof - ATTACHMENT LAYOUT - showing COMPLETE layouts, staggered attachments, span measurement and picture of the mount flashings installed correctly. (2 pics per array min)



Roof - SOLADECK(s) wiring - EGC path to array, attic penetration, entries & exits (duct seal inside the soladeck where the romex connector is.)



TX Dallas Crew 1

Roof - SOLADECK(s) wiring - EGC path to array, attic penetration, entries & exits (duct seal inside the soladeck where the romex connector is.)



TX Dallas Crew 1 Loc: **35.5326, -78.854**

Roof - SOLADECK(s) wiring - EGC path to array, attic penetration, entries & exits (duct seal inside the soladeck where the romex connector is.)



TX Dallas Crew 1 Loc: **35.5327, -78.8541**

Page 7 of 28 Report Created: 06/25/2021

Roof - SOLADECK(s) wiring - EGC path to array, attic penetration, entries & exits (duct seal inside the soladeck where the romex connector is.)



Roof - SOLADECK(s) wiring - EGC path to array, attic penetration, entries & exits (duct seal inside the soladeck where the romex connector is.)



TX Dallas Crew 1 Loc: **35.5326**, **-78.854**

Roof - SOLADECK(s) wiring - EGC path to array, attic penetration, entries & exits (duct seal inside the soladeck where the romex connector is.)



TX Dallas Crew 1 Loc: **35.5327, -78.8541**

Roof - SOLADECK(s) wiring - EGC path to array, attic penetration, entries & exits (duct seal inside the soladeck where the romex connector is.)



TX Dallas Crew 1 Loc: **35.5326**, **-78.8543**

Page 8 of 28 Report Created: 06/25/2021

Roof - SOLADECK(s) wiring - EGC path to array, attic penetration, entries & exits (duct seal inside the soladeck where the romex connector is.)



TX Dallas Crew 1 Loc: **35.5326, -78.8541**

Roof - ARRAY(s) COMPLETED: showing COMPLETE overview of arrays multiple pics and location of soladek (3 pics per array min.) (no close up pics)



Roof - ARRAY(s) COMPLETED: showing COMPLETE overview of arrays multiple pics and location of soladek (3 pics per array min.) (no close up pics)



TX Dallas Crew 1 Loc: **35.5326, -78.854**

Roof - ARRAY(s) COMPLETED: showing COMPLETE overview of arrays multiple pics and location of soladek (3 pics per array min.) (no close up pics)



TX Dallas Crew 1

TX Dallas Crew 1 Loc: **35.5327, -78.8541**

Page 9 of 28 Report Created: 06/25/2021


Roof - ARRAY(s) COMPLETED: showing COMPLETE overview of arrays multiple pics and location of soladek (3 pics per array min.) (no close up pics)



Roof - ARRAY(s) COMPLETED: showing COMPLETE overview of arrays multiple pics and location of soladek (3 pics per array min.) (no close up pics)



Roof - WIRE MANAGEMENT Quality pics (need to show the entire array under the panel through pictures.absolutely no danglers)



TX Dallas Crew 1 Loc: **35.5327**, **-78.8541**

TX Dallas Crew 1 Loc: **35.5327, -78.854**

Roof - WIRE MANAGEMENT Quality pics (need to show the entire array under the panel through pictures.absolutely no danglers)



TX Dallas Crew 1 Loc: **35.5327**, **-78.8541**

Page 10 of 28 Report Created: 06/25/2021

Roof - Close up photos showing inside of every Soladeck



TX Dallas Crew 1 Loc: **35.5327, -78.854**

Roof - Close up photos showing inside of every Soladeck



Roof - Close up photos showing inside of every Soladeck



TX Dallas Crew 1 Loc: **35.5327**, **-78.854**

Roof - Close up photos showing inside of every Soladeck



TX Dallas Crew 1 Loc: **35.5326, -78.8541**

Page 11 of 28 Report Created: 06/25/2021

Roof - Picture showing Micro inverter label. Must show model type.



Roof - Grounding wire photos for each array. 1) Lift the panel and take a photo showing the panel label and ground lug attachment in one photo.



TX Dallas Crew 1 Loc: **35.5327, -78.8541**

Roof - The lowest point of the trim rail must be at least 2.5 inches off the roof surface. Take a photo with a ruler showing the rail is at least 2.5 inches off the roof surface.



TX Dallas Crew 1 Loc: **35.5327**, **-78.854**


Roof - Grounding wire photos for each array. 1) Lift the panel and take a photo showing the panel label and ground lug attachment in one photo.



TX Dallas Crew 1 Loc: **35.5327**, **-78.854**

Page 12 of 28 Report Created: 06/25/2021

Roof - Grounding wire photos for each array. 2) Step back and take a photo of the ground wire attached to the panel and open soladeck also including landmarks in the background (e.g. neighbors house, scenery, play sets) to prove the photo is on site



TX Dallas Crew 1 Loc: **35.5327**, **-78.854**

Roof - N - S Grounding: 1) Up close photo of N-S bonding clamp.




Loc: **35.5327**, **-78.8541**

Roof - Grounding wire photos for each array. 2) Step back and take a photo of the ground wire attached to the panel and open soladeck also including landmarks in the background (e.g. neighbors house, scenery, play sets) to prove the photo is on site



TX Dallas Crew 1 Loc: **35.5327**, **-78.8541**

Roof - N - S Grounding. 2) photo of both panel labels that are grounded by the displayed clamp.



TX Dallas Crew 1 Loc: **35.5327**, **-78.8541**

Page 13 of 28 Report Created: 06/25/2021

Roof - N - S Grounding. 2) photo of both panel labels that are grounded by the displayed clamp.



Roof - E - W Grounding: 1) Up close photo of a splice bar with the row of splices aligned in the background.



TX Dallas Crew 1 Loc: **35.5327, -78.8541**

Roof - N - S Grounding. 3) take a step back and take a photo of the same clamp with landmarks in the background to prove the photo is from site



TX Dallas Crew 1 Loc: **35.5326, -78.8541**

Roof - E - W Grounding: 2) Lift the two panels the splice bar grounded and take a photo of the labels.



TX Dallas Crew 1 Loc: **35.5327, -78.8541**

Page 14 of 28 Report Created: 06/25/2021

Roof - E - W Grounding: 2) Lift the two panels the splice bar grounded and take a photo of the labels.




TX Dallas Crew 1 Loc: **35.5327**, **-78.8541**

Roof - Trim Rail Grounding: 1) Take an up close photo of the trim rail bonding lug.



TX Dallas Crew 1 Loc: **35.5326, -78.8541**

Roof - E - W Grounding: 3) Take a step back and take a photo of the splice with landmarks in the background to prove the photo is from on site.



TX Dallas Crew 1

Roof - Trim Rail Grounding: 1) Take an up close photo of the trim rail bonding lug.



TX Dallas Crew 1 Loc: **35.5327, -78.8541**

Page 15 of 28 Report Created: 06/25/2021

Roof - Trim Rail Grounding: 1) Take an up close photo of the trim rail bonding



Roof - Trim Rail Grounding: 2) Take a step back and take a photo of the trim rail bonding lug with landmarks in the background to prove the photo is from onsite



TX Dallas Crew 1 Loc: **35.5326, -78.8541**

Roof - Trim Rail Grounding: 1) Take an up close photo of the trim rail bonding lug.



TX Dallas Crew 1 Loc: **35.5326, -78.854**

Roof - Trim Rail Grounding: 2) Take a step back and take a photo of the trim rail bonding lug with landmarks in the background to prove the photo is from onsite



TX Dallas Crew 1 Loc: **35.5327**, **-78.8541**

Page 16 of 28 Report Created: 06/25/2021

Roof - Photos of Label on Trunk Cable



TX Dallas Crew 1

Attic - WIRE RUN - All wire entrances showing the wire is stapled within 12" of entrance, full wire run with staples every 4 feet, penetration out of attic showing staples within 12" of the exit (pictures of the entire run, showing all the staples).



TX Dallas Crew 1 Loc: **35.5324, -78.8542**

Attic - WIRE RUN - All wire entrances showing the wire is stapled within 12" of entrance, full wire run with staples every 4 feet, penetration out of attic showing staples within 12" of the exit (pictures of the entire run, showing all the staples).



TX Dallas Crew 1 Loc: **35.5325**, **-78.8541**

Attic - WIRE RUN - All wire entrances showing the wire is stapled within 12" of entrance, full wire run with staples every 4 feet, penetration out of attic showing staples within 12" of the exit (pictures of the entire run, showing all the staples).



TX Dallas Crew 1 Loc: **35.5326, -78.8541**

Page 17 of 28 Report Created: 06/25/2021

Attic - WIRE RUN - All wire entrances showing the wire is stapled within 12" of entrance, full wire run with staples every 4 feet, penetration out of attic showing staples within 12" of the exit (pictures of the entire run, showing all the staples).



TX Dallas Crew 1 Loc: **35.5327**, **-78.854**

Attic - WIRE RUN - All wire entrances showing the wire is stapled within 12" of entrance, full wire run with staples every 4 feet, penetration out of attic showing staples within 12" of the exit (pictures of the entire run, showing all the staples).



TX Dallas Crew 1 Loc: **35.5326, -78.8541** Attic - WIRE RUN - All wire entrances showing the wire is stapled within 12" of entrance, full wire run with staples every 4 feet, penetration out of attic showing staples within 12" of the exit (pictures of the entire run, showing all the staples).



TX Dallas Crew 1 Loc: **35.5327**, **-78.854**

Attic - WIRE RUN - All wire entrances showing the wire is stapled within 12" of entrance, full wire run with staples every 4 feet, penetration out of attic showing staples within 12" of the exit (pictures of the entire run, showing all the staples).



TX Dallas Crew 1 Loc: **35.5325, -78.8542**

Page 18 of 28 Report Created: 06/25/2021

Attic - WIRE RUN - All wire entrances showing the wire is stapled within 12" of entrance, full wire run with staples every 4 feet, penetration out of attic showing staples within 12" of the exit (pictures of the entire run, showing all the staples).



TX Dallas Crew 1 Loc: **35.5326, -78.854**

Attic - WIRE RUN - All wire entrances showing the wire is stapled within 12" of entrance, full wire run with staples every 4 feet, penetration out of attic showing staples within 12" of the exit (pictures of the entire run, showing all the staples).




TX Dallas Crew 1 Loc: **35.5327, -78.8541** Attic - WIRE RUN - All wire entrances showing the wire is stapled within 12" of entrance, full wire run with staples every 4 feet, penetration out of attic showing staples within 12" of the exit (pictures of the entire run, showing all the staples).



TX Dallas Crew 1 Loc: **35.5326**, **-78.8541**

Attic - WIRE RUN - All wire entrances showing the wire is stapled within 12" of entrance, full wire run with staples every 4 feet, penetration out of attic showing staples within 12" of the exit (pictures of the entire run, showing all the staples).



TX Dallas Crew 1 Loc: **35.5329**, **-78.8539**


Page 19 of 28 Report Created: 06/25/2021

Attic - WIRE SIZE - Is it different than original design?



TX Dallas Crew 1 Loc: **35.5327, -78.8541**

Electrical - Photo or Screenshot of PV5 from Permit Pack



TX Dallas Crew 1

Roof Leak Prevention - Photo of at least 1 flashing with sealant applied in the correct U-shape



TX Dallas Crew 1 Loc: **35.5327, -78.8541**

Electrical - Picture showing electrical PPE in use (face shield, insulated gloves, hard hat, etc..)



TX Dallas Crew 1

Page 20 of 28 Report Created: 06/25/2021

Electrical - GROUND: main GEC (photo of MSP overview if none found)



TX Dallas Crew 1

Electrical - GROUND: main GEC (photo of MSP overview if none found)



TX Dallas Crew 1

Electrical - GROUND: main GEC (photo of MSP overview if none found)



TX Dallas Crew 1


Electrical - MSP: Detailed photos of breaker installed



TX Dallas Crew 1

Page 21 of 28 Report Created: 06/25/2021

Electrical - MSP: Detailed photos of breaker installed



TX Dallas Crew 1

Electrical - MSP - Photo of Entire Box After Interconnection



TX Dallas Crew 1

Electrical - MSP: Detailed photos of breaker installed



TX Dallas Crew 1

Electrical - SERIAL NUMBERS: clear photos of combiner/inverter and communication device serial numbers



TX Dallas Crew 1

Page 22 of 28 Report Created: 06/25/2021

Electrical - PV EQUIPMENT: all pv equipment installed and completed, wiring, EGC, entries/exits, open & closed boxes, completed overview.



TX Dallas Crew 1

Electrical - PV EQUIPMENT: Photos of fuse sizes and wire sizes



TX Dallas Crew 1

Electrical - PV EQUIPMENT: all pv equipment installed and completed, wiring, EGC, entries/exits, open & closed boxes, completed overview.



TX Dallas Crew 1

Electrical - PATH TO ARRAY ROOF/ATTIC: conduit run, j-box inside and out, sealed penetration, etc.,



TX Dallas Crew 1

Page 23 of 28 Report Created: 06/25/2021

Electrical - PATH TO ARRAY ROOF/ATTIC: conduit run, j-box inside and out, sealed penetration, etc.,



TX Dallas Crew 1

Electrical - PATH TO ARRAY ROOF/ATTIC: conduit run, j-box inside and out, sealed penetration, etc.,



TX Dallas Crew 1

Electrical - PATH TO ARRAY ROOF/ATTIC: conduit run, j-box inside and out, sealed penetration, etc.,



TX Dallas Crew 1

Electrical - PATH TO ARRAY ROOF/ATTIC: conduit run, j-box inside and out, sealed penetration, etc.,



TX Dallas Crew 1

Page 24 of 28 Report Created: 06/25/2021

Electrical - LABELS: photo of all labels installed, close up and overview (note if missing any)



TX Dallas Crew 1

Electrical - LABELS: photo of all labels installed, close up and overview (note if missing any)



TX Dallas Crew 1

Electrical - LABELS: photo of all labels installed, close up and overview (note if missing any)



TX Dallas Crew 1

Electrical - Photo of location of plans left on site



TX Dallas Crew 1

Page 25 of 28 Report Created: 06/25/2021

Thermostat - Photos of thermostat wiring before and after



TX Dallas Crew 1 Loc: **35.5326, -78.8548**

Thermostat - Photos of thermostat wiring before and after



TX Dallas Crew 1 Loc: **35.5326, -78.8547**

Thermostat - Photos of thermostat wiring before and after



TX Dallas Crew 1 Loc: **35.5326, -78.8546**

Thermostat - Thermostat turned on



TX Dallas Crew 1


Page 26 of 28 Report Created: 06/25/2021

Completion - STICKER MAP: Optimizer/micro-inverter stickers and sticker map showing layout and string map to j-box



TX Dallas Crew 1

Completion - Screenshot showing Wi-Fi connection



TX Dallas Crew 1

Completion - Screenshot of Panels Detected and Communicating in Enphase Installer Toolkit



TX Dallas Crew 1

Completion - Job notes, Issues, concerns, and any feed back?



TX Dallas Crew 1 Loc: **35.5325, -78.8541**

Page 27 of 28 Report Created: 06/25/2021

Completion - Job notes, Issues, concerns, and any feed back?



TX Dallas Crew 1 Loc: **35.5325, -78.8541**

Completion - Job notes, Issues, concerns, and any feed back?



TX Dallas Crew 1 Loc: **35.5325, -78.8541**

Completion - Job notes, Issues, concerns, and any feed back?



TX Dallas Crew 1 Loc: **35.5325, -78.8541**

Completion - Job notes, Issues, concerns, and any feed back?



TX Dallas Crew 1 Loc: **35.5325, -78.8541**

Page 28 of 28 Report Created: 06/25/2021