



of the wire?

Efrain Carmona Mote

580 valley Oak Dr BunnLevel, NC 28328

Job Setup			
Customer Name	Efrain Carmona Mote	Pre-Existing - issues, damages?	Yes
Address	580 valley Oak Dr BunnLevel, NC 28328	Pre-existing issues notes and	getter in back yard
Initial Contact w/homeowner -	Yes	pictures	
Greet, job review and walk through completed? Note any initial homeowner concerns /issues?		Pre-existing issues: Homeowner notified?	Yes
Roof			
	Yes		
Was conduit run on the roof?	Yes		
Roof Was conduit run on the roof? Attic Was the wire run done internally?	Yes	Wire size and type installed:	10 awg

Page 1 of 34 Report Created: 10/25/2022

Roof Leak Prevention			
Were there any misses while finding rafters?	No		
Electrical			
Electrician	Jonathan Garrison	Directory Placard required?	No
Was this a battery installation?	No	Is this a TECO - FL installation	No
Completion			
Job Completed?	Yes	Did any damage occur to the home during installation?	No
Was a Wi-Fi connection achieved?	No	Did you complete a homeowner completion review and walk through?	yes

Page 2 of 34 Report Created: 10/25/2022

Job Setup / Location- Show the front of home with street number clearly visible $\,$



JonathanG Loc: **35.2986, -78.9827**

Roof / Attachment Layout - showing COMPLETE layouts, staggered attachments, span measurement. (2 pics per array min) $\,$




MartinR Loc: **35.4085, -80.7122**

 $\mbox{Roof}\,/\,\mbox{Mount Installation}$ - Need to show the correct sealing technique for at least one solar mount.



MartinR Loc: **35.4085, -80.7122**

Roof / Attachment Layout - showing COMPLETE layouts, staggered attachments, span measurement. (2 pics per array min) $\,$



MartinR Loc: **35.4085, -80.7122**

Page 3 of 34 Report Created: 10/25/2022

Roof / Module Label - Close up picture. This needs to be crystal clear



JonathanG Loc: 35.3064, -78.9892

Roof / Module Label - Close up picture. This needs to be crystal clear



JonathanG Loc: **35.3064**, **-78.9892**

Roof / Module Label - Close up picture. This needs to be crystal clear




JonathanG Loc: 35.3064, -78.9892

Roof / Module Attachments - need to show modules are properly secured to racking.



MartinR Loc: **35.4085**, **-80.7122**

 $\ensuremath{\mathsf{Roof}}$ / $\ensuremath{\mathsf{Module}}$ Attachments - need to show modules are properly secured to racking.



MartinR Loc: **35.4085**, **-80.7122**

Roof / Grounding: 1) Take an up close photo of the rail bonding lug.



Loc: **35.4084**, **-80.7122**

 $\mbox{Roof}\,/\,\mbox{MLPE}$ (micro inverter/optimizer) serial number, must include model number as well.



MartinR Loc: **35.4085, -80.7122**

 $\mbox{Roof}\xspace/\mbox{ Roof conduit photos-}\xspace$ Entire conduit run to be shown along with proper supports.



JonathanG Loc: **35.3171, -78.9926**

Page 5 of 34 Report Created: 10/25/2022

 $\mbox{Roof}\,/\,\mbox{Roof}$ conduit photos- Entire conduit run to be shown along with proper supports.



JonathanG Loc: **35.3114, -78.9912**

Roof / Conduit Pentration- Provide a picture showing the open conduit entrance demonstrating proper conductor strain relief, weather protection, and conduit stability.



JonathanG Loc: **35.3143**, **-78.9919**

 $\mbox{Roof}\,/\,\mbox{Roof}$ conduit photos- Entire conduit run to be shown along with proper supports.



JonathanG Loc: **35.3114, -78.9912**

Roof / Photos of Label on Trunk Cable/PV Wire



MartinR Loc: **35.4085, -80.7122**

Page 6 of 34 Report Created: 10/25/2022

Roof / Photos of Label on Trunk Cable/PV Wire



MartinR Loc: **35.4085, -80.7122**

Roof / Rooftop Junction Box - EGC path to array, attic penetration, entries & exits. (If penetrating the roof to run through the attic, the transition from attic to roof needs to be sealed with duct seal.)



MartinR Loc: **35.4085**, **-80.7122**

Roof / Rooftop Junction Box - EGC path to array, attic penetration, entries & exits. (If penetrating the roof to run through the attic, the transition from attic to roof needs to be sealed with duct seal.)



MartinR Loc: **35.4085, -80.7122**

Roof / Rooftop Junction Box - EGC path to array, attic penetration, entries & exits. (If penetrating the roof to run through the attic, the transition from attic to roof needs to be sealed with duct seal.)



MartinR Loc: **35.4085, -80.7122**

Page 7 of 34 Report Created: 10/25/2022

Roof / Rooftop Junction Box - EGC path to array, attic penetration, entries & exits. (If penetrating the roof to run through the attic, the transition from attic to roof needs to be sealed with duct seal.)




MartinR Loc: **35.4085**, **-80.7122**

Roof / Completed Array(s) showing COMPLETE overview of arrays multiple pics and location of rooftop junction box (3 pics per array min.) (no close up pics)



MartinR Loc: **35.4085, -80.7122**

Roof / Completed Array(s) showing COMPLETE overview of arrays multiple pics and location of rooftop junction box (3 pics per array min.) (no close up nics)



MartinR Loc: **35.4085**, **-80.7122**

Roof / Completed Array(s) showing COMPLETE overview of arrays multiple pics and location of rooftop junction box (3 pics per array min.) (no close up pics)



MartinR Loc: **35.4085**, **-80.7122**

Page 8 of 34 Report Created: 10/25/2022

Roof / Completed Array(s) showing COMPLETE overview of arrays multiple pics and location of rooftop junction box (3 pics per array min.) (no close up nics)



Roof / Completed Array(s) showing COMPLETE overview of arrays multiple pics and location of rooftop junction box (3 pics per array min.) (no close up pics)



MartinR

Loc: 35.4085, -80.7122

MartinR

Loc: 35.4085, -80.7122

Roof / Completed Array(s) showing COMPLETE overview of arrays multiple pics and location of rooftop junction box (3 pics per array min.) (no close up pics)



Loc: **35.4085**, **-80.7122**

Roof / Completed Array(s) need to show tilt of each array completed.



JonathanG

Loc: 35.3223, -78.9927

Page 9 of 34 Report Created: 10/25/2022

Roof / Completed Array(s) need to show tilt of each array completed.



Loc: **35.3223**, **-78.9927**

Roof / Completed Array(s) need to show tilt of each array completed.



JonathanG Loc: **35.3223, -78.9927**

Roof / Completed Array(s) need to show tilt of each array completed.



Loc: **35.3223**, **-78.9927**

Roof $\slash\hspace{-0.6em}$ Wire Management - Quality pictures (need to show the entire array under the panel through pictures.absolutely no dangling wires)



MartinR

Loc: **35.4084**, **-80.7122**

Roof / Wire Management - Quality pictures (need to show the entire array under the panel through pictures.absolutely no dangling wires)



Roof / Wire Management - Quality pictures (need to show the entire array under the panel through pictures.absolutely no dangling wires)



MartinR Loc: **35.4084, -80.7122**

MartinR

Loc: 35.4084, -80.7122

Attic / Wire Run - All wire entrances showing the wire is stapled within 12" of entrance, full wire run with staples every 4 feet, penetration out of attic showing staples within 12" of the exit (pictures of the entire run, showing all the staples).



JonathanG Loc: **35.3404**, **-79.0476**

Attic / Wire Run - All wire entrances showing the wire is stapled within 12" of entrance, full wire run with staples every 4 feet, penetration out of attic showing staples within 12" of the exit (pictures of the entire run, showing all the staples).



JonathanG Loc: **35.3404**, **-79.0476**

Page 11 of 34 Report Created: 10/25/2022



JonathanG Loc: **35.3404**, **-79.0476**

Attic / Wire Run - All wire entrances showing the wire is stapled within 12" of entrance, full wire run with staples every 4 feet, penetration out of attic showing staples within 12" of the exit (pictures of the entire run, showing all the staples).



JonathanG Loc: **35.3404, -79.0476**

Attic / Wire Run - All wire entrances showing the wire is stapled within 12" of entrance, full wire run with staples every 4 feet, penetration out of attic showing staples within 12" of the exit (pictures of the entire run, showing all the staples).



JonathanG Loc: **35.3404**, **-79.0476**

Attic / Wire Run - All wire entrances showing the wire is stapled within 12" of entrance, full wire run with staples every 4 feet, penetration out of attic showing staples within 12" of the exit (pictures of the entire run, showing all the staples).



JonathanG Loc: **35.3404**, **-79.0476**

Page 12 of 34 Report Created: 10/25/2022



Attic / Wire Run - All wire entrances showing the wire is stapled within 12" of entrance, full wire run with staples every 4 feet, penetration out of attic showing staples within 12" of the exit (pictures of the entire run, showing all the staples).



JonathanG Loc: **35.3404**, **-79.0476**

Attic / Wire Run - All wire entrances showing the wire is stapled within 12" of entrance, full wire run with staples every 4 feet, penetration out of attic showing staples within 12" of the exit (pictures of the entire run, showing all the staples).



JonathanG Loc: **35.3404**, **-79.0476** JonathanG Loc: **35.3404**, **-79.0476**

Attic / Wire Run - All wire entrances showing the wire is stapled within 12" of entrance, full wire run with staples every 4 feet, penetration out of attic showing staples within 12" of the exit (pictures of the entire run, showing all the staples).



JonathanG Loc: **35.3404**, **-79.0476**

Page 13 of 34 Report Created: 10/25/2022



Attic / Wire Run - All wire entrances showing the wire is stapled within 12" of entrance, full wire run with staples every 4 feet, penetration out of attic showing staples within 12" of the exit (pictures of the entire run, showing all the staples).



JonathanG Loc: **35.3404**, **-79.0476**

Attic / Wire Run - All wire entrances showing the wire is stapled within 12" of entrance, full wire run with staples every 4 feet, penetration out of attic showing staples within 12" of the exit (pictures of the entire run, showing all the staples).



JonathanG Loc: **35.3404**, **-79.0476**

Attic / Wire Run - All wire entrances showing the wire is stapled within 12" of entrance, full wire run with staples every 4 feet, penetration out of attic showing staples within 12" of the exit (pictures of the entire run, showing all the staples).



JonathanG Loc: **35.3404, -79.0476** JonathanG Loc: **35.3404, -79.0476**

Page 14 of 34 Report Created: 10/25/2022



JonathanG Loc: **35.3404**, **-79.0476**

Electrical / Path To Array Roof/Attic - conduit run, j-box inside and out, sealed penetration, etc.,



JonathanG Loc: **35.3307**, **-78.9951**

Attic / Wire Run - All wire entrances showing the wire is stapled within 12" of entrance, full wire run with staples every 4 feet, penetration out of attic showing staples within 12" of the exit (pictures of the entire run, showing all the staples).



JonathanG Loc: **35.3404, -79.0476**

 ${\bf Electrical\ /\ Path\ To\ Array\ Roof/Attic\ -\ conduit\ run,\ j\text{-}box\ inside\ and\ out,\ sealed\ penetration,\ etc.,}$



JonathanG Loc: **35.3307**, **-78.9951**

Page 15 of 34 Report Created: 10/25/2022

Electrical / Path To Array Roof/Attic - conduit run, j-box inside and out, sealed penetration, etc.,



Electrical / Path To Array Roof/Attic - conduit run, j-box inside and out, sealed penetration, etc.,



JonathanG Loc: **35.3307**, **-78.9951**

Electrical / Path To Array Roof/Attic - conduit run, j-box inside and out, sealed penetration, etc.,



JonathanG Loc: **35.3307**, **-78.9951**

Electrical / Path To Array Roof/Attic - conduit run, j-box inside and out, sealed penetration, etc.,



JonathanG Loc: **35.3307**, **-78.9951**

Page 16 of 34 Report Created: 10/25/2022

Electrical / Path To Array Roof/Attic - conduit run, j-box inside and out, sealed penetration, etc.,



Electrical / Path To Array Roof/Attic - conduit run, j-box inside and out, sealed penetration, etc.,



Electrical / Path To Array Roof/Attic - conduit run, j-box inside and out, sealed penetration, etc.,



JonathanG Loc: **35.3307, -78.9951**

JonathanG Loc: **35.3307, -78.9951**

Electrical / Path To Array Roof/Attic - conduit run, j-box inside and out, sealed penetration, etc.,



JonathanG

Loc: 35.3307, -78.9951

Page 17 of 34 Report Created: 10/25/2022

Electrical / Path To Array Roof/Attic - conduit run, j-box inside and out, sealed penetration, etc.,



Electrical / Path To Array Roof/Attic - conduit run, j-box inside and out, sealed penetration, etc.,



JonathanG Loc: **35.3307**, **-78.9951**

Electrical / Path To Array Roof/Attic - conduit run, j-box inside and out, sealed penetration, etc.,



Electrical / Path To Array Roof/Attic - conduit run, j-box inside and out, sealed penetration, etc.,



JonathanG

Loc: **35.3307**, **-78.9951**

JonathanG

Loc: **35.3307, -78.9951**

Page 18 of 34 Report Created: 10/25/2022

Electrical / Path To Array Roof/Attic - conduit run, j-box inside and out, sealed penetration, etc.,



JonathanG Loc: **35.3265, -78.9938**

 ${\bf Electrical\ /\ GEC\ (Grounding\ Electrode\ Conductor) - main\ GEC\ (photo\ of\ the\ home's\ grounding\ system,\ MSP\ overview\ if\ none\ found)}$




JonathanG Loc: **35.3357**, **-79.034**

Electrical / Path To Array Roof/Attic - conduit run, j-box inside and out, sealed penetration, etc.,



JonathanG Loc: **35.3265, -78.9938**

Electrical / GEC (Grounding Electrode Conductor) - main GEC (photo of the home's grounding system, MSP overview if none found) $\frac{1}{2} \frac{1}{2} \frac{1}$



JonathanG Loc: **35.3357**, **-79.034**


Page 19 of 34 Report Created: 10/25/2022

Electrical / GEC (Grounding Electrode Conductor) - main GEC (photo of the home's grounding system, MSP overview if none found)



JonathanG Loc: **35.3357**, **-79.034**

Electrical / GEC (Grounding Electrode Conductor) - main GEC (photo of the home's grounding system, MSP overview if none found)



JonathanG Loc: **35.3357**, **-79.034**

Electrical / GEC (Grounding Electrode Conductor) - main GEC (photo of the home's grounding system, MSP overview if none found)



JonathanG Loc: **35.3357**, **-79.034**

Electrical / GEC (Grounding Electrode Conductor) - main GEC (photo of the home's grounding system, MSP overview if none found)



JonathanG Loc: **35.3357**, **-79.034**

Page 20 of 34 Report Created: 10/25/2022

Electrical / GEC (Grounding Electrode Conductor) - main GEC (photo of the home's grounding system, MSP overview if none found)



JonathanG Loc: **35.3357**, **-79.034**

Electrical / GEC (Grounding Electrode Conductor) - main GEC (photo of the home's grounding system, MSP overview if none found) $\frac{1}{2} \frac{1}{2} \frac{1}$



JonathanG Loc: **35.3357**, **-79.034**

Electrical / GEC (Grounding Electrode Conductor) - main GEC (photo of the home's grounding system, MSP overview if none found)



JonathanG Loc: **35.3357**, **-79.034**

Electrical / GEC (Grounding Electrode Conductor) - main GEC (photo of the home's grounding system, MSP overview if none found)



JonathanG Loc: **35.3357**, **-79.034**

Page 21 of 34 Report Created: 10/25/2022

Electrical / GEC (Grounding Electrode Conductor) - main GEC (photo of the home's grounding system, MSP overview if none found)



Electrical / GEC (Grounding Electrode Conductor) - main GEC (photo of the home's grounding system, MSP overview if none found)



JonathanG Loc: 35.3357, -79.034

JonathanG Loc: 35.3357, -79.034

Electrical / GEC (Grounding Electrode Conductor) - main GEC (photo of the home's grounding system, MSP overview if none found) $\frac{1}{2} \frac{1}{2} \frac{1}$



Electrical / GEC (Grounding Electrode Conductor) - main GEC (photo of the home's grounding system, MSP overview if none found)



JonathanG

Loc: **35.3357, -79.034**

JonathanG

Loc: 35.3357, -79.034

Page 22 of 34 Report Created: 10/25/2022

Electrical / GEC (Grounding Electrode Conductor) - main GEC (photo of the home's grounding system, MSP overview if none found)



Electrical / MSP (Main Service Panel): Detailed photos of breaker installed



JonathanG Loc: **35.3357**, **-79.034**

Electrical / MSP (Main Service Panel): Detailed photos of breaker installed



JonathanG Loc: **35.3338, -78.9959**

Electrical / MSP (Main Service Panel): Detailed photos of breaker installed



JonathanG Loc: **35.3417**, **-78.998**

Page 23 of 34 Report Created: 10/25/2022

Electrical / MSP (Main Service Panel): Detailed photos of breaker installed




Electrical / MSP (Main Service Panel): Detailed photos of breaker installed




JonathanG Loc: **35.3417**, **-78.998**

Electrical / MSP (Main Service Panel): Detailed photos of breaker installed



JonathanG Loc: **35.3338, -78.9959**

Electrical / MSP (Main Service Panel): Detailed photos of breaker installed



JonathanG Loc: **35.3417**, **-78.998**

Page 24 of 34 Report Created: 10/25/2022

Electrical / MSP (Main Service Panel): Detailed photos of breaker installed



Electrical / MSP (Main Service Panel): Detailed photos of breaker installed



JonathanG Loc: **35.3417**, **-78.998**

Electrical / MSP (Main Service Panel): Detailed photos of breaker installed



Loc: **35.3417**, **-78.998**

Electrical / MSP (Main Service Panel): Detailed photos of breaker installed



JonathanG Loc: **35.3338, -78.9959**

Page 25 of 34 Report Created: 10/25/2022

Electrical / MSP (Main Service Panel): Detailed photos of breaker installed



Electrical / MSP (Main Service Panel): Detailed photos of breaker installed



JonathanG Loc: **35.3417**, **-78.998**

Electrical / MSP (Main Service Panel): Detailed photos of breaker installed



JonathanG Loc: **35.3338, -78.9959**


Electrical / MSP (Main Service Panel): Detailed photos of breaker installed



JonathanG Loc: **35.3417**, **-78.998**

Page 26 of 34 Report Created: 10/25/2022

Electrical / MSP (Main Service Panel): Detailed photos of breaker installed



JonathanG Loc: **35.3417**, **-78.998**

Electrical / MSP (Main Service Panel) - Photo of Entire Box After




JonathanG Loc: **35.337, -78.9968**

Electrical / MSP (Main Service Panel): Detailed photos of breaker installed



JonathanG Loc: **35.3338, -78.9959**


Electrical / MSP (Main Service Panel) - Photo of Entire Box After Interconnection



JonathanG Loc: **35.337**, **-78.9968**

Page 27 of 34 Report Created: 10/25/2022

Electrical / MSP (Main Service Panel) - Photo of Entire Box After Interconnection



JonathanG Loc: **35.337**, **-78.9968**

Electrical / MSP (Main Service Panel) - Photo of Entire Box After Interconnection



JonathanG Loc: **35.337, -78.9968**

Electrical / MSP (Main Service Panel) - Photo of Entire Box After Interconnection



JonathanG Loc: **35.337**, **-78.9968**

Electrical / MSP (Main Service Panel) - Photo of Entire Box After Interconnection



JonathanG Loc: **35.337**, **-78.9968**

Page 28 of 34 Report Created: 10/25/2022

Electrical / MSP (Main Service Panel) - Photo of Entire Box After Interconnection



Electrical / PV Equipment - all PV equipment installed and completed, wiring, EGC (Solar Ground), entries/exits, open & closed boxes, completed overview.



JonathanG Loc: **35.3424, -79.0041**

Electrical / Serial Numbers - clear photos of combiner/inverter and communication device serial numbers



JonathanG Loc: **35.3427, -79.0011**


Electrical / AC Disconnect - Photos of fuse sizes and wire sizes



JonathanG Loc: **35.342**, **-79.0055**

Page 29 of 34 Report Created: 10/25/2022

Electrical / AC Disconnect - Photos of fuse sizes and wire sizes




JonathanG Loc: **35.342**, **-79.0055**

Electrical / AC Disconnect - Photos of fuse sizes and wire sizes



JonathanG Loc: **35.342, -79.0055**

Electrical / AC Disconnect - Photos of fuse sizes and wire sizes



JonathanG Loc: **35.342**, **-79.0055**

Electrical / AC Disconnect - Photos of fuse sizes and wire sizes



JonathanG Loc: **35.342**, **-79.0055**

Page 30 of 34 Report Created: 10/25/2022

Electrical / AC Disconnect - Photos of fuse sizes and wire sizes



JonathanG Loc: **35.342**, **-79.0055**

Electrical / AC Disconnect - Photos of fuse sizes and wire sizes



JonathanG Loc: **35.342**, **-79.0055**

Electrical / Labels - photo of all labels installed, close up and overview (note if missing any)



JonathanG Loc: **35.3379**, **-79.0169**

Electrical / Labels - photo of all labels installed, close up and overview (note if missing any)



JonathanG Loc: **35.3379**, **-79.0169**

Page 31 of 34 Report Created: 10/25/2022

Electrical / Labels - photo of all labels installed, close up and overview (note if missing any)



JonathanG Loc: **35.3379**, **-79.0169**

Electrical / Labels - photo of all labels installed, close up and overview (note if missing any)



JonathanG Loc: **35.3379, -79.0169**

Electrical / Labels - photo of all labels installed, close up and overview (note if missing any)



JonathanG Loc: **35.3379**, **-79.0169**

Electrical / Labels - photo of all labels installed, close up and overview (note if missing any)



JonathanG Loc: **35.3379**, **-79.0169**


Page 32 of 34 Report Created: 10/25/2022

Electrical / Photo of location of plans left on site




JonathanG Loc: **35.3405, -79.0136**

 ${\bf Completion\,/\,STICKER\,\,MAP:\,\,Optimizer/micro-inverter\,\,stickers\,\,and\,\,sticker\,\,map\,\,showing\,\,layout\,\,and\,\,string\,\,map\,\,to\,\,j\text{-box}}$



MartinR Loc: **35.4083**, **-80.7122**

Completion / STICKER MAP: Optimizer/micro-inverter stickers and sticker map showing layout and string map to j-box



Loc: **35.4087**, **-80.7121**

Completion / Screenshot of Panels Detected and Communicating in Commissioning App (Solaredge/Enphase)



JonathanG

Loc: **35.4085, -80.7122**


Page 33 of 34 Report Created: 10/25/2022

Completion / Screenshot of Panels Detected and Communicating in Commissioning App (Solaredge/Enphase)




JonathanG Loc: **35.4086, -80.7121**

Completion / Screenshot of Panels Detected and Communicating in Commissioning App (Solaredge/Enphase)



Thompson and Son Energy Solutions LLC

Completion / Screenshot of Panels Detected and Communicating in Commissioning App (Solaredge/Enphase)



Thompson and Son Energy Solutions LLC

Completion / Clear picture showing cell unit serial number



JonathanG Loc: **35.4084, -80.7122**

Page 34 of 34 Report Created: 10/25/2022