

Bradley Hocevar

257 Beacon HI Rd , Lillington, NC 27546 08/10/2024

Project Information			
Project Name	Bradley Hocevar	Customer Phone Number	(850) 381-5738
Customer Address	257 Beacon HI Rd , Lillington, NC 27546	Installation Date	08/10/2024
Job Check In			
Was the customer home for install?	Yes	MSP Check - Red Flags Present?	No
Did the Customer agree to the equipment location?	Yes	Does Structure Match Plans?	Yes
Roof Check - Red Flags Present?	No	Structural Check - Red Flags Present?	No
MSP Check - Does MSP Match Plans?	Yes	Miscellaneous - Red Flags Present?	No
Project Completion Photos			
Site and Safety			
Rooftop Installation			
Roof Type	Comp Shingle	Does this project have a attic run?	Yes
Comp Shingle Mounting Method	Rail-less	Conduit Transition	Attic Run Only

Electrical Installation

Tilt Legs?

Railess - Flashed or Flashless

Does the Job Require Unirac

Flashless

No

Page 1 of 29 Report Created: 08/12/2024

Does this project include a

Trench?

J-Box Type

No

Deck Mounted J-Box

Were Consumption CT's installed on this project?	No	Was there any Electrical Equiptment/Conduit Installed Inside The Garage/Home?	No
Why were Consumption CT's no	ot installed on this project?	Doca This Preject Include a	Ne
N/a		Does This Project Include a Battery?	No
Commissioning			
Was the Inverter/Combiner Commissioned?	Yes	Were there any errors during the commissioning process?	No
Does this project include a battery?	No	Was PCS utilized or required on the SLD for this project?	No
Crew Lead Review + Quality	Assurance		
Was there a need to change the layout?	Yes, the layout did not fit as designed.	Design Change Approved By:	Nicholas quarrey
Specific details for layout chan-	ge	Are There Any Remaining Punchlist Items?	No
Took last row and added column	50		
Was there a need to change the piont of interconnection method?	No, was able to install POI as designed.	Was permit left onsite?	No
Was there a need to change the BOS Location?	No, was able to install as designed.		
Customer Installation Review	w		
Is the customer home?	Yes	Was the Monitoring set up reviewed with the customer?	Yes
Was the Installation reviewed with the customer?	Yes	Any customer requests outside of punchlist items? No	
Was the final layout reviewed with the customer?	Yes		
Miscellaneous - Trenching, (Critter Guard, Rafter Upgrades		
Removal/Reinstall?	No	Are The Gas & Electrical Meter On The Same Wall?	

Page 2 of 29 Report Created: 08/12/2024

Job Check In / Picture of Front of the House



RGH03 Loc: **35.4096, -78.8913**

Project Completion Photos / Complete Array Photos (all modules MUST be visible in each array)



RGH03 Loc: **35.4096, -78.8911**

Project Completion Photos / Complete Array Photos (all modules MUST be visible in each array)



RGH03 Loc: **35.4095, -78.8908**


Project Completion Photos / Pullback Photos of All BOS Mounted in Completed State



RGH03 Loc: **35.4095, -78.8912**

Page 3 of 29 Report Created: 08/12/2024

Project Completion Photos / Pullback Photos of All BOS Mounted in Completed State



Project Completion Photos / Equipment Labels Complete



RGH03

Loc: 35.4095, -78.8912

RGH03 Loc: **35.4095, -78.8912**

Project Completion Photos / Equipment Labels Complete



Loc: **35.4095**, **-78.8912**

Project Completion Photos / Equipment Labels Complete



RGH03

Project Completion Photos / Equipment Labels Complete



RGH03 Loc: 35.4095, -78.8912

Project Completion Photos / Equipment Labels Complete



RGH03

Loc: 35.4095, -78.8912

Project Completion Photos / Equipment Labels Complete



RGH03 Loc: **35.4095**, **-78.8912**

Rooftop Installation / Sealant Application



RGH03

Rooftop Installation / Sealant Application



RGH03 Loc: **35.4096, -78.8912**

Rooftop Installation / Close Up of Railless Coupling Installed



RGH03 Loc: **35.4096, -78.8911**

Rooftop Installation / Completed Roof Attachment



RGH03 Loc: **35.4096, -78.8911**

Rooftop Installation / Optimizer/ Micro Inverter Installed



RGH03 Loc: **35.4096, -78.891**

Page 6 of 29 Report Created: 08/12/2024

Rooftop Installation / Optimizer/ Micro Inverter Installed



RGH03 Loc: **35.4095, -78.8913**

Rooftop Installation / Optimizer/ Micro Inverter Installed



RGH03 Loc: **35.4095, -78.8913**

Rooftop Installation / Module Ready Photos



RGH03 Loc: **35.4096, -78.8911**

Rooftop Installation / Module Ready Photos



RGH03 Loc: **35.4096, -78.8911**

Page 7 of 29 Report Created: 08/12/2024

Rooftop Installation / Module Ready Photos



Rooftop Installation / Module Ready Photos



RGH03

Loc: 35.4096, -78.8911

RGH03

Loc: 35.4096, -78.8911

Rooftop Installation / Module Label



RGH03

Loc: **35.4095**, **-78.8913**

Rooftop Installation / Module Gapping: Tape Measure showing 3/8" - 1" Gap



RGH03

Loc: **35.4096**, **-78.8911**

Page 8 of 29 Report Created: 08/12/2024

Rooftop Installation / Module Gapping: Tape Measure showing 3/8" - 1" Gap



RGH03 Loc: 35.4096, -78.8911

Rooftop Installation / Array Bonding/Grounding



RGH03 Loc: 35.4096, -78.8912

Rooftop Installation $\slash\hspace{-0.6em}$ Wire management Under the Array (1 photo per row of modules per array)



Rooftop Installation / Wire management Under the Array (1 photo per row of modules per array)



RGH03 Loc: 35.4096, -78.8911

RGH03

Rooftop Installation / Wire management Under the Array (1 photo per row of modules per array)




Rooftop Installation / Wire management Under the Array (1 photo per row of modules per array)



RGH03 Loc: **35.4096, -78.8911**


Rooftop Installation / Wire management Under the Array (1 photo per row of



RGH03

Loc: 35.4096, -78.8911

Rooftop Installation / Wire management Under the Array (1 photo per row of modules per array) $\,$




RGH03

Loc: 35.4095, -78.8911

RGH03

Rooftop Installation / Wire management Under the Array (1 photo per row of modules per array)



Rooftop Installation / Wire management Under the Array (1 photo per row of modules per array) $\,$



RGH03 Loc: **35.4095, -78.8911**

RGH03 Loc: **35.4095, -78.8912**

Rooftop Installation / Entire Attic Run



Rooftop Installation / Entire Attic Run



RGH03 RGH03

Page 11 of 29 Report Created: 08/12/2024

Rooftop Installation / Entire Attic Run



RGH03

Rooftop Installation / Entire Attic Run



RGH03

Rooftop Installation / Entire Attic Run



RGH03

Rooftop Installation / Entire Attic Run



RGH03


Page 12 of 29 Report Created: 08/12/2024

Rooftop Installation / Entire Attic Run



RGH03


Rooftop Installation / J-Box Installed W/ Wiring Complete (All Components)



RGH03

Loc: 35.4096, -78.8912

Rooftop Installation / J-Box Installed W/ Wiring Complete (All Components)



Loc: **35.4096**, **-78.8912**

Rooftop Installation / J-Box Completed W/ Lid Installed



RGH03

Loc: **35.4096, -78.8911**

Page 13 of 29 Report Created: 08/12/2024

Rooftop Installation / J-Box Completed W/ Lid Installed



RGH03 Loc: **35.4096, -78.8911**

Electrical Installation / The Main Service Panel's GEC



RGH03 Loc: **35.4097, -78.8914**

Electrical Installation / Close Up Photo of Panel Label + Main Breaker Rating on The Breaker




RGH03 Loc: **35.4097, -78.8911**

Electrical Installation / Point of Interconnection



RGH03

Electrical Installation / Point of Interconnection



RGH03 Loc: **35.4096, -78.8915**

Electrical Installation / Point of Interconnection



RGH03 Loc: **35.4095, -78.8912**

Electrical Installation / Point of Interconnection



RGH03 Loc: **35.4097, -78.8911**

Electrical Installation / Point of Interconnection



RGH03 Loc: **35.4095, -78.8911**


Page 15 of 29 Report Created: 08/12/2024

Electrical Installation / Point of Interconnection



RGH03 Loc: **35.4096, -78.8912**

Electrical Installation / Point of Interconnection



RGH03


Loc: 35.4095, -78.8912

Electrical Installation / Close Up Photo of the OCPD Rating for PV



RGH03 Loc: **35.4095, -78.8911**

Electrical Installation / Inverter/Combiner Installed & Wired




RGH03

Electrical Installation / Inverter/Combiner Installed & Wired



Electrical Installation / Show All Completed Wiring and Terminations for Each **BOS Component**



RGH03 Loc: 35.4094, -78.8912

RGH03

Loc: 35.4094, -78.8912

Electrical Installation / Show All Completed Wiring and Terminations for Each **BOS Component**



Electrical Installation / Show All Completed Wiring and Terminations for Each **BOS Component**



RGH03 Loc: **35.4095, -78.8912**

RGH03 Loc: 35.4094, -78.8912

Page 17 of 29 Report Created: 08/12/2024

Electrical Installation / Show All Completed Wiring and Terminations for Each BOS Component




RGH03 Loc: **35.4097, -78.8911**

Electrical Installation / Show All Completed Wiring and Terminations for Each BOS Component



RGH03 Loc: **35.4096**, **-78.8915**

Electrical Installation $\slash\hspace{-0.05cm}$ Show All Completed Wiring and Terminations for Each BOS Component



Electrical Installation / Show All Completed Wiring and Terminations for Each BOS Component



RGH03 Loc: **35.4096, -78.8912**

RGH03 Loc: **35.4095, -78.8912**

Page 18 of 29 Report Created: 08/12/2024

Electrical Installation / Show All Completed Wiring and Terminations for Each BOS Component




RGH03 Loc: **35.4096, -78.8912**

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03 Loc: **35.4096, -78.8912**

Electrical Installation / Show All Completed Wiring and Terminations for Each BOS Component



RGH03 Loc: **35.4096, -78.8912**


Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03

Loc: **35.4095**, **-78.8913**

Page 19 of 29 Report Created: 08/12/2024



RGH03 Loc: **35.4096, -78.8913**

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03 Loc: **35.4095, -78.8913**

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03 Loc: **35.4096, -78.8913**

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03 Loc: **35.4096, -78.8913**

Page 20 of 29 Report Created: 08/12/2024



RGH03 Loc: **35.4096, -78.8917**

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03 Loc: **35.4095, -78.8914**

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03 Loc: **35.4095, -78.8912**

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



Loc: **35.4096, -78.891**

Page 21 of 29 Report Created: 08/12/2024

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03 Loc: **35.4095, -78.8915**

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03 Loc: **35.4094, -78.8915**

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03 Loc: **35.4093, -78.8914**

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03 Loc: **35.4093, -78.8914**

Page 22 of 29 Report Created: 08/12/2024



RGH03 Loc: **35.4095, -78.8914**

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03 Loc: **35.4096, -78.8911**

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03 Loc: **35.4096, -78.8912**

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders




RGH03 Loc: **35.4095, -78.8911**

Page 23 of 29 Report Created: 08/12/2024



RGH03 Loc: 35.4096, -78.8911

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03 Loc: 35.4095, -78.8911


Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



Loc: **35.4095**, **-78.8911**

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders





RGH03 Loc: **35.4096, -78.891**

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders




RGH03 Loc: **35.4094, -78.8911**

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03 Loc: **35.4096, -78.8911**

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03



RGH03 Loc: **35.4096, -78.8911**

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03 Loc: **35.4096, -78.8912**

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders




RGH03 Loc: **35.4095**, **-78.891**

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03



RGH03 Loc: **35.4096, -78.891**

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03 Loc: **35.4096, -78.8914**

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders




RGH03 Loc: **35.4096, -78.8911**

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03



RGH03 Loc: **35.4097, -78.8912**

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders




RGH03 Loc: **35.4096, -78.891**

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03

Crew Lead Review + Quality Assurance / Screenshot of Missing Adders



RGH03 Loc: **35.4094, -78.8912**

Page 29 of 29 Report Created: 08/12/2024