



## Duct Leakage Report

Property Address:

230 Rollins Mill Rd. Holly Springs, NC 27540

HVAC System Number: 1

Describe area of home served: 1st Floor

CFM25 Total exempt. Conditioned Floor Area (CFA) served by system:  
1300 s.f.

CFM25 x 100 divided by CFA = exempt CFM25/100SF (e.g. 100 CFM25 x  
100/2,000 CFA = 5 CFM25/100SF)

Fan attachment location: N/A

Company Name:

EcoStructure Energy Consulting, LLC

Contact Information:

Parker Cannady

(919) 452-5829

Parker Cannady

1/7/20

Signature of Tester

Date

Permit Holder, NC Licensed General Contractor, NC Licensed HVAC  
Contractor, NC Licensed Home Inspector,  
Registered Design Professional, Certified BPI Envelope Professional, or  
Certified HERS Rater  
(circle one)



## Duct Leakage Report

Property Address:

230 Rollins Mill Rd. Holly Springs, NC 27540

HVAC System Number: 2

Describe area of home served: 2nd Floor

CFM25 Total 43. Conditioned Floor Area (CFA) served by system:  
1300 s.f.

CFM25 x 100 divided by CFA = 3.3 CFM25/100SF (e.g. 100 CFM25 x  
100/2,000 CFA = 5 CFM25/100SF)

Fan attachment location: 2nd Floor Main Return

Company Name:

EcoStructure Energy Consulting, LLC

Contact Information:

Parker Cannady

(919) 452-5829

Parker Cannady

1/7/20

Signature of Tester

Date

Permit Holder, NC Licensed General Contractor, NC Licensed HVAC  
Contractor, NC Licensed Home Inspector,  
Registered Design Professional, Certified BPI Envelope Professional, or  
Certified HERS Rater  
(circle one)