

### **ECS Southeast, LLP**

6151 Raeford Road Suite A Fayetteville, NC 28304 (910) 401-3288 [Phone] (910) 323-0539 [Fax]

#### LETTER OF TRANSMITTAL

April 6, 2020

Richard Family Builders

3212 Lillian Place

Fayetteville, NC 28306

ATTN: Juanita Richard

RE: Anderson Creek Club - Lot 1095

ECS Job # 4458-L

Permits:

Location: Education Drive

Spring Lake, NC 28390

2)/

CC: Floyd Properties - Alan Ray

Floyd Properties - Darlene Rzonca Floyd Properties - Veronica Page

ENCL: Field Report # 1 4/2/2020

Matthew B. Olsen, P.E. Office Manager, Principal

Watth K. Ols

Donny Johnson

Field Services Manager

#### Disclaimer

<sup>1.</sup> This report (and any attachments) shall not be reproduced except in full without prior written approval of ECS.

<sup>2.</sup> The information in this report relates only to the activities performed on the report date.

<sup>3.</sup> Where appropriate, this report includes statements as to compliance with applicable project drawings, and specifications for the activities, performed on this report date.

<sup>4.</sup> Incomplete or non-conforming work will be reported for future resolution.

<sup>5.</sup> The results of samples and/or specimens obtained or prepared for supersequent laboratory testing will be presented in separate reports/documents.



**ECS Southeast, LLP** 6151 Raeford Road Suite A Favetteville, NC 28304 (910) 401-3288 [Phone] (910) 323-0539 [Fax]

Project Anderson Creek Club - Lot 1095

Location Spring Lake, NC

Client **Richard Family Builders** 

Contractor Floyd Properties

#### FIELD REPORT

Project No. 4458-L

Report No.

Day & Date Thursday 4/2/2020

0.00

Weather 50 °/ Sunny

On-Site Time 1.00 Lab Time 0.50 Travel Time\* 1.25 Total 3.00

Re Obs Time

Remarks

Trip Charges\* Tolls/Parking\* Mileage\* Time of Arrival Departure 50 Chargeable Items 11:00A 12:00P

Summary of Services Performed (field test data, locations, elevations & depths are estimates) & Individuals Contacted.

The undersigned arrived on site, as requested, to observe the bearing capacity of soils via hand auger/dcp method for porch backfill at the front and rear of the residence. Please see the attached sketch.

A hand auger was used to advance the boreholes to different depths noted on the boring logs. Dynamic Cone Penetrometer (DCP) tests were performed in the hand auger boreholes by a 1.5 inch diameter cone driven into the soil by a 15 pound ring weight with a free fall of 20 inches. The number of blows required to drive the cone into the soil a distance of 1.75 inches is termed the DCP Value and is indicated for each test on the hand auger.

A total of 2 hand auger/DCP evaluations were performed to a depth of approximately 3 feet from top of fill. DCP blow counts ranged from 4 to 8 blows per increment. Soils do appear to have been sufficiently placed and compacted for support of the proposed construction.

ECS will return, as requested, to perform additional services.

<sup>\*</sup> Travel time and mileage will be billed in accordance with the contract.

# ODCP Bore Holes





## Dynamic Cone Penetrometer Test Report

Project :	ect : Anderson Creek Club – Lot 1095																		
Project #:	4458- L																		
Technician:	C. Langbis			Temp/Weather:			)/sunr	١٧											
Date:	04/02/20		Top Soil Depth:						Asphalt Depth:										
	0 1102,20	Penetrometer Blow Counts						Soil Descriptions							-				
Test Location	Test Depth			loter Broth Godine		٦, ۵	d)		<del></del>									<b>5</b>	
		1 ¾"	1 ¾"	1 ¾"	Top Soil	Stained Sands	orange	Tan	Brown	Red	Clayey	Sandy	Silty	CLAY	SAND	SILTS	with Silts		Remarks
1	(BOF)(Subgrade)	6	5	6	<u>'</u>					√	√				√				
	-1	6	7	7					√		√				√				
	-2	7	8	9					√		√				√				
	-3	6	6	7					√		√				√				
	-4																		
	-5																		
	(= = =) (=									,	,				,				
2	(BOF)(Subgrade)	4	5	6					,	√	√,				√,				
	-1 -2	5 5	6	8 7					<b>√</b>		√ /				√ /				
	-2 -3	6	8	7					/		√ √				√ /				
	-3 -4	- O	0						√		٧				√				
	-5																		
	-5																		
	(BOF)(Subgrade)																		
	-1																		
	-2																		
	-3																		
	-4																		
	-5																		
	(BOF)(Subgrade)																		
	-1																		
	-2																		
	-3																		
	-4																		
	-5		-	-															
	(BOF)(Subgrade)																		
	-1																		
	-2																		
	-3																		
	-4																		
	-5																		