



**ECS Southeast, LLP**

6151 Raeford Road, Suite A  
Fayetteville, NC 28304  
9104013288  
9103230539

**LETTER OF TRANSMITTAL**

May 12, 2021  
Ben Stout Construction  
PO Box 53798  
Fayetteville, NC 28305  
ATTN: Robert Ivey

RE: **Forest Ridge Lot**  
ECS Job # **33:5565**  
  
Permits:  
Location: **106 Tanna PI**  
**Spout Springs, NC 28326**

Field Reports       For your use       As requested

CC:

ENCL:    Field Report # 1                    5/6/2021

Jack Edgar Cowsert, P.E.  
Senior Project Engineer

Donny Johnson  
Field Services Manager

*Disclaimer*

1. This report (and any attachments) shall not be reproduced except in full without prior written approval of ECS.
2. The information in this report relates only to the activities performed on the report date.
3. Where appropriate, this report includes statements as to compliance with applicable project drawings, and specifications for the activities, performed on this report date.
4. Incomplete or non-conforming work will be reported for future resolution.
5. The results of samples and/or specimens obtained or prepared for subsequent laboratory testing will be presented in separate reports/documents.



ECS Southeast, LLP  
6151 Raeford Road, Suite A  
Fayetteville, NC 28304  
(910) 401-3288 [Phone]  
(910) 323-0539 [Fax]

## FIELD REPORT

Project **Forest Ridge Lot**  
Location **Spout Springs, NC**  
Client **Ben Stout Construction**  
Contractor **Ben Stout Construction**

Project No. **33:5565**  
Report No. **1**  
Day & Date **Thursday 5/6/2021**  
Weather **68 °/ Sunny**  
On-Site Time **0.50**  
Lab Time **0.00**  
Travel Time\* **0.00**  
Total **0.50**  
Re Obs Time **0.00**

Remarks

Trip Charges*	Tolls/Parking*	Mileage*	Time of Arrival	Departure
Chargeable Items			<b>5:30P</b>	<b>6:00P</b>

\* Travel time and mileage will be billed in accordance with the contract.

**Summary of Services Performed (field test data, locations, elevations & depths are estimates) & Individuals Contacted.**

ECS representative arrived on site, as requested, to perform DCP testing for stem wall backfill.

Upon arrival, the stem wall backfill was not complete and DCP testing could not be performed. Please see the attached images.

ECS will return, as requested, for additional services.

# Attachments



IMG\_0091

Figure 1



IMG\_0093

Figure 2