

June 29, 2023

Brian Culver Triangle Home Pros 6312 Lauraca Lane Fuquay Varina, NC 27526

RE: 90 Auger Hole Road "The Harrison" As-built framing review

Dear Mr. Culver:

The above reference plans were reviewed to address the as-built framing items identified during framing inspection. Review of the plans and as-built framing revealed the following:

- At the front porch, a single 2 x 10 ridge was installed with 2 x 6 collar ties @ 16" o.c. in lieu of a (2) ply 2 x 10 ridge beam with and open vault below. This framing configuration is adequate to support all applied loads.
- At the (2) 1 ³/₄" x 9 ¹/₄" LVL valley over the master bedroom, the as-built valley was framed with a splice located approximately three feet from the end bearing point. This framing configuration is adequate to support all applied loads and no reinforcement is required.
- Over the master bedroom, the 12:12 pitch rafters bear on a 2 x 4 plate on top of the 11 7/8" I-joist floor system as noted on the engineered drawings. This framing configuration is adequate to support all applied loads.

Please call me if you have any questions.

Sincerely,

J. Smith Structural Engineering, PLLC Jacob E. Smith, P.E.

Owner



320 N. Salem St. Unit 106B APEX, NC 27502 919.864.1430 jsmithstructural@gmail.com