

LILLINGTON,NC 27546 Phone: Fax:

8/1/2024

## SUBJECT: SFD2401-0039 SINGLE FAMILY DWELLING

To: Justin Harris

Here are the results of all Inspections located at 1141 CAMERON HILL RD:

Inspection Type:ADDRESSScheduled Date/Time:Completed Date/Time:Inspector:GIS BucketResult:Remarks:Notes:

Inspection Type:	GAS PIPING
Scheduled Date/Time:	
Completed Date/Time:	
Inspector:	Steven Gazlay
Result:	
Remarks:	
Notes:	

Inspection Type:	SEWER CONNECTION
Scheduled Date/Time:	
Completed Date/Time:	
Inspector:	Steven Gazlay
Result:	
Remarks:	
Notes:	

Inspection Type:	TEMP POWER CERTIFICATION
Scheduled Date/Time:	
Completed Date/Time:	
Inspector:	Steven Gazlay
Result:	
Remarks:	
Notes:	





LILLINGTON,NC 27546 Phone: Fax:

Inspection Type:	WATER CONNECTION
Scheduled Date/Time:	
Completed Date/Time:	
Inspector:	Steven Gazlay
Result:	
Remarks:	
Notes:	

Inspection Type:	ENVIR OPERATIONS PERMIT
Scheduled Date/Time:	
Completed Date/Time:	
Inspector:	EH Bucket
Result:	
Remarks:	
Notes:	

Inspection Type:	FINAL SFD STEMWALL**
Scheduled Date/Time:	
Completed Date/Time:	
Inspector:	Steven Gazlay
Result:	
Remarks:	
Notes:	

Inspection Type:	FOUNDATION SURVEY
Scheduled Date/Time:	
Completed Date/Time:	
Inspector:	CP Bucket
Result:	
Remarks:	not needed
Notes:	

Inspection Type:	INSULATION
Scheduled Date/Time:	
Completed Date/Time:	
Inspector:	Steven Gazlay
Result:	
Remarks:	
Notes:	





LILLINGTON,NC 27546 Phone: Fax:

Inspection Type: SLAB Scheduled Date/Time: Completed Date/Time: Inspector: Steven Gazlay Result: Remarks: Notes:

Inspection Type: SLAB Scheduled Date/Time: Completed Date/Time: Inspector: Steven Gazlay Result: Remarks: Notes:

Inspection Type:	ROUGH IN REINSPECT
Scheduled Date/Time:	
Completed Date/Time:	
Inspector:	Steven Gazlay
Result:	
Remarks:	
Notes:	

Inspection Type:	FOOTING
Scheduled Date/Time:	5/13/2024
Completed Date/Time:	5/13/2024
Inspector:	John B Kokoszka
Result:	APPROVED
Remarks:	
Notes:	

Inspection Type:	FOUNDATION
Scheduled Date/Time:	5/22/2024
Completed Date/Time:	5/22/2024
Inspector:	Steven Gazlay
Result:	DISAPPROVED
Remarks:	
Notes:	Missing R-10 insu

Missing R-10 insulation. Remove organics and debris from fill areas. Wall will need to be designed with permanent lateral support if unbalanced backfill exceeds 4 foot.



	420 Mc LILLING Phone: Fax:	t <b>County</b> kinney Pkwy TON,NC 27546 FOUNDATION
Scheduled Date Completed Date Inspector: Result: Remarks: Notes:		
Inspection Type Scheduled Date Completed Date Inspector: Result: Remarks: Notes:	/Time:	
Inspection Type Scheduled Date Completed Date Inspector: Result: Remarks: Notes:	/Time:	
Inspection Type Scheduled Date Completed Date Inspector: Result: Remarks: Notes:	/Time:	
Inspection Type Scheduled Date Completed Date Inspector: Result: Remarks: Notes:	/Time:	



**Harnett County** 420 Mckinney Pkwy Harnett LILLINGTON, NC 27546 СОЦИТ Phone: NORTH CAROLINA Fax: Inspection Type: SLAB Scheduled Date/Time: 6/18/2024 Completed Date/Time: 6/18/2024 Inspector: Steven Gazlay Result: CANCELLED Remarks: Notes: **T-POLE** Inspection Type: Scheduled Date/Time: 7/17/2024 Completed Date/Time: 7/17/2024 Inspector: Steven Gazlay Result: CANCELLED Remarks: Notes: Inspection Type: **ROUGH IN** Scheduled Date/Time: 7/17/2024 Completed Date/Time: 7/17/2024 Inspector: Steven Gazlay Result: CANCELLED Remarks: Notes: Inspection Type: ROUGH IN REINSPECT Scheduled Date/Time: 7/19/2024 Completed Date/Time: 7/19/2024 Inspector: James T Hall Result: DISAPPROVED Remarks: Notes: Porch post not installed at time of inspectionNail 2 ply lvl beam over garage door every 12"Missing air barrier under knee wall in garage and seal cracksSeal air barrier on house garage wallsMissing anchor bolt to right of door in garageNail both 2 ply trusses in garage per truss docsAnchor all interior load bearing walls per codeMissing stud on end wall in pantryMissing correct ail guard on water line at top plate in pantryJack stud on left side of window in kitchen not bearing Missing receptacle for kitchen island Missing Insulation baffles Missing nails in



hurricane straps at kitchen window Replace notched stud at bottom plate to right a

fireplaceFire caulk top of fireplace chaseMissing 2x6 nailed in floor trusses in living roomNeed repair letter for floor truss repair in living roomStop inspection in living room at fireplace



LILLINGTON,NC 27546 Phone: Fax:

Inspection Type: Scheduled Date/Time: Completed Date/Time: Inspector: Result: Remarks:	
Notes:	Seal barriers between house ceiling and garage. Jack stud not bearing left of kitchen window. Need letter for truss repair. Missing sheet rock nailer for tub surround. Missing nail plate for drain in bath. Missing insulation baffles. Insulate P-trap for washer. Seal air barrier in bonus room. Missing wall stud by upstairs shower. Missing bracing on trusses. Support horizontal PVC every 4 feet. Cannot use t-ply for fire blocking in chases. Missing header above doorway under stairs.
Inspection Type: Scheduled Date/Time:	T-POLE 7/31/2024
Completed Date/Time:	7/31/2024
Inspector:	Steven Gazlay
Result:	APPROVED
Remarks:	
Notes:	