Takla Engineering, PLLC

NC Firm License # P-1952

Consulting │ Design │ Efficiency

PO Box 71298 Durham, NC 27722 │ Office@TaklaEngr.com

Alfred A. Takla, PE   **Andy A. Takla, PE**
AlfredTakla@TaklaEngr.com   AndyTakla@TaklaEngr.com
NC PE License # 047507   NC PE License # 050695

Project:	Quail Glen Lot 51
Location:	Fuquay Varina, NC
Company:	NVR Homes
Care Of:	Bryan Blanco
Subject:	Roof Truss Repair Review
Job Number:	2-5335-23

Electronically signed by
Andy A. Takla, PE
Date:2023.12.13
Time:1:28:07 PM

As requested, Andy Takla, PE prepared this report on December 13th, 2023 to review the following roof truss repair noted during a recent framing inspection report.

In-place repair to vertical web of roof truss was done by means of 2x4 scab to both sides, nailed with (2) 16D nails at ~ 8" on center. See picture below for reference. Based on review, the in-place repairs are appropriate, consistent with the standard industry truss field repairs, and adequate to restore the structural integrity of the roof trusses. **No changes required.**

DIRECTION ORIENTATION

REAR
LEFT | BUILDING | RIGHT
FRONT
STREET