COMMENTS:

1/6/2009 Made visit to this Lot in Buffalo Lake & observed that the area for the septic drain field had been altered BR+OT

6/24/2009 Met with the builder & spetic contractor, had to make changes in the depth of the drain lines due to added fill material