ENGINEERING BY
TRENCO
A MiTek Affiliate

Trenco
818 Soundside Rd
Edenton, NC 27932

Re: 20137
140.1582 A 10x10 CP

The truss drawing(s) referenced below have been prepared by Truss Engineering Co. under my direct supervision based on the parameters provided by 84 Components - #2383.

Pages or sheets covered by this seal: I36366999 thru I36367038

My license renewal date for the state of North Carolina is December 31, 2019.

North Carolina COA: C-0844


March 12,2019

Johnson, Andrew

**IMPORTANT NOTE:** Truss Engineer's responsibility is solely for design of individual trusses based upon design parameters shown on referenced truss drawings. Parameters have not been verified as appropriate for any use. Any location identification specified is for file reference only and has not been used in preparing design. Suitability of truss designs for any particular building is the responsibility of the building designer, not the Truss Engineer, per ANSI/TPI-1, Chapter 2.

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | B1 | COMMON | 1 | 1 | I36366999 |
| | | | | | Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:06:56 2019 Page 1
ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-F6Gc?fWg9UmHGcPZyHI_dzAnf7YZUM_2gMDhGlzc_Qj

| -0-10-8 | 3-9-13 | 10-1-0 | 16-4-3 | 20-2-0 | 21-0-8 |
|---|---|---|---|---|---|
| 0-10-8 | 3-9-13 | 6-3-3 | 6-3-3 | 3-9-13 | 0-10-8 |

Scale = 1:46.1




| 7-4-5 | 14-6-4 | 20-2-0 |
|---|---|---|
| 7-4-5 | 7-1-15 | 5-7-12 |

Plate Offsets (X,Y)-- [2:0-0-0,0-0-8], [2:0-0-15,0-4-5], [6:0-0-15,0-4-5], [6:0-0-0,0-0-12], [9:0-0-0,0-1-12], [9:0-3-12,0-3-0]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.54 | Vert(LL) | 0.11 | 2-10 | >999 | 240 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.46 | Vert(CT) | -0.14 | 8-10 | >999 | 180 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.43 | Horz(CT) | 0.01 | 8 | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2015/TPI2014 | | Matrix-S | | | | | | | Weight: 104 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.2
BOT CHORD 2x4 SP No.2
WEBS 2x4 SP No.3
WEDGE
Left: 2x4 SP No.3, Right: 2x4 SP No.3

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 6-0-0 oc purlins.
BOT CHORD Rigid ceiling directly applied or 6-0-0 oc bracing.
WEBS 1 Row at midpt 4-8

**REACTIONS.** (lb/size) 2=528/0-3-8, 8=1188/0-3-8
Max Horz 2=181(LC 11)
Max Uplift 2=-89(LC 12), 8=-145(LC 13)
Max Grav 2=559(LC 23), 8=1188(LC 1)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
TOP CHORD 2-3=-653/367, 3-4=-451/362, 4-5=-224/575, 5-6=-253/377
BOT CHORD 2-10=-240/611, 6-8=-229/253
WEBS 4-10=-405/436, 4-8=-933/519, 5-8=-335/223, 3-10=-316/221

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph (3-second gust) Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=25ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) -0-10-8 to 2-1-8, Interior(1) 2-1-8 to 10-1-0, Exterior(2) 10-1-0 to 13-1-0, Interior(1) 13-1-0 to 21-0-8 zone; cantilever right exposed ; porch right exposed;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
4) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members, with BCDL = 10.0psf.
5) One RT7A USP connectors recommended to connect truss to bearing walls due to UPLIFT at jt(s) 2 and 8. This connection is for uplift only and does not consider lateral forces.




March 12,2019




ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | BE | COMMON STRUCTURAL GA | 1 | 1 | I36367000<br>Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:06:57 2019 Page 1
ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-jlq_D?XIwou8um_mW?GD9BiyHWxoDipCv0zEoCzc_Qi

-0-10-8 5-1-11 10-1-0 15-0-5 20-2-0 21-0-8
0-10-8 5-1-11 4-11-5 4-11-5 5-1-11 0-10-8

Scale = 1:47.4




6-9-7 13-4-9 14-8-0 20-2-0
6-9-7 6-7-2 1-3-7 5-6-0

Plate Offsets (X,Y)-- [2:0-0-15,0-4-5], [2:0-0-0,0-0-12], [4:0-2-0,0-0-4], [6:0-0-0,0-0-12], [6:0-0-15,0-4-5], [8:0-1-12,0-0-0], [8:0-3-8,0-3-0]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.55 | Vert(LL) | -0.01 | 8-9 | >999 | 240 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.27 | Vert(CT) | 0.01 | 8-9 | >999 | 180 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.84 | Horz(CT) | 0.00 | 8 | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2015/TPI2014 | | Matrix-S | | | | | | | Weight: 151 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.2
BOT CHORD 2x4 SP No.2
WEBS 2x4 SP No.3
OTHERS 2x4 SP No.3
WEDGE
Left: 2x4 SP No.3, Right: 2x4 SP No.3

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 6-0-0 oc purlins.
BOT CHORD Rigid ceiling directly applied or 6-0-0 oc bracing.

**REACTIONS.** All bearings 14-8-0.
(lb) - Max Horz 2=181(LC 11)
Max Uplift All uplift 100 lb or less at joint(s) 2, 9 except 8=-172(LC 13), 12=-190(LC 12)
Max Grav All reactions 250 lb or less at joint(s) 2, 10, 11, 13, 14, 9 except 8=966(LC 1), 8=966(LC 1), 12=438(LC 19)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
TOP CHORD 3-4=-59/285, 4-5=-255/607, 5-6=-272/386
BOT CHORD 6-8=-236/267
WEBS 4-8=-687/324, 5-8=-340/222, 3-12=-330/225

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph (3-second gust) Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=25ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) -0-10-8 to 2-1-8, Interior(1) 2-1-8 to 10-1-0, Exterior(2) 10-1-0 to 13-1-0, Interior(1) 13-1-0 to 21-0-8 zone; cantilever right exposed ; porch right exposed;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Truss designed for wind loads in the plane of the truss only. For studs exposed to wind (normal to the face), see Standard Industry Gable End Details as applicable, or consult qualified building designer as per ANSI/TPI 1.
4) All plates are 2x4 MT20 unless otherwise indicated.
5) Gable studs spaced at 2-0-0 oc.
6) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
7) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members, with BCDL = 10.0psf.
8) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 2, 9 except (jt=lb) 8=172, 12=190.

NORTH CAROLINA PROFESSIONAL SEAL 45844 ENGINEER ANDREW JOHNSON

March 12,2019




ENGINEERING BY TRENCO A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | BG | COMMON GIRDER | 1 | 2 | I36367001 |
| | | | | | Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:06:59 2019 Page 1
ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-ghykehYYSP8s7388dQIhEcoMcKSvhbgVNKSLt4zc_Qg




Plate Offsets (X,Y)-- [2:0-4-0,0-1-9], [6:Edge,0-1-7], [6:0-0-15,0-4-15], [10:0-6-0,0-6-4], [8:0-6-0,0-6-4], [10:0-6-0,0-2-0]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.30 | Vert(LL) | -0.07 | 8-10 | >999 | 240 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 1.00 | Vert(CT) | -0.14 | 8-10 | >999 | 180 | | |
| BCLL | 0.0 * | Rep Stress Incr | NO | WB | 0.95 | Horz(CT) | 0.02 | 7 | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2015/TPI2014 | | Matrix-S | | | | | | | Weight: 267 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.2
BOT CHORD 2x8 SP No.2
WEBS 2x4 SP No.3
WEDGE
Right: 2x4 SP No.3

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 4-10-13 oc purlins.
BOT CHORD Rigid ceiling directly applied or 6-0-0 oc bracing.

**REACTIONS.** (lb/size) 2=3654/0-3-8, 7=8136/0-3-8 (req. 0-4-13), 6=401/0-3-8
Max Horz 2=176(LC 9)
Max Uplift 2=-535(LC 12), 7=-992(LC 13), 6=-119(LC 8)
Max Grav 2=3654(LC 1), 7=8136(LC 1), 6=507(LC 26)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
TOP CHORD 2-3=-6187/865, 3-4=-3549/444, 4-5=-3554/452, 5-6=-161/973
BOT CHORD 2-10=-743/5010, 8-10=-743/5010, 7-8=-729/175, 6-7=-729/175
WEBS 3-10=-476/2817, 3-8=-2643/615, 4-8=-394/3602, 5-8=-506/4566, 5-7=-5619/708

**NOTES-**
1) 2-ply truss to be connected together with 10d (0.131"x3") nails as follows:
Top chords connected as follows: 2x4 - 1 row at 0-9-0 oc.
Bottom chords connected as follows: 2x8 - 2 rows staggered at 0-5-0 oc.
Webs connected as follows: 2x4 - 1 row at 0-9-0 oc.
2) All loads are considered equally applied to all plies, except if noted as front (F) or back (B) face in the LOAD CASE(S) section. Ply to ply connections have been provided to distribute only loads noted as (F) or (B), unless otherwise indicated.
3) Unbalanced roof live loads have been considered for this design.
4) Wind: ASCE 7-10; Vult=130mph (3-second gust) Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=25ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) -0-10-8 to 2-1-8, Interior(1) 2-1-8 to 10-1-0, Exterior(2) 10-1-0 to 13-1-0, Interior(1) 13-1-0 to 19-5-12 zone; porch right exposed;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
5) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
6) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
7) WARNING: Required bearing size at joint(s) 7 greater than input bearing size.
8) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) except (jt=lb) 7=992.
9) One RT7A USP connectors recommended to connect truss to bearing walls due to UPLIFT at jt(s) 2 and 6. This connection is for uplift only and does not consider lateral forces.
10) Use USP HUS26 (With 16d nails into Girder & 16d nails into Truss) or equivalent spaced at 4-0-0 oc max. starting at 4-11-4 from the left end to 18-6-12 to connect truss(es) to back face of bottom chord.
11) Fill all nail holes where hanger is in contact with lumber.

**LOAD CASE(S)** Standard

Continued on page 2


March 12,2019



ENGINEERING BY
TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

**LOAD CASE(S)** Standard

1) Dead + Roof Live (balanced): Lumber Increase=1.15, Plate Increase=1.15
   Uniform Loads (plf)
   Vert: 1-4=-60, 4-6=-60, 2-6=-20
   Concentrated Loads (lb)
   Vert: 15=-814(B) 16=-1960(B) 17=-1960(B) 18=-1960(B) 19=-1960(B) 20=-964(B) 21=-965(B)

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | H2 | HIP | 1 | 1 | I36367002 |
| | | | | | Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:07:05 2019 Page 1
ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-UrJ0ukdJ2Fv?r_bI_gP5Ut2LvlVj5LCNlFvg4kzc_Qa

| -0-10-8 | 4-9-4 | 9-0-0 | 17-0-14 | 25-0-0 | 32-11-2 | 41-0-0 | 45-2-12 | 49-8-12 |
|---|---|---|---|---|---|---|---|---|
| 0-10-8 | 4-9-4 | 4-2-12 | 8-0-14 | 7-11-2 | 7-11-2 | 8-0-14 | 4-2-12 | 4-6-0 |

Scale = 1:88.0




| 9-0-0 | 17-0-14 | 25-0-0 | 32-11-2 | 41-0-0 | 49-8-12 |
|---|---|---|---|---|---|
| 9-0-0 | 8-0-14 | 7-11-2 | 7-11-2 | 8-0-14 | 8-8-12 |

Plate Offsets (X,Y)-- [5:0-4-0,0-4-8], [7:0-4-0,0-4-8], [17:0-3-4,0-0-0]

| LOADING (psf) | | SPACING- 2-0-0 | | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.51 | Vert(LL) | -0.45 | 14 | >999 | 240 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.97 | Vert(CT) | -0.89 | 14 | >665 | 180 | MT18H | 244/190 |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.81 | Horz(CT) | 0.21 | 10 | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2015/TPI2014 | | Matrix-S | | | | | | | Weight: 316 lb | FT = 20% |

**LUMBER-**

| | |
|---|---|
| TOP CHORD | 2x6 SP No.2 *Except* 1-4,8-10: 2x4 SP No.2 |
| BOT CHORD | 2x6 SP No.2 *Except* 12-15,15-17: 2x6 SP DSS |
| WEBS | 2x4 SP No.3 |

**BRACING-**

| | |
|---|---|
| TOP CHORD | Structural wood sheathing directly applied or 2-6-12 oc purlins, except 2-0-0 oc purlins (2-10-12 max.): 4-8. |
| BOT CHORD | Rigid ceiling directly applied or 2-2-0 oc bracing. |
| WEBS | 1 Row at midpt 6-16, 6-13<br>2 Rows at 1/3 pts 5-18, 7-11 |

**REACTIONS.** (lb/size) 10=1980/Mechanical, 2=2043/0-3-8
Max Horz 2=89(LC 16)
Max Uplift 10=-220(LC 8), 2=-225(LC 9)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.

| | |
|---|---|
| TOP CHORD | 2-3=-3995/661, 3-4=-3777/578, 4-5=-3324/550, 5-6=-5277/837, 6-7=-5250/832, 7-8=-3275/539, 8-9=-3721/571, 9-10=-3893/644 |
| BOT CHORD | 2-18=-551/3510, 16-18=-792/5274, 14-16=-870/5853, 13-14=-870/5853, 11-13=-746/5247, 10-11=-522/3392 |
| WEBS | 4-18=-110/1288, 5-18=-2267/456, 5-16=0/539, 6-16=-716/138, 6-14=0/324, 6-13=-744/141, 7-13=0/551, 7-11=-2291/457, 8-11=-112/1264 |

**NOTES-**

1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph (3-second gust) Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=30ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) -0-10-8 to 4-1-3, Interior(1) 4-1-3 to 9-0-0, Exterior(2) 9-0-0 to 16-0-6, Interior(1) 16-0-6 to 41-0-0, Exterior(2) 41-0-0 to 48-0-6, Interior(1) 48-0-6 to 49-8-0 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Provide adequate drainage to prevent water ponding.
4) All plates are MT20 plates unless otherwise indicated.
5) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
6) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
7) Refer to girder(s) for truss to truss connections.
8) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) except (jt=lb) 10=220.
9) One RT7A USP connectors recommended to connect truss to bearing walls due to UPLIFT at jt(s) 2. This connection is for uplift only and does not consider lateral forces.
10) Graphical purlin representation does not depict the size or the orientation of the purlin along the top and/or bottom chord.


March 12,2019




ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | H3 | HIP | 1 | 1 | I36367003 |
| | | | | | Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:07:06 2019 Page 1
ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-z1tO64expZ1sT8AUXOwK14aR19rqqnJW_veDdAzc_QZ

| -0-10-8 | 6-1-4 | 11-8-0 | 20-6-11 | 29-5-5 | 38-4-0 | 43-10-12 | 49-8-12 |
|---|---|---|---|---|---|---|---|
| 0-10-8 | 6-1-4 | 5-6-12 | 8-10-11 | 8-10-11 | 8-10-11 | 5-6-12 | 5-10-0 |

Scale = 1:88.0




| 6-1-4 | 11-8-0 | 25-0-0 | 38-4-0 | 43-10-12 | 49-8-12 |
|---|---|---|---|---|---|
| 6-1-4 | 5-6-12 | 13-4-0 | 13-4-0 | 5-6-12 | 5-10-0 |

Plate Offsets (X,Y)-- [13:0-4-0,0-4-8], [14:0-3-12,0-4-12]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.80 | Vert(LL) | -0.34 | 13-14 | >999 | 240 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.98 | Vert(CT) | -0.70 | 11-13 | >845 | 180 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.89 | Horz(CT) | 0.17 | 10 | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2015/TPI2014 | | Matrix-S | | | | | | | Weight: 303 lb | FT = 20% |

**LUMBER-**

| | |
|---|---|
| TOP CHORD | 2x4 SP No.2 *Except* 4-6,6-8: 2x6 SP No.2 |
| BOT CHORD | 2x6 SP No.2 *Except* 12-13,13-14: 2x6 SP DSS |
| WEBS | 2x4 SP No.3 |

**BRACING-**

| | |
|---|---|
| TOP CHORD | Structural wood sheathing directly applied or 2-2-0 oc purlins, except 2-0-0 oc purlins (3-2-8 max.): 4-8. |
| BOT CHORD | Rigid ceiling directly applied or 2-2-0 oc bracing. |
| WEBS | 1 Row at midpt 5-14, 7-11 |

**REACTIONS.** (lb/size) 10=1980/Mechanical, 2=2043/0-3-8
Max Horz 2=111(LC 12)
Max Uplift 10=-172(LC 8), 2=-177(LC 9)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
TOP CHORD 2-3=-3927/661, 3-4=-3580/555, 4-5=-3131/540, 5-7=-4411/673, 7-8=-3096/532, 8-9=-3542/546, 9-10=-3851/649
BOT CHORD 2-14=-544/3442, 13-14=-579/4310, 11-13=-548/4298, 10-11=-521/3355
WEBS 3-14=-325/244, 4-14=-72/1157, 5-14=-1495/376, 5-13=0/339, 7-13=0/354, 7-11=-1519/376, 8-11=-81/1140, 9-11=-269/247

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph (3-second gust) Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=30ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) -0-10-8 to 4-1-3, Interior(1) 4-1-3 to 11-8-0, Exterior(2) 11-8-0 to 18-8-6, Interior(1) 18-8-6 to 38-4-0, Exterior(2) 38-4-0 to 45-4-6, Interior(1) 45-4-6 to 49-8-0 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Provide adequate drainage to prevent water ponding.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members, with BCDL = 10.0psf.
6) Refer to girder(s) for truss to truss connections.
7) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) except (jt=lb) 10=172.
8) One RT7A USP connectors recommended to connect truss to bearing walls due to UPLIFT at jt(s) 2. This connection is for uplift only and does not consider lateral forces.
9) Graphical purlin representation does not depict the size or the orientation of the purlin along the top and/or bottom chord.




March 12,2019




ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | H4 | HIP | 1 | 1 | I36367004 |
| | | | | | Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:07:07 2019 Page 1
ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-RDRmJQfaZt9j5Ilh55SZZI7bsYE8ZHfgCZOm9dzc_QY

| -0-10-8 | 7-5-4 | 14-4-0 | 21-5-15 | 28-6-1 | 35-8-0 | 42-6-12 | 49-8-12 |
|---|---|---|---|---|---|---|---|
| 0-10-8 | 7-5-4 | 6-10-12 | 7-1-15 | 7-0-3 | 7-1-15 | 6-10-12 | 7-2-0 |

Scale = 1:89.6




| 7-5-4 | 14-4-0 | 21-5-15 | 28-6-1 | 35-8-0 | 42-6-12 | 49-8-12 |
|---|---|---|---|---|---|---|
| 7-5-4 | 6-10-12 | 7-1-15 | 7-0-3 | 7-1-15 | 6-10-12 | 7-2-0 |

Plate Offsets (X,Y)-- [3:0-2-8,Edge]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.86 | Vert(LL) | -0.26 | 14-16 | >999 | 240 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.78 | Vert(CT) | -0.52 | 14-16 | >999 | 180 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.69 | Horz(CT) | 0.18 | 10 | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2015/TPI2014 | | Matrix-S | | | | | | | Weight: 328 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x6 SP No.2 *Except*
3-4: 2x4 SP No.1, 8-10: 2x4 SP DSS, 1-3: 2x4 SP No.2
BOT CHORD 2x6 SP No.2
WEBS 2x4 SP No.3

**BRACING-**
TOP CHORD Structural wood sheathing directly applied, except
2-0-0 oc purlins (3-9-5 max.): 4-8.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.
WEBS 1 Row at midpt 5-17, 5-14, 7-13

**REACTIONS.** (lb/size) 10=1980/Mechanical, 2=2043/0-3-8
Max Horz 2=133(LC 16)
Max Uplift 10=-142(LC 13), 2=-166(LC 12)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
TOP CHORD 2-3=-3934/597, 3-4=-3318/564, 4-5=-2878/557, 5-7=-3517/627, 7-8=-2856/548, 8-9=-3293/556, 9-10=-3871/581
BOT CHORD 2-19=-477/3433, 17-19=-474/3438, 16-17=-387/3523, 14-16=-387/3523, 13-14=-387/3517, 11-13=-450/3363, 10-11=-450/3363
WEBS 3-19=0/294, 3-17=-618/222, 4-17=-88/1083, 5-17=-1066/221, 5-16=0/343, 7-14=0/320, 7-13=-1070/219, 8-13=-99/1072, 9-13=-564/223, 9-11=0/290

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph (3-second gust) Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=30ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) -0-10-8 to 4-1-3, Interior(1) 4-1-3 to 14-4-0, Exterior(2) 14-4-0 to 21-5-15, Interior(1) 21-5-15 to 35-8-0, Exterior(2) 35-8-0 to 42-6-12, Interior(1) 42-6-12 to 49-8-0 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Provide adequate drainage to prevent water ponding.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members, with BCDL = 10.0psf.
6) Refer to girder(s) for truss to truss connections.
7) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) except (jt=lb) 10=142.
8) One RT7A USP connectors recommended to connect truss to bearing walls due to UPLIFT at jt(s) 2. This connection is for uplift only and does not consider lateral forces.
9) Graphical purlin representation does not depict the size or the orientation of the purlin along the top and/or bottom chord.




March 12,2019




ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | H5 | HIP | 1 | 1 | I36367005 |
| | | | | | Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:07:09 2019 Page 1

ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-NcYWk6gq5UPRKcv3DWU1ejCxDMva1BmzgtttDVzc_QW

| -0-10-8 | 6-0-5 | 11-6-3 | 17-0-0 | 25-0-0 | 33-0-0 | 38-5-13 | 43-11-11 | 49-8-12 |
|---|---|---|---|---|---|---|---|---|
| 0-10-8 | 6-0-5 | 5-5-13 | 5-5-13 | 8-0-0 | 8-0-0 | 5-5-13 | 5-5-13 | 5-9-1 |

Scale = 1:89.6




| 8-9-4 | 17-0-0 | 25-0-0 | 33-0-0 | 41-2-12 | 49-8-12 |
|---|---|---|---|---|---|
| 8-9-4 | 8-2-12 | 8-0-0 | 8-0-0 | 8-2-12 | 8-6-0 |

Plate Offsets (X,Y)-- [7:0-4-0,0-4-8]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.81 | Vert(LL) | -0.26 | 17-18 | >999 | 240 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.79 | Vert(CT) | -0.52 | 17-18 | >999 | 180 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.65 | Horz(CT) | 0.16 | 12 | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2015/TPI2014 | | Matrix-S | | | | | | | Weight: 331 lb | FT = 20% |

**LUMBER-**

| | |
|---|---|
| TOP CHORD | 2x4 SP No.2 *Except* 7-8,6-7: 2x6 SP No.2 |
| BOT CHORD | 2x6 SP No.2 |
| WEBS | 2x4 SP No.3 |

**BRACING-**

| | |
|---|---|
| TOP CHORD | Structural wood sheathing directly applied or 2-2-0 oc purlins, except 2-0-0 oc purlins (4-1-8 max.): 6-8. |
| BOT CHORD | Rigid ceiling directly applied or 10-0-0 oc bracing. |
| WEBS | 1 Row at midpt 7-18, 7-15 |

**REACTIONS.** (lb/size) 2=2043/0-3-8, 12=1980/Mechanical
Max Horz 2=155(LC 12)
Max Uplift 2=-193(LC 12), 12=-169(LC 13)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.

| | |
|---|---|
| TOP CHORD | 2-3=-3949/581, 3-5=-3698/571, 5-6=-3062/556, 6-7=-2689/539, 7-8=-2676/533, 8-9=-3047/549, 9-11=-3639/560, 11-12=-3873/579 |
| BOT CHORD | 2-20=-471/3459, 18-20=-385/3049, 17-18=-303/3114, 15-17=-303/3114, 13-15=-366/3016, 12-13=-448/3372 |
| WEBS | 3-20=-313/194, 5-20=-39/480, 5-18=-560/219, 6-18=-92/1031, 7-18=-730/174, 7-17=0/422, 7-15=-747/174, 8-15=-89/1025, 9-15=-532/217, 9-13=-38/444, 11-13=-268/195 |

**NOTES-**

1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph (3-second gust) Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=30ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) -0-10-8 to 4-1-3, Interior(1) 4-1-3 to 17-0-0, Exterior(2) 17-0-0 to 24-0-6, Interior(1) 24-0-6 to 33-0-0, Exterior(2) 33-0-0 to 40-0-6, Interior(1) 40-0-6 to 49-8-0 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Provide adequate drainage to prevent water ponding.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members, with BCDL = 10.0psf.
6) Refer to girder(s) for truss to truss connections.
7) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) except (jt=lb) 12=169.
8) One RT7A USP connectors recommended to connect truss to bearing walls due to UPLIFT at jt(s) 2. This connection is for uplift only and does not consider lateral forces.
9) Graphical purlin representation does not depict the size or the orientation of the purlin along the top and/or bottom chord.




March 12,2019




ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | H6 | HIP | 1 | 1 | I36367006 |
| | | | | | Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:07:10 2019 Page 1
ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-ro6vxShSsoXIylUGmD?GBwl7amGpmfl6uXcQmyzc_QV

| -0-10-8 | 6-11-0 | 13-3-8 | 19-8-0 | 25-0-0 | 30-4-0 | 36-8-8 | 43-1-0 | 49-8-8 |
|---|---|---|---|---|---|---|---|---|
| 0-10-8 | 6-11-0 | 6-4-8 | 6-4-8 | 5-4-0 | 5-4-0 | 6-4-8 | 6-4-8 | 6-7-8 |

Scale = 1:88.4




| 10-1-4 | 19-8-0 | 25-0-0 | 30-4-0 | 39-10-12 | 42-2-0 | 49-8-8 |
|---|---|---|---|---|---|---|
| 10-1-4 | 9-6-12 | 5-4-0 | 5-4-0 | 9-6-12 | 2-3-4 | 7-6-8 |

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.71 | Vert(LL) | -0.24 | 16-18 | >999 | 240 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.72 | Vert(CT) | -0.46 | 14-16 | >999 | 180 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.60 | Horz(CT) | 0.10 | 12 | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2015/TPI2014 | | Matrix-S | | | | | | | Weight: 318 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.2
BOT CHORD 2x6 SP DSS *Except*
17-19: 2x6 SP No.2
WEBS 2x4 SP No.3

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 2-2-0 oc purlins, except 2-0-0 oc purlins (3-8-14 max.): 6-8.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.
WEBS 1 Row at midpt 5-18, 7-18, 7-16, 9-16

**REACTIONS.** All bearings 0-3-8 except (jt=length) 12=7-10-0.
(lb) - Max Horz 2=178(LC 12)
Max Uplift All uplift 100 lb or less at joint(s) 13 except 2=-217(LC 12), 12=-158(LC 13)
Max Grav All reactions 250 lb or less at joint(s) except 2=1885(LC 1), 12=1111(LC 1), 13=1030(LC 1), 13=1030(LC 1)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
TOP CHORD 2-3=-3550/522, 3-5=-3287/512, 5-6=-2519/493, 6-7=-2182/487, 7-8=-2024/469, 8-9=-2342/472, 9-11=-2029/390, 11-12=-2266/407
BOT CHORD 2-20=-431/3094, 18-20=-312/2637, 16-18=-182/2197, 14-16=-236/1994, 13-14=-290/1946, 12-13=-290/1946
WEBS 3-20=-367/223, 5-20=-48/569, 5-18=-706/262, 6-18=-85/832, 7-18=-261/168, 7-16=-531/155, 8-16=-77/754, 9-14=-585/118, 11-14=-347/228

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph (3-second gust) Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=30ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) -0-10-8 to 4-1-3, Interior(1) 4-1-3 to 19-8-0, Exterior(2) 19-8-0 to 26-8-6, Interior(1) 26-8-6 to 30-4-0, Exterior(2) 30-4-0 to 37-4-6, Interior(1) 37-4-6 to 49-8-8 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Provide adequate drainage to prevent water ponding.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members, with BCDL = 10.0psf.
6) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) except (jt=lb) 12=158.
7) One RT7A USP connectors recommended to connect truss to bearing walls due to UPLIFT at jt(s) 2 and 13. This connection is for uplift only and does not consider lateral forces.
8) Graphical purlin representation does not depict the size or the orientation of the purlin along the top and/or bottom chord.


March 12,2019




ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | H10 | HIP | 1 | 1 | I36367007 |
| | | | | | Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:07:00 2019 Page 1
ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-8tV7r1ZBDjGilDjLB7pwnpKNlkpZQ2geb_BvPXzc_Qf

| -0-10-8 | 6-11-11 | 13-4-13 | 19-10-0 | 24-6-4 | 30-2-0 | 36-7-3 | 43-0-5 | 50-0-0 | 50-10-8 |
|---|---|---|---|---|---|---|---|---|---|
| 0-10-8 | 6-11-11 | 6-5-3 | 6-5-3 | 4-8-4 | 5-7-12 | 6-5-3 | 6-5-3 | 6-11-11 | 0-10-8 |

Scale = 1:98.6




| 10-2-4 | 19-10-0 | 24-6-4 | 29-6-0 | 30-2-0 | 39-9-12 | 50-0-0 |
|---|---|---|---|---|---|---|
| 10-2-4 | 9-7-12 | 4-8-4 | 4-11-12 | 0-8-0 | 9-7-12 | 10-2-4 |

Plate Offsets (X,Y)-- [9:0-6-6,Edge], [17:0-3-0,0-3-12], [20:0-2-0,0-2-0]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.92 | Vert(LL) | -0.61 | 20-22 | >575 | 240 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.91 | Vert(CT) | -1.10 | 20-22 | >317 | 180 | MT18HS | 244/190 |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.90 | Horz(CT) | 0.12 | 13 | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2015/TPI2014 | | Matrix-S | | Attic | -0.28 | 18-20 | 412 | 360 | Weight: 358 lb | FT = 20% |

**LUMBER-**

| | |
|---|---|
| TOP CHORD | 2x4 SP No.2 |
| BOT CHORD | 2x6 SP No.2 *Except* 16-19,19-21: 2x6 SP DSS |
| WEBS | 2x4 SP No.3 *Except* 6-20,9-17,8-18: 2x4 SP No.2 |

**BRACING-**

| | |
|---|---|
| TOP CHORD | Structural wood sheathing directly applied, except 2-0-0 oc purlins (3-1-2 max.): 6-9. |
| BOT CHORD | Rigid ceiling directly applied or 10-0-0 oc bracing. |
| WEBS | 1 Row at midpt 5-20, 10-17 |
| JOINTS | 1 Brace at Jt(s): 23, 24, 25 |

**REACTIONS.** (lb/size) 2=1865/0-3-8, 18=567/0-3-8, 13=1764/0-3-8
Max Horz 2=172(LC 16)
Max Uplift 2=-256(LC 12), 18=-224(LC 13), 13=-102(LC 12)
Max Grav 2=2038(LC 26), 18=851(LC 25), 13=1889(LC 2)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.

| | |
|---|---|
| TOP CHORD | 2-3=-4002/484, 3-5=-3760/473, 5-6=-2858/438, 6-7=-2808/527, 7-8=-2805/525, 8-9=-2413/430, 9-10=-2735/449, 10-12=-3361/447, 12-13=-3611/466 |
| BOT CHORD | 2-22=-504/3508, 20-22=-321/3005, 18-20=-130/2461, 17-18=-127/2428, 15-17=-179/2746, 13-15=-297/3163 |
| WEBS | 3-22=-365/224, 5-22=-60/684, 5-20=-805/273, 20-24=-63/869, 6-24=-53/889, 7-23=-367/147, 9-17=-119/975, 10-17=-672/277, 10-15=-63/533, 12-15=-386/227, 18-25=-403/135, 8-25=-381/145, 6-23=-116/369, 8-23=-127/556 |

**NOTES-**

1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph (3-second gust) Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=30ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) -0-10-8 to 4-1-8, Interior(1) 4-1-8 to 19-10-0, Exterior(2) 19-10-0 to 26-10-14 , Interior(1) 26-10-14 to 30-2-0, Exterior(2) 30-2-0 to 37-2-14, Interior(1) 37-2-14 to 50-10-8 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Provide adequate drainage to prevent water ponding.
4) All plates are MT20 plates unless otherwise indicated.
5) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
6) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members, with BCDL = 10.0psf.
7) Ceiling dead load (5.0 psf) on member(s). 23-24, 23-25
8) Bottom chord live load (40.0 psf) and additional bottom chord dead load (0.0 psf) applied only to room. 18-20
9) One RT7A USP connectors recommended to connect truss to bearing walls due to UPLIFT at jt(s) 2, 18, and 13. This connection is for uplift only and does not consider lateral forces.
10) Graphical purlin representation does not depict the size or the orientation of the purlin along the top and/or bottom chord.
11) ATTIC SPACE SHOWN IS DESIGNED AS UNINHABITABLE.




March 12,2019




ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | H11 | HIP | 1 | 1 | I36367008 |
| | | | | | Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:07:01 2019 Page 1

ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-c33V2Nap_1OZNNIXlqL9K1tbX8F49WynqexSxzzc_Qe

| -0-10-8 | 5-11-11 | 11-4-13 | 16-10-0 | 23-0-4 | 33-2-0 | 38-7-3 | 44-0-5 | 50-0-0 | 50-10-8 |
|---|---|---|---|---|---|---|---|---|---|
| 0-10-8 | 5-11-11 | 5-5-3 | 5-5-3 | 6-2-4 | 10-1-12 | 5-5-3 | 5-5-3 | 5-11-11 | 0-10-8 |

Scale = 1:89.9




| 7-8-4 | 16-10-0 | 29-4-4 | 33-2-0 | 42-3-12 | 50-0-0 |
|---|---|---|---|---|---|
| 7-8-4 | 9-1-12 | 12-6-4 | 3-9-12 | 9-1-12 | 7-8-4 |

Plate Offsets (X,Y)-- [9:0-4-6,Edge]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.73 | Vert(LL) | -0.21 | 18-20 | >999 | 240 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.57 | Vert(CT) | -0.35 | 18-20 | >988 | 180 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.90 | Horz(CT) | 0.02 | 18 | n/a | n/a | | |
| BCDL | 10.0 | Code | IRC2015/TPI2014 | Matrix-S | | | | | | | Weight: 331 lb | FT = 20% |

**LUMBER-**

| | |
|---|---|
| TOP CHORD | 2x4 SP No.2 *Except* 6-8,8-9: 2x6 SP No.2 |
| BOT CHORD | 2x6 SP No.2 |
| WEBS | 2x4 SP No.3 |

**BRACING-**

| | |
|---|---|
| TOP CHORD | Structural wood sheathing directly applied or 4-1-7 oc purlins, except 2-0-0 oc purlins (6-0-0 max.): 6-9. |
| BOT CHORD | Rigid ceiling directly applied or 6-0-0 oc bracing. |
| WEBS | 1 Row at midpt 6-20, 7-18, 9-18 |

**REACTIONS.** (lb/size) 2=945/0-3-8, 18=2679/0-3-8, 13=475/0-3-8
Max Horz 2=146(LC 12)
Max Uplift 2=-153(LC 12), 18=-101(LC 9), 13=-142(LC 13)
Max Grav 2=1000(LC 23), 18=2679(LC 1), 13=558(LC 24)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.

| | |
|---|---|
| TOP CHORD | 2-3=-1673/243, 3-5=-1490/257, 5-6=-730/205, 6-7=-599/223, 7-9=-29/1039, 9-10=-16/608, 10-12=-535/227, 12-13=-719/214 |
| BOT CHORD | 2-22=-278/1427, 20-22=-137/986, 17-18=-494/238, 15-17=-268/142, 13-15=-106/576 |
| WEBS | 3-22=-304/184, 5-22=-81/516, 5-20=-588/236, 7-20=-74/907, 7-18=-1611/352, 9-18=-1295/270, 9-17=-109/501, 10-17=-610/223, 10-15=-63/584, 12-15=-316/186 |

**NOTES-**

1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph (3-second gust) Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=30ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) -0-10-8 to 4-1-8, Interior(1) 4-1-8 to 16-10-0, Exterior(2) 16-10-0 to 23-10-14 , Interior(1) 23-10-14 to 33-2-0, Exterior(2) 33-2-0 to 40-2-14, Interior(1) 40-2-14 to 50-10-8 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Provide adequate drainage to prevent water ponding.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members, with BCDL = 10.0psf.
6) One RT7A USP connectors recommended to connect truss to bearing walls due to UPLIFT at jt(s) 2, 18, and 13. This connection is for uplift only and does not consider lateral forces.
7) Graphical purlin representation does not depict the size or the orientation of the purlin along the top and/or bottom chord.


March 12,2019




ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | H12 | HIP | 1 | 1 | I36367009 |
| | | | | | Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:07:02 2019 Page 1

ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-4GdtGjbRlKXQ_XtjIYsOsEQlbXWguy6x3Ig?TPzc_Qd

| -0-10-8 | 7-5-4 | 14-4-0 | 21-9-4 | 28-6-11 | 29-4-4 | 35-8-0 | 42-6-12 | 50-0-0 | 50-10-8 |
|---|---|---|---|---|---|---|---|---|---|
| 0-10-8 | 7-5-4 | 6-10-12 | 7-5-4 | 6-9-7 | 0-9-9 | 6-3-12 | 6-10-12 | 7-5-4 | 0-10-8 |

Scale = 1:89.9




| 7-5-4 | 14-4-0 | 21-9-4 | 29-4-4 | 35-8-0 | 42-6-12 | 50-0-0 |
|---|---|---|---|---|---|---|
| 7-5-4 | 6-10-12 | 7-5-4 | 7-7-0 | 6-3-12 | 6-10-12 | 7-5-4 |

Plate Offsets (X,Y)-- [3:0-3-0,0-3-4], [5:0-2-12,0-3-4], [8:0-3-0,0-3-4]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.77 | Vert(LL) | -0.31 | 2-16 | >999 | 240 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.87 | Vert(CT) | -0.66 | 2-16 | >527 | 180 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.90 | Horz(CT) | 0.02 | 9 | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2015/TPI2014 | | Matrix-S | | | | | | | Weight: 304 lb | FT = 20% |

**LUMBER-**

| | |
|---|---|
| TOP CHORD | 2x4 SP No.2 |
| BOT CHORD | 2x6 SP No.2 |
| WEBS | 2x4 SP No.3 |

**BRACING-**

| | |
|---|---|
| TOP CHORD | Structural wood sheathing directly applied or 3-6-1 oc purlins, except 2-0-0 oc purlins (4-10-7 max.): 4-7. |
| BOT CHORD | Rigid ceiling directly applied or 6-0-0 oc bracing. |
| WEBS | 1 Row at midpt 6-13, 7-13 |

**REACTIONS.** (lb/size) 2=1023/0-3-8, 13=2488/0-3-8, 9=587/0-3-8
Max Horz 2=126(LC 12)
Max Uplift 2=-140(LC 12), 13=-206(LC 9), 9=-134(LC 13)
Max Grav 2=1058(LC 23), 13=2488(LC 1), 9=640(LC 24)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.

| | |
|---|---|
| TOP CHORD | 2-3=-1644/327, 3-4=-1145/200, 4-5=-935/232, 5-6=-449/160, 6-7=-16/815, 8-9=-719/246 |
| BOT CHORD | 2-16=-255/1395, 15-16=-69/463, 13-15=-814/283, 9-12=-119/571 |
| WEBS | 3-16=-522/307, 5-16=-96/706, 5-15=-969/232, 6-15=-233/1573, 6-13=-1495/341, 7-13=-1182/167, 7-12=0/631, 8-12=-544/307 |

**NOTES-**

1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph (3-second gust) Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=30ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) -0-10-8 to 4-1-8, Interior(1) 4-1-8 to 14-4-0, Exterior(2) 14-4-0 to 21-4-14, Interior(1) 21-4-14 to 35-8-0, Exterior(2) 35-8-0 to 42-8-3, Interior(1) 42-8-3 to 50-10-8 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Provide adequate drainage to prevent water ponding.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members, with BCDL = 10.0psf.
6) One RT7A USP connectors recommended to connect truss to bearing walls due to UPLIFT at jt(s) 2, 13, and 9. This connection is for uplift only and does not consider lateral forces.
7) Graphical purlin representation does not depict the size or the orientation of the purlin along the top and/or bottom chord.


March 12,2019




ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | H13 | HIP | 1 | 1 | I36367010 |
| | | | | | Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:07:03 2019 Page 1
ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-YSBFT3b3WefHchSvsFNdPSyvxxvgdSn4HyQZ0szc_Qc

| 6-1-4 | 11-8-0 | 16-0-10 | 24-9-14 | 29-4-4 | 31-8-0 | 38-4-0 | 43-10-12 | 50-0-0 | 50-10-8 |
|---|---|---|---|---|---|---|---|---|---|
| 6-1-4 | 5-6-12 | 4-4-10 | 8-9-4 | 4-6-6 | 2-3-12 | 6-8-0 | 5-6-12 | 6-1-4 | 0-10-8 |

Scale = 1:87.5




| 6-1-4 | 11-8-0 | 20-5-4 | 29-4-4 | 38-4-0 | 43-10-12 | 50-0-0 |
|---|---|---|---|---|---|---|
| 6-1-4 | 5-6-12 | 8-9-4 | 8-11-0 | 8-11-12 | 5-6-12 | 6-1-4 |

Plate Offsets (X,Y)-- [6:0-3-0,Edge], [12:0-3-12,0-4-8], [16:0-2-12,0-4-8], [16:0-0-0,0-2-12], [17:0-1-12,0-0-0]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.86 | Vert(LL) | -0.14 | 1-17 | >999 | 240 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.63 | Vert(CT) | -0.31 | 1-17 | >999 | 180 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.75 | Horz(CT) | 0.03 | 13 | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2015/TPI2014 | | Matrix-S | | | | | | | Weight: 295 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.2 *Except* 6-8: 2x4 SP No.1
BOT CHORD 2x6 SP No.2
WEBS 2x4 SP No.3

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 3-11-0 oc purlins, except 2-0-0 oc purlins (4-3-4 max.): 3-8.
BOT CHORD Rigid ceiling directly applied or 6-0-0 oc bracing.
WEBS 1 Row at midpt 5-13

**REACTIONS.** (lb/size) 1=967/0-3-8, 13=2475/0-3-8, 10=596/0-3-8
Max Horz 1=-111(LC 17)
Max Uplift 1=-106(LC 12), 13=-286(LC 9), 10=-134(LC 13)
Max Grav 1=986(LC 23), 13=2475(LC 1), 10=635(LC 24)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
TOP CHORD 1-2=-1721/358, 2-3=-1327/235, 3-4=-1107/251, 4-5=-593/143, 5-7=-53/946, 7-8=-307/152, 8-9=-408/128, 9-10=-801/241
BOT CHORD 1-17=-251/1494, 15-17=-152/1036, 12-13=-946/279, 10-12=-130/655
WEBS 2-17=-431/259, 3-17=-20/366, 4-15=-747/193, 5-15=-67/942, 5-13=-1428/240, 7-13=-1177/272, 7-12=-217/1380, 8-12=-308/145, 9-12=-405/244

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph (3-second gust) Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=30ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) 0-1-12 to 5-1-12, Interior(1) 5-1-12 to 11-8-0, Exterior(2) 11-8-0 to 18-8-14, Interior(1) 18-8-14 to 38-4-0, Exterior(2) 38-4-0 to 45-4-14, Interior(1) 45-4-14 to 50-10-8 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Provide adequate drainage to prevent water ponding.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members, with BCDL = 10.0psf.
6) One RT7A USP connectors recommended to connect truss to bearing walls due to UPLIFT at jt(s) 1, 13, and 10. This connection is for uplift only and does not consider lateral forces.
7) Graphical purlin representation does not depict the size or the orientation of the purlin along the top and/or bottom chord.


March 12,2019




ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | H14 | HIP | 1 | 1 | I36367011 |
| | | | | | Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:07:04 2019 Page 1

ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-0eldhPchHyn8Eq06QzusxfV4HLG1MrXEWc96YIzc_Qb

| 4-9-4 | 9-0-0 | 19-8-0 | 29-4-4 | 30-4-0 | 41-0-0 | 45-2-12 | 50-0-0 | 50-10-8 |
|---|---|---|---|---|---|---|---|---|
| 4-9-4 | 4-2-12 | 10-8-0 | 9-8-4 | 0-11-12 | 10-8-0 | 4-2-12 | 4-9-4 | 0-10-8 |

Scale = 1:87.5




| 9-0-0 | 19-8-0 | 29-4-4 | 35-2-2 | 41-0-0 | 50-0-0 |
|---|---|---|---|---|---|
| 9-0-0 | 10-8-0 | 9-8-4 | 5-9-14 | 5-9-14 | 9-0-0 |

Plate Offsets (X,Y)-- [6:0-4-0,0-4-12], [7:0-4-6,Edge]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.89 | Vert(LL) | -0.10 | 15-17 | >999 | 240 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.55 | Vert(CT) | -0.24 | 15-17 | >999 | 180 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.97 | Horz(CT) | 0.06 | 9 | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2015/TPI2014 | | Matrix-S | | | | | | | Weight: 310 lb | FT = 20% |

**LUMBER-**

| | |
|---|---|
| TOP CHORD | 2x6 SP No.2 *Except* 1-3,7-10: 2x4 SP No.2 |
| BOT CHORD | 2x6 SP No.2 |
| WEBS | 2x4 SP No.3 |

**BRACING-**

| | |
|---|---|
| TOP CHORD | Structural wood sheathing directly applied or 3-10-4 oc purlins, except 2-0-0 oc purlins (3-7-0 max.): 3-7. |
| BOT CHORD | Rigid ceiling directly applied or 10-0-0 oc bracing. |
| WEBS | 1 Row at midpt 5-17<br>2 Rows at 1/3 pts 5-13, 7-13 |

**REACTIONS.** (lb/size) 1=1034/0-3-8, 13=2314/0-3-8, 9=691/0-3-8
Max Horz 1=-89(LC 17)
Max Uplift 1=-87(LC 12), 13=-342(LC 9), 9=-116(LC 13)
Max Grav 1=1039(LC 23), 13=2314(LC 1), 9=705(LC 24)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.

| | |
|---|---|
| TOP CHORD | 1-2=-1945/367, 2-3=-1688/277, 3-5=-1474/285, 5-6=-69/697, 6-7=-57/676, 7-8=-786/145, 8-9=-1056/234 |
| BOT CHORD | 1-17=-266/1686, 15-17=-199/1341, 13-15=-199/1341, 11-13=0/655, 9-11=-148/891 |
| WEBS | 3-17=0/413, 5-15=0/384, 5-13=-2199/355, 6-13=-709/312, 7-13=-1387/211, 7-11=0/488, 8-11=-256/189 |

**NOTES-**

1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph (3-second gust) Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=30ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) 0-1-12 to 5-1-12, Interior(1) 5-1-12 to 9-0-0, Exterior(2) 9-0-0 to 16-0-14, Interior(1) 16-0-14 to 41-0-0, Exterior(2) 41-0-0 to 48-0-14, Interior(1) 48-0-14 to 50-10-8 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Provide adequate drainage to prevent water ponding.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
6) One RT7A USP connectors recommended to connect truss to bearing walls due to UPLIFT at jt(s) 1, 13, and 9. This connection is for uplift only and does not consider lateral forces.
7) Graphical purlin representation does not depict the size or the orientation of the purlin along the top and/or bottom chord.


March 12,2019




ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | HG1 | HALF HIP GIRDER | 1 | 1 | I36367012 |
| | | | | | Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:07:13 2019 Page 1
ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-FNo1aUjK9jvspDCqSMYzpZNb6zLtzwgYbVr5MGzc_QS

| -0-10-8 | 3-10-4 | 6-10-0 | 12-4-15 | 17-11-14 | 23-6-13 | 29-1-12 | 34-2-10 | 39-3-8 | 44-4-6 | 49-8-12 |
|---|---|---|---|---|---|---|---|---|---|---|
| 0-10-8 | 3-10-4 | 2-11-12 | 5-6-15 | 5-6-15 | 5-6-15 | 5-6-15 | 5-0-14 | 5-0-14 | 5-0-14 | 5-4-6 |

Scale = 1:85.3




| 3-10-4 | 6-10-0 | 12-4-15 | 17-11-14 | 23-6-13 | 29-1-12 | 34-2-10 | 39-3-8 | 44-4-6 | 49-8-12 |
|---|---|---|---|---|---|---|---|---|---|
| 3-10-4 | 2-11-12 | 5-6-15 | 5-6-15 | 5-6-15 | 5-6-15 | 5-0-14 | 5-0-14 | 5-0-14 | 5-4-6 |

Plate Offsets (X,Y)-- [4:0-7-0,0-2-8], [9:0-3-4,0-1-8], [20:0-4-4,0-1-8], [24:0-1-12,0-0-0], [25:0-5-12,0-4-8], [25:0-0-0,0-2-12]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.94 | Vert(LL) | 0.18 | 23-24 | >999 | 240 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.57 | Vert(CT) | -0.30 | 23-24 | >999 | 180 | | |
| BCLL | 0.0 * | Rep Stress Incr | NO | WB | 0.91 | Horz(CT) | 0.04 | 20 | n/a | n/a | | |
| BCDL | 10.0 | Code | IRC2015/TPI2014 | Matrix-S | | | | | | | Weight: 310 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.2
BOT CHORD 2x6 SP No.2
WEBS 2x4 SP No.3 *Except*
6-24,6-22,9-22,9-19,12-19,12-16: 2x4 SP No.2

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 3-4-6 oc purlins, except end verticals, and 2-0-0 oc purlins (2-5-1 max.): 4-14.
BOT CHORD Rigid ceiling directly applied or 4-3-1 oc bracing.
WEBS 1 Row at midpt 6-22, 9-20

**REACTIONS.** (lb/size) 15=834/Mechanical, 2=1453/0-3-8, 20=3986/0-3-8 (req. 0-4-11)
Max Horz 2=147(LC 12)
Max Uplift 15=-305(LC 8), 2=-335(LC 12), 20=-1398(LC 9)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
TOP CHORD 2-3=-2719/731, 3-4=-2482/743, 4-5=-2774/931, 5-6=-2773/931, 6-8=-308/125, 8-9=-308/125, 9-10=-166/541, 10-12=-166/541, 12-13=-893/341, 13-14=-893/341, 14-15=-755/336
BOT CHORD 2-27=-746/2377, 26-27=-746/2377, 24-26=-700/2200, 23-24=-742/2156, 22-23=-742/2156, 20-22=-2609/878, 19-20=-2609/878, 17-19=-288/679, 16-17=-288/679
WEBS 4-26=0/454, 4-24=-341/685, 5-24=-570/400, 6-24=-233/722, 6-23=0/389, 6-22=-2162/723, 8-22=-534/375, 9-22=-1172/3413, 9-20=-3691/1460, 9-19=-876/2486, 10-19=-474/333, 12-19=-1467/513, 12-17=0/343, 12-16=-83/258, 13-16=-536/374, 14-16=-387/1024

**NOTES-**
1) Wind: ASCE 7-10; Vult=130mph (3-second gust) Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=30ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) -0-10-8 to 3-10-4, Interior(1) 3-10-4 to 6-10-0, Exterior(2) 6-10-0 to 13-10-6, Interior(1) 13-10-6 to 49-7-0 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
2) Provide adequate drainage to prevent water ponding.
3) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
4) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
5) WARNING: Required bearing size at joint(s) 20 greater than input bearing size.
6) Refer to girder(s) for truss to truss connections.
7) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) except (jt=lb) 15=305, 20=1398.
8) One RT7A USP connectors recommended to connect truss to bearing walls due to UPLIFT at jt(s) 2. This connection is for uplift only and does not consider lateral forces.
9) Graphical purlin representation does not depict the size or the orientation of the purlin along the top and/or bottom chord.
10) "NAILED" indicates 3-10d (0.148"x3") or 3-12d (0.148"x3.25") toe-nails per NDS guidlines.
11) In the LOAD CASE(S) section, loads applied to the face of the truss are noted as front (F) or back (B).


March 12,2019

**LOAD CASE(S)** Standard

Continued on page 2



ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

**LOAD CASE(S)** Standard

1) Dead + Roof Live (balanced): Lumber Increase=1.15, Plate Increase=1.15
   Uniform Loads (plf)
   Vert: 1-4=-60, 4-14=-60, 2-15=-20
   Concentrated Loads (lb)
   Vert: 25=-27(F) 27=-57(F) 6=-73(F) 23=-27(F) 11=-73(F) 18=-27(F) 21=-27(F) 28=-63(F) 29=-73(F) 30=-73(F) 31=-73(F) 32=-73(F) 33=-73(F) 34=-73(F) 35=-73(F) 36=-73(F) 37=-73(F) 38=-73(F) 39=-73(F) 40=-73(F) 41=-73(F) 42=-73(F) 43=-73(F) 44=-73(F) 45=-73(F) 46=-73(F) 47=-73(F) 48=-37(F) 49=-27(F) 50=-27(F) 51=-27(F) 52=-27(F) 53=-27(F) 54=-27(F) 55=-27(F) 56=-27(F) 57=-27(F) 58=-27(F) 59=-27(F) 60=-27(F) 61=-27(F) 62=-27(F) 63=-27(F) 64=-27(F) 65=-27(F)

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | HG15 | HIP GIRDER | 1 | 1 | I36367013 |
| | | | | | Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:07:16 2019 Page 1
ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-gyTACVmDSeHRggxP7U6gQB?7iBMYAHB?HT3lzbzc_QP

| 3-10-4 | 6-10-0 | 11-4-1 | 15-10-2 | 20-4-2 | 24-10-3 | 29-4-4 | 33-11-8 | 38-6-12 | 43-2-0 | 46-1-12 | 50-0-0 | 50-10-8 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 3-10-4 | 2-11-12 | 4-6-1 | 4-6-1 | 4-6-1 | 4-6-1 | 4-6-1 | 4-7-4 | 4-7-4 | 4-7-4 | 2-11-12 | 3-10-4 | 0-10-8 |

Scale = 1:85.6




| 3-10-4 | 6-10-0 | 11-4-1 | 15-10-2 | 20-4-2 | 24-10-3 | 29-4-4 | 33-11-8 | 38-6-12 | 43-2-0 | 46-1-12 | 50-0-0 |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 3-10-4 | 2-11-12 | 4-6-1 | 4-6-1 | 4-6-1 | 4-6-1 | 4-6-1 | 4-7-4 | 4-7-4 | 4-7-4 | 2-11-12 | 3-10-4 |

Plate Offsets (X,Y)-- [3:0-7-0,0-2-8], [9:0-3-0,Edge], [12:0-7-0,0-2-8], [18:0-6-0,0-4-8], [18:0-1-12,0-0-0], [19:0-0-0,0-2-12], [21:0-5-0,0-4-0]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.86 | Vert(LL) | 0.17 | 25-27 | >999 | 240 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.57 | Vert(CT) | -0.27 | 25-27 | >999 | 180 | | |
| BCLL | 0.0 * | Rep Stress Incr | NO | WB | 0.93 | Horz(CT) | 0.05 | 14 | n/a | n/a | | |
| BCDL | 10.0 | Code | IRC2015/TPI2014 | Matrix-S | | | | | | | Weight: 312 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.2 *Except* 9-12,6-9: 2x4 SP No.1
BOT CHORD 2x6 SP No.2
WEBS 2x4 SP No.3

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 3-3-15 oc purlins, except 2-0-0 oc purlins (3-1-8 max.): 3-12.
BOT CHORD Rigid ceiling directly applied or 6-0-0 oc bracing.
WEBS 1 Row at midpt 7-21, 10-21

**REACTIONS.** (lb/size) 1=1384/0-3-8, 21=4029/0-3-8 (req. 0-4-12), 14=819/0-3-8
Max Horz 1=-72(LC 13)
Max Uplift 1=-339(LC 12), 21=-1365(LC 9), 14=-182(LC 13)
Max Grav 1=1388(LC 23), 21=4029(LC 1), 14=830(LC 24)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
TOP CHORD 1-2=-2713/795, 2-3=-2465/823, 3-4=-2731/969, 4-5=-2731/969, 5-6=-1516/583, 6-7=-1514/582, 7-8=-871/2761, 8-10=-871/2761, 10-11=-488/191, 11-12=-488/191, 12-13=-995/278, 13-14=-1399/307
BOT CHORD 1-29=-653/2376, 28-29=-653/2376, 27-28=-654/2177, 25-27=-858/2512, 24-25=-858/2512, 23-24=-295/150, 21-23=-295/150, 20-21=-812/350, 18-20=-812/350, 17-18=-147/865, 16-17=-224/1202, 14-16=-224/1202
WEBS 3-28=0/420, 3-27=-329/738, 4-27=-460/324, 5-27=-73/280, 5-25=0/297, 5-24=-1253/411, 6-24=-433/298, 7-24=-750/2235, 7-23=0/252, 7-21=-3086/1070, 8-21=-472/316, 10-21=-2428/792, 10-20=0/255, 10-18=-484/1564, 11-18=-479/332, 12-18=-484/108, 12-17=0/431, 13-17=-414/107

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph (3-second gust) Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=25ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) 0-1-12 to 3-1-12, Interior(1) 3-1-12 to 6-10-0, Exterior(2) 6-10-0 to 11-4-1, Interior(1) 11-4-1 to 43-2-0, Exterior(2) 43-2-0 to 47-4-15, Interior(1) 47-4-15 to 50-10-8 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Provide adequate drainage to prevent water ponding.
4) All plates are 2x4 MT20 unless otherwise indicated.
5) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
6) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
7) WARNING: Required bearing size at joint(s) 21 greater than input bearing size.
8) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) except (jt=lb) 21=1365.
9) One RT7A USP connectors recommended to connect truss to bearing walls due to UPLIFT at jt(s) 1 and 14. This connection is for uplift only and does not consider lateral forces.
10) Graphical purlin representation does not depict the size or the orientation of the purlin along the top and/or bottom chord.
11) "NAILED" indicates 3-10d (0.148"x3") or 3-12d (0.148"x3.25") toe-nails per NDS guidlines.
12) In the LOAD CASE(S) section, loads applied to the face of the truss are noted as front (F) or back (B).

Continued on page 2




March 12,2019



ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

**LOAD CASE(S)** Standard

1) Dead + Roof Live (balanced): Lumber Increase=1.15, Plate Increase=1.15
   Uniform Loads (plf)
      Vert: 1-3=-60, 3-12=-60, 12-15=-60, 1-14=-20
   Concentrated Loads (lb)
      Vert: 26=-27(B) 29=-27(B) 5=-73(B) 25=-27(B) 24=-27(B) 6=-73(B) 20=-27(B) 10=-73(B) 13=-84(B) 16=-57(B) 19=-27(B) 22=-27(B) 32=-73(B) 33=-73(B) 34=-73(B) 35=-73(B) 36=-73(B) 37=-73(B) 38=-73(B) 39=-73(B) 40=-73(B) 41=-73(B) 42=-73(B) 43=-73(B) 44=-73(B) 45=-73(B) 47=-73(B) 48=-73(B) 49=-63(B) 52=-27(B) 53=-27(B) 54=-27(B) 55=-27(B) 56=-27(B) 57=-27(B) 58=-27(B) 59=-27(B) 60=-27(B) 61=-27(B) 62=-27(B) 63=-27(B) 64=-27(B) 65=-27(B) 66=-37(B)

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | J1 | JACK-OPEN | 42 | 1 | I36367014 |
| | | | | | Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:07:16 2019 Page 1
ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-gyTACVmDSeHRggxP7U6gQB?EyBQJAVe?HT3lzbzc_QP




Plate Offsets (X,Y)-- [2:0-0-0,0-0-0], [2:0-0-11,0-4-5]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.39 | Vert(LL) | -0.03 | 2-4 | >999 | 240 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.27 | Vert(CT) | -0.06 | 2-4 | >984 | 180 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.00 | Horz(CT) | -0.00 | 3 | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2015/TPI2014 | | Matrix-P | | | | | | | Weight: 18 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.2
BOT CHORD 2x4 SP No.2
WEDGE
Left: 2x4 SP No.3

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 4-10-8 oc purlins.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.

**REACTIONS.** (lb/size) 3=133/Mechanical, 2=255/0-3-8, 4=47/Mechanical
Max Horz 2=144(LC 12)
Max Uplift 3=-107(LC 12), 2=-11(LC 12)
Max Grav 3=148(LC 19), 2=255(LC 1), 4=93(LC 3)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.

**NOTES-**
1) Wind: ASCE 7-10; Vult=130mph (3-second gust) Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=25ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) -0-10-8 to 2-1-8, Interior(1) 2-1-8 to 4-9-12 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
2) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
3) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
4) Refer to girder(s) for truss to truss connections.
5) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) except (jt=lb) 3=107.
6) One RT7A USP connectors recommended to connect truss to bearing walls due to UPLIFT at jt(s) 2. This connection is for uplift only and does not consider lateral forces.




March 12,2019




ENGINEERING BY
TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | J2 | JACK-OPEN | 2 | 1 | I36367015 |
| | | | | | Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:07:17 2019 Page 1
ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-881YPrmrDxPIIqWchCdvzPXQlan?vyu8V7pIV2zc_QO




Plate Offsets (X,Y)-- [2:0-0-11,0-4-5], [2:0-0-0,0-0-12], [3:0-2-0,0-2-3]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.33 | Vert(LL) | -0.02 | 2-5 | >999 | 240 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.24 | Vert(CT) | -0.05 | 2-5 | >999 | 180 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.00 | Horz(CT) | 0.03 | 4 | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2015/TPI2014 | | Matrix-P | | | | | | | Weight: 18 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.2
BOT CHORD 2x4 SP No.2
WEDGE
Left: 2x4 SP No.3

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 4-10-8 oc purlins, except
2-0-0 oc purlins: 3-4.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.

**REACTIONS.** (lb/size) 4=123/Mechanical, 2=255/0-3-8, 5=57/Mechanical
Max Horz 2=128(LC 12)
Max Uplift 4=-69(LC 12), 2=-21(LC 12)
Max Grav 4=123(LC 1), 2=255(LC 1), 5=88(LC 3)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph (3-second gust) Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=25ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) -0-10-8 to 2-1-8, Interior(1) 2-1-8 to 4-1-11, Exterior(2) 4-1-11 to 4-9-12 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Provide adequate drainage to prevent water ponding.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
6) Refer to girder(s) for truss to truss connections.
7) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 4.
8) One RT7A USP connectors recommended to connect truss to bearing walls due to UPLIFT at jt(s) 2. This connection is for uplift only and does not consider lateral forces.
9) Graphical purlin representation does not depict the size or the orientation of the purlin along the top and/or bottom chord.


March 12,2019




ENGINEERING BY
TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | J3 | JACK-OPEN GIRDER | 2 | 1 | I36367016<br>Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:07:18 2019 Page 1
ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-cLbwdBnT_FY9v_5oEv88Wc4ZH_5WeP8IknYs2Uzc_QN




Plate Offsets (X,Y)-- [2:0-0-11,0-4-5], [2:0-0-0,0-0-8], [3:0-3-0,0-2-3]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.47 | Vert(LL) | -0.03 | 2-6 | >999 | 240 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.35 | Vert(CT) | -0.06 | 2-6 | >883 | 180 | | |
| BCLL | 0.0 * | Rep Stress Incr | NO | WB | 0.00 | Horz(CT) | 0.07 | 4 | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2015/TPI2014 | | Matrix-P | | | | | | | Weight: 20 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.2
BOT CHORD 2x4 SP No.2
WEBS 2x4 SP No.3
WEDGE
Left: 2x4 SP No.3

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 4-10-8 oc purlins, except
2-0-0 oc purlins: 3-4.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.

**REACTIONS.** (lb/size) 2=322/0-3-8, 4=144/Mechanical, 6=77/Mechanical
Max Horz 2=90(LC 35)
Max Uplift 2=-53(LC 12), 4=-69(LC 9)
Max Grav 2=322(LC 1), 4=144(LC 1), 6=118(LC 3)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph (3-second gust) Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=25ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) -0-10-8 to 2-1-8, Interior(1) 2-1-8 to 2-7-11, Exterior(2) 2-7-11 to 4-8-0 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Provide adequate drainage to prevent water ponding.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
6) Refer to girder(s) for truss to truss connections.
7) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 4.
8) One RT7A USP connectors recommended to connect truss to bearing walls due to UPLIFT at jt(s) 2. This connection is for uplift only and does not consider lateral forces.
9) Graphical purlin representation does not depict the size or the orientation of the purlin along the top and/or bottom chord.
10) Gap between inside of top chord bearing and first diagonal or vertical web shall not exceed 0.500in.
11) "NAILED" indicates 3-10d (0.148"x3") or 3-12d (0.148"x3.25") toe-nails per NDS guidlines.
12) In the LOAD CASE(S) section, loads applied to the face of the truss are noted as front (F) or back (B).

**LOAD CASE(S)** Standard
1) Dead + Roof Live (balanced): Lumber Increase=1.15, Plate Increase=1.15
Uniform Loads (plf)
Vert: 1-3=-60, 3-4=-60, 2-5=-20
Concentrated Loads (lb)
Vert: 3=-41(B) 7=-36(B) 9=-24(B) 10=-16(B)

NORTH CAROLINA PROFESSIONAL SEAL 45844 ENGINEER ANDREW JOHNSON
March 12,2019



ENGINEERING BY TRENCO A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | J4 | JACK-OPEN | 2 | 1 | I36367017 |
| | | | | | Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:07:18 2019 Page 1
ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-cLbwdBnT_FY9v_5oEv88Wc4dF_8WeP8IknYs2Uzc_QN




| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.21 | Vert(LL) | -0.01 | 2-4 | >999 | 240 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.16 | Vert(CT) | -0.02 | 2-4 | >999 | 180 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.00 | Horz(CT) | -0.00 | 3 | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2015/TPI2014 | | Matrix-P | | | | | | | Weight: 14 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.2
BOT CHORD 2x4 SP No.2

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 3-10-4 oc purlins.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.

**REACTIONS.** (lb/size) 3=101/Mechanical, 2=216/0-3-8, 4=36/Mechanical
Max Horz 2=88(LC 12)
Max Uplift 3=-65(LC 12), 2=-32(LC 12)
Max Grav 3=101(LC 1), 2=216(LC 1), 4=73(LC 3)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.

**NOTES-**
1) Wind: ASCE 7-10; Vult=130mph (3-second gust) Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=30ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) -0-10-8 to 2-1-8, Interior(1) 2-1-8 to 3-9-8 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
2) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
3) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
4) Refer to girder(s) for truss to truss connections.
5) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 3.
6) One RT7A USP connectors recommended to connect truss to bearing walls due to UPLIFT at jt(s) 2. This connection is for uplift only and does not consider lateral forces.


March 12,2019




ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | J5 | JACK-OPEN | 2 | 1 | I36367018 |
| | | | | | Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:07:19 2019 Page 1
ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-4X9IqXo5lZg0X8g_ocfN2qdpSOU6NsORzRIPawzc_QM




Plate Offsets (X,Y)-- [3:0-2-0,0-2-8]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.18 | Vert(LL) | -0.01 | 2-5 | >999 | 240 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.13 | Vert(CT) | -0.02 | 2-5 | >999 | 180 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.00 | Horz(CT) | 0.01 | 4 | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2015/TPI2014 | | Matrix-P | | | | | | | Weight: 13 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.2
BOT CHORD 2x4 SP No.2

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 3-10-4 oc purlins, except
2-0-0 oc purlins: 3-4.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.

**REACTIONS.** (lb/size) 4=96/Mechanical, 2=216/0-3-8, 5=42/Mechanical
Max Horz 2=44(LC 12)
Max Uplift 4=-38(LC 9), 2=-36(LC 12)
Max Grav 4=96(LC 1), 2=216(LC 1), 5=67(LC 3)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph (3-second gust) Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=25ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Provide adequate drainage to prevent water ponding.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
6) Refer to girder(s) for truss to truss connections.
7) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 4.
8) One RT7A USP connectors recommended to connect truss to bearing walls due to UPLIFT at jt(s) 2. This connection is for uplift only and does not consider lateral forces.
9) Graphical purlin representation does not depict the size or the orientation of the purlin along the top and/or bottom chord.




March 12,2019




ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | JE | MONOPITCH SUPPORTED | 1 | 1 | I36367019<br>Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:07:20 2019 Page 1
ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-Yjjh2tpjWsot9IFBMKAcb19?MosS6JwaC51y6Mzc_QL




Plate Offsets (X,Y)-- [2:0-0-0,0-0-0], [2:0-0-11,0-4-5]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.11 | Vert(LL) | -0.00 | 1 | n/r | 120 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.06 | Vert(CT) | 0.00 | 1 | n/r | 120 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.05 | Horz(CT) | 0.00 | | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2015/TPI2014 | | Matrix-P | | | | | | | Weight: 26 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.2
BOT CHORD 2x4 SP No.2
WEBS 2x4 SP No.3
OTHERS 2x4 SP No.3
WEDGE
Left: 2x4 SP No.3

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 4-10-8 oc purlins, except end verticals.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.

**REACTIONS.** (lb/size) 5=44/4-10-8, 2=156/4-10-8, 6=231/4-10-8
Max Horz 2=142(LC 12)
Max Uplift 5=-17(LC 12), 6=-101(LC 12)
Max Grav 5=46(LC 19), 2=156(LC 1), 6=250(LC 19)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.

**NOTES-**
1) Wind: ASCE 7-10; Vult=130mph (3-second gust) Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=30ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Corner(3) -0-10-8 to 2-1-8, Exterior(2) 2-1-8 to 4-8-12 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
2) Truss designed for wind loads in the plane of the truss only. For studs exposed to wind (normal to the face), see Standard Industry Gable End Details as applicable, or consult qualified building designer as per ANSI/TPI 1.
3) Gable requires continuous bottom chord bearing.
4) Gable studs spaced at 2-0-0 oc.
5) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
6) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
7) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 5 except (jt=lb) 6=101.


March 12,2019




ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | JP1 | JACK-OPEN | 3 | 1 | I36367020 |
| | | | | | Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:07:20 2019 Page 1
ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-Yjjh2tpjWsot9IFBMKAcb19zLoqk6JeaC51y6Mzc_QL




| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.24 | Vert(LL) | 0.02 | 2-4 | >999 | 240 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.17 | Vert(CT) | -0.03 | 2-4 | >999 | 180 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.00 | Horz(CT) | -0.00 | 3 | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2015/TPI2014 | | Matrix-P | | | | | | | Weight: 14 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.2
BOT CHORD 2x4 SP No.2

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 4-0-0 oc purlins.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.

**REACTIONS.** (lb/size) 3=107/Mechanical, 2=220/0-3-0, 4=38/Mechanical
Max Horz 2=91(LC 12)
Max Uplift 3=-68(LC 12), 2=-32(LC 12), 4=-12(LC 8)
Max Grav 3=107(LC 1), 2=220(LC 1), 4=76(LC 3)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.

**NOTES-**
1) Wind: ASCE 7-10; Vult=130mph (3-second gust) Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=25ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) -0-10-8 to 2-1-8, Interior(1) 2-1-8 to 3-11-4 zone; porch left and right exposed;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
2) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
3) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
4) Refer to girder(s) for truss to truss connections.
5) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 3, 4.
6) One RT7A USP connectors recommended to connect truss to bearing walls due to UPLIFT at jt(s) 2. This connection is for uplift only and does not consider lateral forces.


March 12,2019



ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | JP2 | HALF HIP | 2 | 1 | I36367021 |
| | | | | | Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:07:21 2019 Page 1
ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-0wH3FDpMGAwkmSqNw1ir7Fi9xCAZrmtkQlnWepzc_QK




Plate Offsets (X,Y)-- [3:0-2-0,0-2-8]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.18 | Vert(LL) | 0.02 | 2-6 | >999 | 240 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.14 | Vert(CT) | -0.02 | 2-6 | >999 | 180 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.00 | Horz(CT) | 0.01 | 4 | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2015/TPI2014 | | Matrix-P | | | | | | | Weight: 15 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.2
BOT CHORD 2x4 SP No.2
WEBS 2x4 SP No.3

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 4-0-0 oc purlins, except 2-0-0 oc purlins: 3-4.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.

**REACTIONS.** (lb/size) 2=215/0-3-0, 6=46/Mechanical, 4=96/Mechanical
Max Horz 2=46(LC 12)
Max Uplift 2=-48(LC 9), 6=-13(LC 9), 4=-42(LC 9)
Max Grav 2=215(LC 1), 6=77(LC 3), 4=96(LC 1)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph (3-second gust) Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=25ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) zone; porch left and right exposed;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Provide adequate drainage to prevent water ponding.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
6) Refer to girder(s) for truss to truss connections.
7) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 6, 4.
8) One RT7A USP connectors recommended to connect truss to bearing walls due to UPLIFT at jt(s) 2. This connection is for uplift only and does not consider lateral forces.
9) Graphical purlin representation does not depict the size or the orientation of the purlin along the top and/or bottom chord.


March 12,2019




ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | P3 | COMMON | 1 | 1 | I36367022 |
| | | | | | Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:07:22 2019 Page 1
ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-V6rRSYq_1U2bObOZTlD4gSFlbbTjaCjtfPW3BFzc_QJ




Plate Offsets (X,Y)-- [2:0-0-0,0-0-12], [2:0-0-11,0-4-5], [4:0-0-0,0-0-12], [4:0-0-11,0-4-5]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.32 | Vert(LL) | 0.03 | 4-6 | >999 | 240 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.27 | Vert(CT) | -0.03 | 2-6 | >999 | 180 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.09 | Horz(CT) | 0.00 | 4 | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2015/TPI2014 | | Matrix-S | | | | | | | Weight: 43 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.2
BOT CHORD 2x4 SP No.2
WEBS 2x4 SP No.3
WEDGE
Left: 2x4 SP No.3, Right: 2x4 SP No.3

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 6-0-0 oc purlins.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.

**REACTIONS.** (lb/size) 2=450/0-3-0, 4=450/0-3-0
Max Horz 2=-97(LC 10)
Max Uplift 2=-62(LC 12), 4=-62(LC 13)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
TOP CHORD 2-3=-460/339, 3-4=-460/338
BOT CHORD 2-6=-182/304, 4-6=-182/304

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph (3-second gust) Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=25ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) -0-10-8 to 2-1-8, Interior(1) 2-1-8 to 5-0-0, Exterior(2) 5-0-0 to 8-0-0, Interior(1) 8-0-0 to 10-10-8 zone; porch left and right exposed;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
4) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
5) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 4.
6) One RT7A USP connectors recommended to connect truss to bearing walls due to UPLIFT at jt(s) 2. This connection is for uplift only and does not consider lateral forces.


March 12,2019




ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | PB1 | PIGGYBACK | 2 | 1 | I36367023 |
| | | | | | Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:07:22 2019 Page 1
ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-V6rRSYq_1U2bObOZTlD4gSFG_bMpaD7tfPW3BFzc_QJ

2-8-0 8-0-0 10-8-0
2-8-0 5-4-0 2-8-0

Scale = 1:18.3




10-8-0
10-8-0

Plate Offsets (X,Y)-- [2:0-2-10,0-1-8], [3:0-2-0,Edge], [4:0-2-0,Edge], [5:0-2-10,0-1-8]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.42 | Vert(LL) | 0.00 | 6 | n/r | 120 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.71 | Vert(CT) | 0.01 | 6 | n/r | 120 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.00 | Horz(CT) | 0.01 | 5 | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2015/TPI2014 | | Matrix-R | | | | | | | Weight: 30 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.2
BOT CHORD 2x4 SP No.2

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 6-0-0 oc purlins, except 2-0-0 oc purlins (6-0-0 max.): 3-4.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.

**REACTIONS.** (lb/size) 2=384/8-9-6, 5=384/8-9-6
Max Horz 2=-18(LC 17)
Max Uplift 2=-39(LC 9), 5=-39(LC 8)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
TOP CHORD 2-3=-662/298, 3-4=-608/281, 4-5=-662/298
BOT CHORD 2-5=-227/608

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph (3-second gust) Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=30ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) 0-4-11 to 6-10-15, Interior(1) 6-10-15 to 8-0-0, Exterior(2) 8-0-0 to 10-3-5 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Provide adequate drainage to prevent water ponding.
4) Gable requires continuous bottom chord bearing.
5) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
6) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
7) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 2, 5.
8) See Standard Industry Piggyback Truss Connection Detail for Connection to base truss as applicable, or consult qualified building designer.
9) Graphical purlin representation does not depict the size or the orientation of the purlin along the top and/or bottom chord.


March 12,2019




ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | PB2 | PIGGYBACK | 3 | 1 | I36367024 |
| | | | | | Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:07:23 2019 Page 1
ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-zIOpgurconAS0lzl1SkJDgnTn?q7Jgl1u3Gcjhzc_QI




| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.29 | Vert(LL) | -0.01 | 4-6 | >999 | 240 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.19 | Vert(CT) | -0.02 | 4-6 | >999 | 180 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.04 | Horz(CT) | 0.00 | 4 | n/a | n/a | | |
| BCDL | 10.0 | Code | IRC2015/TPI2014 | Matrix-P | | | | | | | Weight: 33 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.2
BOT CHORD 2x4 SP No.2
OTHERS 2x4 SP No.3

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 6-0-0 oc purlins.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.

**REACTIONS.** All bearings 10-6-0 except (jt=length) 5=0-3-8, 5=0-3-8.
(lb) - Max Horz 1=-44(LC 13)
Max Uplift All uplift 100 lb or less at joint(s) except 1=-210(LC 1), 2=-218(LC 12), 4=-174(LC 13), 5=-146(LC 1), 5=-146(LC 1)
Max Grav All reactions 250 lb or less at joint(s) 1, 5 except 2=457(LC 1), 4=406(LC 1), 6=300(LC 1)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph (3-second gust) Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=25ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) 0-4-11 to 3-4-11, Interior(1) 3-4-11 to 5-4-0, Exterior(2) 5-4-0 to 8-4-0, Interior(1) 8-4-0 to 10-5-4 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
4) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
5) Bearing at joint(s) 5 considers parallel to grain value using ANSI/TPI 1 angle to grain formula. Building designer should verify capacity of bearing surface.
6) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 210 lb uplift at joint 1, 218 lb uplift at joint 2, 174 lb uplift at joint 4 and 146 lb uplift at joint 5.
7) See Standard Industry Piggyback Truss Connection Detail for Connection to base truss as applicable, or consult qualified building designer.




March 12,2019



ENGINEERING BY
TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | PH1 | HIP GIRDER | 1 | 1 | I36367025 |
| | | | | | Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:07:24 2019 Page 1
ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-RUyBtEsEZ5IJdvYybAFYltKazPBp26IA6j?AF8zc_QH

| -0-10-8 | 2-9-0 | 7-3-0 | 10-0-0 | 10-10-8 |
|---|---|---|---|---|
| 0-10-8 | 2-9-0 | 4-6-0 | 2-9-0 | 0-10-8 |

Scale = 1:21.8




| 2-9-0 | 7-3-0 | 10-0-0 |
|---|---|---|
| 2-9-0 | 4-6-0 | 2-9-0 |

Plate Offsets (X,Y)-- [3:0-5-12,0-2-0]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.45 | Vert(LL) | 0.02 | 7-8 | >999 | 240 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.16 | Vert(CT) | -0.02 | 7-8 | >999 | 180 | | |
| BCLL | 0.0 * | Rep Stress Incr | NO | WB | 0.09 | Horz(CT) | 0.01 | 5 | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2015/TPI2014 | | Matrix-S | | | | | | | Weight: 55 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.2
BOT CHORD 2x6 SP No.2
WEBS 2x4 SP No.3

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 6-0-0 oc purlins, except 2-0-0 oc purlins (6-0-0 max.): 3-4.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.

**REACTIONS.** (lb/size) 2=608/0-3-0, 5=578/0-3-0
Max Horz 2=-60(LC 10)
Max Uplift 2=-224(LC 9), 5=-199(LC 8)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
TOP CHORD 2-3=-748/517, 3-4=-552/453, 4-5=-716/510
BOT CHORD 2-8=-350/556, 7-8=-359/565, 5-7=-351/544

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph (3-second gust) Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=25ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) -0-10-8 to 2-1-8, Interior(1) 2-1-8 to 2-9-0, Exterior(2) 2-9-0 to 10-10-8 zone; porch left and right exposed;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Provide adequate drainage to prevent water ponding.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
6) One RT7A USP connectors recommended to connect truss to bearing walls due to UPLIFT at jt(s) 2 and 5. This connection is for uplift only and does not consider lateral forces.
7) Graphical purlin representation does not depict the size or the orientation of the purlin along the top and/or bottom chord.
8) "NAILED" indicates 3-10d (0.148"x3") or 3-12d (0.148"x3.25") toe-nails per NDS guidlines.
9) In the LOAD CASE(S) section, loads applied to the face of the truss are noted as front (F) or back (B).

**LOAD CASE(S)** Standard
1) Dead + Roof Live (balanced): Lumber Increase=1.15, Plate Increase=1.15
Uniform Loads (plf)
Vert: 1-3=-60, 3-4=-60, 4-6=-60, 2-5=-20
Concentrated Loads (lb)
Vert: 3=-47(B) 4=-47(B) 8=-18(B) 7=-18(B) 9=-36(B) 11=-47(B) 13=-28(B) 14=-18(B) 15=-28(B)

NORTH CAROLINA PROFESSIONAL SEAL 45844 ENGINEER ANDREW JOHNSON
March 12,2019




ENGINEERING BY TRENCO A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | PH2 | HIP | 1 | 1 | I36367026 |
| | | | | | Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:07:25 2019 Page 1

ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-vhWZ5assKPQ9F3789tmnI5tp6pWZna8JLNljnazc_QG




Plate Offsets (X,Y)-- [2:0-0-0,0-0-0], [2:0-0-11,0-4-5], [5:0-0-11,0-4-5]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.24 | Vert(LL) | -0.02 | 2-8 | >999 | 240 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.20 | Vert(CT) | -0.03 | 2-8 | >999 | 180 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.05 | Horz(CT) | 0.01 | 5 | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2015/TPI2014 | | Matrix-S | | | | | | | Weight: 45 lb | FT = 20% |

**LUMBER-**

TOP CHORD 2x4 SP No.2
BOT CHORD 2x4 SP No.2
WEBS 2x4 SP No.3
WEDGE
Left: 2x4 SP No.3, Right: 2x4 SP No.3

**BRACING-**

TOP CHORD Structural wood sheathing directly applied or 6-0-0 oc purlins, except 2-0-0 oc purlins (6-0-0 max.): 3-4.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.

**REACTIONS.** (lb/size) 2=450/0-3-0, 5=450/0-3-0
Max Horz 2=83(LC 11)
Max Uplift 2=-64(LC 9), 5=-64(LC 8)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
TOP CHORD 2-3=-479/376, 3-4=-325/339, 4-5=-479/376
BOT CHORD 2-8=-217/329, 7-8=-211/325, 5-7=-217/329

**NOTES-**

1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph (3-second gust) Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=25ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) -0-10-8 to 2-1-8, Interior(1) 2-1-8 to 4-3-0, Exterior(2) 4-3-0 to 9-10-8, Interior(1) 9-10-8 to 10-10-8 zone; porch left and right exposed;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Provide adequate drainage to prevent water ponding.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
6) One RT7A USP connectors recommended to connect truss to bearing walls due to UPLIFT at jt(s) 2 and 5. This connection is for uplift only and does not consider lateral forces.
7) Graphical purlin representation does not depict the size or the orientation of the purlin along the top and/or bottom chord.


March 12,2019




ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | T7 | PIGGYBACK BASE | 2 | 1 | I36367027<br>Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:07:26 2019 Page 1
ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-Nt4yIwtU5iY0tDiKibH0qIPqxDkjWp2Ta1UHK0zc_QF

| -0-10-8 | 6-11-0 | 13-3-8 | 19-8-0 | 25-0-0 | 30-4-0 | 36-8-8 | 42-0-4 | 43-1-0 | 49-8-12 |
|---|---|---|---|---|---|---|---|---|---|
| 0-10-8 | 6-11-0 | 6-4-8 | 6-4-8 | 5-4-0 | 5-4-0 | 6-4-8 | 5-3-12 | 1-0-12 | 6-7-12 |

Scale = 1:87.6




| 10-1-4 | 19-8-0 | 25-0-0 | 30-4-0 | 36-8-8 | 42-0-4 | 49-8-12 |
|---|---|---|---|---|---|---|
| 10-1-4 | 9-6-12 | 5-4-0 | 5-4-0 | 6-4-8 | 5-3-12 | 7-8-8 |

Plate Offsets (X,Y)-- [6:0-7-0,0-2-8], [8:0-6-0,0-2-0], [16:0-2-12,0-2-8], [18:0-2-4,0-2-0]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.87 | Vert(LL) | -0.57 | 18-20 | >889 | 240 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.71 | Vert(TL) | -1.22 | 18-20 | >412 | 180 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.90 | Horz(TL) | 0.11 | 12 | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2012/TPI2007 | | Matrix-S | | Attic | -0.30 | 16-18 | 411 | 360 | Weight: 352 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.2
BOT CHORD 2x6 SP DSS *Except*
16-18: 2x6 SP No.2
WEBS 2x4 SP No.3 *Except*
6-18,8-16: 2x4 SP No.2

**BRACING-**
TOP CHORD Structural wood sheathing directly applied, except
2-0-0 oc purlins (2-9-9 max.): 6-8.
BOT CHORD Rigid ceiling directly applied or 9-7-6 oc bracing.
WEBS 1 Row at midpt 5-18
JOINTS 1 Brace at Jt(s): 21, 22, 23

**REACTIONS.** (lb/size) 2=1894/0-3-8, 13=1297/0-3-8, 12=935/Mechanical
Max Horz 2=180(LC 12)
Max Uplift 2=-219(LC 12), 13=-338(LC 13), 12=-181(LC 12)
Max Grav 2=2034(LC 2), 13=1659(LC 27), 12=1027(LC 26)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
TOP CHORD 2-3=-3997/461, 3-5=-3758/451, 5-6=-2852/409, 6-7=-2830/512, 7-8=-2830/512, 8-9=-2774/415, 9-11=-2485/359, 11-12=-2007/435
BOT CHORD 2-20=-442/3504, 18-20=-257/3012, 16-18=-80/2448, 14-16=-130/2161, 13-14=-325/1755, 12-13=-325/1755
WEBS 3-20=-358/221, 5-20=-69/677, 5-18=-835/285, 18-22=-27/859, 6-22=-16/888, 7-21=-337/162, 8-21=-154/587, 16-23=-51/715, 8-23=-39/735, 9-16=-12/425, 9-14=-722/181, 11-14=-151/1066, 11-13=-1408/410, 6-21=-162/413

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph (3-second gust) V(IRC2012)=103mph; TCDL=6.0psf; BCDL=6.0psf; h=30ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) -0-10-8 to 4-1-3, Interior(1) 4-1-3 to 19-8-0, Exterior(2) 19-8-0 to 26-8-6, Interior(1) 26-8-6 to 30-4-0, Exterior(2) 30-4-0 to 37-4-6, Interior(1) 37-4-6 to 49-8-0 zone; porch right exposed;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Provide adequate drainage to prevent water ponding.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members, with BCDL = 10.0psf.
6) Ceiling dead load (5.0 psf) on member(s). 21-22, 21-23
7) Bottom chord live load (40.0 psf) and additional bottom chord dead load (0.0 psf) applied only to room. 16-18
8) Refer to girder(s) for truss to truss connections.
9) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 181 lb uplift at joint 12.
10) One RT7A USP connectors recommended to connect truss to bearing walls due to UPLIFT at jt(s) 2 and 13. This connection is for uplift only and does not consider lateral forces.
11) Graphical purlin representation does not depict the size or the orientation of the purlin along the top and/or bottom chord.
12) ATTIC SPACE SHOWN IS DESIGNED AS UNINHABITABLE.


March 12,2019



ENGINEERING BY
TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | T8 | PIGGYBACK BASE | 1 | 1 | I36367028<br>Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:07:28 2019 Page 1
ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-JGCijcvldKok6Wsjq?KUwjUAo0RF_lvm1LzNOvzc_QD

| -0-10-8 | 6-11-0 | 13-3-8 | 19-8-0 | 24-7-0 | 30-4-0 | 36-8-8 | 43-1-0 | 50-0-0 |
|---|---|---|---|---|---|---|---|---|
| 0-10-8 | 6-11-0 | 6-4-8 | 6-4-8 | 4-11-0 | 5-9-0 | 6-4-8 | 6-4-8 | 6-11-0 |

Scale = 1:95.0




| 10-1-4 | 19-8-0 | 24-7-0 | 29-6-0 | 30-4-0 | 39-10-12 | 50-0-0 |
|---|---|---|---|---|---|---|
| 10-1-4 | 9-6-12 | 4-11-0 | 4-11-0 | 0-10-0 | 9-6-12 | 10-1-4 |

Plate Offsets (X,Y)-- [6:0-7-0,0-2-8], [9:0-3-8,0-2-4], [19:0-2-8,0-2-0]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.85 | Vert(LL) | -0.54 | 19-21 | >655 | 240 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.58 | Vert(TL) | -1.20 | 19-21 | >292 | 180 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.81 | Horz(TL) | 0.13 | 13 | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2012/TPI2007 | | Matrix-S | | Attic | -0.25 | 17-19 | 466 | 360 | Weight: 356 lb | FT = 20% |

**LUMBER-**

| | |
|---|---|
| TOP CHORD | 2x4 SP No.2 *Except* 11-13: 2x4 SP No.1 |
| BOT CHORD | 2x6 SP DSS *Except* 17-19: 2x6 SP No.2 |
| WEBS | 2x4 SP No.3 *Except* 6-19,9-16,8-17: 2x4 SP No.2 |

**BRACING-**

| | |
|---|---|
| TOP CHORD | Structural wood sheathing directly applied, except 2-0-0 oc purlins (3-0-12 max.): 6-9. |
| BOT CHORD | Rigid ceiling directly applied or 10-0-0 oc bracing. |
| WEBS | 1 Row at midpt 5-19, 10-16 |
| JOINTS | 1 Brace at Jt(s): 22, 23, 24 |

**REACTIONS.** (lb/size) 2=1869/0-3-8, 17=556/0-3-8, 13=1708/0-3-8
Max Horz 2=180(LC 16)
Max Uplift 2=-254(LC 12), 17=-218(LC 13), 13=-95(LC 12)
Max Grav 2=2027(LC 26), 17=834(LC 25), 13=1831(LC 2)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.

| | |
|---|---|
| TOP CHORD | 2-3=-3981/483, 3-5=-3743/473, 5-6=-2836/437, 6-7=-2757/517, 7-8=-2757/517, 8-9=-2406/431, 9-10=-2694/444, 10-12=-3355/459, 12-13=-3604/486 |
| BOT CHORD | 2-21=-507/3489, 19-21=-328/2999, 17-19=-133/2433, 16-17=-130/2405, 14-16=-210/2740, 13-14=-351/3160 |
| WEBS | 3-21=-357/221, 5-21=-55/666, 5-19=-820/274, 19-23=-61/888, 6-23=-52/918, 7-22=-310/144, 8-22=-119/516, 9-16=-107/993, 10-16=-692/272, 10-14=-61/537, 12-14=-390/235, 6-22=-132/315, 17-24=-383/124, 8-24=-360/134 |

**NOTES-**

1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph (3-second gust) V(IRC2012)=103mph; TCDL=6.0psf; BCDL=6.0psf; h=30ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) -0-10-8 to 4-1-8, Interior(1) 4-1-8 to 19-8-0, Exterior(2) 19-8-0 to 26-8-14, Interior(1) 26-8-14 to 30-4-0, Exterior(2) 30-4-0 to 37-4-14, Interior(1) 37-4-14 to 49-10-4 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Provide adequate drainage to prevent water ponding.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members, with BCDL = 10.0psf.
6) Ceiling dead load (5.0 psf) on member(s). 22-23, 22-24
7) Bottom chord live load (40.0 psf) and additional bottom chord dead load (0.0 psf) applied only to room. 17-19
8) One RT7A USP connectors recommended to connect truss to bearing walls due to UPLIFT at jt(s) 2, 17, and 13. This connection is for uplift only and does not consider lateral forces.
9) Graphical purlin representation does not depict the size or the orientation of the purlin along the top and/or bottom chord.
10) ATTIC SPACE SHOWN IS DESIGNED AS UNINHABITABLE.


March 12,2019



ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | T9 | PIGGYBACK BASE | 2 | 1 | I36367029<br>Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:07:29 2019 Page 1
ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-nSm4wywNOdwbkgRvOjrjSw1LaQnSjBbvG_jxxLzc_QC

| -0-10-8 | 6-11-0 | 13-3-8 | 19-8-0 | 24-7-0 | 30-4-0 | 36-8-8 | 43-1-0 | 50-0-0 | 50-10-8 |
|---|---|---|---|---|---|---|---|---|---|
| 0-10-8 | 6-11-0 | 6-4-8 | 6-4-8 | 4-11-0 | 5-9-0 | 6-4-8 | 6-4-8 | 6-11-0 | 0-10-8 |

Scale: 1/8"=1'




| 10-1-4 | 19-8-0 | 24-7-0 | 29-6-0 | 30-4-0 | 39-10-12 | 50-0-0 |
|---|---|---|---|---|---|---|
| 10-1-4 | 9-6-12 | 4-11-0 | 4-11-0 | 0-10-0 | 9-6-12 | 10-1-4 |

Plate Offsets (X,Y)-- [6:0-7-0,0-2-8], [9:0-3-8,0-2-4], [20:0-2-8,0-2-0]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.85 | Vert(LL) | -0.54 | 20-22 | >647 | 240 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.58 | Vert(TL) | -1.21 | 20-22 | >289 | 180 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.85 | Horz(TL) | 0.13 | 13 | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2012/TPI2007 | | Matrix-S | | Attic | -0.50 | 18-20 | 457 | 360 | Weight: 358 lb | FT = 20% |

**LUMBER-**

| | |
|---|---|
| TOP CHORD | 2x4 SP No.2 |
| BOT CHORD | 2x6 SP DSS *Except*<br>18-20: 2x6 SP No.2 |
| WEBS | 2x4 SP No.3 *Except*<br>6-20,9-17,8-18: 2x4 SP No.2 |

**BRACING-**

| | |
|---|---|
| TOP CHORD | Structural wood sheathing directly applied, except<br>2-0-0 oc purlins (3-1-8 max.): 6-9. |
| BOT CHORD | Rigid ceiling directly applied or 10-0-0 oc bracing. |
| WEBS | 1 Row at midpt 5-20, 10-17 |
| JOINTS | 1 Brace at Jt(s): 23, 24, 25 |

**REACTIONS.** (lb/size) 2=1862/0-3-8, 18=574/0-3-8, 13=1759/0-3-8
Max Horz 2=172(LC 12)
Max Uplift 2=-253(LC 12), 18=-215(LC 13), 13=-99(LC 12)
Max Grav 2=2018(LC 26), 18=846(LC 25), 13=1870(LC 2)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.

| | |
|---|---|
| TOP CHORD | 2-3=-3962/484, 3-5=-3724/473, 5-6=-2815/437, 6-7=-2705/509, 7-8=-2705/509,<br>8-9=-2381/431, 9-10=-2667/445, 10-12=-3321/445, 12-13=-3567/463 |
| BOT CHORD | 2-22=-498/3472, 20-22=-319/2981, 18-20=-124/2411, 17-18=-120/2380, 15-17=-180/2714,<br>13-15=-295/3123 |
| WEBS | 3-22=-357/221, 5-22=-55/668, 5-20=-822/274, 20-24=-61/885, 6-24=-52/912,<br>6-23=-122/285, 8-23=-110/487, 9-17=-108/979, 10-17=-691/273, 10-15=-58/533,<br>12-15=-376/224, 18-25=-385/123, 8-25=-363/133, 7-23=-313/144 |

**NOTES-**

1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph (3-second gust) V(IRC2012)=103mph; TCDL=6.0psf; BCDL=6.0psf; h=30ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) -0-10-8 to 4-1-8, Interior(1) 4-1-8 to 19-8-0, Exterior(2) 19-8-0 to 26-8-14, Interior(1) 26-8-14 to 30-4-0, Exterior(2) 30-4-0 to 37-4-14, Interior(1) 37-4-14 to 50-10-8 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Provide adequate drainage to prevent water ponding.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members, with BCDL = 10.0psf.
6) Ceiling dead load (5.0 psf) on member(s). 23-24, 23-25
7) Bottom chord live load (40.0 psf) and additional bottom chord dead load (0.0 psf) applied only to room. 18-20
8) One RT7A USP connectors recommended to connect truss to bearing walls due to UPLIFT at jt(s) 2, 18, and 13. This connection is for uplift only and does not consider lateral forces.
9) Graphical purlin representation does not depict the size or the orientation of the purlin along the top and/or bottom chord.
10) ATTIC SPACE SHOWN IS DESIGNED AS UNINHABITABLE.


March 12,2019



ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | V1 | GABLE | 1 | 1 | I36367030 |
| | | | | | Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:07:30 2019 Page 1
ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-GeKS8Iw?9x2SLq06xQMy?8afVqEQSp93VeSUTnzc_QB




| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.26 | Vert(LL) | n/a | - | n/a | 999 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.15 | Vert(CT) | n/a | - | n/a | 999 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.13 | Horz(CT) | 0.00 | 5 | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2015/TPI2014 | | Matrix-S | | | | | | | Weight: 63 lb | FT = 20% |

**LUMBER-**

| | |
|---|---|
| TOP CHORD | 2x4 SP No.2 |
| BOT CHORD | 2x4 SP No.2 |
| WEBS | 2x4 SP No.3 |
| OTHERS | 2x4 SP No.3 |

**BRACING-**

| | |
|---|---|
| TOP CHORD | Structural wood sheathing directly applied or 6-0-0 oc purlins, except end verticals. |
| BOT CHORD | Rigid ceiling directly applied or 6-0-0 oc bracing. |

**REACTIONS.** All bearings 13-9-11.
(lb) - Max Horz 9=-140(LC 13)
Max Uplift All uplift 100 lb or less at joint(s) 5 except 9=-108(LC 19), 8=-147(LC 12), 6=-162(LC 13)
Max Grav All reactions 250 lb or less at joint(s) 9, 5 except 7=403(LC 20), 8=386(LC 19), 6=436(LC 20)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
WEBS 2-8=-273/186, 4-6=-315/209

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph (3-second gust) Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=30ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) 0-1-12 to 3-1-12, Interior(1) 3-1-12 to 5-1-0, Exterior(2) 5-1-0 to 8-1-0, Interior(1) 8-1-0 to 13-3-15 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Gable requires continuous bottom chord bearing.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members, with BCDL = 10.0psf.
6) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 5 except (jt=lb) 9=108, 8=147, 6=162.


March 12,2019




ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | V2 | GABLE | 1 | 1 | I36367031 |
| | | | | | Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:07:30 2019 Page 1
ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-GeKS8Iw?9x2SLq06xQMy?8ahbqF_Spi3VeSUTnzc_QB




| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.19 | Vert(LL) | n/a | - | n/a | 999 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.12 | Vert(CT) | n/a | - | n/a | 999 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.09 | Horz(CT) | 0.00 | 5 | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2015/TPI2014 | | Matrix-S | | | | | | | Weight: 52 lb | FT = 20% |

**LUMBER-**

| | |
|---|---|
| TOP CHORD | 2x4 SP No.2 |
| BOT CHORD | 2x4 SP No.2 |
| WEBS | 2x4 SP No.3 |
| OTHERS | 2x4 SP No.3 |

**BRACING-**

| | |
|---|---|
| TOP CHORD | Structural wood sheathing directly applied or 6-0-0 oc purlins, except end verticals. |
| BOT CHORD | Rigid ceiling directly applied or 6-0-0 oc bracing. |

**REACTIONS.** All bearings 12-3-11.
(lb) - Max Horz 9=-108(LC 8)
Max Uplift All uplift 100 lb or less at joint(s) 9, 5 except 8=-160(LC 12), 6=-134(LC 13)
Max Grav All reactions 250 lb or less at joint(s) 9, 5 except 7=301(LC 1), 8=351(LC 19), 6=339(LC 20)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
WEBS 2-8=-276/193, 4-6=-263/176

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph (3-second gust) Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=30ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) 0-1-12 to 3-1-12, Interior(1) 3-1-12 to 5-1-0, Exterior(2) 5-1-0 to 8-1-0, Interior(1) 8-1-0 to 11-9-15 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Gable requires continuous bottom chord bearing.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
6) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 9, 5 except (jt=lb) 8=160, 6=134.


March 12,2019




ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | V3 | GABLE | 1 | 1 | I36367032 |
| | | | | | Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:07:31 2019 Page 1
ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-krtrLdxdwEAJz_bIV8tBXL6o3EYrBGACjIC2?Ezc_QA




| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.40 | Vert(LL) | n/a | - | n/a | 999 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.27 | Vert(CT) | n/a | - | n/a | 999 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.08 | Horz(CT) | 0.00 | 3 | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2015/TPI2014 | | Matrix-S | | | | | | | Weight: 40 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.2
BOT CHORD 2x4 SP No.2
OTHERS 2x4 SP No.3

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 6-0-0 oc purlins.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.

**REACTIONS.** (lb/size) 1=201/10-9-11, 3=207/10-9-11, 4=418/10-9-11
Max Horz 1=-86(LC 10)
Max Uplift 1=-37(LC 12), 3=-50(LC 13), 4=-13(LC 12)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
WEBS 2-4=-265/83

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph (3-second gust) Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=30ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) 0-0-0 to 3-0-0, Interior(1) 3-0-0 to 5-1-0, Exterior(2) 5-1-0 to 8-1-0, Interior(1) 8-1-0 to 10-3-15 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Gable requires continuous bottom chord bearing.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
6) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 1, 3, 4.




March 12,2019




ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | V4 | VALLEY | 1 | 1 | I36367033 |
| | | | | | Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:07:32 2019 Page 1
ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-C1RDZzyFhYIAb89U3rOQ4Zf?sdw2wk_LyyxbXgzc_Q9




| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.27 | Vert(LL) | n/a | - | n/a | 999 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.14 | Vert(CT) | n/a | - | n/a | 999 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.04 | Horz(CT) | 0.00 | 3 | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2015/TPI2014 | | Matrix-P | | | | | | | Weight: 29 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.2
BOT CHORD 2x4 SP No.2
OTHERS 2x4 SP No.3

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 6-0-0 oc purlins.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.

**REACTIONS.** (lb/size) 1=162/8-4-10, 3=162/8-4-10, 4=276/8-4-10
Max Horz 1=-62(LC 8)
Max Uplift 1=-36(LC 12), 3=-44(LC 13)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph (3-second gust) Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=30ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) 0-5-12 to 3-5-12, Interior(1) 3-5-12 to 4-2-11, Exterior(2) 4-2-11 to 7-2-11, Interior(1) 7-2-11 to 7-11-10 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Gable requires continuous bottom chord bearing.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
6) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 1, 3.


March 12,2019




ENGINEERING BY
TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | V5 | VALLEY | 1 | 1 | I36367034 |
| | | | | | Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:07:32 2019 Page 1
ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-C1RDZzyFhYIAb89U3rOQ4Zf2fdvJwkcLyyxbXgzc_Q9




Plate Offsets (X,Y)-- [2:0-2-0,Edge]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.09 | Vert(LL) | n/a | - | n/a | 999 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.25 | Vert(CT) | n/a | - | n/a | 999 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.00 | Horz(CT) | 0.00 | 3 | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2015/TPI2014 | | Matrix-P | | | | | | | Weight: 16 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.2
BOT CHORD 2x4 SP No.2

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 5-5-6 oc purlins.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.

**REACTIONS.** (lb/size) 1=179/5-4-10, 3=179/5-4-10
Max Horz 1=-37(LC 8)
Max Uplift 1=-19(LC 12), 3=-19(LC 13)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph (3-second gust) Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=30ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Gable requires continuous bottom chord bearing.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
6) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 1, 3.


March 12,2019




ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | V6 | VALLEY | 1 | 1 | I36367035 |
| | | | | | Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:07:33 2019 Page 1
ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-gD?bmJztSsQ1ClkgdZvfdmCEf1I5fBsVBch846zc_Q8




Plate Offsets (X,Y)-- [2:0-2-0,Edge]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.01 | Vert(LL) | n/a | - | n/a | 999 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.02 | Vert(CT) | n/a | - | n/a | 999 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.00 | Horz(CT) | 0.00 | 3 | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2015/TPI2014 | | Matrix-P | | | | | | | Weight: 6 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.2
BOT CHORD 2x4 SP No.2

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 2-5-6 oc purlins.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.

**REACTIONS.** (lb/size) 1=59/2-4-10, 3=59/2-4-10
Max Horz 1=-12(LC 8)
Max Uplift 1=-6(LC 12), 3=-6(LC 13)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph (3-second gust) Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=30ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Gable requires continuous bottom chord bearing.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
6) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 1, 3.




March 12,2019




ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | V7 | VALLEY | 1 | 1 | I36367036 |
| | | | | | Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:07:34 2019 Page 1

ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-8QZz_fzVD9ZuqRJtAGRu9_kJDRanOe5eQGQicZzc_Q7




Scale = 1:21.7

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.40 | Vert(LL) | n/a | - | n/a | 999 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.25 | Vert(CT) | n/a | - | n/a | 999 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.00 | Horz(CT) | 0.00 | | n/a | n/a | | |
| BCDL | 10.0 | Code | IRC2015/TPI2014 | Matrix-P | | | | | | | Weight: 20 lb | FT = 20% |

**LUMBER-**

| | |
|---|---|
| TOP CHORD | 2x4 SP No.2 |
| BOT CHORD | 2x4 SP No.2 |
| WEBS | 2x4 SP No.3 |

**BRACING-**

| | |
|---|---|
| TOP CHORD | Structural wood sheathing directly applied or 5-1-14 oc purlins, except end verticals. |
| BOT CHORD | Rigid ceiling directly applied or 10-0-0 oc bracing. |

**REACTIONS.** (lb/size) 1=181/5-1-14, 3=181/5-1-14
Max Horz 1=117(LC 12)
Max Uplift 3=-72(LC 12)
Max Grav 1=181(LC 1), 3=193(LC 19)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.

**NOTES-**

1) Wind: ASCE 7-10; Vult=130mph (3-second gust) Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=30ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) 0-5-12 to 3-5-12, Interior(1) 3-5-12 to 5-0-2 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
2) Gable requires continuous bottom chord bearing.
3) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
4) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
5) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 3.




March 12,2019




ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | V8 | VALLEY | 1 | 1 | I36367037 |
| | | | | | Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:07:34 2019 Page 1

ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-8QZz_fzVD9ZuqRJtAGRu9_kNuRc3Oe5eQGQicZzc_Q7




| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.17 | Vert(LL) | n/a | - | n/a | 999 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.11 | Vert(CT) | n/a | - | n/a | 999 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.00 | Horz(CT) | 0.00 | | n/a | n/a | | |
| BCDL | 10.0 | Code | IRC2015/TPI2014 | Matrix-P | | | | | | | Weight: 14 lb | FT = 20% |

**LUMBER-**

| | |
|---|---|
| TOP CHORD | 2x4 SP No.2 |
| BOT CHORD | 2x4 SP No.2 |
| WEBS | 2x4 SP No.3 |

**BRACING-**

| | |
|---|---|
| TOP CHORD | Structural wood sheathing directly applied or 3-7-14 oc purlins, except end verticals. |
| BOT CHORD | Rigid ceiling directly applied or 10-0-0 oc bracing. |

**REACTIONS.** (lb/size) 1=121/3-7-14, 3=121/3-7-14
Max Horz 1=78(LC 12)
Max Uplift 3=-48(LC 12)
Max Grav 1=121(LC 1), 3=129(LC 19)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.

**NOTES-**

1) Wind: ASCE 7-10; Vult=130mph (3-second gust) Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=30ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
2) Gable requires continuous bottom chord bearing.
3) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
4) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
5) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 3.


March 12,2019




ENGINEERING BY
TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | 140.1582 A 10x10 CP |
|---|---|---|---|---|---|
| 20137 | V9 | VALLEY | 1 | 1 | I36367038 |
| | | | | | Job Reference (optional) |

84 Components (Dunn), Dunn, NC - 28334, 8.220 s Nov 16 2018 MiTek Industries, Inc. Mon Mar 11 14:07:35 2019 Page 1
ID:RUSz4LGuFS2C1bODNZWBaZyX6cZ-cc7LB?_8zThlSbu3kzy7iBHahrza75LoewAF8?zc_Q6




Scale = 1:10.0

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.04 | Vert(LL) | n/a | - | n/a | 999 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.02 | Vert(CT) | n/a | - | n/a | 999 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.00 | Horz(CT) | 0.00 | | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2015/TPI2014 | | Matrix-P | | | | | | | Weight: 7 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.2
BOT CHORD 2x4 SP No.2
WEBS 2x4 SP No.3

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 2-1-14 oc purlins, except end verticals.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.

**REACTIONS.** (lb/size) 1=61/2-1-14, 3=61/2-1-14
Max Horz 1=39(LC 12)
Max Uplift 3=-24(LC 12)
Max Grav 1=61(LC 1), 3=65(LC 19)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.

**NOTES-**
1) Wind: ASCE 7-10; Vult=130mph (3-second gust) Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=30ft; Cat. II; Exp B; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
2) Gable requires continuous bottom chord bearing.
3) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
4) * This truss has been designed for a live load of 20.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
5) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 3.


March 12,2019



ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

# Symbols

## PLATE LOCATION AND ORIENTATION




Center plate on joint unless x, y offsets are indicated. Dimensions are in ft-in-sixteenths. Apply plates to both sides of truss and fully embed teeth.




For 4 x 2 orientation, locate plates 0- 1/16" from outside edge of truss.

This symbol indicates the required direction of slots in connector plates.

*** Plate location details available in MiTek 20/20 software or upon request.**

## PLATE SIZE

4 x 4

The first dimension is the plate width measured perpendicular to slots. Second dimension is the length parallel to slots.

## LATERAL BRACING LOCATION



Indicated by symbol shown and/or by text in the bracing section of the output. Use T or I bracing if indicated.

## BEARING



Indicates location where bearings (supports) occur. Icons vary but reaction section indicates joint number where bearings occur. Min size shown is for crushing only.

**Industry Standards:**

ANSI/TPI1: National Design Specification for Metal Plate Connected Wood Truss Construction.
DSB-89: Design Standard for Bracing.
BCSI: Building Component Safety Information, Guide to Good Practice for Handling, Installing & Bracing of Metal Plate Connected Wood Trusses.

# Numbering System




**JOINTS ARE GENERALLY NUMBERED/LETTERED CLOCKWISE AROUND THE TRUSS STARTING AT THE JOINT FARTHEST TO THE LEFT.**

**CHORDS AND WEBS ARE IDENTIFIED BY END JOINT NUMBERS/LETTERS.**

## PRODUCT CODE APPROVALS

ICC-ES Reports:

ESR-1311, ESR-1352, ESR1988
ER-3907, ESR-2362, ESR-1397, ESR-3282

Trusses are designed for wind loads in the plane of the truss unless otherwise shown.

Lumber design values are in accordance with ANSI/TPI 1 section 6.3 These truss designs rely on lumber values established by others.



MiTek®

ENGINEERING BY TRENCO
A MiTek Affiliate

MiTek Engineering Reference Sheet: MII-7473 rev. 10/03/2015

# General Safety Notes

Failure to Follow Could Cause Property Damage or Personal Injury

1. Additional stability bracing for truss system, e.g. diagonal or X-bracing, is always required. See BCSI.
2. Truss bracing must be designed by an engineer. For wide truss spacing, individual lateral braces themselves may require bracing, or alternative Tor I bracing should be considered.
3. Never exceed the design loading shown and never stack materials on inadequately braced trusses.
4. Provide copies of this truss design to the building designer, erection supervisor, property owner and all other interested parties.
5. Cut members to bear tightly against each other.
6. Place plates on each face of truss at each joint and embed fully. Knots and wane at joint locations are regulated by ANSI/TPI 1.
7. Design assumes trusses will be suitably protected from the environment in accord with ANSI/TPI 1.
8. Unless otherwise noted, moisture content of lumber shall not exceed 19% at time of fabrication.
9. Unless expressly noted, this design is not applicable for use with fire retardant, preservative treated, or green lumber.
10. Camber is a non-structural consideration and is the responsibility of truss fabricator. General practice is to camber for dead load deflection.
11. Plate type, size, orientation and location dimensions indicated are minimum plating requirements.
12. Lumber used shall be of the species and size, and in all respects, equal to or better than that specified.
13. Top chords must be sheathed or purlins provided at spacing indicated on design.
14. Bottom chords require lateral bracing at 10 ft. spacing, or less, if no ceiling is installed, unless otherwise noted.
15. Connections not shown are the responsibility of others.
16. Do not cut or alter truss member or plate without prior approval of an engineer.
17. Install and load vertically unless indicated otherwise.
18. Use of green or treated lumber may pose unacceptable environmental, health or performance risks. Consult with project engineer before use.
19. Review all portions of this design (front, back, words and pictures) before use. Reviewing pictures alone is not sufficient.
20. Design assumes manufacture in accordance with ANSI/TPI 1 Quality Criteria.